



United States Coast Guard

MISLE Incident Investigation Report For

SLNC GOODWILL / Loss of Life

On 05Aug2020 00:42:00 EDT



MISLE Activity Number: 7025155
MISLE Case Number: 1229748

I. INCIDENT INVESTIGATION – GENERAL INFORMATION

On 05Aug21, the SLNC GOODWILL (ON 1266919) was underway en route to Busan, Republic of Korea. At approx. 1342 Japan Standard time (Zulu +9), the #1 ship's service diesel generator (SSDG), hereafter referred to as DG#1, was being restarted following a change-out of the generator's governor; this restart was being conducted by the Chief Engineer (CE), 1st Assistant Engineer (1/AE), and 3rd Assistant Engineer (3/AE). The first attempt to restart DG #1 resulted in the rpms increasing to the point that the overspeed protection device tripped the engine offline. The governor was visually examined for loose connections, leaks, or other signs of malfunction; none were identified. The overspeed protection device was reset and DG #1 was restarted a second time. Again, the rpms steadily increased past the normal operating speed of 900 rpms, but this time the overspeed protection device didn't trip. The 1/AE quickly attempted to manually stop the engine at the governor, but was unsuccessful. While the 1/AE ran to the aft of the generator to manually activate the overspeed protection device and with the CE shouting for everyone to get back, the generator's flywheel broke apart at high speed sending large sections of the component hurtling through the surrounding area. One such section struck the 3/AE, who was still standing in the vicinity of the engine at the time, in the neck and upper torso.

The 1/AE ran to the engine control room to notify the bridge of the casualty while the CE attempted to render first aid to the 3/AE. The vessel's Fire Team arrived on scene within minutes and transported the 3/AE to the vessel's hospital space. The Medical Officer supervised the treatment of the 3/AE along with support from other crewmembers as well as a shoreside medical advisory service. The 3/AE was semi-conscious during initial treatment, but later lost consciousness and died as a result of the injuries sustained from being struck by the flywheel section.

As a result of this investigation, the U.S. Coast Guard has determined that the initiating event for this casualty was a mechanical failure of the governor recently installed on DG #1. This failure resulted in an uncontrolled supply of fuel to the engine which in turn resulted in an uncontrolled increase of the engine's rpms. The overspeed protection device failed to trip and the rpms increased to the point that the flywheel fractured, fatally striking the 3/AE and damaging the vessel's electrical and propulsion control systems. The causal factors that contributed to this casualty include: (1) mechanical damage to internal components of the governor installed on DG #1, (2) improper storage of the governor, (3) failure to verify internal condition of the governor, (4) governor storage procedures and recommendations, (5) inability to confirm the governor's maintenance history, (6) improper recordkeeping of governor, (7) failure of the engine's overspeed protection device, (8) inadequate mechanical properties of DG #1 flywheel, (9) inadequate chemical composition of DG#1 flywheel, (10) no reasonable PPE exists to prevent loss of life, (11) inability to conduct visual teleconferencing during medical treatment, (12) significant damage to vessel's electrical generation/distribution system, and (13) significant damage to the vessel's propulsion control systems.

Personnel Casualty Summary

Total Missing = 0

Total Dead = 1

Total Injured = 0

Total At Risk, Not Injured = 2

Total People At Risk = 3

Vessel(s) Status Summary

Actual Total Loss = 0

Total Constructive Loss Salvaged = 0

Total Constructive Loss Unsalvaged = 0

Damaged = 0

Undamaged = 1

Property Damage Summary

Vessel(s) = \$ 0

MISLE Incident Investigation Report

Cargo = \$ 0

Facility(s) = \$ 0

Other = \$ 0

* Includes estimates

II. LOCATIONS

<u>Description</u>	<u>Latitude</u>	<u>Longitude</u>
Sea of Japan, approx.74 NM southwest of the port of Sasebo, Japan	32°29.0 N	128°29.0 E

III. INVOLVED PERSONNEL

Name: (b) (6), (b) (7)(C)
Team Lead: No
Point Of Contact: No
Role: Investigating Officer - Field Investigation
Status: Assigned
Department Id: 000599
Type/Rank: (b) (6), (b) (7)(C)
Agency Type/Agency: Federal - DHS/Federal - DHS
Source Id/Source: (b) (6), (b) (7)(C)/Direct Access Personnel
Comments:

Name: (b) (6), (b) (7)(C).
Team Lead: Yes
Point Of Contact: Yes
Role: Investigating Officer - Field Investigation
Status: Assigned
Department Id: 000599
Type/Rank: Officer - (b) (6), (b) (7)(C)
Agency Type/Agency: Federal - DHS/Federal - DHS
Source Id/Source: (b) (6), (b) (7)(C)/Direct Access Personnel
Comments:

Name: (b) (6), (b) (7)(C)
Team Lead: No
Point Of Contact: No
Role: Investigating Officer - Field Investigation
Status: Assigned
Department Id: 000599
Type/Rank: (b) (6), (b) (7)(C)
Agency Type/Agency: Federal - DHS/Federal - DHS
Source Id/Source: (b) (6), (b) (7)(C)/Direct Access Personnel
Comments:

Name: (b) (6), (b) (7)(C)
Team Lead: No
Point Of Contact: No

MISLE Incident Investigation Report

Role: Investigation Administration/Review
Status: Assigned
Department Id: 000599
Type/Rank: Officer - (b) (6), (b) (7)(C)
Agency Type/Agency: Federal - DHS/Federal - DHS
Source Id/Source: (b) (6), (b) (7)(C)/Direct Access Personnel
Comments:

IV. INVOLVED TEAM

V. INVOLVED SUBJECTS

Involved Vessels

Name: SLNC GOODWILL
Flag: UNITED STATES
Primary VIN: 1266919
Call Sign: WDI5693
Damage Status: Undamaged
Role: Involved in a Marine Casualty
Classification, Type, Subtype: Tank Ship, Chemical Tank Ship, Oil & Chemical Tank Ship

Gross Tonnage:
Net Tonnage:
Dead Wt. Tonnage: 50326
Length: 580.4
Home/Hailing Port: WILMINGTON
Keel Laid Date: 21Nov2008
Delivery Date: 08May2009
Place of Construction: CHINA
Builder Name:
Propulsion Type: Diesel Direct
Ahead HP: 12712
Master: (b) (6), (b) (7)(C)
Classification Society: DET NORISKE VERITAS
Owner: NORD GOODWILL LLC
Operator: SCHUYLER LINE NAVIGATION CORP
Inspection Subchapter: OD
Most Recent Vessel Inspection Activity: 7014645, 23Jul2020 20:32:44 EDT
Current Certificate of Inspection: Issued On: 28Jan2016 by Activities Far East

Name: SLNC GOODWILL
Flag: UNITED STATES
Primary VIN: 1266919
Call Sign: WDI5693
Damage Status: Undamaged
Role: Involved in a Marine Casualty
Classification, Type, Subtype: Tank Ship, Chemical Tank Ship, Oil & Chemical Tank Ship

Gross Tonnage:
Net Tonnage:
Dead Wt. Tonnage: 50326
Length: 580.4
Home/Hailing Port: WILMINGTON
Keel Laid Date: 21Nov2008
Delivery Date: 08May2009
Place of Construction: CHINA

MISLE Incident Investigation Report

Builder Name: Diesel Direct
Propulsion Type: 12712
Ahead HP: (b) (6), (b) (7)(C)
Master: DNV
Classification Society: NORD GOODWILL LLC
Owner: SCHUYLER LINE NAVIGATION CORP
Operator: OD
Inspection Subchapter: 7014645, 23Jul2020 20:32:44 EDT
Most Recent Vessel Inspection Activity: Issued On: 28Jan2016 by Activities Far East
Current Certificate of Inspection:

Involved Persons

(b) (6), (b) (7)(C)
Status: Not at Risk
Role: Witness
Gender: (b) (6), (b) (7)(C)
Age: (b) (6)
SSN: (b) (6), (b) (7)(C)
Birth Date: (b) (6), (b) (7)(C)
Email Address: (b) (6), (b) (7)(C)
Phone Number (Primary): (b) (6), (b) (7)(C)
Address (Home/Primary Residence): (b) (6), (b) (7)(C)
(b) (7)(C), (b) (6)

Comments: (b) (6), (b) (7)(C)
Status: Not at Risk
Role: Witness
Gender: (b) (6), (b) (7)(C)
Age: (b) (6)
SSN: (b) (6), (b) (7)(C)
Birth Date: (b) (6), (b) (7)(C)
Email Address: (b) (6), (b) (7)(C)
Phone Number: (b) (6), (b) (7)(C)
Address (Home/Primary Residence): (b) (6), (b) (7)(C)
(b) (7)(C), (b) (6)

Comments: (b) (6), (b) (7)(C)
Status: Not at Risk
Role: Other
Gender: (b) (6), (b) (7)(C)
Age: (b) (6)
SSN: (b) (6), (b) (7)(C)
Birth Date: (b) (6), (b) (7)(C)
Email Address: (b) (6), (b) (7)(C)
Phone Number: (b) (6), (b) (7)(C)
Address: (b) (6), (b) (7)(C)
(b) (7)(C), (b) (6)

Comments: (b) (6), (b) (7)(C)
Status: Not at Risk
Role: Witness
Gender: (b) (6), (b) (7)(C)
Age: (b) (6)
SSN: (b) (6), (b) (7)(C)
Birth Date: (b) (6), (b) (7)(C)
Email Address: (b) (7)(C), (b) (6)

MISLE Incident Investigation Report

Phone Number (Phone Number):
Address (Home/Primary Residence):

(b) (6), (b) (7)(C)
(b) (6), (b) (7)(C)
(b) (7)(C), (b) (6)

Comments:

(b) (6), (b) (7)(C)

Status:
Role:
Gender:
Age:
SSN:
Birth Date:
Email Address:
Phone Number (Work):
Address (Primary):

Not at Risk
Medical Review Officer

(b) (6), (b) (7)(C)

(b) (6), (b) (7)(C)
(b) (6), (b) (7)(C)
(b) (6), (b) (7)(C)

(b) (7)(C), (b) (6)

Comments:

LLOYD-REES, TRENTON

Status:
Role:
Gender:
Age:
SSN:
Birth Date:
Email Address:
Phone Number:
Address (Home/Primary Residence):

Dead
Subject of Investigation

(b) (6), (b) (7)(C)

(b) (6)

(b) (6), (b) (7)(C)

(b) (6), (b) (7)(C)

(b) (6), (b) (7)(C)

(b) (7)(C), (b) (6)

Comments:

(b) (6), (b) (7)(C)

Status:
Role:
Gender:
Age:
SSN:
Birth Date:
Email Address:
Phone Number (Phone Number):
Address (Home/Primary Residence):

Not at Risk
Witness

(b) (6), (b) (7)(C)

(b) (6)

(b) (6), (b) (7)(C)

(b) (6), (b) (7)(C)

(b) (6), (b) (7)(C)

(b) (6), (b) (7)(C)

(b) (6), (b) (7)(C)

(b) (7)(C), (b) (6)

Comments:

(b) (6), (b) (7)(C)

Status:
Role:
Gender:
Age:
SSN:
Birth Date:
Email Address:
Phone Number:
Address (Home/Primary Residence):

At Risk, Not Injured
Witness

(b) (6), (b) (7)(C)

(b) (6)

(b) (6), (b) (7)(C)

(b) (6), (b) (7)(C)

(b) (6), (b) (7)(C)

(b) (7)(C), (b) (6)

Comments:

(b) (6), (b) (7)(C)

MISLE Incident Investigation Report

Status: Not at Risk
Role: Witness
Gender:
Age:
SSN:
Birth Date:
Email Address:
Phone Number:
Address:
Comments: Mechanical Engineer & Principal Specialist of the Classification Society's Failure Investigation Team

(b) (6), (b) (7)(C)

Status: At Risk, Not Injured
Role: Witness
Gender: (b) (6), (b) (7)(C)
Age: (b) (6)
SSN: (b) (6), (b) (7)(C)
Birth Date: (b) (6), (b) (7)(C)
Email Address:
Phone Number (Phone Number): (b) (6), (b) (7)(C)
Address (Home/Primary Residence): (b) (6), (b) (7)(C)

Comments:

(b) (7)(C), (b) (6)
(b) (6), (b) (7)(C)

Drug and Alcohol Testing. The following people have been determined by the Coast Guard, Law Enforcement Personnel, and/or the Marine Employer to have been directly involved in a Serious Marine Incident as defined in 46 CFR 4.03-2:

(b) (6), (b) (7)(C) (b) (6), (b) (7)(C) Witness
(b) (6), (b) (7)(C) Witness
(b) (6), (b) (7)(C) (b) (6), (b) (7)(C) Witness
(b) (6), (b) (7)(C) (b) (6), (b) (7)(C) Witness
(b) (6), (b) (7)(C) (b) (6), (b) (7)(C) Witness

Involved Organizations

Lloyd's Register Europe, Middle East, and Africa (EMEA)
Role: Other
Email Address:
Phone Number:
Address (Primary): Lloyd's Register EMEA
Global Technology Centre
Southampton SO16 7QF
United Kingdom
Comments: conducted post-casualty analysis of flywheel

NORD GOODWILL LLC
Role: Other
Email Address:
Phone Number:
Address (Primary Place of Business): 130 SEVERN AVENUE SUITE 201
ANNAPOLIS, Maryland 21403
UNITED STATES
Comments:

R-Tech Materials
Role: Other
Email Address: info@r-techmaterials.com
Phone Number:

MISLE Incident Investigation Report

Address (Primary): Testing House,
Kenfig Industrial Estate,
Margam,
Port Talbot, UK.
SA13 2PE

Comments: conducted post-casualty analysis of flywheel

SCHUYLER LINE NAVIGATION CORP

Role: Other

Email Address:

Phone Number (NVDC Phone Number): 410-216-6020

Address (Primary Place of Business): 130 SEVERN AVENUE SUITE 201
ANNAPOLIS, Maryland 21403
UNITED STATES

Comments:

Woodward Inc.

Role: Witness

Email Address:

Phone Number (Work): 800-543-5811

Address (Work): 1081 Woodward Way
Fort Collins, Colorado 80524
UNITED STATES

Comments: manufacturer of the governor installed on DG #1 at the
time of the casualty (Governor C)

Involved Facilities: None

Involved Waterways

EAST CHINA SEA

Role: Location

Description: Sea of Japan, approx.74 NM southwest of the port of
Sasebo, Japan

Involved Other Subjects: None

VI. EVIDENCE

Control Number: 7025155 - MISLE - 0

Description: MISLE Notification #963833 for a report of an incident received by Cellular phone call
to Coast Guard

Evidence Type: Misle Notification

Collection Information

Date/Time: 05Aug2020 18:32:09 EDT

Location: Activities Far East

Collected By: (b) (6), (b) (7)(C); U. S. Coast Guard

Attachments

MISLE Incident Investigation Report

Control Number: 7025155-(b) (6), (b) (7)(C)001
Description: CG_2692
Evidence Type: Standard

Collection Information

Date/Time: 16Sep2021 20:53:55 EDT
Location:
Collected By: (b) (6), (b) (7)(C) U. S. Coast Guard

Attachments

CG2692; CG-2692-Rpt of Marine, Comm Dive, or OCS Casualty;
24Oct2021 20:59:03 EDT; No

Control Number: 7025155-(b) (6), (b) (7)(C)002
Description: CG_2692B with test results
Evidence Type: Standard

Collection Information

Date/Time: 16Sep2021 20:54:19 EDT
Location:
Collected By: (b) (6), (b) (7)(C) U. S. Coast Guard

Attachments

CG02-CG2692B, results; CG-2692B-Rpt of Mandatory Chem Test Following SMI;
09Dec2021 00:28:17 EST; No

Control Number: 7025155-(b) (6), (b) (7)(C)003
Description: CG_2692C
Evidence Type: Standard

Collection Information

Date/Time: 16Sep2021 20:54:57 EDT
Location:
Collected By: (b) (6), (b) (7)(C) U. S. Coast Guard

Attachments

CG2692C; CG-2692C-Personnel Casualty Addendum;
24Oct2021 21:00:07 EDT; No

Control Number: 7025155-(b) (6), (b) (7)(C)004
Description: Deck logbook entries, SLNC GOODWILL
Evidence Type: Standard

Collection Information

Date/Time: 16Sep2021 20:55:16 EDT
Location:
Collected By: (b) (6), (b) (7)(C) U. S. Coast Guard

Attachments

deck logbook; Documentary Evidence;
24Oct2021 21:00:31 EDT; No

MISLE Incident Investigation Report

Control Number: 7025155-(b) (6), (b) (7)(C)005

Description: Activity Timeline (provided by Master)
Evidence Type: Standard

Collection Information

Date/Time: 16Sep2021 20:55:52 EDT
Location:
Collected By: (b) (6), (b) (7)(C) U. S. Coast Guard

Attachments

deck timeline; Documentary Evidence;
24Oct2021 21:00:57 EDT; No

Control Number: 7025155-(b) (6), (b) (7)(C)006

Description: Witness statement, Chief Engineer
Evidence Type: Standard

Collection Information

Date/Time: 16Sep2021 20:56:38 EDT
Location:
Collected By: (b) (6), (b) (7)(C) U. S. Coast Guard

Attachments

Witness statement, (b) (7)(C), (b) (6); Witness Statement/Interview Record;
24Oct2021 21:01:40 EDT; No

Control Number: 7025155-(b) (6), (b) (7)(C)007

Description: Audio recording, Chief Engineer interview
Evidence Type: Standard

Collection Information

Date/Time: 16Sep2021 20:57:30 EDT
Location:
Collected By: (b) (6), (b) (7)(C) U. S. Coast Guard

Attachments

audio recording of interview, (b) (6), (b) (7)(C); Witness Statement/Interview Record;
24Oct2021 21:02:06 EDT; No

Control Number: 7025155-(b) (6), (b) (7)(C)008

Description: Witness statement, Chief Mate
Evidence Type: Standard

Collection Information

Date/Time: 16Sep2021 20:57:57 EDT
Location:
Collected By: (b) (6), (b) (7)(C) U. S. Coast Guard

Attachments

witness statement, (b) (6), (b) (7)(C) Witness Statement/Interview Record;
24Oct2021 21:02:33 EDT; No

MISLE Incident Investigation Report

Control Number: 7025155-(b) (6), (b) (7)(C)009

Description: Audio recording, Chief Mate interview
Evidence Type: Standard

Collection Information

Date/Time: 16Sep2021 20:58:15 EDT
Location:
Collected By: (b) (6), (b) (7)(C) U. S. Coast Guard

Attachments

audio recording of interview, (b) (6), (b) (7)(C) Witness Statement/Interview Record;
24Oct2021 21:02:55 EDT; No

Control Number: 7025155-(b) (6), (b) (7)(C)010

Description: Witness statement, Second Mate
Evidence Type: Standard

Collection Information

Date/Time: 16Sep2021 20:58:42 EDT
Location:
Collected By: (b) (6), (b) (7)(C) U. S. Coast Guard

Attachments

witness statement, 2M; Witness Statement/Interview Record;
24Oct2021 21:03:55 EDT; No

Control Number: 7025155-(b) (6), (b) (7)(C)011

Description: Audio recording, Second Mate interview
Evidence Type: Standard

Collection Information

Date/Time: 16Sep2021 20:59:27 EDT
Location:
Collected By: (b) (6), (b) (7)(C) U. S. Coast Guard

Attachments

witness statement, 2M; Witness Statement/Interview Record;
24Oct2021 21:10:19 EDT; No

Control Number: 7025155-(b) (6), (b) (7)(C)012

Description: Audio recording, Fourth Mate interview
Evidence Type: Standard

Collection Information

Date/Time: 16Sep2021 21:03:11 EDT
Location:
Collected By: (b) (6), (b) (7)(C) U. S. Coast Guard

Attachments

audio recording of interview, 4M (b) (6), (b) (7)(C) Witness Statement/Interview Record;
24Oct2021 21:13:51 EDT; No

MISLE Incident Investigation Report

Control Number: 7025155-(b) (6), (b) (7)(C)013

Description: Audio recording, First Assistant Engineer interview
Evidence Type: Standard

Collection Information

Date/Time: 16Sep2021 21:03:37 EDT
Location:
Collected By: (b) (6), (b) (7)(C) U. S. Coast Guard

Attachments

audio recording of interview, 1AE, (b) (6), (b) (7)(C) Witness Statement/Interview Record;
24Oct2021 21:14:21 EDT; No

Control Number: 7025155-(b) (6), (b) (7)(C)014

Description: Audio recording, Master interview
Evidence Type: Standard

Collection Information

Date/Time: 16Sep2021 21:04:08 EDT
Location:
Collected By: (b) (6), (b) (7)(C) U. S. Coast Guard

Attachments

audio recording of interview, Master; Witness Statement/Interview Record;
24Oct2021 21:18:32 EDT; No

Control Number: 7025155-(b) (6), (b) (7)(C)015

Description: Sign on paperwork, Third Assistant Engineer
Evidence Type: Standard

Collection Information

Date/Time: 16Sep2021 21:04:23 EDT
Location:
Collected By: (b) (6), (b) (7)(C) U. S. Coast Guard

Attachments

sign on paperwork, 3AE; Documentary Evidence;
24Oct2021 21:23:36 EDT; No

Control Number: 7025155-(b) (6), (b) (7)(C)016

Description: Photo index, engine room alarm log
Evidence Type: Standard

Collection Information

Date/Time: 16Sep2021 22:25:05 EDT
Location:
Collected By: (b) (6), (b) (7)(C) U. S. Coast Guard

Attachments

photo index, alarm log; Documentary Evidence;
24Oct2021 21:27:26 EDT; No

MISLE Incident Investigation Report

IMG_0124; Photograph;
24Oct2021 21:28:09 EDT; No

IMG_0125; Photograph;
24Oct2021 21:28:25 EDT; No

IMG_0126; Photograph;
24Oct2021 21:28:40 EDT; No

IMG_0127; Photograph;
24Oct2021 21:28:57 EDT; No

Control Number: 7025155-(b) (6), (b) (7)(C)017

Description: Photo index, engine room logbook entries

Evidence Type: Standard

Collection Information

Date/Time: 16Sep2021 22:25:40 EDT

Location:

Collected By: (b) (6), (b) (7)(C) U. S. Coast Guard

Attachments

photo index, engine logbook; Documentary Evidence;
24Oct2021 21:29:46 EDT; No

IMG_0129; Photograph;
24Oct2021 21:30:29 EDT; No

IMG_0130; Photograph;
24Oct2021 21:30:45 EDT; No

IMG_0131; Photograph;
24Oct2021 21:31:03 EDT; No

IMG_0132; Photograph;
24Oct2021 21:31:19 EDT; No

IMG_0133; Photograph;
24Oct2021 21:31:33 EDT; No

IMG_0135; Photograph;
24Oct2021 21:31:48 EDT; No

Control Number: 7025155-(b) (6), (b) (7)(C)018

Description: Photo index, debris in engine room between DG#1 and DG#2

Evidence Type: Standard

Collection Information

Date/Time: 17Sep2021 01:29:07 EDT

Location:

Collected By: (b) (6), (b) (7)(C) U. S. Coast Guard

Attachments

photo index, debris between DG#1 and DG#2; Documentary Evidence;
24Oct2021 21:32:28 EDT; No

IMG_0042; Photograph;
24Oct2021 21:32:59 EDT; No

MISLE Incident Investigation Report

IMG_0043; Photograph;
24Oct2021 21:33:11 EDT; No

IMG_0044; Photograph;
24Oct2021 21:33:25 EDT; No

IMG_0047; Photograph;
24Oct2021 21:34:06 EDT; No

Control Number: 7025155-(b) (6), (b) (7)(C)019

Description: Photo index, debris between DG#1 and DG#2
Evidence Type: Standard

Collection Information

Date/Time: 19Oct2021 20:07:08 EDT
Location:
Collected By: (b) (6), (b) (7)(C) U. S. Coast Guard

Attachments

photo index, DG#1; Documentary Evidence;
24Oct2021 21:34:43 EDT; No

IMG_0045; Photograph;
24Oct2021 21:35:14 EDT; No

IMG_0049; Photograph;
24Oct2021 21:35:30 EDT; No

IMG_0060; Photograph;
24Oct2021 21:35:46 EDT; No

IMG_0065; Photograph;
24Oct2021 21:36:00 EDT; No

IMG_0066; Photograph;
24Oct2021 21:36:16 EDT; No

IMG_0074; Photograph;
24Oct2021 21:36:39 EDT; No

Control Number: 7025155-(b) (6), (b) (7)(C)020

Description: Photo index, undamaged DG#2 for reference
Evidence Type: Standard

Collection Information

Date/Time: 19Oct2021 20:08:15 EDT
Location:
Collected By: (b) (6), (b) (7)(C) U. S. Coast Guard

Attachments

photo index, DG#2, undamaged; Documentary Evidence;
24Oct2021 21:37:24 EDT; No

IMG_0082; Photograph;
24Oct2021 21:38:01 EDT; No

IMG_0083; Photograph;
24Oct2021 21:38:16 EDT; No

MISLE Incident Investigation Report

IMG_0085; Photograph;
24Oct2021 21:38:31 EDT; No

IMG_0099; Photograph;
24Oct2021 21:38:47 EDT; No

Control Number: 7025155-(b) (6), (b) (7)(C)021

Description: Photo index, governor

Evidence Type: Standard

Collection Information

Date/Time: 19Oct2021 20:09:03 EDT

Location:

Collected By: (b) (6), (b) (7)(C) U. S. Coast Guard

Attachments

photo index, governor; Documentary Evidence;
24Oct2021 21:53:06 EDT; No

IMG_0161; Photograph;
24Oct2021 21:53:42 EDT; No

IMG_0162; Photograph;
24Oct2021 21:54:05 EDT; No

IMG_0163; Photograph;
24Oct2021 22:23:04 EDT; No

IMG_0165; Photograph;
24Oct2021 22:23:26 EDT; No

IMG_0184; Photograph;
24Oct2021 22:23:44 EDT; No

IMG_0193; Photograph;
24Oct2021 22:24:03 EDT; No

Control Number: 7025155-(b) (6), (b) (7)(C)022

Description: Photo index, flywheel pieces

Evidence Type: Standard

Collection Information

Date/Time: 19Oct2021 20:18:23 EDT

Location:

Collected By: (b) (6), (b) (7)(C) U. S. Coast Guard

Attachments

photo index, flywheel pieces; Documentary Evidence;
24Oct2021 22:33:53 EDT; No

IMG_0208; Photograph;
25Oct2021 01:12:43 EDT; No

IMG_0209; Photograph;
25Oct2021 01:13:03 EDT; No

MISLE Incident Investigation Report

IMG_0211; Photograph;
25Oct2021 01:13:17 EDT; No

Control Number: 7025155-(b) (6), (b) (7)(C)023

Description: Photo, depiction of the 1/AE's position at the time of the casualty
Evidence Type: Standard

Collection Information

Date/Time: 19Oct2021 20:18:50 EDT
Location:
Collected By: (b) (6), (b) (7)(C) U. S. Coast Guard

Attachments

photo, position of 3AE; Photograph;
25Oct2021 01:16:02 EDT; No

Control Number: 7025155-(b) (6), (b) (7)(C)024

Description: Photo index, engine room damage
Evidence Type: Standard

Collection Information

Date/Time: 19Oct2021 20:19:37 EDT
Location:
Collected By: (b) (6), (b) (7)(C) U. S. Coast Guard

Attachments

photo index, damage to engine room; Documentary Evidence;
25Oct2021 01:18:04 EDT; No

IMG_0067; Photograph;
25Oct2021 01:22:21 EDT; No

IMG_0068; Photograph;
25Oct2021 01:22:34 EDT; No

IMG_0069; Photograph;
25Oct2021 01:22:48 EDT; No

IMG_0114; Photograph;
25Oct2021 01:23:05 EDT; No

MISLE Incident Investigation Report

Control Number: 7025155-(b) (6), (b) (7)(C)025

Description: Work/Rest history, 1AE

Evidence Type: Standard

Collection Information

Date/Time: 20Oct2021 21:55:04 EDT

Location:

Collected By: (b) (6), (b) (7)(C) U. S. Coast Guard

Attachments

work-rest, 1AE; Documentary Evidence;
25Oct2021 01:30:29 EDT; No

Control Number: 7025155-(b) (6), (b) (7)(C)026

Description: Work/Rest history, 2AE

Evidence Type: Standard

Collection Information

Date/Time: 20Oct2021 21:55:40 EDT

Location:

Collected By: (b) (6), (b) (7)(C) U. S. Coast Guard

Attachments

work-rest, 2AE; Documentary Evidence;
25Oct2021 01:41:21 EDT; No

Control Number: 7025155-(b) (6), (b) (7)(C)027

Description: Work/Rest history, 3AE

Evidence Type: Standard

Collection Information

Date/Time: 20Oct2021 21:56:04 EDT

Location:

Collected By: (b) (6), (b) (7)(C) U. S. Coast Guard

Attachments

work-rest, 3AE; Documentary Evidence;
25Oct2021 01:41:57 EDT; No

Control Number: 7025155-(b) (6), (b) (7)(C)028

Description: Work/Rest history, Chief Engineer

Evidence Type: Standard

Collection Information

Date/Time: 20Oct2021 21:56:27 EDT

Location:

Collected By: (b) (6), (b) (7)(C) U. S. Coast Guard

Attachments

CG28 - Work-rest, CE; Documentary Evidence;
25Oct2021 01:42:21 EDT; No

MISLE Incident Investigation Report

Control Number: 7025155-**(b) (6), (b) (7)(C)**029

Description: Work/Rest history: Oiler #1, Oiler #2, QMED
Evidence Type: Standard

Collection Information

Date/Time: 20Oct2021 21:56:51 EDT
Location:
Collected By: **(b) (6), (b) (7)(C)** U. S. Coast Guard

Attachments

work-rest - Oiler1, Oiler2, QMED; Documentary Evidence;
25Oct2021 01:42:56 EDT; No

Control Number: 7025155-**(b) (6), (b) (7)(C)**030

Description: Excerpt from ops manual regarding 3AE duties
Evidence Type: Standard

Collection Information

Date/Time: 21Oct2021 01:21:21 EDT
Location:
Collected By: **(b) (6), (b) (7)(C)** U. S. Coast Guard

Attachments

exerpt, description of duties, 3AE; Documentary Evidence;
25Oct2021 01:43:32 EDT; No

Control Number: 7025155-**(b) (6), (b) (7)(C)**031

Description: Excerpt from ops manual regarding emergency procedures
Evidence Type: Standard

Collection Information

Date/Time: 21Oct2021 01:58:15 EDT
Location:
Collected By: **(b) (6), (b) (7)(C)** U. S. Coast Guard

Attachments

exerpt, emergency procedures; Documentary Evidence;
25Oct2021 02:05:42 EDT; No

Control Number: 7025155-**(b) (6), (b) (7)(C)**032

Description: Report of Death, 3AE
Evidence Type: Standard

Collection Information

Date/Time: 21Oct2021 01:58:59 EDT
Location:
Collected By: **(b) (6), (b) (7)(C)** U. S. Coast Guard

Attachments

3AE, report of death; Documentary Evidence;
25Oct2021 02:06:21 EDT; No

MISLE Incident Investigation Report

Control Number: 7025155-(b) (6), (b) (7)(C)033

Description: Excerpt from ops manual regarding DG#1 particulars
Evidence Type: Standard

Collection Information

Date/Time: 21Oct2021 01:59:16 EDT
Location:
Collected By: (b) (6), (b) (7)(C) U. S. Coast Guard

Attachments

excerpt, engine particulars; Documentary Evidence;
25Oct2021 02:06:46 EDT; No

Control Number: 7025155-(b) (6), (b) (7)(C)034

Description: Excerpt from ops manual regarding DG#1 maintenance schedule
Evidence Type: Standard

Collection Information

Date/Time: 21Oct2021 02:00:30 EDT
Location:
Collected By: (b) (6), (b) (7)(C) U. S. Coast Guard

Attachments

excerpt from ops manual, maintenance schedule; Documentary Evidence;
25Oct2021 02:10:20 EDT; No

Control Number: 7025155-(b) (6), (b) (7)(C)035

Description: Excerpt from ops manual regarding DG#1 maintenance
Evidence Type: Standard

Collection Information

Date/Time: 21Oct2021 02:02:52 EDT
Location:
Collected By: (b) (6), (b) (7)(C) U. S. Coast Guard

Attachments

excerpt, engine maintenance; Documentary Evidence;
25Oct2021 02:12:12 EDT; No

Control Number: 7025155-(b) (6), (b) (7)(C)036

Description: Excerpt from ops manual showing fly wheel diagram
Evidence Type: Standard

Collection Information

Date/Time: 21Oct2021 02:03:32 EDT
Location:
Collected By: (b) (6), (b) (7)(C) U. S. Coast Guard

Attachments

excerpt, fly wheel diagram; Documentary Evidence;
25Oct2021 02:14:04 EDT; No

MISLE Incident Investigation Report

Control Number: 7025155-(b) (6), (b) (7)(C)037

Description: Excerpt from ops manual regarding DG#1 operation
Evidence Type: Standard

Collection Information

Date/Time: 21Oct2021 02:04:08 EDT
Location:
Collected By: (b) (6), (b) (7)(C) U. S. Coast Guard

Attachments

excerpt, operating the engine; Documentary Evidence;
25Oct2021 02:14:59 EDT; No

Control Number: 7025155-(b) (6), (b) (7)(C)038

Description: Excerpt from ops manual regarding DG#1 overhaul recommendations
Evidence Type: Standard

Collection Information

Date/Time: 21Oct2021 02:05:05 EDT
Location:
Collected By: (b) (6), (b) (7)(C) U. S. Coast Guard

Attachments

excerpt, overhaul recommendation; Documentary Evidence;
25Oct2021 02:15:34 EDT; No

Control Number: 7025155-(b) (6), (b) (7)(C)039

Description: Excerpt from ops manual regarding disturbances while running DG#1
Evidence Type: Standard

Collection Information

Date/Time: 21Oct2021 02:07:57 EDT
Location:
Collected By: (b) (6), (b) (7)(C) U. S. Coast Guard

Attachments

excerpt, disturbances during running; Documentary Evidence;
25Oct2021 02:16:11 EDT; No

Control Number: 7025155-(b) (6), (b) (7)(C)040

Description: Rough log of DG#1 maintenance
Evidence Type: Standard

Collection Information

Date/Time: 21Oct2021 02:08:51 EDT
Location:
Collected By: (b) (6), (b) (7)(C) U. S. Coast Guard

Attachments

rough log, DG#1 maintenance; Documentary Evidence;
25Oct2021 02:16:47 EDT; No

MISLE Incident Investigation Report

Control Number: 7025155-**(b) (6), (b) (7)(C)**041
Description: DG#1 maintenance data
Evidence Type: Standard

Collection Information

Date/Time: 21Oct2021 02:09:17 EDT
Location:
Collected By: **(b) (6), (b) (7)(C)** U. S. Coast Guard

Attachments

DG#1 maintenance spreadsheet; Documentary Evidence;
25Oct2021 02:17:54 EDT; No

Control Number: 7025155-**(b) (6), (b) (7)(C)**042
Description: DG#1 service reports, 2019
Evidence Type: Standard

Collection Information

Date/Time: 21Oct2021 02:09:48 EDT
Location:
Collected By: **(b) (6), (b) (7)(C)** U. S. Coast Guard

Attachments

DG#1 service reports, 2019; Documentary Evidence;
25Oct2021 02:19:11 EDT; No

Control Number: 7025155-**(b) (6), (b) (7)(C)**043
Description: DG#1 - 200 hour service report, 23Jul20
Evidence Type: Standard

Collection Information

Date/Time: 21Oct2021 02:10:31 EDT
Location:
Collected By: **(b) (6), (b) (7)(C)** U. S. Coast Guard

Attachments

DG#1, 2000 HR service, 23Jul20; Documentary Evidence;
25Oct2021 02:21:47 EDT; No

Control Number: 7025155-**(b) (6), (b) (7)(C)**044
Description: Excerpt from ops manual regarding DG#1 governor
Evidence Type: Standard

Collection Information

Date/Time: 21Oct2021 02:12:07 EDT
Location:
Collected By: **(b) (6), (b) (7)(C)** U. S. Coast Guard

Attachments

exerpt, governor info; Documentary Evidence;
25Oct2021 02:22:13 EDT; No

MISLE Incident Investigation Report

Control Number: 7025155-(b) (6), (b) (7)(C)045

Description: Excerpt from ops manual regarding a tool used for adjusting governor overspeed stop
Evidence Type: Standard

Collection Information

Date/Time: 21Oct2021 02:12:45 EDT
Location:
Collected By: (b) (6), (b) (7)(C) U. S. Coast Guard

Attachments

CG45 - excerpt, tool for adjusting overspeed stop; Documentary Evidence;
25Oct2021 02:24:00 EDT; No

Control Number: 7025155-(b) (6), (b) (7)(C)046

Description: Product manual, UG-8 Speed Adjusting Devices
Evidence Type: Standard

Collection Information

Date/Time: 21Oct2021 02:13:35 EDT
Location:
Collected By: (b) (6), (b) (7)(C) U. S. Coast Guard

Attachments

governor manual; Documentary Evidence;
25Oct2021 02:24:35 EDT; No

Control Number: 7025155-(b) (6), (b) (7)(C)047

Description: Product manual, Shutdown Solenoid for UG Governor
Evidence Type: Standard

Collection Information

Date/Time: 21Oct2021 02:15:02 EDT
Location:
Collected By: (b) (6), (b) (7)(C) U. S. Coast Guard

Attachments

shutdown solenoid manual; Documentary Evidence;
25Oct2021 02:25:24 EDT; No

Control Number: 7025155-(b) (6), (b) (7)(C)048

Description: Product manual, Speed Adjusting (Synchronizing) Motor
Evidence Type: Standard

Collection Information

Date/Time: 21Oct2021 02:16:07 EDT
Location:
Collected By: (b) (6), (b) (7)(C) U. S. Coast Guard

Attachments

sync motor manual; Documentary Evidence;
25Oct2021 02:26:08 EDT; No

MISLE Incident Investigation Report

Control Number: 7025155-(b) (6), (b) (7)(C)049

Description: Company procedures for governor testing
Evidence Type: Standard

Collection Information

Date/Time: 21Oct2021 02:17:11 EDT
Location:
Collected By: (b) (6), (b) (7)(C) U. S. Coast Guard

Attachments

governor testing instructions, company; Documentary Evidence;
25Oct2021 02:26:50 EDT; No

Control Number: 7025155-(b) (6), (b) (7)(C)050

Description: Excerpt from ops manual regarding preventative maintenance plan
Evidence Type: Standard

Collection Information

Date/Time: 21Oct2021 02:18:21 EDT
Location:
Collected By: (b) (6), (b) (7)(C) U. S. Coast Guard

Attachments

excerpt, preventative maintenance plan; Documentary Evidence;
25Oct2021 02:28:22 EDT; No

Control Number: 7025155-(b) (6), (b) (7)(C)051

Description: Annual service reports, governor
Evidence Type: Standard

Collection Information

Date/Time: 24Oct2021 20:41:01 EDT
Location:
Collected By: (b) (6), (b) (7)(C) U. S. Coast Guard

Attachments

governor, annual servicing reports; Documentary Evidence;
25Oct2021 02:29:59 EDT; No

Control Number: 7025155-(b) (6), (b) (7)(C)052

Description: Quarterly safety checks, DG#1
Evidence Type: Standard

Collection Information

Date/Time: 24Oct2021 20:42:26 EDT
Location:
Collected By: (b) (6), (b) (7)(C) U. S. Coast Guard

Attachments

quarterly safety checks, 13Jul20.pdf; Documentary Evidence;
25Oct2021 02:30:20 EDT; No

MISLE Incident Investigation Report

Control Number: 7025155-(b) (6), (b) (7)(C)053

Description: Work report, governor A overhaul
Evidence Type: Standard

Collection Information

Date/Time: 24Oct2021 20:43:19 EDT
Location:
Collected By: (b) (6), (b) (7)(C) U. S. Coast Guard

Attachments

work report, governor A (8521-0047DC) overhaul; Documentary Evidence;
25Oct2021 02:31:35 EDT; No

Control Number: 7025155-(b) (6), (b) (7)(C)054

Description: Work report, governor B overhaul
Evidence Type: Standard

Collection Information

Date/Time: 24Oct2021 20:43:47 EDT
Location:
Collected By: (b) (6), (b) (7)(C) U. S. Coast Guard

Attachments

CG54a - work report, governor B (8520-0041) overhaul; Documentary Evidence;
25Oct2021 02:32:45 EDT; No

CG54b - work report, governor B overhaul; Documentary Evidence;
25Oct2021 02:33:04 EDT; No

Control Number: 7025155-(b) (6), (b) (7)(C)055

Description: Preliminary report issued by Classification Society
Evidence Type: Standard

Collection Information

Date/Time: 24Oct2021 20:44:15 EDT
Location:
Collected By: (b) (6), (b) (7)(C) U. S. Coast Guard

Attachments

CG55 - Class preliminary report; Documentary Evidence;
25Oct2021 02:33:20 EDT; No

MISLE Incident Investigation Report

Control Number: 7025155-(b) (6), (b) (7)(C)056

Description: Technical report

Evidence Type: Standard

Collection Information

Date/Time: 24Oct2021 20:44:49 EDT

Location:

Collected By: (b) (6), (b) (7)(C) U. S. Coast Guard

Attachments

CG56 - technical report, flywheel failure; Documentary Evidence;
25Oct2021 02:33:35 EDT; No

Control Number: 7025155-(b) (6), (b) (7)(C)057

Description: Final summary issued by Classification Society

Evidence Type: Standard

Collection Information

Date/Time: 03Nov2021 20:46:34 EDT

Location:

Collected By: (b) (6), (b) (7)(C) U. S. Coast Guard

Attachments

CG57 - Class Final Report Summary; Documentary Evidence;
03Nov2021 20:48:29 EDT; No

Control Number: 7025155-(b) (6), (b) (7)(C)058

Description: Email correspondence regarding governor

Evidence Type: Standard

Collection Information

Date/Time: 18Nov2021 18:08:40 EST

Location:

Collected By: (b) (6), (b) (7)(C) U. S. Coast Guard

Attachments

CG58 - Email, governor info; Documentary Evidence;
18Nov2021 18:10:05 EST; No

Control Number: 7025155-(b) (6), (b) (7)(C)059

Description: Governor storage instructions

Evidence Type: Standard

Collection Information

Date/Time: 28Nov2021 20:45:43 EST

Location:

Collected By: (b) (6), (b) (7)(C) U. S. Coast Guard

Attachments

CG59 - Governor storage; Documentary Evidence;
28Nov2021 20:50:12 EST; No

MISLE Incident Investigation Report

Control Number: 7025155-(b) (6), (b) (7)(C)060

Description: Email regarding storage of governor
Evidence Type: Standard

Collection Information

Date/Time: 29Nov2021 18:54:51 EST
Location:
Collected By: (b) (6), (b) (7)(C) U. S. Coast Guard

Attachments

CG60 - Email, storage; Documentary Evidence;
29Nov2021 18:56:58 EST; No

Control Number: 7025155-(b) (6), (b) (7)(C)061

Description: Email regarding testing of mechanical & electrical governors
Evidence Type: Standard

Collection Information

Date/Time: 09Dec2021 00:53:24 EST
Location:
Collected By: (b) (6), (b) (7)(C) U. S. Coast Guard

Attachments

CG61 - Email, testing; Documentary Evidence;
09Dec2021 00:54:32 EST; No

Control Number: 7025155-(b) (6), (b) (7)(C)062

Description: Periodic Safety Test Procedures, Rev. 6
Evidence Type: Standard

Collection Information

Date/Time: 09Dec2021 01:34:35 EST
Location:
Collected By: (b) (6), (b) (7)(C) U. S. Coast Guard

Attachments

CG62 - PSTP Rev. 6; Documentary Evidence;
09Dec2021 01:35:23 EST; No

VII. TIMELINE

30Jun1981 19:00:00 EDT to 30Jun1981 19:00:00 EDT (Estimated): The First Assistant Engineer (1/AE), (b) (6), (b) (7)(C) graduated from the Philippine Merchant Marine Academy in 1981 and has been in the maritime industry since that time. He was hired by SLNC in April 2016 and has only sailed on the SLNC GOODWILL since that time totaling five - six assignments.

Timeline Type: Condition
Timeline Subtype: Person - Person Condition
Location: Unknown

Subject(s) and Details

MISLE Incident Investigation Report

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
(b) (6), (b) (7)(C)	Person	At Risk, Not Injured	Witness

System: Personnel
Subsystem: Work Experience
Component: Total Time in Industry (Years and Months)
Cite:
Involves CG Approved Equipment: No
Security Violation: No
Deficiency: No

31May2002 23:00:00 EDT to 31May2002 23:00:00 EDT (Estimated): The Chief Engineer (CE), (b) (6), (b) (7)(C) had been sailing since 2002. He had been employed by Schuyler Line Navigation Company (SLNC) since November 2019; this was his third assignment aboard the SLNC GOODWILL.

Timeline Type: Condition
Timeline Subtype: Person - Person Condition
Location: Unknown

Subject(s) and Details

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
(b) (6), (b) (7)(C)	Person	At Risk, Not Injured	Witness

System: Personnel
Subsystem: Work Experience
Component: Total Time in Industry (Years and Months)
Cite:
Involves CG Approved Equipment: No
Security Violation: No
Deficiency: No

31May2004 23:00:00 EDT to 31May2004 23:00:00 EDT (Estimated): The Second Mate (2M), (b) (6), (b) (7)(C) had been sailing since 2004. He had completed two previous trips on another vessel owned by SLNC. This was his first assignment to the SLNC GOODWILL.

Timeline Type: Condition
Timeline Subtype: Person - Person Condition
Location: Unknown

Subject(s) and Details

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
(b) (6), (b) (7)(C)	Person	Not at Risk	Witness

System: Personnel
Subsystem: Work Experience
Component: Total Time in Industry (Years and Months)
Cite:
Involves CG Approved Equipment: No
Security Violation: No
Deficiency: No

MISLE Incident Investigation Report

31May2004 23:01:00 EDT to 31May2004 23:01:00 EDT (Estimated): The 2M was also the vessel's Medical Officer. He had completed a full Medical Officer course three (03) times and had served in this position on other vessels.

Timeline Type: Condition
Timeline Subtype: Person - Person Condition
Location: Unknown

Subject(s) and Details

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
(b) (6), (b) (7)(C) (b) (6), (b) (7)(C)	Person	Not at Risk	Witness

System: Personnel
Subsystem: Training
Component: Medical, Person in Charge/Management
Cite:
Involves CG Approved Equipment: No
Security Violation: No
Deficiency: No

31May2007 23:00:00 EDT to 31May2007 23:00:00 EDT (Estimated): The Master, (b) (6), (b) (7)(C) had been sailing as an officer since 2007. He had worked for SLNC since 2016 and had been the Master of the SLNC GOODWILL since 2018.

Timeline Type: Condition
Timeline Subtype: Person - Person Condition
Location: Unknown

Subject(s) and Details

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
(b) (6), (b) (7)(C)	Person	Not at Risk	Witness

System: Personnel
Subsystem: Work Experience
Component: Total Time in Industry (Years and Months)
Cite:
Involves CG Approved Equipment: No
Security Violation: No
Deficiency: No

20Nov2008 22:00:00 EST to 20Nov2008 22:00:00 EST (Estimated): The SLNC GOODWILL (ON 1266919) was a 580.4 ft, 30,241 GT chemical/tank ship of steel construction with a keel laid date of 21Nov2008. It had diesel direct propulsion on an oceans/SOLAS route owned by Nord Goodwill LLC and operated by Schuyler Line Navigation Company, LLC. The vessel's initial COI was issued IAW MSP on 29Jan2016 (reflagged); most recent COI annual inspection was conducted remotely from 01 to 27Apr20 with 00 deficiencies noted and 00 outstanding.

Timeline Type: Condition
Timeline Subtype: Vessel - Material/Equipment Condition
Location: Unknown

Subject(s) and Details

MISLE Incident Investigation Report

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
SLNC GOODWILL	Vessel	Undamaged	Involved in a Marine Casualty
System: Operations/Management			
Subsystem: Vessel Activity			
Component: Construction/Repair			
Cite:			
<u>Involves CG Approved Equipment</u> : No			
Security Violation: No			
Deficiency: No			

20Nov2008 22:01:00 EST to 20Nov2008 22:01:00 EST (Estimated): Electrical services for the SLNC GOODWILL were provided by three (03) auxiliary generating sets each with a MAN B&W - ZJMD 6L23/30H type prime mover rated to deliver 960 KW at 900 rpm.

Timeline Type: Condition
 Timeline Subtype: Vessel - Material/Equipment Condition
 Location: Unknown

Subject(s) and Details

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
SLNC GOODWILL	Vessel	Undamaged	Involved in a Marine Casualty
System: Electrical			
Subsystem: Electric Generation Source (service)			
Component: Generator			
Cite:			
<u>Involves CG Approved Equipment</u> : No			
Security Violation: No			
Deficiency: No			

20Nov2008 22:02:00 EST to 20Nov2008 22:02:00 EST (Estimated): Each generator was equipped with a governor. The purpose of the governor was to regulate the flow of fuel to the engine in order to maintain a relatively constant speed (rpm) independent of the electrical load placed on the generator.

Timeline Type: Condition
 Timeline Subtype: Vessel - Material/Equipment Condition
 Location: Unknown

Subject(s) and Details

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
SLNC GOODWILL	Vessel	Undamaged	Involved in a Marine Casualty
System: Engineering			
Subsystem: Diesel Engine (auxiliary)			
Component: Governor			
Cite:			
<u>Involves CG Approved Equipment</u> : No			
Security Violation: No			
Deficiency: No			

MISLE Incident Investigation Report

20Nov2008 22:03:00 EST to 20Nov2008 22:03:00 EST (Estimated): Each generator was equipped with a flywheel. The flywheel was a component mounted to the engine's crank shaft and designed to store the mechanical energy of the engine during power stroke and imparts that stored energy to the preparatory strokes in an effort to keep shaft rotation uniform.

Timeline Type: Condition
Timeline Subtype: Vessel - Material/Equipment Condition
Location: Unknown

Subject(s) and Details

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
SLNC GOODWILL	Vessel	Undamaged	Involved in a Marine Casualty

System: Engineering
Subsystem: Diesel Engine (auxiliary)
Component: Crankshaft
Cite:
Involves CG Approved Equipment: No
Security Violation: No
Deficiency: No

31May2012 23:00:00 EDT to 31May2012 23:00:00 EDT (Estimated): The Chief Mate (CM), (b) (6), (b) (7)(C) had been sailing 2012 and had been employed by SLNC since 2018. He had completed four assignments onboard the SLNC GOODWILL; this was his second time sailing with the 3/AE.

Timeline Type: Condition
Timeline Subtype: Person - Person Condition
Location: Unknown

Subject(s) and Details

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
(b) (6), (b) (7)(C)	Person	Not at Risk	Witness

System: Personnel
Subsystem: Work Experience
Component: Total Time in Industry (Years and Months)
Cite:
Involves CG Approved Equipment: No
Security Violation: No
Deficiency: No

28Feb2015 22:00:00 EST to 28Feb2015 22:00:00 EST (Estimated): The manufacturer of Governor C, Woodward Inc., released instructions for the storage of mechanical-hydraulic controls (governors). These instructions included that oil meeting the US MIL-H-17672 standard should be used to coat the internal surfaces of the device.

Timeline Type: Condition
Timeline Subtype: Organization - Organization Condition
Location: Unknown

Subject(s) and Details

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
Woodward Inc.	Organization		Witness

MISLE Incident Investigation Report

31May2017 23:00:00 EDT to 31May2017 23:00:00 EDT (Estimated): The Fourth Mate (4M), (b) (6), (b) (7)(C) had been sailing since 2017. This was his first assignment on any SLNC vessel.

Timeline Type: Condition
Timeline Subtype: Person - Person Condition
Location: Unknown

Subject(s) and Details

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
(b) (6), (b) (7)(C)	Person	Not at Risk	Witness

System: Personnel
Subsystem: Work Experience
Component: Total Time in Industry (Years and Months)
Cite:
Involves CG Approved Equipment: No
Security Violation: No
Deficiency: No

30Mar2019 19:00:00 EDT to 30Mar2019 19:00:00 EDT (Estimated): The DG#1 connecting rod calibration was conducted by a third-party vendor.

Timeline Type: Condition
Timeline Subtype: Vessel - Material/Equipment Condition
Location: Unknown

Subject(s) and Details

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
SLNC GOODWILL	Vessel	Undamaged	Involved in a Marine Casualty

System: Engineering
Subsystem: Diesel Engine (auxiliary)
Component: Connecting Rod
Cite:
Involves CG Approved Equipment: No
Security Violation: No
Deficiency: No

21May2019 19:00:00 EDT to 21May2019 19:00:00 EDT (Estimated): The governor installed on DG #1 prior to the casualty, Governor B (Part # 8520-0041, Serial # 15592175), was serviced in place by third party contractors licensed by the governor's manufacturing company.

Timeline Type: Condition
Timeline Subtype: Vessel - Material/Equipment Condition
Location: Unknown

Subject(s) and Details

MISLE Incident Investigation Report

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
SLNC GOODWILL	Vessel	Undamaged	Involved in a Marine Casualty
System: Engineering			
Subsystem: Diesel Engine (auxiliary)			
Component: Governor			
Cite:			
<u>Involves CG Approved Equipment</u> : No			
Security Violation: No			
Deficiency: No			

21May2019 19:01:00 EDT to 21May2019 19:01:00 EDT (Estimated): A third governor, Governor C, arrived onboard the vessel for use as a spare; it was a rebuilt governor, not brand new, and had not been installed on any generator onboard the vessel prior to DG #1 on 04Aug21.

Timeline Type: Condition
Timeline Subtype: Vessel - Material/Equipment Condition
Location: Unknown

Subject(s) and Details

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
SLNC GOODWILL	Vessel	Undamaged	Involved in a Marine Casualty
System: Engineering			
Subsystem: Diesel Engine (auxiliary)			
Component: Governor			
Cite:			
<u>Involves CG Approved Equipment</u> : No			
Security Violation: No			
Deficiency: No			

21May2019 19:02:00 EDT to 21May2019 19:02:00 EDT (Estimated): The data plate installed on Governor C included the same serial # and part # as Governor B. Although the numbers were the same at the time of the casualty, the operating company believes the original serial # for Governor C was 16178255.

Timeline Type: Condition
Timeline Subtype: Vessel - Material/Equipment Condition
Location: Unknown

Subject(s) and Details

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
SLNC GOODWILL	Vessel	Undamaged	Involved in a Marine Casualty
System: Engineering			
Subsystem: Diesel Engine (auxiliary)			
Component: Governor			
Cite:			
<u>Involves CG Approved Equipment</u> : No			
Security Violation: No			
Deficiency: No			

MISLE Incident Investigation Report

21May2019 19:03:00 EDT to 21May2019 19:03:00 EDT (Estimated): At some point either during or after overhaul, mechanical damage was sustained on the surfaces of Governor C's pilot valve bushing and shaft drive.

Timeline Type: Condition
Timeline Subtype: Vessel - Material/Equipment Condition
Location: Unknown

Subject(s) and Details

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
SLNC GOODWILL	Vessel	Undamaged	Involved in a Marine Casualty

System: Engineering
Subsystem: Diesel Engine (auxiliary)
Component: Governor
Cite:
Involves CG Approved Equipment: No
Security Violation: No
Deficiency: No

21Jul2019 19:00:00 EDT to 21Jul2019 19:00:00 EDT (Estimated): The governor installed on DG#2, Governor A (Part # 8521-0047DC, Serial # 14639129), was overhauled.

Timeline Type: Condition
Timeline Subtype: Vessel - Material/Equipment Condition
Location: Unknown

Subject(s) and Details

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
SLNC GOODWILL	Vessel	Undamaged	Involved in a Marine Casualty

System: Engineering
Subsystem: Diesel Engine (auxiliary)
Component: Governor
Cite:
Involves CG Approved Equipment: No
Security Violation: No
Deficiency: No

03Oct2019 23:00:00 EDT to 03Oct2019 23:00:00 EDT (Estimated): The Third Assistant Engineer (3AE), Trenton Lloyd-Rees, started employment with SLNC and was serving aboard the SLNC GOODWILL.

Timeline Type: Condition
Timeline Subtype: Person - Person Condition
Location: Unknown

Subject(s) and Details

MISLE Incident Investigation Report

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
TRENTON LLOYD- REES	Person	Dead	Subject of Investigation

System: Personnel
Subsystem: Work Experience
Component: Total Time in Industry (Years and Months)
Cite:
Involves CG Approved Equipment: No
Security Violation: No
Deficiency: No

25Dec2019 18:00:00 EST to 25Dec2019 18:00:00 EST (Estimated): An annual test was conducted on the DG#1 governor under normal operating conditions; at the time of the test, the engine had 42617 run hours and the rebuilt governor had 1500 run hours. Oil levels, linkages, fuel rack, and speed sensor were all checked and a new micro-switch was installed on the overspeed device.

Timeline Type: Condition
Timeline Subtype: Vessel - Material/Equipment Condition
Location: Unknown

Subject(s) and Details

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
SLNC GOODWILL	Vessel	Undamaged	Involved in a Marine Casualty

System: Engineering
Subsystem: Diesel Engine (auxiliary)
Component: Governor
Cite:
Involves CG Approved Equipment: No
Security Violation: No
Deficiency: No

26Dec2019 06:00:00 EST to 26Dec2019 06:00:00 EST (Estimated): The next annual maintenance on the DG#1 governor was scheduled for 24Dec20.

Timeline Type: Condition
Timeline Subtype: Vessel - Material/Equipment Condition
Location: Unknown

Subject(s) and Details

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
SLNC GOODWILL	Vessel	Undamaged	Involved in a Marine Casualty

System: Engineering
Subsystem: Diesel Engine (auxiliary)
Component: Governor
Cite:
Involves CG Approved Equipment: No
Security Violation: No
Deficiency: No

03Jun2020 18:00:00 EDT to 03Jun2020 18:00:00 EDT (Estimated): The 2/M joined the vessel; it was his first assignment to the SLNC GOODWILL.

MISLE Incident Investigation Report

Timeline Type: Action
Timeline Subtype: Bridge Operations - Changing Watch
Location: Unknown

Subject(s) and Details

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
(b) (6), (b) (7)(C) (b) (6), (b) (7)(C)	Person	Not at Risk	Witness

04Jun2020 18:00:00 EDT to 04Jun2020 18:00:00 EDT (Estimated): The CE joined the vessel; it was his third assignment to the SLNC GOODWILL.

Timeline Type: Action
Timeline Subtype: Engineering Operations - Changing Watch
Location: Unknown

Subject(s) and Details

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
(b) (6), (b) (7)(C) (b) (6), (b) (7)(C)	Person	At Risk, Not Injured	Witness

12Jul2020 19:00:00 EDT to 12Jul2020 19:00:00 EDT (Estimated): A quarterly safety check was conducted on the DG#1 which included alarm, pressure, and temperature testing. It did not included a test of the overspeed trip.

Timeline Type: Action
Timeline Subtype: Engineering Operations - Routine, Scheduled, and Preventive Maintenance
Location: Unknown

Subject(s) and Details

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
TRENTON LLOYD- REES	Person	Dead	Subject of Investigation

12Jul2020 19:00:00 EDT to 22Jul2020 19:00:00 EDT (Estimated): The 2000 hr scheduled, preventative maintenance was conducted on the DG#1. Included in the maintenance was a test of the overspeed alarm, shut-downs, and changing the oil in the governor.

Timeline Type: Action
Timeline Subtype: Engineering Operations - Routine, Scheduled, and Preventive Maintenance
Location: Unknown

Subject(s) and Details

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
TRENTON LLOYD- REES	Person	Dead	Subject of Investigation

12Jul2020 19:01:00 EDT to 12Jul2020 19:01:00 EDT (Estimated): The design specification requirement for the DG#1 flywheel was for grey cast iron of Grade C4 with an ultimate tensile strength of between 300 -400 megapascals (MPa) and a Brinell hardness of between 200-250 HB.

Timeline Type: Condition
Timeline Subtype: Vessel - Material/Equipment Condition
Location: Unknown

Subject(s) and Details

MISLE Incident Investigation Report

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
SLNC GOODWILL	Vessel	Undamaged	Involved in a Marine Casualty
System: Electrical			
Subsystem: Electric Generation Source (service)			
Component: Generator			
Cite:			
<u>Involves CG Approved Equipment</u> : No			
Security Violation: No			
Deficiency: No			

12Jul2020 19:02:00 EDT to 12Jul2020 19:02:00 EDT (Estimated): The flywheel installed on DG#1 did not meet the design requirements of the engine licensor (MAN Engergy Soluction SE). After eight tests, the flywheel measured between 56%-64% of the required minimum strength and the hardness was, on average, 83% of the required minimum hardness.

Timeline Type: Condition
Timeline Subtype: Vessel - Material/Equipment Condition
Location: Unknown

Subject(s) and Details

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
SLNC GOODWILL	Vessel	Undamaged	Involved in a Marine Casualty
System: Electrical			
Subsystem: Electric Generation Source (service)			
Component: Generator			
Cite:			
<u>Involves CG Approved Equipment</u> : No			
Security Violation: No			
Deficiency: No			

12Jul2020 19:03:00 EDT to 12Jul2020 19:03:00 EDT (Estimated): Micro-shrinkage voids were present in the area around the flywheel coupling bolt holes.

Timeline Type: Condition
Timeline Subtype: Vessel - Material/Equipment Condition
Location: Unknown

Subject(s) and Details

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
SLNC GOODWILL	Vessel	Undamaged	Involved in a Marine Casualty
System: Electrical			
Subsystem: Electric Generation Source (service)			
Component: Generator			
Cite:			
<u>Involves CG Approved Equipment</u> : No			
Security Violation: No			
Deficiency: No			

13Jul2020 07:00:00 EDT to 13Jul2020 07:00:00 EDT (Estimated): The next quarterly safety check was scheduled for 12Oct20.

MISLE Incident Investigation Report

Timeline Type: Condition
Timeline Subtype: Vessel - Material/Equipment Condition
Location: Unknown

Subject(s) and Details

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
SLNC GOODWILL	Vessel	Undamaged	Involved in a Marine Casualty
System: Electrical			
Subsystem: Electric Generation Source (service)			
Component: Generator			
Cite:			
<u>Involves CG Approved Equipment</u> : No			
Security Violation: No			
Deficiency: No			

25Jul2020 18:00:00 EDT to 25Jul2020 18:00:00 EDT (Estimated): The Master and 4/M joined the vessel.

Timeline Type: Action
Timeline Subtype: Bridge Operations - Changing Watch
Location: Unknown

Subject(s) and Details

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
(b) (6), (b) (7)(C)	Person	Not at Risk	Witness

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
(b) (6), (b) (7)(C)	Person	Not at Risk	Witness

02Aug2020 22:59:01 EDT to 02Aug2020 22:59:01 EDT (Estimated): No oil was in Governor C while it was stored onboard the vessel and it was found on it's side. The 1/AE stated that, in his experience, oil was kept in governors being stored onboard vessels and they were kept in a vertical position.

Timeline Type: Condition
Timeline Subtype: Vessel - Material/Equipment Condition
Location: Unknown

Subject(s) and Details

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
SLNC GOODWILL	Vessel	Undamaged	Involved in a Marine Casualty
System: Engineering			
Subsystem: Diesel Engine (auxiliary)			
Component: Governor			
Cite:			
<u>Involves CG Approved Equipment</u> : No			
Security Violation: No			
Deficiency: No			

MISLE Incident Investigation Report

02Aug2020 22:59:02 EDT to 02Aug2020 22:59:02 EDT (Estimated): The manufacturer of Governor C recommends their governors be transported and stored in an upright position to prevent the ballhead assembly from sliding out of its support bracket as well as preventing oil from leaking out of "breather holes"; those holes are necessary to allow internal air pressure to adjust to ambient air pressure.

Timeline Type: Condition
Timeline Subtype: Organization - Organization Condition
Location: Unknown

Subject(s) and Details

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
Woodward Inc.	Organization		Witness

02Aug2020 23:00:00 EDT to 02Aug2020 23:00:00 EDT (Estimated): When started during cargo operations, DG#1 would "hunt". This meant that the rotational speed (rpms) of the engine was fluctuating and wouldn't remain consistent. When placed in "idle", DG#1 would stop.

Timeline Type: Condition
Timeline Subtype: Vessel - Material/Equipment Condition
Location: Unknown

Subject(s) and Details

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
SLNC GOODWILL	Vessel	Undamaged	Involved in a Marine Casualty

System: Electrical
Subsystem: Electric Generation Source (service)
Component: Generator
Cite:
Involves CG Approved Equipment: No
Security Violation: No
Deficiency: No

03Aug2020 00:00:00 EDT to 03Aug2020 00:00:00 EDT (Estimated): The CE made the decision to change out Governor B with Governor C on DG#1 in an attempt to resolve DG #1 "hunting".

Timeline Type: Action
Timeline Subtype: Engineering Operations - Unscheduled, Corrective Repair
Location: Unknown

Subject(s) and Details

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
TRENTON LLOYD-REES	Person	Dead	Subject of Investigation

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
(b) (6), (b) (7)(C)	Person	At Risk, Not Injured	Witness

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
(b) (6), (b) (7)(C)	Person	At Risk, Not Injured	Witness

03Aug2020 19:00:00 EDT to 03Aug2020 19:00:00 EDT (Known): The 1/AE was involved with work on the vessel's oily-water separator.

MISLE Incident Investigation Report

Timeline Type: Condition
Timeline Subtype: Person - Person Condition
Location: Unknown

Subject(s) and Details

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
(b) (6), (b) (7)(C)	Person	At Risk, Not Injured	Witness

System: Personnel
Subsystem: Psychological Condition
Component: Workload
Cite:
Involves CG Approved Equipment: No
Security Violation: No
Deficiency: No

03Aug2020 22:59:00 EDT to 03Aug2020 22:59:00 EDT (Estimated): Prior to installing Governor C, the CE, 1/AE, and 3/AE visually inspected it to look for obvious signs of damage, water staining, or debris; nothing was noted and installation commenced.

Timeline Type: Condition
Timeline Subtype: Vessel - Material/Equipment Condition
Location: Unknown

Subject(s) and Details

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
SLNC GOODWILL	Vessel	Undamaged	Involved in a Marine Casualty

System: Engineering
Subsystem: Diesel Engine (auxiliary)
Component: Governor
Cite:
Involves CG Approved Equipment: No
Security Violation: No
Deficiency: No

04Aug2020 00:00:00 EDT to 05Aug2020 07:00:00 EDT (Estimated): Installation of Governor C on DG#1 was started by the CE, 1/AE, and 3/AE in the afternoon. It was not completed that day and work was halted around 2000; DG#1 remained offline.

Timeline Type: Action
Timeline Subtype: Engineering Operations - Unscheduled, Corrective Repair
Location: Unknown

Subject(s) and Details

MISLE Incident Investigation Report

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
TRENTON LLOYD- REES	Person	Dead	Subject of Investigation

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
(b) (6), (b) (7)(C)	Person	At Risk, Not Injured	Witness

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
(b) (6), (b) (7)(C)	Person	At Risk, Not Injured	Witness

04Aug2020 00:01:00 EDT to 04Aug2020 00:01:00 EDT (Estimated): The 1/AE hadn't changed a governor onboard the SLNC GOODWILL, but had several times on other vessels. The 3/AE hadn't changed a governor before and was there for training.

Timeline Type: Condition
 Timeline Subtype: Person - Person Condition
 Location: Unknown

Subject(s) and Details

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
TRENTON LLOYD- REES	Person	Dead	Subject of Investigation

System: Personnel
 Subsystem: Work Experience
 Component: Other Experience - Shipboard
 Cite:
Involves CG Approved Equipment: No
 Security Violation: No
 Deficiency: No

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
(b) (6), (b) (7)(C)	Person	At Risk, Not Injured	Witness

System: Personnel
 Subsystem: Work Experience
 Component: Other Experience - Shipboard
 Cite:
Involves CG Approved Equipment: No
 Security Violation: No
 Deficiency: No

04Aug2020 17:00:00 EDT to 04Aug2020 17:00:00 EDT (Estimated): During the four days prior to the casualty, the C/E had worked 9.5 hours each day. Leading up to the day of the casualty, he stopped work at 1830 the day before and resumed work at 0600 the day of.

Timeline Type: Condition
 Timeline Subtype: Person - Person Condition
 Location: Unknown

Subject(s) and Details

MISLE Incident Investigation Report

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
(b) (6), (b) (7)(C) (b) (6), (b) (7)(C)	Person	At Risk, Not Injured	Witness

System: Personnel
Subsystem: Physical Condition
Component: Other physical capability
Cite:
Involves CG Approved Equipment: No
Security Violation: No
Deficiency: No

04Aug2020 18:00:00 EDT to 04Aug2020 23:00:00 EDT (Estimated): The 1/AE was involved with unscheduled work in the inert gas system due to a blocked sprayer in the combustion chamber.
Timeline Type: Action
Timeline Subtype: Engineering Operations - Routine, Scheduled, and Preventive Maintenance
Location: Unknown

Subject(s) and Details

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
(b) (6), (b) (7)(C) (b) (6), (b) (7)(C)	Person	At Risk, Not Injured	Witness

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
(b) (6), (b) (7)(C)	Person	At Risk, Not Injured	Witness

04Aug2020 18:00:00 EDT to 04Aug2020 18:00:00 EDT (Estimated): During the four days prior to the casualty, the 1/AE had worked 10 (01Aug), 10.5 (02Aug), 8.5 (03Aug), and 11 (04Aug) hours respectively. Leading up to the day of the casualty, he stopped work at 1830 the day before and started again at 0700 the day of.
Timeline Type: Condition
Timeline Subtype: Person - Person Condition
Location: Unknown

Subject(s) and Details

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
(b) (6), (b) (7)(C)	Person	At Risk, Not Injured	Witness

System: Personnel
Subsystem: Physical Condition
Component: Other physical capability
Cite:
Involves CG Approved Equipment: No
Security Violation: No
Deficiency: No

04Aug2020 23:00:00 EDT to 04Aug2020 23:00:00 EDT (Estimated): During the four days prior to the casualty, the 3/AE had worked 10.5 hours each day. Leading up to the day of the casualty, he had stopped work at midnight and started work at 1200.

MISLE Incident Investigation Report

Timeline Type: Condition
Timeline Subtype: Person - Person Condition
Location: Unknown

Subject(s) and Details

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
TRENTON LLOYD- REES	Person	Dead	Subject of Investigation

System: Personnel
Subsystem: Physical Condition
Component: Other physical capability
Cite:
Involves CG Approved Equipment: No
Security Violation: No
Deficiency: No

04Aug2020 23:30:00 EDT to 04Aug2020 23:30:00 EDT (Estimated): The 1/AE and 3/AE resumed the installation of Governor C on DG#1. The CE arrived later to oversee the installation and testing.

Timeline Type: Action
Timeline Subtype: Engineering Operations - Unscheduled, Corrective Repair
Location: Unknown

Subject(s) and Details

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
TRENTON LLOYD- REES	Person	Dead	Subject of Investigation

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
(b) (6), (b) (7)(C) (b) (6), (b) (7)(C)	Person	At Risk, Not Injured	Witness

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
(b) (6), (b) (7)(C)	Person	At Risk, Not Injured	Witness

04Aug2020 23:31:00 EDT to 04Aug2020 23:31:00 EDT (Estimated): Two pages of the Woodward product manual were determined to be relevant to the governor change-out; they were printed out and taken to DG #1. The manual being used as a reference by the 1/AE and 3/AE was for a different governor than what was being installed. The 1/AE used Governor A on DG#2 as a reference.

Timeline Type: Condition
Timeline Subtype: Organization - Organization Condition
Location: Unknown

Subject(s) and Details

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
SCHUYLER LINE NAVIGATION CORP	Organization		Other

04Aug2020 23:35:00 EDT to 04Aug2020 23:35:00 EDT (Estimated): The 1/AE visually checked that the linkage setting for Governor C on DG#1 matched the linkage setting of Governor A on DG #2 and showed the 3/AE for training.

MISLE Incident Investigation Report

Timeline Type: Condition
Timeline Subtype: Vessel - Material/Equipment Condition
Location: Unknown

Subject(s) and Details

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
SLNC GOODWILL	Vessel	Undamaged	Involved in a Marine Casualty

System: Engineering
Subsystem: Diesel Engine (auxiliary)
Component: Governor
Cite:
Involves CG Approved Equipment: No
Security Violation: No
Deficiency: No

04Aug2020 23:45:00 EDT to 04Aug2020 23:45:00 EDT (Estimated): The CE installed the synchronizing motor on Governor C. It was the same synchronizing motor used on Governor B.

Timeline Type: Action
Timeline Subtype: Engineering Operations - Unscheduled, Corrective Repair
Location: Known

Primary Location: Yes
Description: Sea of Japan, approx.74 NM southwest of the port of Sasebo, Japan

Latitude: 32°29.0 N Longitude: 128°29.0 E

Subject(s) and Details

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
(b) (6), (b) (7)(C) (b) (6), (b) (7)(C)	Person	At Risk, Not Injured	Witness

05Aug2020 00:00:00 EDT to 05Aug2020 00:00:00 EDT (Estimated): Governor C's overspeed protection device and pneumatic shut off were tested by the CE, 1/AE, and 3/AE prior to starting DG#1; both were functioning as designed.

Timeline Type: Condition
Timeline Subtype: Vessel - Material/Equipment Condition
Location: Known

Primary Location: Yes
Description: Sea of Japan, approx.74 NM southwest of the port of Sasebo, Japan

Latitude: 32°29.0 N Longitude: 128°29.0 E

Subject(s) and Details

MISLE Incident Investigation Report

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
SLNC GOODWILL	Vessel	Undamaged	Involved in a Marine Casualty
System: Engineering			
Subsystem: Diesel Engine (auxiliary)			
Component: Governor			
Cite:			
<u>Involves CG Approved Equipment</u> : No			
Security Violation: No			
Deficiency: No			

05Aug2020 00:01:00 EDT to 05Aug2020 00:01:00 EDT (Estimated): The engine had an electronic and mechanical overspeed protection device that were set to activate and shut down DG#1 if the engine's rpms exceeded approx. 1,020. The normal, designed operating speed for DG#1 was 900 rpms.

Timeline Type: Condition
Timeline Subtype: Vessel - Material/Equipment Condition
Location: Known

Primary Location: Yes
Description: Sea of Japan, approx.74 NM southwest of the port of Sasebo, Japan

Latitude: 32°29.0 N Longitude: 128°29.0 E

Subject(s) and Details

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
SLNC GOODWILL	Vessel	Undamaged	Involved in a Marine Casualty
System: Engineering			
Subsystem: Diesel Engine (auxiliary)			
Component: Governor			
Cite:			
<u>Involves CG Approved Equipment</u> : No			
Security Violation: No			
Deficiency: No			

05Aug2020 00:35:00 EDT to 05Aug2020 00:35:00 EDT (Estimated): The 1/AE started up DG#1 for the first time since installing Governor C. The 3/AE and CE were nearby to observe and assist.

Timeline Type: Action
Timeline Subtype: Engineering Operations - Engineering Systems Operations
Location: Known

Primary Location: Yes
Description: Sea of Japan, approx.74 NM southwest of the port of Sasebo, Japan

Latitude: 32°29.0 N Longitude: 128°29.0 E

Subject(s) and Details

MISLE Incident Investigation Report

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
TRENTON LLOYD- REES	Person	Dead	Subject of Investigation

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
(b) (6), (b) (7)(C) (b) (6), (b) (7)(C)	Person	At Risk, Not Injured	Witness

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
(b) (6), (b) (7)(C)	Person	At Risk, Not Injured	Witness

05Aug2020 00:36:00 EDT to 05Aug2020 00:36:00 EDT (Estimated): DG#1 rpms were unstable and steadily increased.

Timeline Type: Condition
Timeline Subtype: Vessel - Material/Equipment Condition
Location: Known

Primary Location: Yes
Description: Sea of Japan, approx.74 NM southwest of the port of Sasebo, Japan

Latitude: 32°29.0 N Longitude: 128°29.0 E

Subject(s) and Details

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
SLNC GOODWILL	Vessel	Undamaged	Involved in a Marine Casualty

System: Electrical
Subsystem: Electric Generation Source (service)
Component: Generator
Cite:
Involves CG Approved Equipment: No
Security Violation: No
Deficiency: No

05Aug2020 00:37:00 EDT to 05Aug2020 00:37:00 EDT (Estimated): The overspeed protection device activated when DG#1 rpms exceeded approx. 1,020 and successfully shut down DG#1.

Timeline Type: Condition
Timeline Subtype: Vessel - Material/Equipment Condition
Location: Known

Primary Location: Yes
Description: Sea of Japan, approx.74 NM southwest of the port of Sasebo, Japan

Latitude: 32°29.0 N Longitude: 128°29.0 E

Subject(s) and Details

MISLE Incident Investigation Report

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
SLNC GOODWILL	Vessel	Undamaged	Involved in a Marine Casualty
System: Engineering			
Subsystem: Diesel Engine (auxiliary)			
Component: Overspeed Device			
Cite:			
<u>Involves CG Approved Equipment</u> : No			
Security Violation: No			
Deficiency: No			

05Aug2020 00:38:00 EDT to 05Aug2020 00:38:00 EDT (Estimated): The 1/AE, CE, and 3/AE inspected the governor installation to ensure fittings were secure and if there were any obvious signs of a problem. None were found and the overspeed protection device was reset.

Timeline Type: Action
Timeline Subtype: Engineering Operations - Engineering Systems Inspection and Testing
Location: Known

Primary Location: Yes
Description: Sea of Japan, approx.74 NM southwest of the port of Sasebo, Japan

Latitude: 32°29.0 N Longitude: 128°29.0 E

Subject(s) and Details

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
TRENTON LLOYD-REES	Person	Dead	Subject of Investigation

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
(b) (6), (b) (7)(C) (b) (6), (b) (7)(C)	Person	At Risk, Not Injured	Witness

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
(b) (6), (b) (7)(C)	Person	At Risk, Not Injured	Witness

05Aug2020 00:39:00 EDT to 05Aug2020 00:39:00 EDT (Estimated): The 1/AE attempted to restart DG#1 a second time.

Timeline Type: Action
Timeline Subtype: Engineering Operations - Engineering Systems Inspection and Testing
Location: Known

Primary Location: Yes
Description: Sea of Japan, approx.74 NM southwest of the port of Sasebo, Japan

Latitude: 32°29.0 N Longitude: 128°29.0 E

Subject(s) and Details

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
(b) (6), (b) (7)(C)	Person	At Risk, Not Injured	Witness

MISLE Incident Investigation Report

05Aug2020 00:39:01 EDT to 05Aug2020 00:39:01 EDT (Estimated): A material failure occurred within the casing of Governor C that prevented the regulation of fuel to DG #1.

Timeline Type: Event
Timeline Subtype: Material Failure/Malfunction
Location: Known

Primary Location: Yes
Description: Sea of Japan, approx.74 NM southwest of the port of Sasebo, Japan

Latitude: 32°29.0 N Longitude: 128°29.0 E

Subject(s) and Details

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
SLNC GOODWILL	Vessel	Undamaged	Involved in a Marine Casualty

System: Engineering
Subsystem: Diesel Engine (auxiliary)
Component: Governor
Cite:
Involves CG Approved Equipment: No
Security Violation: No
Deficiency: No
Failure/Malfunction Type: Catastrophic Failure/Malfunction

05Aug2020 00:40:02 EDT to 05Aug2020 00:40:02 EDT (Estimated): The CE was standing at the aft end of DG#1, the 3/AE was standing with the 1/AE between DG#1 and DG#2.

Timeline Type: Condition
Timeline Subtype: Person - Person Condition
Location: Known

Primary Location: Yes
Description: Sea of Japan, approx.74 NM southwest of the port of Sasebo, Japan

Latitude: 32°29.0 N Longitude: 128°29.0 E

Subject(s) and Details

MISLE Incident Investigation Report

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
TRENTON LLOYD- REES	Person	Dead	Subject of Investigation

System: Personnel
Subsystem: Physical Condition
Component: Other physical capability
Cite:
Involves CG Approved Equipment: No
Security Violation: No
Deficiency: No

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
(b) (6), (b) (7)(C)	Person	At Risk, Not Injured	Witness

System: Personnel
Subsystem: Physical Condition
Component: Other physical capability
Cite:
Involves CG Approved Equipment: No
Security Violation: No
Deficiency: No

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
(b) (6), (b) (7)(C)	Person	At Risk, Not Injured	Witness

System: Personnel
Subsystem: Physical Condition
Component: Other physical capability
Cite:
Involves CG Approved Equipment: No
Security Violation: No
Deficiency: No

05Aug2020 00:41:30 EDT to 05Aug2020 00:41:30 EDT (Estimated): DG#1 rpms steadily increased, accompanied by an unfamiliar noise and vibration; Governor C's overspeed trip device didn't activate.

Timeline Type: Condition
Timeline Subtype: Vessel - Material/Equipment Condition
Location: Known

Primary Location: Yes
Description: Sea of Japan, approx.74 NM southwest of the port of Sasebo, Japan

Latitude: 32°29.0 N Longitude: 128°29.0 E

Subject(s) and Details

MISLE Incident Investigation Report

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
SLNC GOODWILL	Vessel	Undamaged	Involved in a Marine Casualty
System: Electrical			
Subsystem: Electric Generation Source (service)			
Component: Generator			
Cite:			
<u>Involves CG Approved Equipment</u> : No			
Security Violation: No			
Deficiency: No			

05Aug2020 00:41:35 EDT to 05Aug2020 00:41:35 EDT (Known): The overspeed protection device failed to trip.

Timeline Type: Event
Timeline Subtype: Material Failure/Malfunction
Location: Known

Primary Location: Yes
Description: Sea of Japan, approx.74 NM southwest of the port of Sasebo, Japan

Latitude: 32°29.0 N Longitude: 128°29.0 E

Subject(s) and Details

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
SLNC GOODWILL	Vessel	Undamaged	Involved in a Marine Casualty
System: Engineering			
Subsystem: Diesel Engine (auxiliary)			
Component: Overspeed Device			
Cite:			
<u>Involves CG Approved Equipment</u> : No			
Security Violation: No			
Deficiency: No			
Failure/Malfunction Type: Catastrophic Failure/Malfunction			

05Aug2020 00:41:45 EDT to 05Aug2020 00:41:45 EDT (Estimated): The 1/AE attempted to stop the generator at both the governor and start box via the electronic and mechanical overspeed device; nothing happened when he pushed the button for a manual stop.

Timeline Type: Action
Timeline Subtype: Engineering Operations - Engineering Systems Operations
Location: Known

Primary Location: Yes
Description: Sea of Japan, approx.74 NM southwest of the port of Sasebo, Japan

Latitude: 32°29.0 N Longitude: 128°29.0 E

Subject(s) and Details

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
(b) (6), (b) (7)(C)	Person	At Risk, Not Injured	Witness

MISLE Incident Investigation Report

05Aug2020 00:41:46 EDT to 05Aug2020 00:41:46 EDT (Estimated): Smoke began to be visible from the engine and rpms continued to increase. Despite having passed the upper limit for DG#1 rpms, the overspeed trip device in Governor C failed to activate.

Timeline Type: Condition
Timeline Subtype: Vessel - Material/Equipment Condition
Location: Known

Primary Location: Yes
Description: Sea of Japan, approx.74 NM southwest of the port of Sasebo, Japan

Latitude: 32°29.0 N Longitude: 128°29.0 E

Subject(s) and Details

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
SLNC GOODWILL	Vessel	Undamaged	Involved in a Marine Casualty
System: Engineering			
Subsystem: Diesel Engine (auxiliary)			
Component: Emergency shutdown			
Cite:			
<u>Involves CG Approved Equipment</u> : No			
Security Violation: No			
Deficiency: No			

05Aug2020 00:41:50 EDT to 05Aug2020 00:41:50 EDT (Estimated): The 1/AE ran to the aft end of DG#1 to secure the fuel oil delivery to the engine while the 3/AE remained in the vicinity of Governor C, between DG #1 and DG #2. The CE yelled for everyone to get back.

Timeline Type: Action
Timeline Subtype: Engineering Operations - Engineering Systems Operations
Location: Known

Primary Location: Yes
Description: Sea of Japan, approx.74 NM southwest of the port of Sasebo, Japan

Latitude: 32°29.0 N Longitude: 128°29.0 E

Subject(s) and Details

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
(b) (6), (b) (7)(C)	Person	At Risk, Not Injured	Witness
(b) (6), (b) (7)(C)			

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
(b) (6), (b) (7)(C)	Person	At Risk, Not Injured	Witness

05Aug2020 00:42:00 EDT to 05Aug2020 00:42:00 EDT (Estimated): The DG#1 flywheel broke apart into several sections.

Timeline Type: Event
Timeline Subtype: Material Failure/Malfunction
Location: Known

Primary Location: Yes
Description: Sea of Japan, approx.74 NM southwest of the port of Sasebo, Japan

MISLE Incident Investigation Report

Latitude: 32°29.0 N Longitude: 128°29.0 E

Subject(s) and Details

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
SLNC GOODWILL	Vessel	Undamaged	Involved in a Marine Casualty

System: Electrical
Subsystem: Electric Generation Source (service)
Component: Generator
Cite:
Involves CG Approved Equipment: No
Security Violation: No
Deficiency: No
Failure/Malfunction Type: Catastrophic Failure/Malfunction

05Aug2020 00:42:01 EDT to 05Aug2020 00:42:01 EDT (Estimated): The sections of the flywheel were hurled through the engine room at a high rate of speed. One large section struck the 3/AE who was still standing between DG#1 and DG#2.

Timeline Type: Condition
Timeline Subtype: Vessel - Material/Equipment Condition
Location: Known

Primary Location: Yes
Description: Sea of Japan, approx.74 NM southwest of the port of Sasebo, Japan

Latitude: 32°29.0 N Longitude: 128°29.0 E

Subject(s) and Details

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
SLNC GOODWILL	Vessel	Undamaged	Involved in a Marine Casualty

System: Electrical
Subsystem: Electric Generation Source (service)
Component: Generator
Cite:
Involves CG Approved Equipment: No
Security Violation: No
Deficiency: No

05Aug2020 00:42:02 EDT to 05Aug2020 00:42:02 EDT (Estimated): The 3/AE was struck in the upper torso and neck by a piece of the flywheel after it had broken apart, causing significant blunt-force trauma and bleeding. He was given medical treatment onboard the vessel, but never recovered from his injuries. His death was recorded as having occurred at 1823, cause of death was listed as hemorrhagic shock.

Timeline Type: Event
Timeline Subtype: Personnel Casualty - Death
Location: Known

Primary Location: Yes
Description: Sea of Japan, approx.74 NM southwest of the port of Sasebo, Japan

Latitude: 32°29.0 N Longitude: 128°29.0 E

Subject(s) and Details

MISLE Incident Investigation Report

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
TRENTON LLOYD- REES	Person	Dead	Subject of Investigation

Nature Of Event Causing Death: Contact Injury- Struck by Moving Object

Cause Of Death: struck by section of cast iron flywheel after it broke free from DG#1

Casualty Involved Diving: No

05Aug2020 00:42:03 EDT to 05Aug2020 00:42:03 EDT (Estimated): The pieces of DG#1 flywheel struck and ruptured air piping and water piping running through the generator space.

Timeline Type: Condition
Timeline Subtype: Vessel - Material/Equipment Condition
Location: Known

Primary Location: Yes
Description: Sea of Japan, approx.74 NM southwest of the port of Sasebo, Japan

Latitude: 32°29.0 N Longitude: 128°29.0 E

Subject(s) and Details

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
SLNC GOODWILL	Vessel	Undamaged	Involved in a Marine Casualty

System: Electrical

Subsystem: Electric Generation Source (service)

Component: Generator

Cite:

Involves CG Approved Equipment: No

Security Violation: No

Deficiency: No

05Aug2020 00:42:04 EDT to 05Aug2020 00:42:04 EDT (Estimated): The vessel lost electrical power.

Timeline Type: Event
Timeline Subtype: Loss of Electrical Power
Location: Known

Primary Location: Yes
Description: Sea of Japan, approx.74 NM southwest of the port of Sasebo, Japan

Latitude: 32°29.0 N Longitude: 128°29.0 E

Subject(s) and Details

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
SLNC GOODWILL	Vessel	Undamaged	Involved in a Marine Casualty

05Aug2020 00:42:05 EDT to 05Aug2020 00:42:05 EDT (Estimated): The vessel's main diesel engine shut down and the vessel was drifting approx. 12 NM off the coast of Japan.

Timeline Type: Event
Timeline Subtype: Loss/Reduction of Vessel Propulsion/Steering
Location: Known

MISLE Incident Investigation Report

Primary Location: Yes
Description: Sea of Japan, approx.74 NM southwest of the port of Sasebo, Japan

Latitude: 32°29.0 N Longitude: 128°29.0 E

Subject(s) and Details

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
SLNC GOODWILL	Vessel	Undamaged	Involved in a Marine Casualty

05Aug2020 00:50:00 EDT to 05Aug2020 04:25:00 EDT (Estimated): The 3/AE was transported to the vessel's hospital space and given onboard medical treatment beyond first aid to include: dressings for bleeding, morphine injection (one), epinephrin injection (two), needle thoracostomy (needle inserted into lung to relieve fluid/pressure), nasopharyngeal airway, CPR, and automated external defibrillator (AED; never advised to shock).

Timeline Type: Action
Timeline Subtype: Safety and Emergency Operations - General Safety
Location: Known

Primary Location: Yes
Description: Sea of Japan, approx.74 NM southwest of the port of Sasebo, Japan

Latitude: 32°29.0 N Longitude: 128°29.0 E

Subject(s) and Details

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
TRENTON LLOYD-REES	Person	Dead	Subject of Investigation

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
(b) (6), (b) (7)(C) (b) (6), (b) (7)(C)	Person	Not at Risk	Witness

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
(b) (6), (b) (7)(C)	Person	Not at Risk	Witness

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
(b) (6), (b) (7)(C)	Person	Not at Risk	Witness

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
(b) (6), (b) (7)(C)	Person	Not at Risk	Witness

05Aug2020 00:51:00 EDT to 05Aug2020 00:51:00 EDT (Estimated): The vessel was not equipped with the ability to conduct video teleconferencing in the medical space.

Timeline Type: Condition
Timeline Subtype: Vessel - Material/Equipment Condition
Location: Known

Primary Location: Yes
Description: Sea of Japan, approx.74 NM southwest of the port of Sasebo, Japan

MISLE Incident Investigation Report

Latitude: 32°29.0 N

Longitude: 128°29.0 E

Subject(s) and Details

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
SLNC GOODWILL	Vessel	Undamaged	Involved in a Marine Casualty

System: Accommodation/Occupational Safety
Subsystem: Medical/First Aid
Component: Hospital Space
Cite:
Involves CG Approved Equipment: No
Security Violation: No
Deficiency: No

05Aug2020 01:02:00 EDT to 05Aug2020 01:02:00 EDT (Estimated): The Master requested a helicopter medivac for the 3/AE. The Moji Coast Guard confirmed they were responding and gave an ETA of 1730.

Timeline Type: Action
Timeline Subtype: Communications
Location: Known

Primary Location: Yes
Description: Sea of Japan, approx.74 NM southwest of the port of Sasebo, Japan

Latitude: 32°29.0 N

Longitude: 128°29.0 E

Subject(s) and Details

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
(b) (6), (b) (7)(C)	Person	Not at Risk	Witness

05Aug2020 01:15:00 EDT to 05Aug2020 01:15:00 EDT (Estimated): The vessel's 2/M and Master administered medical treatment to the 3/AE while receiving consultation from shoreside Medical Alert Services (MAS). The crew described injuries verbally and received instruction from MAS personnel.

Timeline Type: Condition
Timeline Subtype: Person - Communications Condition
Location: Known

Primary Location: Yes
Description: Sea of Japan, approx.74 NM southwest of the port of Sasebo, Japan

Latitude: 32°29.0 N

Longitude: 128°29.0 E

Subject(s) and Details

MISLE Incident Investigation Report

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
(b) (6), (b) (7)(C) (b) (6), (b) (7)(C)	Person	Not at Risk	Witness

Communications Type: Ship to Shore

Communication Direction: Both

Means Of Communication: Verbal

Frequency/Channel:

Frequency Or Channel Used:

Power Setting:

Communications Acknowledged: Yes

Communication Effectiveness: Communication Effective

Effectiveness Description:

Interference Encountered: No Known Interference

Interference Description:

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
(b) (6), (b) (7)(C)	Person	Not at Risk	Witness

Communications Type: Ship to Shore

Communication Direction: Both

Means Of Communication: Verbal

Frequency/Channel:

Frequency Or Channel Used:

Power Setting:

Communications Acknowledged: Yes

Communication Effectiveness: Communication Effective

Effectiveness Description:

Interference Encountered: No Known Interference

Interference Description:

05Aug2020 02:40:00 EDT to 05Aug2020 02:40:00 EDT (Estimated): The CE and 3/AE were able to start DG #3 in emergency mode and restore some power to the vessel.

Timeline Type: Action
Timeline Subtype: Engineering Operations - Unscheduled, Corrective Repair
Location: Known

Primary Location: Yes
Description: Sea of Japan, approx.74 NM southwest of the port of Sasebo, Japan

Latitude: 32°29.0 N Longitude: 128°29.0 E

Subject(s) and Details

MISLE Incident Investigation Report

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
(b) (6), (b) (7)(C) (b) (6), (b) (7)(C)	Person	At Risk, Not Injured	Witness

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
(b) (6), (b) (7)(C)	Person	At Risk, Not Injured	Witness

05Aug2020 04:00:00 EDT to 05Aug2020 04:31:00 EDT (Estimated): The Moji Coast Guard helicopter arrived on station and lowered crew to the vessel. The 3/AE was transported out on deck and raised to the helicopter, then the remaining crew were recovered and the helicopter returned to shore to continue medical treatment of 3/AE.

Timeline Type: Condition
Timeline Subtype: Vessel - Material/Equipment Condition
Location: Known

Primary Location: Yes
Description: Sea of Japan, approx.74 NM southwest of the port of Sasebo, Japan

Latitude: 32°29.0 N Longitude: 128°29.0 E

Subject(s) and Details

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
SLNC GOODWILL	Vessel	Undamaged	Involved in a Marine Casualty

System: Operations/Management
Subsystem: Casualty Reporting/Post-Casualty Actions
Component: Rendering Necessary Assistance
Cite:
Involves CG Approved Equipment: No
Security Violation: No
Deficiency: No

05Aug2020 05:00:00 EDT to 05Aug2020 05:00:00 EDT (Estimated): The vessel's power and propulsion systems were restored. The vessel got back underway and anchored in Sasebo, Japan without further incident.

Timeline Type: Condition
Timeline Subtype: Vessel - Material/Equipment Condition
Location: Known

Primary Location: Yes
Description: Sea of Japan, approx.74 NM southwest of the port of Sasebo, Japan

Latitude: 32°29.0 N Longitude: 128°29.0 E

Subject(s) and Details

MISLE Incident Investigation Report

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
SLNC GOODWILL	Vessel	Undamaged	Involved in a Marine Casualty
System: Electrical			
Subsystem: Electric Generation Source (service)			
Component: Generator			
Cite:			
<u>Involves CG Approved Equipment</u> : No			
Security Violation: No			
Deficiency: No			

05Aug2020 05:05:00 EDT to 05Aug2020 05:05:00 EDT (Estimated): No alcohol testing was conducted due to the extended medical response and engineering repairs being conducted by the crew; no evidence suggests that any persons directly involved were under the influence of alcohol during the casualty.

Timeline Type: Condition
 Timeline Subtype: Person - Person Condition
 Location: Known

Primary Location: Yes
 Description: Sea of Japan, approx.74 NM southwest of the port of Sasebo, Japan

Latitude: 32°29.0 N Longitude: 128°29.0 E

Subject(s) and Details

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
(b) (6), (b) (7)(C) (b) (6), (b) (7)(C)	Person	At Risk, Not Injured	Witness
System: Personnel			
Subsystem: Physiological Condition			
Component: Alcohol/Drugs - Alcohol			
Cite:			
<u>Involves CG Approved Equipment</u> : No			
Security Violation: No			
Deficiency: No			

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
(b) (6), (b) (7)(C)	Person	At Risk, Not Injured	Witness
System: Personnel			
Subsystem: Physiological Condition			
Component: Alcohol/Drugs - Alcohol			
Cite:			
<u>Involves CG Approved Equipment</u> : No			
Security Violation: No			
Deficiency: No			

05Aug2020 20:30:00 EDT to 05Aug2020 20:30:00 EDT (Estimated): The vessel's crew, with the exception of the 3/AE, were subject to Post-Casualty DOT drug testing IAW 46 CFR 4.06; all results were

(b) (7)(C), (b) (6)

MISLE Incident Investigation Report

Timeline Type: Action
Timeline Subtype: Drug/Alcohol Testing - DOT Drug Testing
Location: Unknown

Subject(s) and Details

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
(b) (6), (b) (7)(C) (b) (6), (b) (7)(C)	Person	At Risk, Not Injured	Witness

Reason Directed To Provide Sample(s): Post-casualty

Direction To Provide Sample(s)

Date/Time Directed: 06Aug2020 01:39 EDT

Means Of Direction: verbal

Organization Directing Chemical Test Sample: Marine Employer

Description: post-casualty

Mariner Directed To Get A DOT Drug Test: Yes

Chemical Test Sample Provided: Yes

Sample

Drug Test Sample Taken Using DOT Protocols: Yes

Sample Type: Urine

Date/Time Sample Was Taken: 05Aug2020 20:34 EDT

Sampling Location: SLNC GOODWILL

Collection Agent: (b) (6), (b) (7)(C) (b) (6), (b) (7)(C)

Collection Agent's Organization: SLNC GOODWILL

Donor Certify Sample: Yes

Irregularities Noted: (b) (6)

Drug Analysis

Analyzing Laboratory: Quest Diagnostics (LabOne, Inc. d/b/a Quest Diagnostics), Lenexa, KS, 66219

Specimen Analyzed Using DOT Protocols: Yes

Specimen Transferred And Chain Of Custody Complete: Yes

MISLE Incident Investigation Report

Primary Specimen Test Result

Result: (b) (6), (b) (7)(C)

(b) (6), (b) (7)(C)

Specimen Dilute: (b) (6), (b) (7)(C)

Reason(s) Rejected For Testing:

Remarks:

Review Conducted By

Medical Review Officer: (b) (6), (b) (7)(C)

Coroner:

Determination/Verification: (b) (6), (b) (7)(C)

Specimen Dilute (MRO): (b) (6)

Split Specimen Analyzed: No

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
(b) (6), (b) (7)(C)	Person	At Risk, Not Injured	Witness

Reason Directed To Provide Sample(s): Post-casualty

Direction To Provide Sample(s)

Date/Time Directed: 06Aug2020 03:43 EDT

Means Of Direction: verbal

Organization Directing Chemical Test Sample: Marine Employer

Description: post-casualty

Mariner Directed To Get A DOT Drug Test: Yes

Chemical Test Sample Provided: Yes

Sample

Drug Test Sample Taken Using DOT Protocols: Yes

Sample Type: Urine

Date/Time Sample Was Taken: 05Aug2020 20:49 EDT

Sampling Location: SLNC GOODWILL

Collection Agent: (b) (6), (b) (7)(C) (b) (6), (b) (7)(C)

Collection Agent's Organization: SLNC GOODWILL

Donor Certify Sample: Yes

Irregularities Noted: (b) (6)

MISLE Incident Investigation Report

Drug Analysis

Analyzing Laboratory: Quest Diagnostics (LabOne, Inc. d/b/a Quest Diagnostics), Lenexa, KS, 66219

Specimen Analyzed Using DOT Protocols: Yes

Specimen Transferred And Chain Of Custody Complete: Yes

Primary Specimen Test Result

Result: (b) (6), (b) (7)(C)

(b) (6), (b) (7)(C)

Specimen Dilute: (b) (6), (b) (7)(C)

Reason(s) Rejected For Testing:

Remarks:

Review Conducted By

Medical Review Officer: (b) (6), (b) (7)(C) (b) (6), (b) (7)(C)

Coroner:

Determination/Verification: (b) (6), (b) (7)(C)

Specimen Dilute (MRO): (b) (6)

Split Specimen Analyzed: No

08Aug2020 23:00:00 EDT to 08Aug2020 23:00:00 EDT (Estimated): The Master submitted a completed CG_2692.

Timeline Type: Action

Timeline Subtype: Incident/Casualty Reporting/Notification - CG-2692

Location: Unknown

Subject(s) and Details

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
(b) (6), (b) (7)(C)	Person	Not at Risk	Witness

MISLE Incident Investigation Report

09Aug2020 01:00:00 EDT to 09Aug2020 01:00:00 EDT (Estimated): The electrical governor installed on DG #1 was damaged beyond repair following the flywheel failure and unable to be tested. The mechanical governor was not not subject to post-casualty testing; the last operational test was conducted two (02) weeks prior during a USCG inspection.

Timeline Type: Condition
Timeline Subtype: Vessel - Material/Equipment Condition
Location: Unknown

Subject(s) and Details

<u>Name</u>	<u>Type</u>	<u>Status</u>	<u>Role</u>
SLNC GOODWILL	Vessel	Undamaged	Involved in a Marine Casualty
System: Engineering			
Subsystem: Diesel Engine (auxiliary)			
Component: Overspeed Device			
Cite:			
<u>Involves CG Approved Equipment</u> : No			
Security Violation: No			
Deficiency: No			

VIII. CORRESPONDENCE

OCMI endorsement, signed

Source: USCG

Date: 3/17/2022 2:48:59 AM

Attachments:

OCMI MISLE Endorsement, signed; Other;

(b) (6), (b) (7)(C) 17Mar2022 01:22:42 EDT; No

ROI - Command Endorsement, Executive Summary, & Investigating Officer's Report

Source: USCG

Date: 3/17/2022 2:49:10 AM

Attachments:

ROI, SLNC GOODWILL.docx; Investigative Officer Report;

(b) (6), (b) (7)(C) 12May2022 20:43:44 EDT; No

D14 review, complete

Source: USCG

Date: 5/13/2022 12:45:04 AM

Attachments:

RE_ ROI - SLNC GOODWILL _ Loss of Life, 05Aug20; Other;

(b) (6), (b) (7)(C) 12May2022 20:45:43 EDT; No

Redacted ROI

Source: USCG

Date: 5/16/2022 1:41:13 PM

Attachments:

ROI, SLNC GOODWILL.docx_Redacted; Investigative Officer Report;

(b) (6), (b) (7)(C) 16May2022 09:42:09 EDT; No

IX. CONCLUSIONS – PART 1. CAUSE

Initiating Event:

Material Failure/Malfunction (05Aug2020 00:39:01 EDT)

Precondition

Vessel/Facility/Equipment (Hardware)– Condition - Mechanical damage to internal components of Governor C

Post-casualty analysis of the governor installed on DG #1 at the time of the casualty (Governor C) identified visible evidence of mechanical damage to the surfaces of the governor pilot valve bushing and shaft drive. The damage was inconsistent with that caused by the break-up of the flywheel, which indicates that it was present prior to the casualty. Because both those internal components are involved with regulating the oil pressure in the governor, which in turn directly affects the amount of fuel supplied to DG #1, damage to either of them could have prevented an indication or response to an overspeed of DG #1. Had both of those components been operating as designed, the oil pressure and fuel supply would have remained within designed parameters and prevented DG #1 from overspeeding.

Condition/Vessel - Material/Equipment Condition (20Nov2008 22:02:00 EST); Location Unknown; Each generator was equipped with a governor. The purpose of the governor was to regulate the flow of fuel to the engine in order to maintain a relatively constant speed (rpm) independent of the electrical load placed on the generator.; SLNC GOODWILL

Condition/Vessel - Material/Equipment Condition (21May2019 19:01:00 EDT); Location Unknown; A third governor, Governor C, arrived onboard the vessel for use as a spare; it was a rebuilt governor, not brand new, and had not been installed on any generator onboard the vessel prior to DG #1 on 04Aug21.; SLNC GOODWILL

Condition/Vessel - Material/Equipment Condition (21May2019 19:03:00 EDT); Location Unknown; At some point either during or after overhaul, mechanical damage was sustained on the surfaces of Governor C's pilot valve bushing and shaft drive.; SLNC GOODWILL

Vessel/Facility/Equipment (Hardware)– Condition - Improper storage of Governor C

Governor C had been kept in storage onboard the vessel since May 2019. Either since that time or at some point after, the governor was drained of oil and not refilled. Additionally, despite being installed in a vertical position, it was stored horizontally. Neither of these conditions of storage accurately reflect the conditions of use experienced when the governor is installed and operational, and could well result in some of the internal components not operating as designed. Additionally, the manufacturer had storage instructions that specify the internal surfaces should be coated with oil that meets US MIL-H-17672 specification. Had Governor C been stored in a vertical position with the appropriate amount of oil it would have been in compliance with manufacturer's storage procedures, more accurately reflected the component's actual working conditions, and made them less likely to fail once the governor was installed.

Condition/Vessel - Material/Equipment Condition (02Aug2020 22:59:01 EDT); Location Unknown; No oil was in Governor C while it was stored onboard the vessel and it was found on it's side. The 1/AE stated that, in his experience, oil was kept in governors being stored onboard vessels and they were kept in a vertical position.; SLNC GOODWILL

Condition/Vessel - Material/Equipment Condition (21May2019 19:01:00 EDT); Location Unknown; A third governor, Governor C, arrived onboard the vessel for use as a spare; it was a rebuilt governor, not brand new, and had not been installed on any generator onboard the vessel prior to DG #1 on 04Aug21.; SLNC GOODWILL

Organization

Oversight - Improper recordkeeping for Governor C

Following the casualty, it was found that Governor B and Governor C, both installed on DG #1, had the same serial # and part # stamped on their data plates. Because the work completion report uses these numbers to identify which governor was overhauled, this error made it very difficult to determine whether or not both governors were actually overhauled and, if it was only one that was overhauled, which one it was. Had either someone on the 3rd party repair team or a crewmember/manager of the

MISLE Incident Investigation Report

vessel noticed the mistaken numbers stamped on the data plate, they could have clarified the work done and condition of each governor and have a clear record for each.

Condition/Vessel - Material/Equipment Condition (21May2019 19:00:00 EDT); Location Unknown; The governor installed on DG #1 prior to the casualty, Governor B (Part # 8520-0041, Serial # 15592175), was serviced in place by third party contractors licensed by the governor's manufacturing company.; SLNC GOODWILL

Condition/Vessel - Material/Equipment Condition (21May2019 19:01:00 EDT); Location Unknown; A third governor, Governor C, arrived onboard the vessel for use as a spare; it was a rebuilt governor, not brand new, and had not been installed on any generator onboard the vessel prior to DG #1 on 04Aug21.; SLNC GOODWILL

Condition/Vessel - Material/Equipment Condition (21May2019 19:02:00 EDT); Location Unknown; The data plate installed on Governor C included the same serial # and part # as Governor B. Although the numbers were the same at the time of the casualty, the operating company believes the original serial # for Governor C was 16178255.; SLNC GOODWILL

Production

Planning Error - Knowledge-based Mistake (Bias) - Failure to verify internal condition of Governor C

After being kept in storage for over a year, being found in a horizontal position, and then realizing no oil was present in Governor C, there were no additional steps taken by the vessel's engineering crew to verify if its internal components were still fully operational. Even if a year wouldn't be considered an excessively long time for a governor to sit in storage, either the fact that it was stored on its side or that there was no oil in it could have prompted someone to either open the governor and visually inspect the internal components or wait for the vessel to make port in Korea and have a third party technician confirm proper operation of the governor. Because the first option would require specific certifications, the second option would seem more plausible especially since the vessel had already sailed from Guam using Governor B. Had someone waited to verify the internal condition of Governor C, the material defects may have been found prior to it being used.

Action/Engineering Operations - Unscheduled, Corrective Repair (04Aug2020 00:00:00 EDT); Location Unknown; Installation of Governor C on DG#1 was started by the CE, 1/AE, and 3/AE in the afternoon. It was not completed that day and work was halted around 2000; DG#1 remained offline.; (b) (6), (b) (7)(C) TRENTON LLOYD-REES, (b) (6), (b) (7)(C) (b) (6), (b) (7)(C)

Action/Engineering Operations - Unscheduled, Corrective Repair (04Aug2020 23:30:00 EDT); Location Unknown; The 1/AE and 3/AE resumed the installation of Governor C on DG#1. The CE arrived later to oversee the installation and testing.; TRENTON LLOYD-REES, (b) (6), (b) (7)(C) (b) (6), (b) (7)(C) (b) (6), (b) (7)(C)

Action/Engineering Operations - Engineering Systems Operations (05Aug2020 00:35:00 EDT); Sea of Japan, approx.74 NM southwest of the port of Sasebo, Japan; The 1/AE started up DG#1 for the first time since installing Governor C. The 3/AE and CE were nearby to observe and assist.; TRENTON LLOYD-REES, (b) (6), (b) (7)(C) (b) (6), (b) (7)(C) (b) (6), (b) (7)(C)

Defense

Disabled - Inadequate storage procedures for Governor C

The governor manufacturer (Woodward) published Manual 25075 (Revision B, Mar2015) which detailed the storage procedures for mechanical-hydraulic controls. They also recommend their governors be kept in an upright position to keep the internal components in their proper positions and to prevent oil from leaking out of "breather holes" in the top of the assembly. It is unknown if Governor C was initially stored on its side, or if it fell over at some point later on. Also, it's unclear whether Governor C had oil originally but it leaked out due to it being on its side, or if it never had oil after being overhauled. Either way, the result was the same: on the day it was retrieved for installation, Governor C was on its side and empty of oil. Had the storage procedures been followed fully and maintained during storage, that may have prevented damage to the internal components of Governor C and allowed it to function as designed.

MISLE Incident Investigation Report

Condition/Vessel - Material/Equipment Condition (02Aug2020 22:59:01 EDT); Location Unknown; No oil was in Governor C while it was stored onboard the vessel and it was found on it's side. The 1/AE stated that, in his experience, oil was kept in governors being stored onboard vessels and they were kept in a vertical position.; SLNC GOODWILL

Condition/Organization - Organization Condition (28Feb2015 22:00:00 EST); Location Unknown; The manufacturer of Governor C, Woodward Inc., released instructions for the storage of mechanical-hydraulic controls (governors). These instructions included that oil meeting the US MIL-H-17672 standard should be used to coat the internal surfaces of the device.; Woodward Inc.

Condition/Organization - Organization Condition (02Aug2020 22:59:02 EDT); Location Unknown; The manufacturer of Governor C recommends their governors be transported and stored in an upright position to prevent the ballhead assembly from sliding out of its support bracket as well as preventing oil from leaking out of "breather holes"; those holes are necessary to allow interal air pressure to adjust to ambient air pressure.; Woodward Inc.

Disabled - Inability to confirm maintenance history for Governor C

All three governors referenced in this incident were subject to preventative maintenance which included them being sent ashore to qualified technicians for overhaul, inspection, and repair. However, because the same part # and serial # were used for both Governor B and Governor C, this made it difficult to determine which one was being inspected. Had the data plates for Governor B and Governor C been maintained with the correct part # and serial #, it would have been obvious which one was being maintained and which one needed maintenance performed on it. Currently, there is no way to clearly identify whether it was Governor B or Governor C that was overhauled in May 2019, so it is possible that Governor C was well past its inspection interval and should not have been placed in service. Had the data plates been correct, it would have been clear to trace which governor was currently on maintenance schedule and should have been installed for use.

Condition/Vessel - Material/Equipment Condition (21May2019 19:01:00 EDT); Location Unknown; A third governor, Governor C, arrived onboard the vessel for use as a spare; it was a rebuilt governor, not brand new, and had not been installed on any generator onboard the vessel prior to DG #1 on 04Aug21.; SLNC GOODWILL

Condition/Vessel - Material/Equipment Condition (21May2019 19:02:00 EDT); Location Unknown; The data plate installed on Governor C included the same serial # and part # as Governor B. Although the numbers were the same at the time of the casualty, the operating company believes the original serial # for Governor C was 16178255.; SLNC GOODWILL

Failures of Defense Against Subsequent Events in the Incident

Subsequent Event # 1:

Material Failure/Malfunction (05Aug2020 00:42:00 EDT)

Defense Factors

Disabled - Inadequate mechanical properties of DG #1 flywheel

The engine licensor, MAN Energy Solutions SE, established design requirements for the flywheel that include an ultimate tensile strength of between 300MPa and 400MPa. Eight post-casualty tensile tests of flywheel fragments showed a range of results between 168 MPa and 194MPa; this is 56% to 64% of the required minimum strength. Additionally, microscopic inspection of the flywheel's bolt holes revealed areas of "microshrinkage", which are voids within the casting that can develop during the pour. These would have also reduced the flywheel's tensile strength because they induce planes of weakness and propagate cracking. Had the flywheel's tensile strength met at least the minimum requirements specified by the engine licensor, it is possible that the flywheel could have remained intact until either the 1/AE could have secured the fuel to DG #1 or, failing to secure DG #1, the crew could have had time to evacuate the space before it broke apart.

Condition/Vessel - Material/Equipment Condition(12Jul2020 23:01:00Z);
Location Unknown; The design specification requirement for the DG#1 flywheel was for grey cast iron of Grade C4 with an ultimate tensile strength of between 300-400 megapascals (MPa) and a Brinell hardness of between 200-250 HB.;
SLNC GOODWILL

Condition/Vessel - Material/Equipment Condition(12Jul2020 23:02:00Z);
Location Unknown; The flywheel installed on DG#1 did not meet the design requirements of the engine licensor (MAN Energy Solution SE). After eight tests, the flywheel measured between 56%-64% of the required minimum strength and the hardness was, on average, 83% of the required minimum hardness.;
SLNC GOODWILL

Condition/Vessel - Material/Equipment Condition(12Jul2020 23:03:00Z);
Location Unknown; Micro-shrinkage voids were present in the area around the flywheel coupling bolt holes.;
SLNC GOODWILL

Disabled - Inadequate chemical composition of DG#1 flywheel

The engine licensor, MAN Energy Solutions SE, established design requirements for the flywheel that include a Brinell hardness of between 200HB and 250HB. Eight post-casualty tests of flywheel fragments found the hardness to be 167HB on average; this is 83% of the required minimum hardness. Had the flywheel's hardness met at least the minimum requirements specified by the engine licensor, it is possible that the flywheel could have remained intact until either the 1/AE could have secured the fuel to DG #1 or, failing to secure DG #1, the crew could have had time to evacuate the space before it broke apart.

Condition/Vessel - Material/Equipment Condition(12Jul2020 23:01:00Z);
Location Unknown; The design specification requirement for the DG#1 flywheel was for grey cast iron of Grade C4 with an ultimate tensile strength of between 300-400 megapascals (MPa) and a Brinell hardness of between 200-250 HB.;
SLNC GOODWILL

Condition/Vessel - Material/Equipment Condition(12Jul2020 23:02:00Z);
Location Unknown; The flywheel installed on DG#1 did not meet the design requirements of the engine licensor (MAN Energy Solution SE). After eight tests, the flywheel measured between 56%-64% of the required minimum strength and the hardness was, on average, 83% of the required minimum hardness.;
SLNC GOODWILL

Subsequent Event # 2:

Personnel Casualty - Death (05Aug2020 00:42:02 EDT)

Defense Factors

Does Not Exist - No reasonable protective measures exist to prevent loss of life

The 3/AE was standing in a position that should have been reasonably safe under routine operating conditions and was wearing all the applicable personal protective equipment (PPE) for working in the vessel's engine room. Once the flywheel broke apart, there was no time to react nor any PPE normally worn in that environment that could have reasonably prevented the 3/AE from sustaining the injury that ultimately led to his death.

Condition/Vessel - Material/Equipment Condition(05Aug2020 04:42:01Z); Sea of Japan, approx.74 NM southwest of the port of Sasebo, Japan; The sections of the flywheel were hurled through the engine room at a high rate of speed. One large section struck the 3/AE who was still standing between DG#1 and DG#2.; SLNC GOODWILL

Condition/Vessel - Material/Equipment Condition(05Aug2020 04:42:03Z); Sea of Japan, approx.74 NM southwest of the port of Sasebo, Japan; The pieces of DG#1 flywheel struck and ruptured air piping and water piping running through the generator space.; SLNC GOODWILL

Inadequate - Inability to conduct visual teleconferencing during medical treatment

During interview, the 2/M stated that he had served on at least one other vessel that had the ability to conduct video teleconferencing in it's medical space. However, the SLNC GOODWILL was not equipped with that capability. As a result, a crewmember was required to describe the injury, sometimes while actively applying medical treatment, to a shoreside medical support service who was then required to visualize the description and attempt to offer the appropriate treatment option. If the vessel was able to dial up the same medical personnel and have them watching the treatment and see the extent of the injuries, it may have led to more timely recommendations/advice and active feedback during more technical medical treatment that was performed during this casualty such as use of a nasopharyngeal airway, intravenous injection, and needle thoracostomy.

Condition/Vessel - Material/Equipment Condition(05Aug2020 04:51:00Z); Sea of Japan, approx.74 NM southwest of the port of Sasebo, Japan; The vessel was not equipped with the ability to conduct video teleconferencing in the medical space.; SLNC GOODWILL

Condition/Person - Communications Condition(05Aug2020 05:15:00Z); Sea of Japan, approx.74 NM southwest of the port of Sasebo, Japan; The vessel's 2/M and Master administered medical treatment to the 3/AE while receiving consultation from shoreside Medical Alert Services (MAS). The crew described injuries verbally and received instruction from MAS personnel.; (b) (6), (b) (7)(C)

(b) (6), (b) (7)(C) (b) (6), (b) (7)(C)

Subsequent Event # 3:

Loss of Electrical Power (05Aug2020 00:42:04 EDT)

Defense Factors

Does Not Exist - Significant damage to vessel's electrical generation/distribution

When the flywheel on DG #1 broke apart violently, the fragments caused significant damage to multiple systems within the vessel's engine room to include control, water supply, air supply, and electrical distribution. There was no reasonable defense that could have been used to prevent the fragments from causing this damage which subsequently resulted in a loss of power until repairs could be made.

Condition/Vessel - Material/Equipment Condition(05Aug2020 04:42:01Z); Sea of Japan, approx.74 NM southwest of the port of Sasebo, Japan; The sections of the flywheel were hurled through the engine room at a high rate of speed. One large section struck the 3/AE who was still standing between DG#1 and DG#2.; SLNC GOODWILL

Condition/Vessel - Material/Equipment Condition(05Aug2020 04:42:03Z); Sea of Japan, approx.74 NM southwest of the port of Sasebo, Japan; The pieces of DG#1 flywheel struck and ruptured air piping and water piping running through the generator space.; SLNC GOODWILL

Subsequent Event # 4:

Loss/Reduction of Vessel Propulsion/Steering (05Aug2020 00:42:05 EDT)

Defense Factors

Does Not Exist - Significant damage to propulsion control systems

When the flywheel on DG #1 broke apart violently, the fragments caused significant damage to multiple systems within the vessel's generator room to include control, water supply, air supply, and electrical distribution. All of these systems are necessary in order to maintain operation of the main diesel engine. There was no reasonable defense that could have been used to prevent the fragments from causing this damage which directly resulted in a loss of propulsion until repairs could be made.

Condition/Vessel - Material/Equipment Condition(05Aug2020 04:42:01Z); Sea of Japan, approx.74 NM southwest of the port of Sasebo, Japan; The sections of the flywheel were hurled through the engine room at a high rate of speed. One large section struck the 3/AE who was still standing between DG#1 and DG#2.; SLNC GOODWILL

Condition/Vessel - Material/Equipment Condition(05Aug2020 04:42:03Z); Sea of Japan, approx.74 NM southwest of the port of Sasebo, Japan; The pieces of DG#1 flywheel struck and ruptured air piping and water piping running through the generator space.; SLNC GOODWILL

Subsequent Event # 5:

Material Failure/Malfunction (05Aug2020 00:41:35 EDT)

Defense Factors

Disabled - Failure of the overspeed protection device

DG #1 was equipped with an electrical and mechanical overspeed protection device, or "overspeed trip", which are a secondary safety measure designed to prevent an uncontrolled increase in engine rpms should the governor fail to operate as designed. In this specific instance, DG #1 normally operates at 900 rpms and the overspeed device is set to trip at 1,020 rpms. All evidence clearly indicates that the rpms on DG #1 exceeded 1,020 rpms, but the overspeed device failed to trip. Additionally, the overspeed device had operated as designed just prior to this casualty: the first attempt to start DG #1 resulted in increased rpms and the activation of the overspeed protection device. Whether it was reset incorrectly or experienced a mechanical failure that prevented it from activating is unknown and cannot be supported either way using the evidence provided. Either way, had the overspeed trip device worked as designed it would have prevented the uncontrolled increase in rpms.

Condition/Vessel - Material/Equipment Condition(05Aug2020 04:36:00Z); Sea of Japan, approx.74 NM southwest of the port of Sasebo, Japan; DG#1 rpms were unstable and steadily increased.; SLNC GOODWILL

Condition/Vessel - Material/Equipment Condition(05Aug2020 04:37:00Z); Sea of Japan, approx.74 NM southwest of the port of Sasebo, Japan; The overspeed protection device activated when DG#1 rpms exceeded approx. 1,020 and successfully shut down DG#1.; SLNC GOODWILL

Condition/Vessel - Material/Equipment Condition(05Aug2020 04:41:30Z); Sea of Japan, approx.74 NM southwest of the port of Sasebo, Japan; DG#1 rpms steadily increased, accompanied by an unfamiliar noise and vibration; Governor C's overspeed trip device didn't activate.; SLNC GOODWILL

Condition/Vessel - Material/Equipment Condition(05Aug2020 04:41:46Z); Sea of Japan, approx.74 NM southwest of the port of Sasebo, Japan; Smoke began to be visible from the engine and rpms continued to increase. Despite having passed the upper limit for DG#1 rpms, the overspeed trip device in Governor C failed to activate.; SLNC GOODWILL

X. CONCLUSIONS – PART 2. ENFORCEMENT REFERRALS

None

XI. SAFETY RECOMMENDATIONS

Safety Alerts:



U.S. Department of State

REPORT OF DEATH OF A U.S. CITIZEN OR U.S. NON-CITIZEN NATIONAL ABROAD

Fukuoka, Japan

08-13-2020

Post

Date of Issue (mm-dd-yyyy)

SSA No. (b) (7)(C), (b) (6)

Name in full Trenton David LLOYD-REES

Age 23

Date (mm-dd-yyyy) and Place of Birth (b) (7)(C), (b) (6)

(b) (6), (b) (7)(C)

Evidence of U.S. Citizenship Regular passport # (b) (7)(C), (b) (6) issued on July 28, 2015

Address in U.S.A. (b) (6), (b) (7)(C)

Permanent or Temporary Address Abroad

Date of death August 05 06: 23 p.m. 2020
Month Day Hour Minute Year

Place of death Nagasaki Airport, Omura-shi, Nagasaki-ken, Japan

Number and street, or Hospital/ hotel City Country

Cause of death Hemorrhagic shock according to Dr. Hiroyuki Hiu of Nagasaki Medical Center,
Including authority for statement - if physician, include full name and official title, if any

Omura-shi, Nagasaki-ken, Japan.

Disposition of the remains Embalmed and shipped for burial in the USA.

Local law governing disinterment of remains provides that

Disposition of the effects In custody of Master SLNC Goodwill (b) (6), (b) (7)(C)

Person or official responsible for custody of effects and accounting therefore

Master SLNC Goodwill (b) (6), (b) (7)(C)

Traveling/residing abroad with relatives or friends as follows:

NAME ADDRESS

Informed by telegram or telephone

NAME

ADDRESS

DATE (mm-dd-yyyy) NOTIFIED

Ms (b) (6), (b) (7)(C)

(b) (6), (b) (7)(C)

08-05-2020

Copy of this report sent to:

NAME

ADDRESS

DATE (mm-dd-yyyy) SENT

(b) (6), (b) (7)(C)

(b) (6), (b) (7)(C)

08-13-2020

Nishi Kyushu Warehouse

3-7 Inari-cho, Sasebo-shi, Nagasaki-ken, Japan

08-13-2020

Notification or copy sent to Federal Agencies: SSA X VA OPM Other ME State Agency

The original copy of this document and information concerning the effects are being placed in the permanent files of the U.S. Department of State, Passport Vital Records Section, CA/PPT/S/TO/RS/DO/MR, 1150 Passport Services PL, 6th Floor, Dulles, VA 20189-1150.

Remarks:

Passport (b) (6), (b) (7)(C) canceled and returned to Mr. and Mrs (b) (6), (b) (7)(C) (b) (6), (b) (7)(C) on reverse if necessary.)

[SEAL]

Signature on all copies

(b) (6), (b) (7)(C) Consul of the United States of America.

For Additional Certified Copies, see http://travel.state.gov/passport/faq/faq_5057.html

LLOYD-REES (Last name)
TRENTON (First name)
DAVID (Middle name)
08-05-2020 (Date (mm-dd-yyyy) of death)

Evidence Control Number (ECN) 7025155-^{(b) (6), (b) (7)(C)} 013 corresponds with an audio recording of an interview with ^{(b) (6), (b) (7)(C)} 1AE of the SLNC GOODWILL at the time of the casualty. The interview was conducted by ^{(b) (6), (b) (7)(C)} ^{(b) (6), (b) (7)(C)} onboard the SLNC GOODWILL. A digital copy of the interview will be maintained at USCG Activities Far East.

Evidence Control Number (ECN) 7025155-^{(b) (6), (b) (7)(C)}012 corresponds with an audio recording of an interview with ^{(b) (6), (b) (7)(C)}, 4M of the SLNC GOODWILL at the time of the casualty. The interview was conducted by ^{(b) (6), (b) (7)(C)} onboard the SLNC GOODWILL on 08 August 2020. A digital copy of the interview will be maintained at USCG Activities Far East.

Evidence Control Number (ECN) 7025155-^{(b) (6), (b) (7)(C)}007 corresponds with an audio recording of an interview with ^{(b) (6), (b) (7)(C)}, Chief Engineer of the SLNC GOODWILL at the time of the casualty. The interview was conducted by ^{(b) (6), (b) (7)(C)} and witnessed by ^{(b) (6), (b) (7)(C)} onboard the SLNC GOODWILL on 07 August 2020. A digital copy of the interview will be maintained at USCG Activities Far East.

Evidence Control Number (ECN) 7025155-^{(b) (6), (b) (7)(C)}009 corresponds with an audio recording of an interview with ^{(b) (6), (b) (7)(C)}, ^{(b) (6), (b) (7)(C)} of the SLNC GOODWILL at the time of the casualty. The interview was conducted by ^{(b) (6), (b) (7)(C)} ^{(b) (6), (b) (7)(C)} onboard the SLNC GOODWILL on 08 August 2020. A digital copy of the interview will be maintained at USCG Activities Far East.

Evidence Control Number (ECN) 7025155-^{(b) (6), (b) (7)(C)}014 corresponds with an audio recording of an interview with ^{(b) (6), (b) (7)(C)} Captain of the SLNC GOODWILL at the time of the casualty. The interview was conducted by ^{(b) (6), (b) (7)(C)} ^{(b) (6), (b) (7)(C)} onboard the SLNC GOODWILL on 07 August 2020. A digital copy of the interview will be maintained at USCG Activities Far East.

For Official Use Only: Public Availability to be Determined under 5 U.S.C. 552.

Case History Report

**Commandant (CG-INV-3)
17JUL2023 14:40Z**

---Administrative Data---

MISLE Case Id: 1229748 Open Date: 05AUG2020 22:24Z
Status: Open - In Progress
Title: Case Created from Misle Notification
Owning Unit: Activities Far East Originating Unit: Activities Far East

Other Activities (Non IMA or Non Sortie) in Case:

MISLE Activity Id: 7025153	Enf Activity Id:	Type: Preliminary Investigation
MISLE Activity Id: 7025155	Enf Activity Id:	Type: Incident Investigation
MISLE Activity Id: 7028636	Enf Activity Id:	Type: Vessel Inspection

---Incident Data---

---Involved Subjects---

Vessel Name: SLNC GOODWILL	Call Sign: WDI5693
Primary VIN: 1266919	Gross Tonnage:
Role: Involved in a Marine Casualty	Approx. Length: 580.4 Feet
Flag: UNITED STATES	Year Completed:
Service: Tank Ship	Propulsion Type: Diesel Direct
Damage Status: Undamaged	

Person Name: (b) (6), (b) (7)(C) (b) (6), (b) (7)(C)	Status: At Risk, Not Injured
Role: Witness	Birth Date: (b) (7)(C), (b) (6)
Identification(s)	
SSN: (b) (7)(C), (b) (6)	
Person Name: (b) (6), (b) (7)(C)	Status: At Risk, Not Injured
Role: Witness	Birth Date: (b) (6), (b) (7)(C)

For Official Use Only: Public Availability to be Determined under 5 U.S.C. 552.

Identification(s)
SSN: (b) (7)(C), (b) (6)
Person Name: LLOYD-REES, TRENTON Status: Dead
Role: Subject of Investigation Birth Date: (b) (7)(C), (b) (6)

Identification(s)
SSN: (b) (7)(C), (b) (6)
Person Name: LLOYD-REES, TRENTON Status: Dead
Role: Subject of Investigation Birth Date: (b) (7)(C), (b) (6)

Identification(s)
SSN: (b) (7)(C), (b) (6)
Person Name: (b) (6), (b) (7)(C) Status: Not at Risk
Role: Medical Review Officer Birth Date:

Identification(s)
Miscellaneous ID: MEDICAL REVIEW OFFICER
Miscellaneous ID: MRO
Person Name: (b) (6), (b) (7)(C) Status: Not at Risk
Role: Other Birth Date:

Identification(s)
Drivers License: (b) (6), (b) (7)(C)
Person Name: (b) (6), (b) (7)(C) Status: Not at Risk
Role: Other Birth Date:

Identification(s)
Drivers License: (b) (7)(C), (b) (6)
Person Name: (b) (6), (b) (7)(C) Status: Not at Risk
Role: Witness Birth Date: (b) (6), (b) (7)(C)

Identification(s)
SSN: (b) (6), (b) (7)(C)
Person Name: (b) (6), (b) (7)(C) Status: Not at Risk
Role: Witness Birth Date: (b) (6), (b) (7)(C)

Identification(s)
SSN: (b) (6), (b) (7)(C)
US Merchant Mariner Credential: (b) (6), (b) (7)(C)
Person Name: (b) (6), (b) (7)(C), (b) (6), (b) (7)(C) Status: Not at Risk
Role: Witness Birth Date: (b) (6), (b) (7)(C)

Identification(s)
SSN: (b) (6), (b) (7)(C)

For Official Use Only: Public Availability to be Determined under 5 U.S.C. 552.

US Merchant Mariner Credential: (b) (6), (b) (7)(C)

Person Name: (b) (6), (b) (7)(C)

Status: Not at Risk

Role: Witness

Birth Date: (b) (6), (b) (7)(C)

Identification(s)

SSN: (b) (6), (b) (7)(C)

Person Name: (b) (6), (b) (7)(C)

Status: Not at Risk

Role: Witness

Birth Date:

Identification(s)

Organization Name: NORD GOODWILL LLC

Role: Other

Identification(s)

Tax ID: (b) (6), (b) (7)(C)

Organization Name: SCHUYLER LINE NAVIGATION CORP

Role: Other

Identification(s)

Tax ID: (b) (6), (b) (7)(C)

IMO Company Number: 5779287

Organization Name: Woodward Inc.

Role: Witness

Identification(s)

Waterway: Sea of Japan, approx.74 NM southwest of the port of Sasebo, Japan

Role: Location

REPORT OF MANDATORY CHEMICAL TESTING FOLLOWING A SERIOUS MARINE INCIDENT INVOLVING VESSELS IN COMMERCIAL SERVICE

Note: This form shall be used to report data on persons directly involved in a serious marine incident involving a vessel in commercial service and the mandatory chemical drug and alcohol testing.

Section I - Reporting Vessel Information - Casualty Date/Time

1. Vessel Name SLNC GOODWILL	2. Vessel Official Number or IMO Number 9448334	3. Date/Time (local) of Occurrence 2020AUG05 1342
---------------------------------	--	--

Section II - Reason for Submitting this Report (Check all that apply)

4. The above vessel is in commercial service and was involved in a Serious Marine Incident that resulted in (46 CFR 4.03-2):

- One or more deaths
- An injury to a crewmember, passenger, or other person that requires professional medical treatment beyond first aid, and, in the case of a person employed on board a vessel in commercial service, which renders the individual unfit to perform routine vessel duties
- Damage to property in excess of \$200,000
- Actual or constructive total loss of any vessel subject to inspection under 46 USC 3301
- Actual or constructive total loss of any self-propelled vessel, not subject to inspection under 46 USC 3301, of 100 gross tons or more
- A discharge of oil of 10,000 gallons or more into the navigable waters of the United States, as defined in 33 USC 1321
- A discharge of a reportable quantity of a hazardous substance into the navigable waters of the United States
- A release of a reportable quantity of a hazardous substance into the environment United States

Section III - Personnel and Testing Information

5. Individuals Directly Involved in Serious Marine Incident 6. Drug and Alcohol Testing

5a. Name (Last, First, Middle)	5b. USCG Credentialed?	6a. Drug Test Urine Sample Provided Within 32 Hours?	6b. Alcohol Test Specimen Provided within 2 Hours?	6c. Type of Alcohol Test Specimen Provided	6d. Alcohol Test Results
(b) (6), (b) (7)(C)	(b) (6), (b) (7)(C)	(b) (6), (b) (7)(C)	(b) (6), (b) (7)(C)	(b) (6), (b) (7)(C)	(b) (6), (b) (7)(C)

7. Explanation of why test samples were not collected within required timeframes or not at all and/or why testing was not conducted (Required for each "No" checked in columns 6a or 6b)

Due to an ongoing medical response to a crewmember casualty, and then efforts to restore power to the vessel the ship's crew was engaged in operations for the safety of the vessel past the two hour to eight hour Alcohol test time frame.

8. SAMHSA Accredited Laboratory Conducting Chemical Drug Tests
Name: Quest Diagnostics - Toxicology

Address: 10101 Renner Blvd Lenexa KS 66700

Telephone: 1-800-877-7484

Email:

9. Laboratory or Individual Conducting Alcohol Tests
Name:

Address:

Telephone:

Email:

Section IV - Person Making this Report

10. Name (PRINT) (Last, First, Middle) (b) (6), (b) (7)(C)	11. Signature (b) (6), (b) (7)(C)	12. Date 08/09/2020
13. Title Master	14. Address (b) (6), (b) (7)(C)	United States
15. Telephone No. (b) (6), (b) (7)(C)	16. Email (b) (6), (b) (7)(C)	

REPORT OF MANDATORY CHEMICAL TESTING FOLLOWING A SERIOUS MARINE INCIDENT INVOLVING VESSELS IN COMMERCIAL SERVICE

Note: This form shall be used to report data on persons directly involved in a serious marine incident involving a vessel in commercial service and the mandatory chemical drug and alcohol testing.

Section I - Reporting Vessel Information - Casualty Date/Time

Table with 3 columns: 1. Vessel Name (SLNC GOODWILL), 2. Vessel Official Number or IMO Number (9448334), 3. Date/Time (local) of Occurrence (2020AUG05 1342)

Section II - Reason for Submitting this Report (Check all that apply)

4. The above vessel is in commercial service and was involved in a Serious Marine Incident that resulted in (46 CFR 4.03-2):

- Checked boxes: One or more deaths, Damage to property in excess of \$200,000. Other options include injury to crewmember, loss of vessel, oil discharge, and hazardous substance release.

Section III - Personnel and Testing Information

5. Individuals Directly Involved in Serious Marine Incident 6. Drug and Alcohol Testing

Table with 5 columns: 5a. Name (Last, First, Middle), 5b. USCG Credentialed?, 6a. Drug Test Urine Sample Provided Within 32 Hours?, 6b. Alcohol Test Specimen Provided within 2 Hours?, 6c. Type of Alcohol Test Specimen Provided, 6d. Alcohol Test Results

Large redacted area covering personnel and testing information with (b) (6), (b) (7)(C) markings.

7. Explanation of why test samples were not collected within required timeframes or not at all and/or why testing was not conducted (Required for each "No" checked in columns 6a or 6b)

Due to an ongoing medical response to a crewmember casualty, and then efforts to restore power to the vessel the ship's crew was engaged in operations for the safety of the vessel past the two hour to eight hour Alcohol test time frame.

8. SAMHSA Accredited Laboratory Conducting Chemical Drug Tests

Name: Quest Diagnostics - Toxicology
Address: 10101 Renner Blvd Lenexa KS 66700
Telephone: 1-800-877-7484
Email:

9. Laboratory or Individual Conducting Alcohol Tests

Name:
Address:
Telephone:
Email:

Section IV - Person Making this Report

Table with 3 columns: 10. Name (PRINT) (Last, First, Middle), 11. Signature, 12. Date; 13. Title, 14. Address; 15. Telephone No., 16. Email. All fields are redacted with (b) (6), (b) (7)(C).

INSTRUCTIONS FOR COMPLETION OF FORM CG-2692B
Report of Chemical Testing Following a Serious Marine Incident Involving a Commercial Vessel

An agency may not conduct or sponsor, and a person is not required to respond to a collection of information unless it displays a valid OMB control number. The Coast Guard estimates that the average burden for this report is .5 hours. You may submit any comments concerning the accuracy of this burden estimate or any suggestions for reducing the burden to: Commandant (CG-INV), U.S. Coast Guard Stop 7501, 2703 Martin Luther King Jr Ave SE, Washington, DC 20593-7501 or Office of Management and Budget, Paperwork Reduction Project (1625-0001), Washington, DC 20503.

WHEN TO USE THIS FORM

1. This form, when submitted in conjunction with a CG-2692 or submitted alone, satisfies the requirement found in the Code of Federal Regulations for written reports of chemical drug and alcohol testing of individuals engaged or employed on board a commercial vessel who are identified as being directly involved in serious marine incidents consisting of one or more of the occurrences lists in block 4. Alcohol tests are to be conducted not later than 2 hours (unless there are safety concerns directly related to the casualty that need to be addressed by the individual(s)) and drug test specimens collected not later than 32 hours after a serious marine incident.

INDIVIDUAL DIRECTLY INVOLVED IN A SERIOUS MARINE INCIDENT

2. The term "Individual Directly Involved in a Serious Marine Incident" means an individual whose order, action, or failure to act is determined to be, or cannot be ruled out as, a causative factor in the events leading to or causing a serious marine incident.

COMPLETION OF THIS FORM

3. In accordance with 46 CFR Subpart 4.06 this form shall be filled out as completely and accurately as possible. Please type or print clearly. Fill in all blanks that apply to the kind of accident that has occurred. If a block is not applicable, the abbreviation "NA" should be entered in that space. If the answer is unknown and cannot be obtained before the report has to be submitted (i.e. within 5 days of the accident), the abbreviation "UNK" should be entered in that block. If "NONE" is the correct response, enter it in the block.

4. If more than 10 individuals are directly involved in the Serious Marine Incident additional CG-2692Bs should be completed.

5. Once completed, deliver, email, or fax this form with a corresponding CG-2692 within 5 days of the casualty to the Coast Guard Sector, Marine Safety Unit, or Activity nearest the location of the casualty or, if at sea, nearest the arrival port. <https://www.uscg.mil/Units/Organization>

6. Upon receipt of a report of chemical test results. The marine employer shall submit a copy of the test results for each person listed in block 5a of this form to the Coast Guard Officer in Charge, Marine Inspection where the CG-2692B was submitted in accordance with 46 CFR §4.06-60(d).

7. Block 6d - Alcohol Test Result: When the alcohol test results are available, the alcohol concentration shall be expressed numerically in percent by weight (i.e. 0.04, 0.10, etc.); otherwise indicate positive for alcohol being present or negative for no alcohol present.

NOTICE: The information collected on this form is routinely available for public inspection. It is needed by the Coast Guard to carry out its responsibility to investigate marine casualties, to identify hazardous conditions or situations and to conduct statistical analysis. The information is used to determine whether new or revised safety initiatives are necessary for the protection of life or property in the marine environment.

I.M.T.

(b) (6), (b) (7)(C)

1451 Tallevast Rd
Sarasota, FL 34243

Voice: (b) (6), (b) (7)(C) Fax: 941.753.9975

MRO REPORT - FEDERAL Controlled Substance Testing Results

Name of Donor:	(b) (6), (b) (7)(C)	<u>Urine Specimen Tested For:</u>
SSN / ID#:	(b) (6), (b) (7)(C)	(b) (7)(C), (b) (6)
Name of Company:	AMS/ SCHUYLER LINE NAVIGATION	
Collection Date:	8/6/2020 10:17 AM	
Specimen ID Number:	(b) (6), (b) (7)(C)	
Reason for Test:	POST ACCIDENT	
Analyzing Laboratory:	QUEST DIAGNOSTICS 10101 RENNER BLVD. LENEXA, KS 66219	
MRO CCF Received:	8/12/2020 - 3:15 PM	
Split Specimen:	YES	
Certified MRO:	(b) (6), (b) (7)(C)	
Verified Test Result:	(b) (6), (b) (7)(C)	

I have received and reviewed the Laboratory result for the specimen represented by this form in accordance with the US Coast Guard Controlled Substance Testing requirements as contained in 49 CFR part 40 and 46 CFR part 16.

(b) (6), (b) (7)(C)

8/12/2020
Verified Date

Certified Medical Review Officer (b) (6), (b) (7)(C)

This information is required by Section 49 CFR part 40 to be retained in the employee's qualification file

(b) (6), (b) (7)(C)

I.M.T.

(b) (6), (b) (7)(C)

1451 Tallevast Rd
Sarasota, FL 34243

Voice (b) (6), (b) (7)(C) Fax: 941.753.9975

MRO REPORT - FEDERAL Controlled Substance Testing Results

Name of Donor: (b) (6), (b) (7)(C)

SSN / ID#:

(b) (6), (b) (7)(C)

Name of Company: AMS/ SCHUYLER LINE NAVIGATION

Collection Date: 8/6/2020 10:30 AM

Specimen ID Number:

(b) (6), (b) (7)(C)

Reason for Test: POST ACCIDENT

Analyzing Laboratory: QUEST DIAGNOSTICS
10101 RENNER BLVD.
LENEXA, KS 66219

MRO CCF Received: 8/12/2020 - 3:15 PM

Split Specimen: YES

Certified MRO:

(b) (6), (b) (7)(C)

Urine Specimen Tested For:

(b) (7)(C), (b) (6)

Verified Test Result:

(b) (6), (b) (7)(C)

I have received and reviewed the Laboratory result for the specimen represented by this form in accordance with the US Coast Guard Controlled Substance Testing requirements as contained in 49 CFR part 40 and 46 CFR part 16.

(b) (6), (b) (7)(C)

8/12/2020

Verified Date

Certified Medical Review Officer (b) (6), (b) (7)(C)

This information is required by Section 49 CFR part 40 to be retained in the employee's qualification file

(b) (6), (b) (7)(C)

I.M.T.

(b) (6), (b) (7)(C)

1451 Tallevast Rd
Sarasota, FL 34243

Voice: (b) (6), (b) (7)(C) Fax: 941 753.9975

MRO REPORT - FEDERAL Controlled Substance Testing Results

Name of Donor: (b) (6), (b) (7)(C)
SSN / ID#: (b) (6), (b) (7)(C)
Name of Company: AMS/ SCHUYLER LINE NAVIGATION
Collection Date: 8/6/2020 9:34 AM
Specimen ID Number: (b) (6), (b) (7)(C)
Reason for Test: POST ACCIDENT
Analyzing Laboratory: QUEST DIAGNOSTICS
10101 RENNER BLVD.
LENEXA, KS 66219
MRO CCF Received: 8/12/2020 - 3:15 PM
Split Specimen: YES
Certified MRO: (b) (6), (b) (7)(C)

Urine Specimen Tested For:

(b) (7)(C), (b) (6)

Verified Test Result: (b) (6), (b) (7)(C)

I have received and reviewed the Laboratory result for the specimen represented by this form in accordance with the US Coast Guard Controlled Substance Testing requirements as contained in 49 CFR part 40 and 46 CFR part 16.

(b) (6), (b) (7)(C)

Certified Medical Review Officer (b) (6), (b) (7)(C)

8/12/2020
Verified Date

This information is required by Section 49 CFR part 40 to be retained in the employee's qualification file

(b) (6), (b) (7)(C)

I.M.T.

(b) (6), (b) (7)(C)

1451 Tallevast Rd
Sarasota, FL 34243

Voice: (b) (6), (b) (7)(C) Fax: 941.753.9975

MRO REPORT - FEDERAL Controlled Substance Testing Results

Name of Donor:	(b) (6), (b) (7)(C)	<u>Urine Specimen Tested For:</u>
SSN / ID#:	(b) (6), (b) (7)(C)	(b) (7)(C), (b) (6)
Name of Company:	AMS/ SCHUYLER LINE NAVIGATION	
Collection Date:	8/6/2020 10:51 AM	
Specimen ID Number:	(b) (6), (b) (7)(C)	
Reason for Test:	POST ACCIDENT	
Analyzing Laboratory:	QUEST DIAGNOSTICS 10101 RENNER BLVD. LENEXA, KS 66219	
MRO CCF Received:	8/12/2020 - 3:15 PM	
Split Specimen:	YES	
Certified MRO:	(b) (6), (b) (7)(C)	
Verified Test Result:	(b) (6), (b) (7)(C)	

I have received and reviewed the Laboratory result for the specimen represented by this form in accordance with the US Coast Guard Controlled Substance Testing requirements as contained in 49 CFR part 40 and 46 CFR part 16.

(b) (6), (b) (7)(C)

Certified Medical Review Officer (b) (6), (b) (7)(C)

8/12/2020
Verified Date

This information is required by Section 49 CFR part 40 to be retained in the employee's qualification file

(b) (6), (b) (7)(C)

I.M.T.

(b) (6), (b) (7)(C)

1451 Tallevast Rd
Sarasota, FL 34243

Voice: (b) (6), (b) (7)(C) Fax: 941.753.9975

MRO REPORT - FEDERAL Controlled Substance Testing Results

Name of Donor: (b) (6), (b) (7)(C)

SSN / ID#: (b) (6), (b) (7)(C)

Name of Company: AMS/ SCHUYLER LINE NAVIGATION

Collection Date: 8/6/2020 10:22 AM

Specimen ID Number: (b) (6), (b) (7)(C)

Reason for Test: POST ACCIDENT

Analyzing Laboratory: QUEST DIAGNOSTICS
10101 RENNER BLVD.
LENEXA, KS 66219

MRO CCF Received: 8/12/2020 - 3:15 PM

Split Specimen: YES

Certified MRO: (b) (6), (b) (7)(C)

Urine Specimen Tested For:

(b) (7)(C), (b) (6)

Verified Test Result: (b) (6), (b) (7)(C)

Comments:
CORRECTABLE FLAW AMENDED BY COLLECTION SITE.

I have received and reviewed the Laboratory result for the specimen represented by this form in accordance with the US Coast Guard Controlled Substance Testing requirements as contained in 49 CFR part 40 and 46 CFR part 16.

(b) (6), (b) (7)(C)

8/19/2020

Verified Date

Certified Medical Review Officer (b) (6), (b) (7)(C)

This information is required by Section 49 CFR part 40 to be retained in the employee's qualification file

(b) (6), (b) (7)(C)

I.M.T.

(b) (6), (b) (7)(C)

1451 Tallevast Rd
Sarasota, FL 34243

Voice (b) (6), (b) (7)(C) Fax: 941.753.9975

MRO REPORT - FEDERAL Controlled Substance Testing Results

Name of Donor:

(b) (6), (b) (7)(C)

Urine Specimen Tested For:

SSN / ID#:

(b) (6), (b) (7)(C)

(b) (7)(C), (b) (6)

Name of Company:

AMS/ SCHUYLER LINE NAVIGATION

Collection Date:

8/6/2020 10:44 AM

Specimen ID Number:

(b) (6), (b) (7)(C)

Reason for Test:

POST ACCIDENT

Analyzing Laboratory:

QUEST DIAGNOSTICS
10101 RENNER BLVD.
LENEXA, KS 66219

MRO CCF Received:

8/12/2020 - 3:15 PM

Split Specimen:

YES

Certified MRO:

(b) (6), (b) (7)(C)

Verified Test Result:

(b) (6), (b) (7)(C)

Comments:

CORRECTABLE FLAW AMENDED BY COLLECTION SITE.

I have received and reviewed the Laboratory result for the specimen represented by this form in accordance with the US Coast Guard Controlled Substance Testing requirements as contained in 49 CFR part 40 and 46 CFR part 16.

(b) (6), (b) (7)(C)
(b) (6), (b) (7)(C)

8/19/2020

Verified Date

Certified Medical Review Officer (b) (6), (b) (7)(C)

This information is required by Section 49 CFR part 40 to be retained in the employee's qualification file

(b) (6), (b) (7)(C)

I.M.T.

(b) (6), (b) (7)(C)

1451 Tallevast Rd

Sarasota, FL 34243

Voice: (b) (6), (b) (7)(C) Fax: 941.753.9975

MRO REPORT - FEDERAL Controlled Substance Testing Results

Name of Donor: (b) (6), (b) (7)(C)
SSN / ID#: (b) (6), (b) (7)(C)
Name of Company: AMS/ SCHUYLER LINE NAVIGATION
Collection Date: 8/6/2020 10:37 AM
Specimen ID Number: (b) (6), (b) (7)(C)
Reason for Test: POST ACCIDENT
Analyzing Laboratory: QUEST DIAGNOSTICS
10101 RENNER BLVD.
LENEXA, KS 66219
MRO CCF Received: 8/12/2020 - 3:15 PM
Split Specimen: YES
Certified MRO: (b) (6), (b) (7)(C)

Urine Specimen Tested For:

(b) (7)(C), (b) (6)

Dilute Values:

CREATININE (b) (6), (b) (7)(C)

SPECIFIC GRAVITY (b) (6), (b) (7)(C)

Verified Test Result: (b) (6), (b) (7)(C)

Comments:

You may retest the individual, but not under direct observation.

I have received and reviewed the Laboratory result for the specimen represented by this form in accordance with the US Coast Guard Controlled Substance Testing requirements as contained in 49 CFR part 40 and 46 CFR part 16.

(b) (6), (b) (7)(C)

Certified Medical Review Officer (b) (6), (b) (7)(C)

8/12/2020

Verified Date

This information is required by Section 49 CFR part 40 to be retained in the employee's qualification file

(b) (6), (b) (7)(C)

I.M.T.

(b) (6), (b) (7)(C)

1451 Tallevast Rd
Sarasota, FL 34243

Voice (b) (6), (b) (7)(C) Fax: 941.753.9975

MRO REPORT - FEDERAL Controlled Substance Testing Results

Name of Donor: (b) (6), (b) (7)(C)
SSN / ID#: [REDACTED]
Name of Company: AMS/ SCHUYLER LINE NAVIGATION
Collection Date: 8/11/2020
Specimen ID Number: (b) (6), (b) (7)(C)
Reason for Test: POST ACCIDENT
Collected By: (b) (7)(C), (b) (6)
Analyzing Laboratory: QUEST DIAGNOSTICS
10101 RENNER BLVD.
LENEXA, KS 66219
MRO CCF Received: 8/12/2020 - 3:15 PM
Split Specimen: YES
Certified MRO: (b) (6), (b) (7)(C)
Verified Test Result: (b) (6), (b) (7)(C)

Urine Specimen Tested For:

(b) (7)(C), (b) (6)

I have received and reviewed the Laboratory result for the specimen represented by this form in accordance with the US Coast Guard Controlled Substance Testing requirements as contained in 49 CFR part 40 and 46 CFR part 16.

(b) (6), (b) (7)(C)

Certified Medical Review Officer • (b) (6), (b) (7)(C)

8/12/2020
Verified Date

This information is required by Section 49 CFR part 40 to be retained in the employee's qualification file

(b) (6), (b) (7)(C)

I.M.T.

(b) (6), (b) (7)(C)

1451 Tallevast Rd
Sarasota, FL 34243

Voice: (b) (6), (b) (7)(C) Fax: 941.753.9975

MRO REPORT - FEDERAL Controlled Substance Testing Results

Name of Donor:

(b) (6), (b) (7)(C)

SSN / ID#:

(b) (6), (b) (7)(C)

Name of Company:

AMS/ SCHUYLER LINE NAVIGATION

Collection Date:

8/6/2020 10:09 AM

Specimen ID Number:

(b) (6), (b) (7)(C)

Reason for Test:

POST ACCIDENT

Analyzing Laboratory:

QUEST DIAGNOSTICS
10101 RENNER BLVD.
LENEXA, KS 66219

MRO CCF Received:

8/12/2020 - 3:15 PM

Split Specimen:

YES

Certified MRO:

(b) (6), (b) (7)(C)

Urine Specimen Tested For:

(b) (7)(C), (b) (6)

Verified Test Result:

(b) (6), (b) (7)(C)

I have received and reviewed the Laboratory result for the specimen represented by this form in accordance with the US Coast Guard Controlled Substance Testing requirements as contained in 49 CFR part 40 and 46 CFR part 16.

(b) (6), (b) (6), (b) (7)(C)

8/12/2020

Verified Date

Certified Medical Review Officer (b) (6), (b) (7)(C)

This information is required by Section 49 CFR part 40 to be retained in the employee's qualification file

(b) (6), (b) (7)(C)

I.M.T.

(b) (6), (b) (7)(C)

1451 Tallevast Rd
Sarasota, FL 34243

Voice: (b) (6), (b) (7)(C) Fax: 941.753.9975

MRO REPORT - FEDERAL Controlled Substance Testing Results

Name of Donor: (b) (6), (b) (7)(C)

SSN / ID#:

Name of Company: AMS/ SCHUYLER LINE NAVIGATION

Collection Date: 8/6/2020 10:02 AM

Specimen ID Number: (b) (6), (b) (7)(C)

Reason for Test: POST ACCIDENT

Analyzing Laboratory: QUEST DIAGNOSTICS
10101 RENNER BLVD.
LENEXA, KS 66219

MRO CCF Received: 8/12/2020 - 3:15 PM

Split Specimen: YES

Certified MRO: (b) (6), (b) (7)(C)

Urine Specimen Tested For:

(b) (7)(C), (b) (6)

Verified Test Result: (b) (6), (b) (7)(C)

I have received and reviewed the Laboratory result for the specimen represented by this form in accordance with the US Coast Guard Controlled Substance Testing requirements as contained in 49 CFR part 40 and 46 CFR part 16.

(b) (6), (b) (7)(C)

Certified Medical Review Officer (b) (6), (b) (7)(C)

8/12/2020
Verified Date

This information is required by Section 49 CFR part 40 to be retained in the employee's qualification file

(b) (6), (b) (7)(C)

I.M.T.

(b) (6), (b) (7)(C)

1451 Tallevast Rd
Sarasota, FL 34243

Voice: (b) (6), (b) (7)(C) Fax: 941.753.9975

MRO REPORT - FEDERAL Controlled Substance Testing Results

Name of Donor:	(b) (6), (b) (7)(C)	<u>Urine Specimen Tested For:</u>
SSN / ID#:	(b) (6), (b) (7)(C)	(b) (7)(C), (b) (6)
Name of Company:	AMS/ SCHUYLER LINE NAVIGATION	
Collection Date:	8/6/2020 9:55 AM	
Specimen ID Number:	(b) (6), (b) (7)(C)	
Reason for Test:	POST ACCIDENT	
Analyzing Laboratory:	QUEST DIAGNOSTICS 10101 RENNER BLVD. LENEXA, KS 66219	
MRO CCF Received:	8/12/2020 - 3:15 PM	
Split Specimen:	YES	
Certified MRO:	(b) (6), (b) (7)(C)	
Verified Test Result:	(b) (6), (b) (7)(C)	

I have received and reviewed the Laboratory result for the specimen represented by this form in accordance with the US Coast Guard Controlled Substance Testing requirements as contained in 49 CFR part 40 and 46 CFR part 16.

(b) (6), (b) (7)(C)

Certified Medical Review Officer (b) (6), (b) (7)(C)

8/12/2020
Verified Date

This information is required by Section 49 CFR part 40 to be retained in the employee's qualification file

(b) (6), (b) (7)(C)

I.M.T.

(b) (6), (b) (7)(C)

1451 Tallevast Rd
Sarasota, FL 34243

Voice: (b) (6), (b) (7)(C) Fax: 941.753.9975

MRO REPORT - FEDERAL Controlled Substance Testing Results

Name of Donor:

(b) (6), (b) (7)(C)

SSN / ID#:

[REDACTED]

Name of Company:

AMS/ SCHUYLER LINE NAVIGATION

Collection Date:

8/6/2020 9:49 AM

Specimen ID Number:

(b) (6), (b) (7)(C)

Reason for Test:

POST ACCIDENT

Analyzing Laboratory:

QUEST DIAGNOSTICS
10101 RENNER BLVD.
LENEXA, KS 66219

MRO CCF Received:

8/12/2020 - 3:15 PM

Split Specimen:

YES

Certified MRO:

(b) (6), (b) (7)(C)

Urine Specimen Tested For:

(b) (7)(C), (b) (6)

[REDACTED]

Verified Test Result:

(b) (6), (b) (7)(C)

I have received and reviewed the Laboratory result for the specimen represented by this form in accordance with the US Coast Guard Controlled Substance Testing requirements as contained in 49 CFR part 40 and 46 CFR part 16.

(b) (6), (b) (7)(C)

8/12/2020

Verified Date

Certified Medical Review Officer (b) (6), (b) (7)(C)

This information is required by Section 49 CFR part 40 to be retained in the employee's qualification file

(b) (6), (b) (7)(C)

I.M.T.

(b) (6), (b) (7)(C)

1451 Tallevast Rd
Sarasota, FL 34243

Voice (b) (6), (b) (7)(C) Fax: 941.753.9975

MRO REPORT - FEDERAL Controlled Substance Testing Results

Name of Donor:	(b) (6), (b) (7)(C)	Urine Specimen Tested For:	(b) (7)(C), (b) (6)
SSN / ID#:	(b) (6), (b) (7)(C)		
Name of Company:	AMS/ SCHUYLER LINE NAVIGATION		
Collection Date:	8/6/2020 9:14 AM		
Specimen ID Number:	(b) (6), (b) (7)(C)		
Reason for Test:	POST ACCIDENT		
Analyzing Laboratory:	QUEST DIAGNOSTICS 10101 RENNER BLVD. LENEXA, KS 66219		
MRO CCF Received:	8/12/2020 - 3:15 PM		
Split Specimen:	YES		
Certified MRO:	(b) (6), (b) (7)(C)		
Verified Test Result:	(b) (6), (b) (7)(C)		

I have received and reviewed the Laboratory result for the specimen represented by this form in accordance with the US Coast Guard Controlled Substance Testing requirements as contained in 49 CFR part 40 and 46 CFR part 16.

(b) (6), (b) (7)(C)

8/12/2020

Verified Date

Certified Medical Review Officer (b) (6), (b) (7)(C)

This information is required by Section 49 CFR part 40 to be retained in the employee's qualification file

(b) (6), (b) (7)(C)

I.M.T.

(b) (6), (b) (7)(C) FP. CMRO

(b) (6), (b) (7)(C)

Voice

MRO REPORT - FEDERAL Controlled Substance Testing Results

Name of Donor: (b) (6), (b) (7)(C)

SSN / ID#: (b) (6), (b) (7)(C)

Name of Company: AMS/ SCHUYLER LINE NAVIGATION

Collection Date: 8/6/2020 9:55 AM

Specimen ID Number: (b) (6), (b) (7)(C)

Reason for Test: POST ACCIDENT

Analyzing Laboratory: QUEST DIAGNOSTICS
10101 RENNER BLVD.
LENEXA, KS 66219

MRO CCF Received: 8/12/2020 - 3:15 PM

Split Specimen: YES

Certified MRO: (b) (6), (b) (7)(C)

Urine Specimen Tested For:
(b) (7)(C), (b) (6)

Verified Test Results: (b) (6), (b) (7)(C)

I have received and reviewed the Laboratory result for the specimen represented by this form in accordance with the US Coast Guard Controlled Substance Testing requirements as contained in 49 CFR part 40 and 46 CFR part 16.

(b) (6), (b) (7)(C)
(b) (6), (b) (7)(C)

8/12/2020
Verified Date

Certified Medical Review Officer • AAMRO/951015207

This information is required by Section 49 CFR part 40 to be retained in the employee's qualification file

(b) (6), (b) (7)(C)

I.M.T.

(b) (6), (b) (7)(C) ABFP, CMRO

(b) (6), (b) (7)(C)

Voic

MRO REPORT - FEDERAL Controlled Substance Testing Results

Name of Donor:

(b) (6), (b) (7)(C)

SSN / ID#:

(b) (6), (b) (7)(C)

Name of Company:

AMS/ SCHUYLER LINE NAVIGATION

Collection Date:

8/6/2020

Specimen ID Number:

(b) (6), (b) (7)(C)

Reason for Test:

POST ACCIDENT

Analyzing Laboratory:

QUEST DIAGNOSTICS
10101 RENNER BLVD.
LENEXA, KS 66219

MRO CCF Received:

8/12/2020 - 3:15 PM

Split Specimen:

YES

Certified MRO:

(b) (6), (b) (7)(C)

Urine Specimen Tested For:

(b) (7)(C), (b) (6)

Verified Test Result:

(b) (6), (b) (7)(C)

I have received and reviewed the Laboratory result for the specimen represented by this form in accordance with the US Coast Guard Controlled Substance Testing requirements as contained in 49 CFR part 40 and 46 CFR part 16.

(b) (6), (b) (7)(C)

8/12/2020

Verified Date

Certified Medical Review Officer • AAAMRO/931015207

This information is required by Section 49 CFR part 40 to be retained in the employee's qualification file

(b) (6), (b) (7)(C)

I.M.T.

(b) (6), (b) (7)(C)

1451 Tallevast Rd
Sarasota, FL 34243

Voice (b) (6), (b) (7)(C) Fax: 941.753.9975

MRO REPORT - FEDERAL Controlled Substance Testing Results

Name of Donor:

(b) (6), (b) (7)(C)

SSN / ID#:

(b) (6), (b) (7)(C)

Name of Company:

AMS/ SCHUYLER LINE NAVIGATION

Collection Date:

8/6/2020 9:42 AM

Specimen ID Number:

(b) (6), (b) (7)(C)

Reason for Test:

POST ACCIDENT

Analyzing Laboratory:

QUEST DIAGNOSTICS
10101 RENNER BLVD.
LENEXA, KS 66219

MRO CCF Received:

8/12/2020 - 3:15 PM

Split Specimen:

YES

Certified MRO:

(b) (6), (b) (7)(C)

Urine Specimen Tested For:

(b) (7)(C), (b) (6)

Verified Test Result:

(b) (6), (b) (7)(C)

I have received and reviewed the Laboratory result for the specimen represented by this form in accordance with the US Coast Guard Controlled Substance Testing requirements as contained in 49 CFR part 40 and 46 CFR part 16.

(b) (6), (b) (7)(C)

8/12/2020

Verified Date

Certified Medical Review Officer • (b) (6), (b) (7)(C)

This information is required by Section 49 CFR part 40 to be retained in the employee's qualification file

(b) (6), (b) (7)(C)

I.M.T.

(b) (6), (b) (7)(C)

1451 Tallevast Rd
Sarasota, FL 34243

Voice: (b) (6), (b) (7)(C) Fax: 941.753.9975

MRO REPORT - FEDERAL Controlled Substance Testing Results

Name of Donor: (b) (6), (b) (7)(C)

SSN / ID#: [REDACTED]

Name of Company: AMS/ SCHUYLER LINE NAVIGATION

Collection Date: 8/6/2020 4:54 PM

Specimen ID Number: (b) (6), (b) (7)(C)

Reason for Test: POST ACCIDENT

Analyzing Laboratory: QUEST DIAGNOSTICS
10101 RENNER BLVD.
LENEXA, KS 66219

MRO CCF Received: 8/12/2020 - 3:15 PM

Split Specimen: YES

Certified MRO: (b) (6), (b) (7)(C)

Urine Specimen Tested For:

(b) (7)(C), (b) (6)

Verified Test Result: (b) (6), (b) (7)(C)

I have received and reviewed the Laboratory result for the specimen represented by this form in accordance with the US Coast Guard Controlled Substance Testing requirements as contained in 49 CFR part 40 and 46 CFR part 16.

(b) (6), (b) (7)(C)
(b) (6), (b) (7)(C)

8/12/2020
Verified Date

Certified Medical Review Officer (b) (6), (b) (7)(C)

This information is required by Section 49 CFR part 40 to be retained in the employee's qualification file

(b) (6), (b) (7)(C)

I.M.T.

(b) (6), (b) (7)(C) ABFP, CMRO

1451 Tallevast Rd
Sarasota, FL 34243

Voice: 941.753.9199 Fax: 941.753.9975

MRO REPORT - FEDERAL Controlled Substance Testing Results

Name of Donor: (b) (6), (b) (7)(C)
SSN / ID#: [REDACTED]
Name of Company: AMS/ SCHUYLER LINE NAVIGATION
Collection Date: 8/6/2020 10:57 AM
Specimen ID Number: (b) (6), (b) (7)(C)
Reason for Test: POST ACCIDENT
Analyzing Laboratory: QUEST DIAGNOSTICS
10101 RENNER BLVD.
LENEXA, KS 66219
MRO CCF Received: 8/12/2020 - 3:15 PM
Split Specimen: YES
Certified MRO: (b) (6), (b) (7)(C)

Urine Specimen Tested For:

(b) (7)(C), (b) (6)
[REDACTED]

Verified Test Result: (b) (6), (b) (7)(C)

I have received and reviewed the Laboratory result for the specimen represented by this form in accordance with the US Coast Guard Controlled Substance Testing requirements as contained in 49 CFR part 40 and 46 CFR part 16.

(b) (6), (b) (7)(C)

Certified Medical Review Officer (b) (6), (b) (7)(C)

8/12/2020
Verified Date

This information is required by Section 49 CFR part 40 to be retained in the employee's qualification file

(b) (6), (b) (7)(C)

(b) (6), (b) (7)(C)

10974473

1230569

SPECIMEN ID NO.

LAB ACCESSION NO.

STEP 1: COMPLETED BY COLLECTOR OR EMPLOYER REPRESENTATIVE

(b) (6), (b) (7)(C)

(b) (6), (b) (7)(C)

C. Donor SSN or Employee I.D. No. (b) (6), (b) (7)(C)

D. Specify Testing Authority: HHS DHS DOT Agency FMCSA FAA FRA FTA PHMSA USCG

E. Reason for Test: Pre-employment Random Reasonable Suspicion/Cause Post Accident Return to Duty Follow-up Other (specify)

F. Drug Tests to be Performed: THC, COC, PCP, OPI, AMP THC & COC Only Other (specify)

G. Collection Site Name: SLNC GODWILL Collection Site Code: _____
 Address: 120 SEVENH AVE SUITE 200 Collector Phone No.: (b) (6), (b) (7)(C)
 City, State and Zip: ANNA POLY MD 21403 Collector Fax No.: _____

STEP 2: COMPLETED BY COLLECTOR (make remarks when appropriate) Collector reads specimen temperature within 4 minutes.

Temperature between 90° and 100° F? Yes No, Enter Remark: _____ Collection: Split Single None Provided, Enter Remark: _____ Observed, (Enter Remark)

REMARKS

STEP 3: Collector affixes bottle seal(s) to bottle(s). Collector dates seal(s). Donor initials seal(s). Donor completes STEP 5 on Copy 2 (MRO Copy)

STEP 4: CHAIN OF CUSTODY - INITIATED BY COLLECTOR AND COMPLETED BY TEST FACILITY

I certify that the specimen given to me by the donor identified in the certification section on Copy 2 of this form was collected, labeled, sealed, and released to the Delivery Service noted in accordance with applicable Federal requirements.

(b) (6), (b) (7)(C) Signature of Collector

(b) (6), (b) (7)(C) (Print) Collector's Name (First, MI, Last)

18/06/2020 08:34 AM Date (Mo./Day/Yr.) Time of Collection

SPECIMEN BOTTLE(S) RELEASED TO:

Quest Diagnostics Courier FedEx Other

Name of Delivery Service

STEP 5: COMPLETED BY DONOR

I certify that I provided my urine specimen to the collector; that I have not adulterated it in any manner; each specimen bottle used was sealed with a tamper-evident seal in my presence; and that the information provided on this form and on the label affixed to each specimen bottle is correct.

(b) (6), (b) (7)(C) Signature of Donor

(b) (6), (b) (7)(C) Date (Mo./Day/Yr.)

08/10/2020

Daytime Phone (b) (6), (b) (7)(C) Evening Phone (b) (6), (b) (7)(C) Date of Birth (b) (6), (b) (7)(C)

After the Medical Review Officer receives the test results for the specimen identified by this form, he/she may contact you to ask about prescriptions and over-the-counter medications you may have taken. Therefore, you may want to make a list of those medications for your own records. THIS LIST IS NOT NECESSARY. If you choose to make a list, do so either on a separate piece of paper or on the back of your copy (Copy 5). - DO NOT PROVIDE THIS INFORMATION ON THE BACK OF ANY OTHER COPY OF THE FORM. TAKE COPY 5 WITH YOU.

STEP 6: COMPLETED BY MEDICAL REVIEW OFFICER - PRIMARY SPECIMEN

In accordance with applicable Federal requirements, my verification is:

(b) (6), (b) (7)(C)

REMARKS:

Signature of Medical Review Officer (PRINT) Medical Review Officer's Name (First, MI, Last) Date (Mo./Day/Yr.)

STEP 7: COMPLETED BY MEDICAL REVIEW OFFICER - SPLIT SPECIMEN

In accordance with applicable Federal requirements, my verification for split specimen (if tested) is:

RECONFIRMED for: _____ TEST CANCELLED

FAILED TO RECONFIRM for: _____

REMARKS:

Signature of Medical Review Officer (PRINT) Medical Review Officer's Name (First, MI, Last) (b) (6), (b) (7)(C) Date (Mo./Day/Yr.)

Quest Diagnostics, the Quest Diagnostics logo and all associated marks, logos, trademarks, and/or other marks are trademarks of Quest Diagnostics Incorporated. © Quest Diagnostics Incorporated. All rights reserved. QDZO 0930-0158 Rev 08/11/12

OMB No. 0930-0158

(b) (6), (b) (7)(C)

LAB ACCESSION NO.

A. Employer Name, Address, I.D. No. SCHUYLER LIKE NAVIGATION
 MICHOELA BARKER
 130 SEVERN AVE
 ANNAPOLIS, MD 21403
 PH: 443-521-4154 FAX

B. MRO Name, Address, Phone No. and Fax No. (b) (6), (b) (7)(C)
 INDUSTRIAL DRUG TESTING
 1491 VALLEVASI RD
 SARASOTA, FL 34240
 PH: 941-553-9975

C. Donor SSN or Employee I.D. No. (b) (6), (b) (7)(C)

D. Specify Testing Authority: HHS DOT Agency FMCSA FAA FRA FTA PHMSA USCG

E. Reason for Test: Pre-employment Random Reasonable Suspicion/Cause Post Accident Return to Duty Follow-up Other (specify)

F. Drug Tests to be Performed: THC, COC, PCP, OPI, AMP THC & COC Only Other (specify)

G. Collection Site Name: SLNC GARDNILL
 Address: 130 SEVERN AVE SUITE 20
 City, State and Zip: ANNAPOLIS, MD 21403
 Collection Site Code:
 Collector Phone No.:
 Collector Fax No.:

STEP 2: COMPLETED BY COLLECTOR (make remarks when appropriate) Collector reads specimen temperature within 4 minutes.

Temperature between 90° and 100° F? Yes No, Enter Remark: Collection: Split Single None Provided, Enter Remark: Observed, (Enter Remark)

REMARKS

STEP 3: Collector affixes bottle seal(s) to bottle(s). Collector dates seal(s). Donor initials seal(s). Donor completes STEP 5 on Copy 2 (MRO Copy) STEP 4: CHAIN OF CUSTODY - INITIATED BY COLLECTOR AND COMPLETED BY TEST FACILITY

I certify that the specimen given to me by the donor, identified in the certification section on Copy 2 of this form was collected, labeled, sealed, and released to the Delivery Service noted in accordance with applicable Federal requirements.

(b) (6), (b) (7)(C) Collector

(Print) Collector's Name (First, MI, Last) Date (Mo./Day/Yr.) Time of Collection AM PM

SPECIMEN BOTTLE(S) RELEASED TO:

Quest Diagnostics Courier
 FedEx
 Other

Name of Delivery Service

STEP 5: COMPLETED BY DONOR

I certify that I provided my urine specimen to the collector; that I have not adulterated it in any manner; each specimen bottle used was sealed with a tamper-evident seal in my presence; and that the information provided on this form and on the label affixed to each specimen bottle is correct.

(b) (6), (b) (7)(C)

(PRINT) Donor's Name (First, MI, Last) Date (Mo./Day/Yr.)

Daytime Phone No. (b) (6), (b) (7)(C) Evening Phone No. () Date of Birth (b) (6), (b) (7)(C)

After the Medical Review Officer receives the test results for the specimen identified by this form, he/she may contact you to ask about prescriptions and over-the-counter medications you may have taken. Therefore, you may want to make a list of those medications for your own records. THIS LIST IS NOT NECESSARY. If you choose to make a list, do so either on a separate piece of paper or on the back of your copy (Copy 5). - DO NOT PROVIDE THIS INFORMATION ON THE BACK OF ANY OTHER COPY OF THE FORM. TAKE COPY 5 WITH YOU.

STEP 6: COMPLETED BY MEDICAL REVIEW OFFICER - PRIMARY SPECIMEN

In accordance with applicable Federal requirements, my verification is:

NEGATIVE POSITIVE for: DILUTE

REFUSAL TO TEST because - check reason(s) below: TEST CANCELLED

ADULTERATED (adulterant/reason): SUBSTITUTED

OTHER

REMARKS:

Signature of Medical Review Officer (PRINT) Medical Review Officer's Name (First, MI, Last)

STEP 7: COMPLETED BY MEDICAL REVIEW OFFICER - SPLIT SPECIMEN

In accordance with applicable Federal requirements, my verification for split specimen (if tested) is:

RECONFIRMED for: TEST CANCELLED

FAILED TO RECONFIRM for:

REMARKS:

Signature of Medical Review Officer (PRINT) Medical Review Officer's Name (First, MI, Last)

(b) (6), (b) (7)(C)

STEP 1: COMPLETED BY COLLECTOR OR EMPLOYER REPRESENTATIVE

LAB ACCESSION NO.

A. Employer Name, Address, I.D. No. SCHUYLER LTD NAVIGATION
 B. MRO Name, Address, Phone No. and Fax No. WANT J KRELL, BS
INDUSTRIAL DRUG TESTING
1437 TALLENTS RD
SPRINGFIELD, MO 65761
MO 314-208-8626 FAX: 314-252-9112

C. Donor SSN or Employee I.D. No. (b) (6), (b) (7)(C)

D. Specify Testing Authority: HHS NRC Specify DOT Agency: FMCSA FAA FRA FTA PHMSA USCG

E. Reason for Test: Pre-employment Random Reasonable Suspicion/Cause Post Accident Return to Duty Follow-up Other (specify) _____

F. Drug Tests to be Performed: THC, COC, PCP, OPI, AMP THC & COC Only Other (specify) _____

G. Collection Site Name: 3216 GOODWILL Collection Site Code: _____
 Address: 130 BELCAN AVE SUITE 201 Collector Phone No.: _____
 City, State and Zip: ANNAPOLIS MD 21403 USA Collector Fax No.: _____

STEP 2: COMPLETED BY COLLECTOR (make remarks when appropriate) Collector reads specimen temperature within 4 minutes.

Temperature between 90° and 100° F? Yes No, Enter Remark: _____ Collection: Split Single None Provided, Enter Remark: _____ Observed, (Enter Remark) _____

REMARKS

STEP 3: Collector affixes bottle seal(s) to bottle(s). Collector dates seal(s). Donor initials seal(s). Donor completes STEP 5 on Copy 2 (MRO Copy)

STEP 4: CHAIN OF CUSTODY - INITIATED BY COLLECTOR AND COMPLETED BY TEST FACILITY

I certify that the specimen given to me by the donor identified in the certification section on Copy 2 of this form was collected, labeled, sealed, and released to the Delivery Service noted in accordance with applicable Federal requirements.

(b) (6), (b) (7)(C) Collector

AM PM

Date (Mo./Day/Yr.) 08/06/20 Time of Collection _____

SPECIMEN BOTTLE(S) RELEASED TO:
 Quest Diagnostics Courier
 FedEx
 Other _____

Name of Delivery Service _____

STEP 5: COMPLETED BY DONOR

I certify that I provided my urine specimen to the collector; that I have not adulterated it in any manner; each specimen bottle used was sealed with a tamper-evident seal in my presence; and that the information provided on this form and on the label affixed to each specimen bottle is correct.

(b) (6), (b) (7)(C) _____ (b) (6), (b) (7)(C) _____

Date (Mo./Day/Yr.) 08/06/20

Daytime Phone (b) (6), (b) (7)(C) Evening Phone No. _____ Date of Birth (b) (6), (b) (7)(C)

After the Medical Review Officer receives the test results for the specimen identified by this form, he/she may contact you to ask about prescriptions and over-the-counter medications you may have taken. Therefore, you may want to make a list of those medications for your own records. THIS LIST IS NOT NECESSARY. If you choose to make a list, do so either on a separate piece of paper or on the back of your copy (Copy 5). - DO NOT PROVIDE THIS INFORMATION ON THE BACK OF ANY OTHER COPY OF THE FORM. TAKE COPY 5 WITH YOU.

STEP 6: COMPLETED BY MEDICAL REVIEW OFFICER - PRIMARY SPECIMEN

In accordance with applicable Federal requirements, my verification is:

NEGATIVE POSITIVE for: _____
 DILUTE

REFUSAL TO TEST because - check reason(s) below: TEST CANCELLED

ADULTERATED (adulterant/reason): _____
 SUBSTITUTED
 OTHER _____

REMARKS: _____

 Signature of Medical Review Officer (PRINT) Medical Review Officer's Name (First, MI, Last) _____ Date (Mo./Day/Yr.) _____

STEP 7: COMPLETED BY MEDICAL REVIEW OFFICER - SPLIT SPECIMEN

In accordance with applicable Federal requirements, my verification for split specimen (if tested) is:

RECONFIRMED for: _____ TEST CANCELLED

FAILED TO RECONFIRM for: _____

REMARKS: _____

 Signature of Medical Review Officer (PRINT) Medical Review Officer's Name (First, MI, Last) _____ Date (Mo./Day/Yr.) _____



RECORD OF HOURS OF REST

Aug 2020

IMO STCW 2010(+Manila)

Vessel: SLNC Goodwill

IMO No: 9448334

Flag: United States

Seafarer (Full Name): 06 (b) (6), (b) (7)(C) (b) (6), (b) (7)(C)

Position (Rank): (b) (6), (b) (7)(C)

Watchkeeper: NO



Date	Periods of work are shaded																								Hours of work in 24h period	Hours of rest in 24h period	Comments	NOT TO BE COMPLETED BY THE SEAFARER		
	00	01	02	03	04	05	06	07	08	09	10	11	12	13	14	15	16	17	18	19	20	21	22	23				24	Hours of rest in any 24h period	Hours of rest in any 7 day period
8/1/2020																										9.5	14.5		13.0	101.5
8/2/2020																										9.5	14.5		13.0	101.5
8/3/2020																										9.5	14.5		13.0	101.5
8/4/2020																										9.5	14.5		13.0	101.5
8/5/2020																										16.0	8.0		7.5	95.0
8/6/2020																										15.0	9.0		5.0	89.5
8/7/2020																										7.5	16.5		10.5	91.5
8/8/2020																										9.5	14.5		13.0	91.5
8/9/2020																										9.5	14.5		13.0	91.5
8/10/2020																										9.5	14.5		13.0	91.5
8/11/2020																										9.5	14.5		13.0	91.5
8/12/2020																										9.5	14.5		13.0	98.0
8/13/2020																										9.5	14.5		13.0	103.5
8/14/2020																										9.5	14.5		13.0	101.5
8/15/2020																										9.5	14.5		13.0	101.5
8/16/2020																										9.5	14.5		13.0	101.5
8/17/2020																										9.5	14.5		13.0	101.5
8/18/2020																										9.5	14.5		13.0	101.5
8/19/2020																										9.5	14.5		13.0	101.5
8/20/2020																										9.5	14.5		13.0	101.5
8/21/2020																										9.5	14.5		13.0	101.5
8/22/2020																										9.5	14.5		13.0	101.5
8/23/2020																										9.5	14.5		13.0	101.5
8/24/2020																										9.5	14.5		13.0	101.5
8/25/2020																										9.5	14.5		13.0	101.5
8/26/2020																										9.5	14.5		13.0	101.5
8/27/2020																										9.5	14.5		13.0	101.5
8/28/2020																										9.5	14.5		13.0	101.5
8/29/2020																										9.5	14.5		13.0	101.5
8/30/2020																										9.5	14.5		13.0	101.5
8/31/2020																										9.5	14.5		13.0	101.5
	00	01	02	03	04	05	06	07	08	09	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	304.5	439.5			

The following national laws, regulations and/or collective agreements governing limitations on working hours or minimum rest periods apply to this ship:

USCG, IMO STCW 2010, OPA 90, MM&P, SIU

I AGREE THAT THIS RECORD IS AN ACCURATE REFLECTION OF THE HOURS OF WORK OR REST OF THE SEAFARER CONCERNED.

Name of master or person authorized by master to sign this record: (b) (6), (b) (7)(C), Chief Officer

Signature of master or authorized person: _____

Signature of seafarer: _____


A copy of this record is to be given to the seafarer. This form is subject to examination and endorsement under procedures established by:

United States (name of competent authority)

M3-1

INSTRUCTION BOOK

ZHENJIANG MARINE DIESEL WORKS



Instruction Book

L23/30H

..... Shipyard :

Ship name :

Hull No. :

Rule :

Add: 250,Guangtangqiao Zhenjiang


Jiangsu Province P.R.China

Tel: (b) (6), (b) (7)(C)

Fax: +86.511 451 0033

Plate Page 1 (1)	Tools for Control and Safety Systems Automatics and Instruments	52009-02H
---------------------	--	------------------

L23/30H

Illustration of Tools	Designation	Dimensions			Ш/5	Item No.
		A	B	C		
	Spanner for adjusting of overspeed stop.	125	ø20	100	S	016

S = Standard E = Extra

08028-0D/H5250/94.08.12

WORK COMPLETION REPORT


JEWON ENGINEERING
Technical Repairing Team

- ◆ CUSTOMER/END USER : SCHUYLER LINE
- ◆ Ref. No. : GW-19-603a
- ◆ Location : PUSAN / KOREA
- ◆ Site / Ship(Hull)'s Name : M/V SLNC GOODWILL
- ◆ DATE : 20TH ~ 22ND.MAY.2019
- ◆ Reason : No.1 D/G governor overhaul
- ◆ Charged Person : (b) (6), (b) (7)(C)
- ◆ GOVERNOR INFORMATION
 - 1. Governor Manufacturer : WOODWARD
 - 2. Governor Vendor/Type : UG-8D
 - 3. Governor P/N & S/N :

	PART NO	SERIAL NO	REMARKS
UG-8D	8520-0041	15592175	D/G NO.1

◆ TIME TABLE for TRAVEL/WORK SERVICE

DATE	TIME for WORK				TIME for TRAVEL		REMARKS
	Start Time	End Time	Reg. Times	Over Times	Reg. Times	Over Times	
20 TH MAY.2019					4.0		BUSAN – ULSAN – BUSAN (Try to onboard but failed because of weather)
20 TH MAY.2019							WORK
21 ST MAY.2019							WORK
22 ND MAY 2019							BUSAN – ULSAN – BUSAN (Install and test)



I certify and confirm that the works contained in this report has been completed to my satisfaction and list of re (b) (6), (b) (7)(C) correct.


CUSTOMER (b) (6)

SERVICE ENGINEER Signature

(b) (6), (b) (7)(C)


◆ USING SPARE PARTS

	Part. Name.	Reference No.	Part. No.	Number	Unit	Remark
1	OVERHAUL KIT			1	SET	
2	PILOT VALVE BUSHING		31188	1	EA	
3	PILOT VALVE PLUNGER		30084	1	EA	
4	LAMINATED DRIVE SPRING		30317	12	EA	
5	SIGHT GLASS		1832-109	1	EA	
6	FLYWEIGHT		196089	2	EA	
7	FLYWEIGHT BEARING		180013	4	EA	
8	PIPE PLUG		187034	2	EA	
9	BEVEL GEAR BEARING		16008	1	EA	
10	ELASTIC STOP NUT		1137-821	1	EA	
11	FLEXLOC STOP NUT		1137-425	1	EA	
12	MOTOR OVERHAUL			1	SET	
13	MOTOR BEARING		1782-013	1	EA	
14	MOTOR BEARING		1782-014	1	EA	
15	BRUSH CAP		37928	2	EA	
16	-BLANK-					
17						
18						
19						
20						
21						
22						
23						
24						
25						
26						
27						



I certify and confirm that the works contained in this report has been completed to my satisfaction and list of replacement is correct.

CUSTOMER SIGNATURE
(b) (6), (b) (7)(C)



SERVICE ENGINEER SIGNATURE
(b) (6), (b) (7)(C)

WORK COMPLETION REPORT

JEWON ENGINEERING
Technical Repairing Team

- ◆ CUSTOMER/END USER : SCHUYLER LINE
- ◆ Ref. No. : GW-19-603a
- ◆ Location : PUSAN / KOREA
- ◆ Site / Ship(Hull)'s Name : M/V SLNC GOODWILL
- ◆ DATE : 20TH ~ 22ND.MAY.2019
- ◆ Reason : No.1 D/G governor overhaul
- ◆ Charged Person : (b) (6), (b) (7)(C) [REDACTED]
- ◆ GOVERNOR INFORMATION
 - 1. Governor Manufacturer : WOODWARD
 - 2. Governor Vendor/Type : UG-8D
 - 3. Governor P/N & S/N :

	PART NO	SERIAL NO	REMARKS
UG-8D	8520-0041	15592175	D/G NO.1

◆ TIME TABLE for TRAVEL/WORK SERVICE

DATE	TIME for WORK				TIME for TRAVEL		REMARKS
	Start Time	End Time	Reg. Times	Over Times	Reg. Times	Over Times	
20 TH MAY.2019					4.0		BUSAN – ULSAN – BUSAN (Try to onboard but failed because of weather)
20 TH MAY.2019							WORK
21 ST MAY.2019							WORK
22 ND MAY.2019					4.0		BUSAN – ULSAN – BUSAN (Install and test)

I certify and confirm that the works contained
in this report has been completed to my satisfaction
and list of replacement is correct.

CUSTOMER Signature

SERVICE ENGINEER Signature

◆ USING SPARE PARTS

	Part. Name.	Reference No.	Part. No.	Number	Unit	Remark
1	OVERHAUL KIT			1	SET	
2	PILOT VALVE BUSHING		31188	1	EA	
3	PILOT VALVE PLUNGER		30084	1	EA	
4	LAMINATED DRIVE SPRING		30317	12	EA	
5	SIGHT GLASS		1832-109	1	EA	
6	FLYWEIGHT		196089	2	EA	
7	FLYWEIGHT BEARING		180013	4	EA	
8	PIPE PLUG		187034	2	EA	
9	BEVEL GEAR BEARING		16008	1	EA	
10	ELASTIC STOP NUT		1137-821	1	EA	
11	FLEXLOC STOP NUT		1137-425	1	EA	
12	MOTOR OVERHAUL			1	SET	
13	MOTOR BEARING		1782-013	1	EA	
14	MOTOR BEARING		1782-014	1	EA	
15	BRUSH CAP		37928	2	EA	
16	-BLANK-					
17						
18						
19						
20						
21						
22						
23						
24						
25						
26						
27						

I certify and confirm that the works contained in this report has been completed to my satisfaction and list of replacement is correct.

CUSTOMER Signature

SERVICE ENGINEER Signature

Purpose of work

1. It is highly recommended that Hydraulic-Mechanical Governor/Actuator receives periodical maintenance in order to extend its service life, Hydraulic-Mechanical Governor/Actuator consist of mechanically moving parts and life limited parts in it that requires periodical maintenance or overhaul.
2. Periodical maintenance.

Work

1. 20TH.MAY.2019, receive governor from the agent of M/V SLNC GOODWILL at JEWON ENGINEERING
2. Carried out governor overhaul.
 - 2-1. Disassembled governor : Contaminated by oil



2-2. Cleaning & Parts inspection



2-3. Renewed Part




- a) P.V. PLUNGER & P.V. BUSHING : It was jiggling problem on test stand so replace P.V. PLUNGER & P.V. BUSHING (Control land wear)



- b) FLYWEIGHT : Flyweight toe was wear down. (That part's reason for the hunting & jiggling)



c) SIGHT OIL GAUGE : Sight oil gauge wear and break. (Oil leakage)



2-4. Governor test : test the governor on the woodward test stand.



3. 22ND.MAY.2019 install the governor on the engine of M/V SLNC GOODWILL.

- 3-1. Install the governor to No.1 Diesel engine.
- 3-2. Carried out engine & governor running test.

Remark

1. I recommend governor should be overhaul at least every 2 years.
2. Upper listed parts exchanged. Exchange that parts beside overhaul kits.
3. It was jiggling problem on test stand so replace P.V. PLUNGER & P.V. BUSHING, Flyweight.
4. Governor motor overhaul and both side of bearing was replaced.

---END---

General Test Record for Woodward UG 8D Governors

Customer M/V SLNC GOODWILL Location D/G NO.1
Part No. 8520-0041 Serial No. 15592175
Tested by: (b) (6), (b) (7)(C) Assembled by: (b) (6), (b) (7)(C) Date: 21th.MAY.2019

Check **X**'s proceeding Numbers Not Applicable.

Test at 71°C to 82°C using oil viscosity of approximately 20 mm²/s

1. Compensation system leakage and needle valve seating checked. √
2. Compensating piston bypass in both directions checked. √
3. Governor oil pressure at 350 rpm (UG8, 758 / UG10, 910kPa.)check in both direction. 200 PSI.
- X** 4. With governor control at 400 rpm, apply 90.5 N-m for UG8, 11.7 N- for UG10 torque in fuel off direction
Speed is _____ rpm, r/min min-1, 395 min.
5. Jiggle is with tolerance. √
6. Steady-state regulation is acceptable +/-0.1% √
7. Off speed recovery is acceptable. √
8. Droop is set to give 1 rpm, r/min, min-1 rise above 1001 rpm, r/min, min-1 for .80 term.
shaft travel.
9. High speed stop is set at 1513 rpm, r/min, min-1 9.9 indicator.(within 0 to + 10 rpm)
10. Low speed set at 1023 rpm, r/min, min-1 0.0 indicator.(within 0 to -10 rpm)
Note:Tolerance for coarse metric speeder screw is +20 to 0 for H.S and +0 to -20 for L.S.
Stop pin set at _____rpm, r/min, min-1.
- X** 11. Shutdown nuts adjusted. _____
- X** 12. Pneumatic speed set _____rpm, r/min, min-1 at _____ kPa. air.
_____rpm, r/min, min-1 at _____ kPa. air.
- X** 13. Air, oil, water shutdown _____kPa and above _____ below _____.
- X** 14. Shutdown solenoid operates at 85 rated voltage. √ _____VDC _____VAC
Energize to S.D. √ De-energize to S.D. _____ Latch _____ Potted _____
15. Governor is free of oil leaks. √
16. Needle valve set 1/2 turn open. (Final adjustment to be done in the field.)

Four UG-D only, continued on next sheet.

Serial No. 15592175

General Test Record for Woodward UG 18D Governors

17. Sync. knob positioned and pinned. ✓
18. Load indicator positioned knob pinned. ✓
19. Speed droop knob is pinned, "0" on dial matched pointer. ✓
20. Friction clutch is set. ✓ (0.51-0.62 N-m w/motor), (0.17-0.28 N-m w/o motor)
21. Sync. motor operates properly. ✓ VAC 24 VDC
- ✕ 22. Test & Record mag. P.U. voltage at 400 rpm. V
(0.25V min true rpm for Exp. proof P.U) (0.6V min true rpm for Std. mag P.U)
- ✕ 23. Max. speed limit switch operates at rpm, r/min, min-1 and above.
- ✕ 24. Min. speed limit switch operates at rpm, r/min, min-1 and below.
- ✕ 25. Signal limit switch operates at rpm, r/min, min-1.
-

WORK COMPLETION REPORT


JEWON ENGINEERING
Technical Repairing Team

- ◆ CUSTOMER/END USER : SCHUYLER LINE
- ◆ Ref. No. : GW-19-603a
- ◆ Location : PUSAN / KOREA
- ◆ Site / Ship(Hull)'s Name : M/V SLNC GOODWILL
- ◆ DATE : 20TH ~ 22ND.MAY.2019
- ◆ Reason : No.1 D/G governor overhaul
- ◆ Charged Person : (b) (6), (b) (7)(C)
- ◆ GOVERNOR INFORMATION
 - 1. Governor Manufacturer : WOODWARD
 - 2. Governor Vendor/Type : UG-8D
 - 3. Governor P/N & S/N :

	PART NO	SERIAL NO	REMARKS
UG-8D	8520-0041	15592175	D/G NO.1

◆ TIME TABLE for TRAVEL/WORK SERVICE

DATE	TIME for WORK				TIME for TRAVEL		REMARKS
	Start Time	End Time	Reg. Times	Over Times	Reg. Times	Over Times	
20 TH MAY.2019					4.0		BUSAN - ULSAN - BUSAN (Try to onboard but failed because of weather)
20 TH MAY.2019							WORK
21 ST MAY.2019							WORK
22 ND MAY.2019							BUSAN - ULSAN - BUSAN (Install and test)



I certify and confirm that the works contained in this report has been completed to my satisfaction and list of replacement is correct.


CUSTOMER: (b) (6), (b) (7)(C)

DATE: _____
CHIEF ENGINEER

(b) (6), (b) (7)(C) signature


◆ USING SPARE PARTS

	Part. Name.	Reference No.	Part. No.	Number	Unit	Remark
1	OVERHAUL KIT			1	SET	
2	PILOT VALVE BUSHING		31188	1	EA	
3	PILOT VALVE PLUNGER		30084	1	EA	
4	LAMINATED DRIVE SPRING		30317	12	EA	
5	SIGHT GLASS		1832-109	1	EA	
6	FLYWEIGHT		196089	2	EA	
7	FLYWEIGHT BEARING		180013	4	EA	
8	PIPE PLUG		187034	2	EA	
9	BEVEL GEAR BEARING		16008	1	EA	
10	ELASTIC STOP NUT		1137-821	1	EA	
11	FLEXLOC STOP NUT		1137-425	1	EA	
12	MOTOR OVERHAUL			1	SET	
13	MOTOR BEARING		1782-013	1	EA	
14	MOTOR BEARING		1782-014	1	EA	
15	BRUSH CAP		37928	2	EA	
16	-BLANK-					
17						
18						
19						
20						
21						
22						
23						
24						
25						
26						
27						



I certify and confirm that the works contained in this report has been completed to my satisfaction and list of replacement is correct.

CUST (b) (6), (b) (7)(C)



SERVICE ENGINEER Signature

(b) (6), (b) (7)(C)

WORK COMPLETION REPORT

JEWON ENGINEERING
Technical Repairing Team

- ◆ CUSTOMER/END USER : SCHUYLER LINE
- ◆ Ref. No. : GW-19-603a
- ◆ Location : PUSAN / KOREA
- ◆ Site / Ship(Hull)'s Name : M/V SLNC GOODWILL
- ◆ DATE : 20TH ~ 22ND.MAY.2019
- ◆ Reason : No.1 D/G governor overhaul
- ◆ Charged Person : (b) (6), (b) (7)(C)
- ◆ GOVERNOR INFORMATION
 - 1. Governor Manufacturer : WOODWARD
 - 2. Governor Vendor/Type : UG-8D
 - 3. Governor P/N & S/N :

	PART NO	SERIAL NO	REMARKS
UG-8D	8520-0041	15592175	D/G NO.1

◆ TIME TABLE for TRAVEL/WORK SERVICE

DATE	TIME for WORK				TIME for TRAVEL		REMARKS
	Start Time	End Time	Reg. Times	Over Times	Reg. Times	Over Times	
20 TH MAY.2019					4.0		BUSAN – ULSAN – BUSAN (Try to onboard but failed because of weather)
20 TH MAY.2019							WORK
21 ST MAY.2019							WORK
22 ND MAY.2019					4.0		BUSAN – ULSAN – BUSAN (Install and test)

I certify and confirm that the works contained
in this report has been completed to my satisfaction
and list of replacement is correct.

CUSTOMER Signature

SERVICE ENGINEER Signature



◆ USING SPARE PARTS

	Part. Name.	Reference No.	Part. No.	Number	Unit	Remark
1	OVERHAUL KIT			1	SET	
2	PILOT VALVE BUSHING		31188	1	EA	
3	PILOT VALVE PLUNGER		30084	1	EA	
4	LAMINATED DRIVE SPRING		30317	12	EA	
5	SIGHT GLASS		1832-109	1	EA	
6	FLYWEIGHT		196089	2	EA	
7	FLYWEIGHT BEARING		180013	4	EA	
8	PIPE PLUG		187034	2	EA	
9	BEVEL GEAR BEARING		16008	1	EA	
10	ELASTIC STOP NUT		1137-821	1	EA	
11	FLEXLOC STOP NUT		1137-425	1	EA	
12	MOTOR OVERHAUL			1	SET	
13	MOTOR BEARING		1782-013	1	EA	
14	MOTOR BEARING		1782-014	1	EA	
15	BRUSH CAP		37928	2	EA	
16	-BLANK-					
17						
18						
19						
20						
21						
22						
23						
24						
25						
26						
27						

I certify and confirm that the works contained in this report has been completed to my satisfaction and list of replacement is correct.

CUSTOMER Signature


SERVICE ENGINEER Signature

Purpose of work





1. It is highly recommended that Hydraulic-Mechanical Governor/Actuator receives periodical maintenance in order to extend its service life, Hydraulic-Mechanical Governor/Actuator consist of mechanically moving parts and life limited parts in it that requires periodical maintenance or overhaul.
2. Periodical maintenance.

Work


1. 20TH.MAY.2019, receive governor from the agent of M/V SLNC GOODWILL at JEWON ENGINEERING
2. Carried out governor overhaul.
2-1. Disassembled governor : Contaminated by oil



2-2. Cleaning & Parts inspection




2-3. Renewed Part





- a) P.V. PLUNGER & P.V. BUSHING : It was jiggling problem on test stand so replace P.V. PLUNGER & P.V. BUSHING (Control land wear)




- b) FLYWEIGHT : Flyweight toe was wear down. (That part's reason for the hunting & jiggling)



c) SIGHT OIL GAUGE : Sight oil gauge wear and break. (Oil leakage)



2-4. Governor test : test the governor on the woodward test stand.



3. 22ND.MAY.2019 install the governor on the engine of M/V SLNC GOODWILL.

- 3-1. Install the governor to No.1 Diesel engine.
- 3-2. Carried out engine & governor running test.

Remark

1. I recommend governor should be overhaul at least every 2 years.
2. Upper listed parts exchanged. Exchange that parts beside overhaul kits.
3. It was jiggling problem on test stand so replace P.V. PLUNGER & P.V. BUSHING, Flyweight.
4. Governor motor overhaul and both side of bearing was replaced.

--END--

General Test Record for Woodward UG 8D Governors

Customer M/V SLNC GOODWILL Location D/G NO.1
Part No. 8520-0041 Serial No. 15592175
Tested by: (b) (6), (b) (7)(C) Assembled by: (b) (6), (b) (7)(C) Date: 21th.MAY.2019

Check **X**'s proceeding Numbers Not Applicable.

Test at 71°C to 82°C using oil viscosity of approximately 20 mm²/s

1. Compensation system leakage and needle valve seating checked. √
2. Compensating piston bypass in both directions checked. √
3. Governor oil pressure at 350 rpm (UG8, 758 / UG10, 910kPa.)check in both direction. 200 PSI.
- X** 4. With governor control at 400 rpm, apply 90.5 N-m for UG8, 11.7 N- for UG10 torque in fuel off direction
Speed is rpm, r/min min-1, 395 min.
5. Jiggle is with tolerance. √
6. Steady-state regulation is acceptable +/-0.1% √
7. Off speed recovery is acceptable. √
8. Droop is set to give 1 rpm, r/min, min-1 rise above 1001 rpm, r/min, min-1 for .80 term.
shaft travel.
9. High speed stop is set at 1513 rpm, r/min, min-1 9.9 indicator.(within 0 to + 10 rpm)
10. Low speed set at 1023 rpm, r/min, min-1 0.0 indicator.(within 0 to -10 rpm)
Note:Tolerance for coarse metric speeder screw is +20 to 0 for H.S and +0 to -20 for L.S.
Stop pin set at rpm, r/min, min-1.
- X** 11. Shutdown nuts adjusted.
- X** 12. Pneumatic speed set rpm, r/min, min-1 at kPa. air.
 rpm, r/min, min-1 at kPa. air.
- X** 13. Air, oil, water shutdown kPa and above below .
- X** 14. Shutdown solenoid operates at 85 rated voltage. √ VDC VAC
Energize to S.D. √ De-energize to S.D. Latch Potted
15. Governor is free of oil leaks. √
16. Needle valve set 1/2 turn open. (Final adjustment to be done in the field.)

Four UG-D only, continued on next sheet.

Serial No. 15592175

General Test Record for Woodward UG 18D Governors

17. Sync. knob positioned and pinned. √
18. Load indicator positioned knob pinned. √
19. Speed droop knob is pinned, "0" on dial matched pointer, √
20. Friction clutch is set. √ (0.51-0.62 N-m w/motor), _____ (0.17-0.28 N-m w/o motor)
21. Sync. motor operates properly. √ _____ VAC 24 VDC
- × 22. Test & Record mag. P.U. voltage at 400 rpm. _____ V
(0.25V min true rpm for Exp. proof P.U) (0.6V min true rpm for Std. mag P.U)
- × 23. Max. speed limit switch operates at _____ rpm, r/min, min-1 and above.
- × 24. Min. speed limit switch operates at _____ rpm, r/min, min-1 and below.
- × 25. Signal limit switch operates at _____ rpm, r/min, min-1.

Schuyler Line Navigation Company LLC

Attention: (b) (6), (b) (7)(C) : Schuyler Line Navigation Company
CC: (b) (6), (b) (7)(C)

Lloyd's Register EMEA
Global Technology Centre
Southampton SO16 7QF
United Kingdom

T +44 (0)330 414 0486
E (b) (6), (b) (7)(C)
www.lr.org

21 January 2021

STATEMENT OF PRELIMINARY FINDINGS

For settlement purposes only

At the request of Schuyler Line Navigation Company LLC (SLNC), The Client, Lloyd's Register EMEA's Technical Investigation Department (TID), on behalf of Lloyd's Register North America, Inc., is undertaking an investigation to establish the cause of failure of the number 1 diesel generator installed onboard the vessel SLNC Goodwill, IMO Number 9448334.

MT SLNC Goodwill, IMO number 9448334 is an oil products/chemical tanker built in 2009 at the Guangzhou Shipyard International Co., Ltd., China as their yard number 06131056.

SLNC Goodwill hotel and electric services are provided by three auxiliary generating sets each with an MAN B&W – ZJMD 6L23/30H type prime mover rated to deliver 960 KW at 900 rpm. The generating sets are located in two separate rooms. Set numbers 1 and 2 are in one room and set 3 is in an adjoining room to starboard.

Failure of the diesel generator number 1 occurred on 05 August 2020. According to reports received, Ship's Engineers had carried out maintenance on the engine on 04 August 2020, installing a replacement governor in an effort to rectify engine rotational speed problems. At the first start of the engine on 05 August with the replacement governor, it is reported that the engine speed was unstable and gradually increasing. Reports indicate that the manual overspeed trip was activated at approximately 1,020 rpm, which is in line with the design intent setting of 1,030 rpm. After an inspection of the engine and generator, the overspeed trip was reset and the engine was started a second time. Reports indicate that it became immediately obvious that there was something wrong. Noise and vibrations were heard and felt. Actions to try and stop the engine were taken, unfortunately the severity of the problem was such that the flywheel burst, discharging the four segments of failed flywheel and other engine parts into the engine room resulting in fatal injury to the attending Third Assistant Engineer, and causing extensive damage to the engine, generator and surrounding support structures. It is not known at what rotational speed the flywheel burst.

The investigation to date has undertaken visual inspections, metallurgical examinations and theoretical calculations. This statement presents the following preliminary conclusions into the cause of the engine failure.

1. The engine failed because the flywheel burst under overspeed conditions. The burst occurred because at the increased speed, the centrifugal force and corresponding stresses imposed in the flywheel at the bolted connection between engine, flywheel and generator were greater than the resisting strength of the flywheel material.
2. Investigation has identified that the mechanical properties and chemical composition of the flywheel material did not meet the design requirements of the engine licensor MAN.
3. In respect of the mechanical strength of the flywheel, the design specification is for a grey cast iron of Grade C4 with a tensile strength of between 300MPa and 400MPa and a Brinnell hardness of between 200HB and 250HB.
4. Two sets of tensile tests have been undertaken. Each of the sets of tensile tests looked at mechanical strength of test pieces taken from both radial and tangential directions. For the first series of tests, using material from the centre of the flywheel, four tests yielded an average strength of 174MPa with a range from 168MPa to 182MPa.
5. For the second series of tests, using material taken from in way of the bolt holes at the centre of one of the four segments, four tests yielded an average strength of 186.5 MPa with a range from 176MPa to 194MPa.
6. In respect of the material hardness, test results found the hardness to be 167HB.
7. In respect of the material chemical composition of the flywheel casting the following table presents the results of tests in relation to the design requirements.

Element	Design Specification (%)	Test Results (%)
Carbon	3.1 Nominal	2.2*
Silicon	1.7 Nominal	2.25
Manganese	0.8 Nominal	0.694
Phosphorous	0.2 Max	0.076
Sulphur	0.15 Max	0.081*

*Determined by Combustion analysis

8. In addition to the above, investigation has also found that the casting in way of the failure locations at the centre of the flywheel contained micro-shrinkage. Such a characteristic would also adversely affect the mechanical strength of the flywheel.
9. Calculations carried out show that, if the flywheel had possessed mechanical properties which met MAN's original design requirements, it should not have failed, even under overspeed conditions. Periodic tests of the engine overspeed devices, most recently in July 2020, had been carried out successfully.

10. The calculations also show that, for the mechanical properties of the flywheel as identified by laboratory testing, failure would occur at speeds above the setting point of the overspeed trip devices installed on the engine.
11. The investigation has also identified that the engine went into an overspeed condition because the governor fitted to the engine developed a fault causing it to fail.
12. Failure of the governor resulted in an uncontrolled acceleration of the engine rotational speed to an overspeed condition.
13. The reason for the governor failure is still under investigation.

For and on behalf of Lloyd's Register,

(b) (6), (b) (7)(C)

(b) (6), (b) (7)(C)

Principal Specialist and Team Leader,
Technical and Failure Investigation Department
Advisory Services
Lloyd's Register EMEA, Lloyd's Register Global Technology Centre,
Southampton Boldrewood Innovation Campus, Burgess Road, Southampton, SO16 7QF, UK

Lloyd's Register Group Limited, its affiliates and subsidiaries and their respective officers, employees or agents are individually and collectively, referred to in this clause as 'Lloyd's Register'. Lloyd's Register assumes no responsibility and shall not be liable to any person for any loss, damage or expense caused by reliance on the information or advice in this document or howsoever provided, unless that person has signed a contract with the relevant Lloyd's Register entity for the provision of this information or advice and in that case any responsibility or liability is exclusively on the terms and conditions set out in that contract.



(b) (7)(C), (b) (7)(C), (b) (6)

(b) (6), (b) (7)(C)
























Figure 1 – Flywheel Fractured Sections



Figure 2 – Flywheel Fractured Sections



































20 μ m

EHT = 20.09 kV
WD = 12.5 mm

Signal A = SE1
Photo No. = 7426

Date :15 Oct 2020
Time :14:09:32





200 μ m



EHT = 20.09 kV
WD = 14.5 mm


Signal A = SE1
Photo No. = 7431

Date :15 Oct 2020
Time :14:15:44






























Diesel Generator Failure Investigation

Report for: SLNC Goodwill, IMO 9448334

Name of company: Schuyler Line Navigation Company LLC

Report no: 2008-0018

31 March 2021



Document Control Page

Written by:	Reviewed by:	Approved by:
(b) (6), (b) (7)(C)	(b) (6), (b) (7)(C)	(b) (6), (b) (7)(C)
Signature:	Signature:	Signature:
(b) (6), (b) (7)(C)		
Designation:	Designation:	Designation:
Principal Specialist Failure Investigation team Leader	Principal Specialist Analysis Team Leader	Marine Advisory Manager
Date of approval:		
31 March 2021		

Version history	Date	Reason for Revision:
5v1	31 March 2021	1 st Issued

The contents of this report are for the confidential information of the client and members of the Lloyd's Register Group.

Lloyd's Register and variants of it are trading names of Lloyd's Register Group Limited, its subsidiaries and affiliates. Lloyd's Register EMEA (Reg. no. 29592 R) is an Industrial and Provident Society registered in England and Wales. Registered office: 71 Fenchurch Street, London, EC3M 4BS, UK. A member of the Lloyd's Register group.

Lloyd's Register Group Limited, its affiliates and subsidiaries and their respective officers, employees or agents are, individually and collectively, referred to in this clause as 'Lloyd's Register'. Lloyd's Register assumes no responsibility and shall not be liable to any person for any loss, damage or expense caused by reliance on the information or advice in this document or howsoever provided, unless that person has signed a contract with the relevant Lloyd's Register entity for the provision of this information or advice and in that case any responsibility or liability is exclusively on the terms and conditions set out in that contract.

Report Summary

At the request of Schuyler Line Navigation Company LLC (SLNC), the undersigned Specialist has undertaken an investigation to understand the cause of failure of the number 1 diesel generator installed onboard the vessel SLNC Goodwill, which occurred on 05 August 2020.

The results of component inspections, reviews of documentary information, a materials investigation and torsional vibration and finite element calculations are presented which have established the following principal findings.

Root cause Investigation:

- The root cause of the damage to the number one diesel generator installed onboard the vessel SLNC Goodwill was the failure of the UG 8D governor which had been fitted on the 04 August 2020 to remediate engine speed regulation concerns.
- The failure of the governor caused the engine speed to accelerate in an uncontrolled manner to an overspeed condition higher than the normal set point of 1,030 rpm at which the engine mounted overspeed trip devices should stop the engine.
- The implications are that the engine mounted overspeed protection devices failed to stop the engine runaway. The reason remains unclear since the manual device was reset immediately before the failure.
- As a result of the overspeed condition, the flywheel burst causing fatal injuries to the attending Third Assistant Engineer and extensive damage to the engine and generator and surrounding structures.
- The following factors have been considered in relation to the root cause of failure and the consequent series of events:
 - Assembly of the governor to the engine.
 - The overhaul of the governor.
 - The mechanical properties of the flywheel.
 - Other contributory factors.
- While it cannot irrefutably be concluded that the governor was installed on the engine correctly, on the basis of evidence obtained from visual examinations, materials investigation, documentary evidence and supplementary analysis, it is considered that the governor was probably installed on the engine in accordance with Woodward procedures [1].
- The possibility that the governor was installed incorrectly on the engine is considered to be less likely.
- On the basis of the evidence from visual examinations it is considered that factors associated with the overhaul of the governor identified in the report as '2019.8', carried out in July 2019 are most likely to be contributory to the cause of its failure.
- Visible evidence of mechanical damage to the surfaces of the governor pilot valve bushing and shaft drive surfaces exists, the nature and cause of which cannot be established as consistent with it occurring as a result of the governor failure.
- In addition, evidence associated with the 2021 overhaul of the governor identified in the report as '2019.5' overhauled in May 2019 suggest that shortcomings in care and attention to cleanliness may have existed at that time.
- Further evidence that a lack of care and attention existed is presented in the preparation of the two governor reports [2], [3], where details of test results were incorrectly transferred from test rig to record sheets.
- Once the connection between the governor shaft drive and the pilot valve bushing was broken, the ability to control the engine fuelling and speed was lost by the governor, and the engine accelerated to an uncontrolled overspeed condition. It is uncertain what speed the engine reached before the flywheel burst.
- The burst occurred because at the increased speed, the centrifugal forces and corresponding stresses induced in the flywheel at the bolted connection between engine, flywheel and generator were greater than the resisting strength of the flywheel material.

Materials Investigation:

- A materials investigation has identified that the mechanical properties and chemical composition of the flywheel material did not meet the design requirements of the engine licensor MAN Energy Solutions SE.
- In respect of the mechanical strength of the flywheel, the design specification requirement is for a grey cast iron of Grade C4 with an ultimate tensile strength of between 300MPa and 400MPa and a Brinell hardness of between 200HB and 250HB.
- Eight tensile tests were undertaken, yielding a range of results between 168MPa and 194MPa, i.e. between 56% and 64% of the required minimum strength. The hardness of the material was found on average to be 167HB, or 83% of the required minimum hardness.
- The chemical composition of the material was found to have reduced levels of carbon and manganese. Carbon being 2.2% relative to a specification nominal value of 3.1% and Manganese being 0.694% relative to a specification nominal value of 0.8%.
- The materials investigation also identified the presence of microshrinkage in the casting in way of the flywheel coupling bolt holes. Such a microstructural characteristic would additionally adversely affect the already reduced tensile strength of the material.

Finite element and torsional vibration analysis investigation:

- Finite element analysis results show good agreement with MAN Energy Solutions ES [4] in their assessment of principal stresses at the 12 coupling bolts locations.
- Dynamic torque effects due to torsional vibrations increased the induced stress due to centrifugal forces. Analyses were carried out, including the torsional vibration effects for cases of the engine fitted with a tuning wheel and a viscous damper, the latter at 100% damping, 50% damping and for a seized damper. In each case flywheel flange contact pressures of 0 MPa (representing a loose fitting of the flywheel flange) and at 24 MPa (representing a tight fitting of the flywheel flange) were considered.
- The induced principal stress, S1, in the flywheel reached the lower measured UTS (168 MPa) of the flywheel material at the following engine speeds, with:
 - The tuning wheel; at 1311 rpm (loose fit) and at 1325 rpm (tight fit).
 - The seized viscous damper; at 1228 rpm (loose fit) and at 1500 rpm (tight fit).
 - Viscous damper at 50% damping; at 1361 rpm (loose fit) and at 1500 rpm (tight fit).
 - Viscous damper at 100% damping; at 1385 rpm (loose fit) and at 1517 rpm (tight fit).
- The induced principal stress, S1, in the flywheel reached the lower specified requirement UTS (300 MPa) of the flywheel material at the following engine speeds, with:
 - The tuning wheel; at 1919 rpm (loose fit) and at 1979 rpm (tight fit).
 - The seized viscous damper; at 1912 rpm (loose fit) and at 1992 rpm (tight fit).
 - Viscous damper at 50% damping; at 1917 rpm (loose fit) and at 1986 rpm (tight fit).
 - Viscous damper at 100% damping; at 1929 rpm (loose fit) and at 1992 rpm (tight fit).
- The analysis also recognises that in all cases, the maximum principal stress on the flywheel was close to the two short retaining bolts on the alternator side of the flywheel. The presence of these bolts is for location of the flywheel during assembly of the engine and alternator on the base frame.
- From the above analysis, it is considered that If the flywheel had been of the correct strength material. The likelihood is that it would not have burst before damage to the cylinders and running gear would have stopped the engine.

The following recommendations are made:

- Noting that MPI checks have been carried out on the number 2 and number 3 generating sets, it is recommended that as soon as reasonably practical, the mechanical strength properties of the flywheels on the number 2 and number 3 generating sets are established. This is probably best achieved by carrying out hardness tests in regions as close to the flywheel hub as possible. Unfortunately, since the material is grey cast iron and non-homogeneous, only certain instruments are able to be used. It is also likely that to achieve best results, the flywheels will need to be removed from the generating sets.

- Closer inspection of the flywheel coupling bolt holes might also give an indication of casting quality. Investigation of the failed flywheel has identified that the bolt hole surfaces were very rough as a result of the microshrinkage. This inspection could be achieved by endoscope or borescope inspection and/or the casting of rubber replicas. TID can undertake such assessments.
- A general assessment of casting microstructure could be carried out using a method known as replication, where acetate strips are applied to the polished, etched casting surface. This method might not however, necessarily give an indication of casting strength.
- In relation to the above, submission of a three (3) gram sample of filings from each of the flywheels will allow full chemical analysis of the material, the results of which will permit an assessment of chemical composition for comparison against the required specification and as a comparison against the failed flywheel.
- TID is able to assist in setting up and managing the above suite of checks recommended to understand more closely the material properties of the flywheels of the number 2 and number 3 generating set engines.
- It is recommended that the condition of the damper on the number 1 generator crankshaft is inspected and the condition of the fluid established. The condition of the dampers on the number 2 and number 3 generator engines should also be verified.
- In relation to the above, it is also recommended that MAN Energy Solutions SE discuss with the engine builder the discrepancies identified in the torsional vibration calculations and additionally, the apparent discrepancy between what the engine builder thinks is fitted on the engine and what is actually fitted on the engine.
- Recommendations have previously been made [7] to subject the mechanical overspeed trip to testing, to understand why it failed to activate during the second overspeed event. Investigation should also be undertaken to test the functionality of the electronic overspeed trip device and associated components fitted to the damaged engine. It is also recommended that the functionality of the second and third generator set overspeed trip devices is confirmed.
- It was recommended early in the investigation [7] that the overspeed trip settings of the number 2 and number 3 generating sets should be lowered to below 1000 rpm. This recommendation is reiterated until such time that the material properties of the flywheels can be verified.
- It is recommended that the process of filling replacement governors is reviewed with a view to ensuring that the risks associated with introducing debris into the governors are understood and can be mitigated.

Lloyd's Register and variants of it are trading names of Lloyd's Register Group Limited, its subsidiaries and affiliates. Lloyd's Register EMEA (Reg. no. 29592 R) is an Industrial and Provident Society registered in England and Wales. Registered office: 71 Fenchurch Street, London, EC3M 4BS, UK. A member of the Lloyd's Register group.

Lloyd's Register Group Limited, its affiliates and subsidiaries and their respective officers, employees or agents are, individually and collectively, referred to in this clause as 'Lloyd's Register'. Lloyd's Register assumes no responsibility and shall not be liable to any person for any loss, damage or expense caused by reliance on the information or advice in this document or howsoever provided, unless that person has signed a contract with the relevant Lloyd's Register entity for the provision of this information or advice and in that case any responsibility or liability is exclusively on the terms and conditions set out in that contract.

12. References

1. Woodward Governor product manual 03040, UG Dial Governor.
2. Jewon Engineering Technical Repairing Team report: Dated according to the governor test report as 26 July 2019.
3. Jewon Engineering Technical Repairing Team report: Dated according to the governor test report as 21 May 2019.
4. H.B Nielson, L23/30 Flywheel Calculation of Safety Against Bursting, four stroke GenSet Design. Presentation date 19 Sept 2014, MAB Diesel and Turbo
5. Chief Engineer Statement, dated 08 August 2020
6. Bud Hall, Fleet Technical Manager. Chief Engineer and First Engineer Interview report, dated 29 August 2020
7. TID report 2008-0018 No.1 Generator Engine Flywheel Failure Investigation 1v1, dated 15 September 2020.
8. TID report 2008-0018 No.1 Generator Engine Flywheel Failure Investigation 2v1, dated 24 February 2021.
9. Junma, Service report, 23 April 2019
10. Junma, Work done report, 01 April 2019
11. Junma, Inspection report, 25 April 2019
12. Junma, Turbo service report NR20R/172, 14 April 2019
13. JWE, Work completion report, 25 July 2019
14. JWE, Work completion report, 21 May 2019
15. Dieselman Singapore Pte Ltd. Job No J207351, Fuel pump inspection report Dated 29 October 2020
16. Dieselman Singapore Pte Ltd. Job No J207351, Fuel injector inspection report Dated 29 September 2020
17. ASM international: Gear materials, properties and manufacture, JR Davis ISBN 13: 978-0-87170-815-1
18. Turner ECS repair report RO00194U Governor UG 8 Dial. Dated according to the governor test report as 09 February 2021.

From: (b) (6), (b) (7)(C)
To: (b) (6), (b) (7)(C) -USCG ACTIVITIES FAR EAS (USA)
Cc: [Bud Hall](#)
Subject: [Non-DoD Source] Re: [EXTERNAL]:FW: SLNC GOODWILL casualty investigation
Date: Wednesday, November 10, 2021 9:24:47 AM
Attachments: [image001.png](#)

Good morning (b) (6), (b) (7)(C) –

My apologies for having you wait on this, I've been somewhat out of pocket over the weekend.

We agree with your conclusion that there were two governors with the same serial number. We are fairly certain that JEWON, the Woodward licensed service company in Korea, made a mistake with the serial numbers during overhaul of these governors that resulted in this discrepancy. Please note we believe the Original serial number on the governor in use at the time of the incident was **16178255**.

We are still working with the previous managers to determine when the error with the serial numbers took place, and our intention is to eventually provide to JEWON and Woodward our findings for quality improvement purposes, both on governor overhaul performance and unit identification.

Hope this info helps explain where we are right now.

Regards

(b) (6), (b) (7)(C)

Port Captain / DPA

Schuyler Line Navigation Company LLC

(b) (6), (b) (7)(C)

O (b) (6), (b) (7)(C) | M 443-871-4475

From: "(b) (6), (b) (7)(C) (b) (6), (b) (7)(C) USCG ACTIVITIES FAR EAS (USA)"

<(b) (6), (b) (7)(C)@schuylerline.com>

Date: Thursday, November 4, 2021 at 10:00 PM

To: (b) (6), (b) (7)(C)@schuylerline.com>

Cc: (b) (6), (b) (7)(C)@schuylerline.com>

Subject: RE: [EXTERNAL]:FW: SLNC GOODWILL casualty investigation

(b) (6), (b) (7)(C)

Thank you for clarifying the two different serial #s, I was under the impression they were both installed on the #1 Generator so that is very helpful.

Now that I review the evidence with this in mind it leads me to one other question: when the

(b) (6), (b) (7)(C)

Governor with serial #15592175 was changed out due to hunting on 04Aug, what was the serial # of the Governor that was installed in its place? From the photos that the CG collected on scene, it appears both the replaced and the newly installed Governor have the same part and serial # listed on their data plates.

v/r

(b) (6), (b) (7)(C)

From: (b) (6), (b) (7)(C) @schuylerline.com>
Sent: Friday, November 5, 2021 7:35 AM
To: (b) (6), (b) (7)(C) USCG ACTIVITIES FAR EAS (USA) <(b) (6), (b) (7)(C)@uscg.mil>
Cc: (b) (6), (b) (7)(C) @schuylerline.com>
Subject: [Non-DoD Source] Re: [EXTERNAL]:FW: SLNC GOODWILL casualty investigation

Good morning (b) (6), (b) (7)(C) –

Hopefully I can answer your question. This is what I understand with reference to the governors.

The Governor with Serial #14639129 (report dated 22Jul19) was fitted on No. 2 Auxy Engine by Jewon 22 Jul19 and was NOT associated with No. 1 Auxiliary Engine.

The Governor with Serial #15592175 on No. 1 Auxiliary Engine was serviced IN PLACE by engineers from Woodward Licensed workshop Jewon on 17 May 2019. It was removed from No. 1 Auxiliary Engine the day prior to the incident as the engineers could not control the engine speed with it.

Hope this helps, if not let me know and I'll try to get further clarification.

Regards

(b) (6), (b) (7)(C)

Port Captain / DPA

Schuyler Line Navigation Company LLC

(b) (6), (b) (7)(C) @schuylerline.com

O (b) (6), (b) (7)(C) | M 443-871-4475

From: "(b) (6), (b) (7)(C) (b) (6), (b) (7)(C) USCG ACTIVITIES FAR EAS (USA)"
<(b) (6), (b) (7)(C)@uscg.mil>
Date: Wednesday, November 3, 2021 at 9:07 PM
To: "(b) (6), (b) (7)(C) @schuylerline.com">
Cc: (b) (6), (b) (7)(C)
Subject: RE: [EXTERNAL]:FW: SLNC GOODWILL casualty investigation

(b) (6), (b) (7)(C)

(b) (6), (b) (7)(C)

One thing I remain unsure of is which governor was removed on 04Aug20 and which one was installed and being tested at the time of the casualty? In the photos collected on scene, both governors had identical part # and serial # on their data plates. However, I have two work completion reports from Jewon Engineering regarding Woodward UG-8D governors with two different part/serial #s:

Governor 1 – Part #8521-0047DC, Serial #14639129 (report dated 22Jul19)

Governor 2 – Part #8520-0041 Serial #15592175 (report dated 22May19)

At your earliest convenience, could you please clarify which governor was removed and which was installed? I was hoping the Class report would clarify, but I didn't see it in there.

Thank you.

v/r

(b) (6), (b) (7)(C)

From: (b) (6), (b) (7)(C) <(b) (6), (b) (7)(C)@schuylerline.com>

Sent: Thursday, November 4, 2021 6:40 AM

To: (b) (6), (b) (7)(C) <(b) (6), (b) (7)(C)@schuylerline.com> USCG ACTIVITIES FAR EAS (USA) <(b) (6), (b) (7)(C)@uscg.mil>

Cc: (b) (6), (b) (7)(C) <(b) (6), (b) (7)(C)@schuylerline.com>

Subject: [Non-DoD Source] Re: [EXTERNAL]:FW: SLNC GOODWILL casualty investigation

(b) (6), (b) (7)(C) –

Please see attached for the Diesel Generator Failure Investigation as prepared by Lloyd's Register for us.

Will plan to provide more information if/when it becomes available.

Regards

(b) (6), (b) (7)(C)

Port Captain / DPA

Schuyler Line Navigation Company LLC

(b) (6), (b) (7)(C) <(b) (6), (b) (7)(C)@schuylerline.com>

O (b) (6), (b) (7)(C) | M 443-871-4475

From: "(b) (6), (b) (7)(C) <(b) (6), (b) (7)(C)@uscg.mil>"

<(b) (6), (b) (7)(C)@uscg.mil>

(b) (6), (b) (7)(C)

(b) (6), (b) (7)(C) @schuylerline.com

(b) (6), (b) (7)(C)

From: (b) (6), (b) (7)(C) (b) (6), (b) (7)(C) "USCG ACTIVITIES FAR EAS (USA)"

<(b) (6), (b) (7)(C)@uscg.mil>

Date: Tuesday, October 26, 2021 at 7:47 PM

To: "(b) (6), (b) (7)(C) @schuylerline.com">

Cc: (b) (6), (b) (7)(C)@schuylerline.com>

Subject: RE: [EXTERNAL]:FW: SLNC GOODWILL casualty investigation

(b) (6), (b) (6), (b) (7)(C)

Roger sir, thank you for the assistance. I am steadily working through everything that was already provided and greatly appreciate the cooperation we have received from your company in working through this investigation. By no means am I requesting to start over as my predecessor organized all the documentation collected thus far. For the sake of clarification, I am only inquiring about the following:

1. Was there any analysis of the flywheel or governor after 05Feb21? If so, respectfully request a copy.
2. Was there any investigative report regarding this casualty generated after 21Jan21? If so, respectfully request a copy.
3. Results of the post-casualty DOT drug testing (I am in receipt of the CG-2692B that identifies the 20 crewmembers were drug tested, just not the results).
4. Any results of post-mortem toxicology conducted on the 3AE related to the presence of drugs or alcohol.

I fully appreciate that some time has passed and I'm still familiarizing myself with the casualty and asking for documentation from several different sources, so if you'd like to schedule a phone call to discuss or clarify further please don't hesitate to let me know; I'm getting used to having phone conferences in the middle of the night here, so whenever is convenient for your I'm happy to accommodate.

Again, thank you for your time.

v/r

(b) (6), (b) (7)(C) (b) (6), (b) (7)(C)

Senior Investigating Officer
US Coast Guard Activities Far East
Yokota Air Base
Fussa-shi, Tokyo, Japan 197-0001

(b) (6), (b) (7)(C)

Desk: (b) (6), (b) (7)(C)
DSN: (b) (6), (b) (7)(C)
Mobile/Data: (b) (6), (b) (7)(C)
[FEACT Marine Investigations \(uscg.mil\)](http://FEACT Marine Investigations (uscg.mil))

From: (b) (6), (b) (7)(C) <[@schuylerline.com](mailto:(b) (6), (b) (7)(C)@schuylerline.com)>
Sent: Tuesday, October 26, 2021 9:36 PM
To: (b) (6), (b) (7)(C) USCG ACTIVITIES FAR EAS (USA) <(b) (6), (b) (7)(C)@uscg.mil>; Sri Durga <(b) (6), (b) (7)(C)@schuylerline.com>
Subject: [Non-DoD Source] Re: [EXTERNAL]:FW: SLNC GOODWILL casualty investigation

Good evening (b) (6), (b) (7)(C) –

My apologies sir, I do recall seeing your previous email but let it slip by. Sounds like there have been personnel changes on both sides, and I would prefer a good working relationship with your office. Please allow me to circle back to our Technical Department and gather what they have and I will look to get this to you by the end of the week. Thank you, sir.

(b) (6), (b) (7)(C)

Regards
(b) (6), (b) (7)(C)
Port Captain / DPA
Schuyler Line Navigation Company LLC
(b) (6), (b) (7)(C)
[Redacted]

From: (b) (6), (b) (7)(C) USCG ACTIVITIES FAR EAS (USA)" <(b) (6), (b) (7)(C)@uscg.mil>
Date: Tuesday, October 26, 2021 at 12:34 AM
To: (b) (6), (b) (7)(C) <(b) (6), (b) (7)(C)@schuylerline.com>, (b) (6), (b) (7)(C) <jmalone@schuylerline.com>
Subject: RE: [EXTERNAL]:FW: SLNC GOODWILL casualty investigation

Thank you very much, I greatly appreciate the assistance.

v/r
(b) (6), (b) (7)(C)

From: (b) (6), (b) (7)(C) <[@schuylerline.com](mailto:(b) (6), (b) (7)(C)@schuylerline.com)>

(b) (6), (b) (7)(C)

Sent: Tuesday, October 26, 2021 11:11 AM

To: (b) (6), (b) (7)(C) (b) (6), (b) (7)(C) USCG ACTIVITIES FAR EAS (USA) <(b) (6), (b) (7)(C)@uscg.mil>; (b) (6), (b) (7)(C)@schuylerline.com>

Subject: [Non-DoD Source] RE: [EXTERNAL]:FW: SLNC GOODWILL casualty investigation

Good morning (b) (6), (b) (7)(C)

Thank you for your email. My colleague, (b) (6), (b) (7)(C), will be able to assist with your request on SLNC Goodwill.

Over to you, (b) (6)

(b) (6), (b) (7)(C)

Technical Coordinator

Company Mobile: +(b) (6), (b) (7)(C)

19 Kian Teck Drive

Singapore 628836

Email: (b) (7)(C), (b) (6)@schuylerline.com

Private Mobile (Urgent only): +(b) (6), (b) (7)(C), (b) (6), (b) (7)(C)



From: (b) (6), (b) (7)(C) (b) (6), (b) (7)(C) USCG ACTIVITIES FAR EAS (USA) <(b) (6), (b) (7)(C)@uscg.mil>

Sent: Tuesday, 26 October 2021 9:56 am

To: (b) (6), (b) (7)(C) (b) (6), (b) (7)(C)

Subject: [EXTERNAL]:FW: SLNC GOODWILL casualty investigation

Good morning,

Respectfully request your assistance with the subject investigation. I understand there have been some personnel changes and as I am new I am having trouble contacting the right personnel regarding this incident. Any assistance with the requested documentation, along with the Post-casualty DOT drug test results, would be greatly appreciated.

Thank you for your time and attention.

v/r

(b) (6), (b) (7)(C) (b) (6), (b) (7)(C)

(b) (6), (b) (7)(C)

US Coast Guard Activities Far East

(b) (6), (b) (7)(C)

Yokota Air Base
Fussa-shi, Tokyo, Japan 197-0001

(b) (6), (b) (7)(C)

DSN: 225-7833

Mobile/Data: (b) (6), (b) (7)(C)

[FEACT Marine Investigations \(uscg.mil\)](http://FEACT.MarineInvestigations.uscg.mil)

DISCLAIMER: The information contained in this communication may be confidential, is intended only for the use of the recipient(s) named above, and may be legally privileged. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution, or copying of this communication, or any of its contents, is strictly prohibited. If you have received this communication in error, please re-send this communication to the sender and delete the original message and any copy of it from your computer system. Thank you in advance.

From: (b) (6), (b) (7)(C) USCG ACTIVITIES FAR EAS (USA)

Sent: Wednesday, October 20, 2021 9:06 AM

To: (b) (6), (b) (7)(C)@schuylerline.com' (b) (6), (b) (7)(C)@schuylerline.com>

Subject: SLNC GOODWILL casualty investigation

To Whom It May Concern:

Hello and I hope this email finds you doing well. I have recently assumed (b) (6), (b) (7)(C) duties as Senior Investigating Officer with the Coast Guard at Activities Far East and am slowly but surely getting caught up on the case involving the fatality onboard the SLNC GOODWILL last year and would like to complete the CG's investigation into the incident within the next month. I've been going through the evidence she'd already gathered, but found an email dated 06Apr21 where she had contacted a representative of SLNC regarding final analysis on why the governor failed as well as when the flywheel was replaced. At the time, a final report, so I wanted to touch base and see if that document and the information regarding the flywheel history were now available. I have a Statement of Preliminary Findings, dated 21Jan21, and an Examination of the Failed Flywheel, dated 05Feb21; my inquiry would be regarding any further analysis.

Thank you very much for your continued assistance with this investigation.

v/r

(b) (6), (b) (7)(C) (b) (6), (b) (7)(C)

Senior Investigating Officer
US Coast Guard Activities Far East
Yokota Air Base
Fussa-shi, Tokyo, Japan 197-0001

(b) (6), (b) (7)(C)

(b) (6), (b) (7)(C)

DSN: 225-7833

Mobile/Data: (b) (6), (b) (7)(C)

[FEACT Marine Investigations \(uscg.mil\)](http://uscg.mil)

DISCLAIMER: The information contained in this communication may be confidential, is intended only for the use of the recipient(s) named above, and may be legally privileged. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution, or copying of this communication, or any of its contents, is strictly prohibited. If you have received this communication in error, please re-send this communication to the sender and delete the original message and any copy of it from your computer system. Thank you in advance.

(b) (6), (b) (7)(C)

Commercial Preservation Packaging for Storage of Mechanical-Hydraulic Controls

Manual 25075 (Revision B, 3/2015)

In order to protect a governor or actuator from damage caused by rust or corrosion, certain storage procedures must be followed. The procedures outlined here do not replace military specifications, although some military specifications are listed as references. These procedures are meant for commercial use only.

Storage Procedures

Use rust- and oxidation-inhibiting oil such as Texaco Regal R & O oil, or other oil that meets US MIL-H-17672 (hydraulic fluid, petroleum inhibited) specifications, to coat all internal surfaces of the device. If the governor or actuator is operated with oil other than rust- and oxidation-inhibiting oil, flush the unit with rust- and oxidation-inhibiting oil during operation before storage.

Plug all external openings to prevent contamination by solvents, cleaning agents, moisture, or other elements.

Coat the external surface of the governor or actuator with rust- and oxidation-inhibiting oil. Wrap the unit in a cushioning material to prevent projections, sharp corners, and sharp edges from damaging the barrier bag.

Enclose the governor or actuator in a barrier bag just large enough to enclose the control. Enclose the unit in a second heat-sealed barrier bag of the same material as the inner bag with the calculated amount of desiccant.

Calculate the amount of desiccant required by using the following formula:

$$U = AC + DX$$

where:

U = The number of units of desiccant required

A = Area (square inches) of barrier material to be used

C = 0.011

D = The number of pounds of packing material, other than metal, used within the barrier

X = 8 for cellulosic material, including wood, use as packing material. See US MIL-P-116 for other materials.

Use desiccants which meet the requirements of US MIL-D-3464 Type I or Type II. One producer of such desiccants is the Eagle Chemical Company, Inc.

Position the desiccant in bags of standard unit size and in appropriate locations in order to expose all voids in the governor to the dehydrating action of the desiccant.

Use a heat-sealable barrier bag that meets the requirements of Type I material per US MIL-B-22191 (latest revision).

Visually inspect the barrier material to see if the heat seal is complete and that no tears or damages are present. Pad the storage or shipping crate sufficiently to prevent tearing the barrier material.

Tag each packaged unit with the following:

- Unit Part Number (XXXX-XXXX)
- Unit Serial Number (XXXXXXXX)
- Date unit was packaged for storage

NOTICE

Damage to the barrier material in any way requires a complete repeat of the storage procedure.

References

These US Military Specifications were used as references:

MIL-P-116	Preservation-packaging, methods of
MIL-B-22191	Barrier materials, transparent, flexible, heat-sealable
QPL-22191	Qualified products list of MIL-B-22191
MIL-D-3464	Desiccants, activated, bagged, packaging use and static dehumidification
QPL-3464	Qualified products list of MIL-D-3464

Woodward reserves the right to update any portion of this publication at any time. Information provided by Woodward is believed to be correct and reliable. However, no responsibility is assumed by Woodward unless otherwise expressly undertaken.

We appreciate your comments about the content of our publications.

Send comments to: icinfo@woodward.com

Please reference publication **25075B**.

(b) (7)(C), (b) (6)



PO Box 1519, Fort Collins CO 80522-1519, USA
1000 East Drake Road, Fort Collins CO 80525, USA
Phone +1 (970) 482-5811 • Fax +1 (970) 498-3058

Email and Website—www.woodward.com

Woodward has company-owned plants, subsidiaries, and branches,
as well as authorized distributors and other authorized service and sales facilities throughout the world.

Complete address / phone / fax / email information for all locations is available on our website.

(b) (7)(C)

From: (b) (6), (b) (7)(C)
To: (b) (6), (b) (7)(C); (b) (6), (b) (7)(C) <(b) (6), (b) (7)(C)> USCG ACTIVITIES FAR EAS (USA)
Subject: [Non-DoD Source] RE: [EXTERNAL] Power Management Technical Inquiry
Date: Monday, November 29, 2021 11:50:46 PM

Dear (b) (6), (b) (7)(C)

Glad to be of help. Woodward recommends to always store governors upright. This has to do with the ballhead assembly not sliding out of its support bracket. Storing a unit upright also prevents oil spillage, governor covers often have small breather holes to allow internal air pressure to adjust to ambient. We advise (for the same reasons) to also always transport units standing up.

(b) (6), (b) (7)(C); (b) (6), (b) (7)(C); (b) (7)(C), (b) (6)

Woodward Nederland B.V.
Staff Application Engineer | LE APPLICATION ESP

Was this message helpful?

On Sun, 28th Nov 2021 at 7:19 pm, (b) (6), (b) (7)(C); (b) (6), (b) (7)(C) <(b) (6), (b) (7)(C)> USCG ACTIVITIES FAR EAS (USA) <(b) (6), (b) (7)(C)> uscg.mil> wrote:

(b) (6), (b) (7)(C); (b) (6), (b) (7)(C)

Thank you again for the storage guidelines. After reading through the document, I have one follow up question: does it matter if the governor was stored in a horizontal position instead of a vertical one? Could being kept laying on its side have any impact on the alignment or function of the internal components?

Thank you again for your assistance.

v/r

(b) (6), (b) (7)(C)

The information in this email is confidential and intended solely for the individual or entity to whom it is addressed. If you have received this email in error please notify the sender by return e-mail, delete this email, and refrain from any disclosure or action based on the information.

On Sun, 28th Nov 2021 at 4:15 pm, (b) (6), (b) (7)(C) <(b) (6), (b) (7)(C)> USCG ACTIVITIES FAR EAS (USA) <(b) (6), (b) (7)(C)> uscg.mil> wrote:

(b) (6), (b) (7)(C); (b) (6), (b) (7)(C)

Thank you sir for your prompt response, the documentation provided is very helpful.

I appreciate your time and assistance, and hope you have a great day.

v/r

(b) (6), (b) (7)(C)

(b) (6), (b) (7)(C)

The information in this email is confidential and intended solely for the individual or entity to whom it is addressed. If you have received this email in error please notify the sender by return e-mail, delete this email, and refrain from any disclosure or action based on the information.

On Wed, 24th Nov 2021 at 1:31 am, (b) (6), (b) (7)(C) wrote:

Dear (b) (6), (b) (7)(C)

Thanks for your email. Woodward does have storage guidelines for mechanical governors, please find attached a copy.

(b) (6), (b) (7)(C)

Woodward Nederland B.V.
Staff Application Engineer | LE APPLICATION ESP

On Tue, 23rd Nov 2021 at 5:50 pm, (b) (6), (b) (7)(C) USCG ACTIVITIES FAR EAS (USA)

<(b) (6), (b) (7)(C)@uscg.mil> wrote:

To Whom It may Concern:

I am trying to locate any guidance provided by Woodward on the storage of governors (UG-8 Speed Adjusting Device) onboard vessels, but don't see anything listed on the company website or any mention of it in Product Manual 03045. Are you aware if any such guidance exists, and if so could I please receive a copy?

Thank you for your time and assistance.

v/r

(b) (6), (b) (7)(C) (b) (6), (b) (7)(C)

(b) (6), (b) (7)(C)

US Coast Guard Activities Far East

Yokota Air Base

Fussa-shi, Tokyo, Japan 197-0001

Desk: (b) (6), (b) (7)(C)

DSN: 225-7833

Mobile/Data: (b) (6), (b) (7)(C)

[FEACT Marine Investigations \(uscg.mil\)](https://support.woodward.com/)

Woodward Inc. · <https://support.woodward.com/>

The information in this email is confidential and intended solely for the individual or entity to whom it is addressed. If you have received this email in error please notify the sender by return e-mail, delete this email, and refrain from any disclosure or action based on the information.

(b) (6), (b) (7)(C)

(b) (6), (b) (7)(C) (b) (6), (b) (7)(C) **USCG ACTIVITIES FAR EAS (USA)**

Subject: FW: [EXTERNAL]:FW: SLNC GOODWILL casualty investigation
Attachments: BRN3C2AF460C0FA_004441.pdf

From: (b) (6), (b) (7)(C) @schuylerline.com>
Sent: Wednesday, December 8, 2021 2:30 AM
To: (b) (6), (b) (7)(C) (b) (6), (b) (7)(C) USCG ACTIVITIES FAR EAS (USA) <(b) (6), (b) (7)(C)@uscg.mil>
Subject: [Non-DoD Source] Re: [EXTERNAL]:FW: SLNC GOODWILL casualty investigation

I'm sorry for the delay (b) (6), (b) (7)(C) (b) (6), (b) (7)(C)
One of those things that went out of sight out of mind for me.
Please see attached for (b) (6), (b) (7)(C) and (b) (6), (b) (7)(C) it looks like (b) (6), (b) (7)(C) was the specimen collector, not crew.
And confirm no post accident testing was conducted on the mechanical overspeed. The last testing was during the COI 2 weeks prior.

Regards
(b) (6), (b) (7)(C)
Port Captain / DPA
Schuyler Line Navigation Company LLC
(b) (6), (b) (7)(C)@schuylerline.com
(b) (6), (b) (7)(C)

From: (b) (6), (b) (7)(C) USCG ACTIVITIES FAR EAS (USA)" <(b) (6), (b) (7)(C)@uscg.mil>
Date: Wednesday, December 1, 2021 at 6:39 PM
To: (b) (6), (b) (7)(C) @schuylerline.com>
Cc: (b) (6), (b) (7)(C)@schuylerline.com>
Subject: RE: [EXTERNAL]:FW: SLNC GOODWILL casualty investigation

(b) (6), (b) (7)(C)

Thank you sir. In regards to the Custody Forms, if I could get the ones for (b) (6), (b) (7)(C) , and (b) (6), (b) (7)(C) that will be enough.

I understand the electronic overspeed was destroyed and you are confirming the status of whether or not testing was done on the mechanical; I appreciate the assistance and am standing by for whenever you can confirm.

Thank you for your continued assistance.

v/r
(b) (6), (b) (7)(C)

From: (b) (6), (b) (7)(C) @schuylerline.com>
Sent: Thursday, December 2, 2021 8:07 AM
To: (b) (6), (b) (7)(C) (b) (6), (b) (7)(C) USCG ACTIVITIES FAR EAS (USA) <(b) (6), (b) (7)(C)@uscg.mil>

(b) (6), (b) (7)(C)

Cc: [REDACTED]@schuylerline.com>

Subject: [Non-DoD Source] Re: [EXTERNAL]:FW: SLNC GOODWILL casualty investigation

It's no problem sir.

Attached is one of the completed custody forms for Capt [REDACTED]

I can share all of them if needed, wasn't sure if it was just one or all, and unfortunately the scan is not the best quality.

I do have answers on the other, and will address separately, but the short story is that the electronic overspeed was destroyed during the event, and the mechanical was not tested because it had just been successfully tested a couple weeks prior during the COI in Guam → I need to confirm with the vessel.

Regards

[REDACTED]

Port Captain / DPA

Schuyler Line Navigation Company LLC

[REDACTED]

SLNC GOODWILL

Automated Machinery Test Procedures

Revision 6 dated 22 June 2020



Record of Changes

Date	Procedure Number	Description
3/7/16	7	Deleted word "Duty" in Procedures number 4.
3/7/16	8	Corrected procedures for conducting test
3/7/16	28	Corrected slowdown setpoint
3/15/16	43	Changed procedure from "Main Engine FO Leak-off alarm" to "FO/LO leakage tank alarm"
1/15/16	46 & 47	Added "after cooling water temperature reaches [xxx] degrees F" to results/remarks section
1/15/16	129	Added "after air pressure reaches lag setpoint in switch [xxx]" to results/remarks section
1/16/16	Various	See USCG Letter Serial # E2-1600757 dated March 16, 2016
4/12/16	Various	Added procedures #142 and 239 through 248 in response to Email from MSC (b) (6), (b) (7)(C) and (b) (6), (b) (7)(C) dated 4/12/16
10/27/16	39	Corrected number of cylinders in description from 7 to 6
10/27/16	42	Added "Apply air pressure to collector on the side of fuel pump. Diaphragm shifts relay air valve which activates pressure switch which sends alarm signal." To procedure
10/27/16	52	Added "Enter 5 digit password" to procedure
10/27/16	60 & 61	Changed Setpoints and Results temps to 35°C
10/27/16	66	Changed FO Transfer to FO Supply
10/27/16	80	Changed "E-Stop" to "Stop Button"
10/27/16	Various	Changed Temperatures for Setpoint #183 from 80°C to 87°C and Setpoints #187 through 191 from 55°C to 65°C
10/27/16	206	Added Setpoint of -150 mm
10/27/16	208	Added " use manual bypass" to Procedure #2
10/27/16	213 & 214	Corrected Setpoint Temps for High FO inlet and Low FO inlet
10/27/16	228	Deleted Alarm Description "Uptake Temperature High"
10/27/16	237	Changed "Per Below" to "Page 60 - Machinery Space Fire Detect. SYS Detectors"
10/27/16	239 & 240	Added underline to "qualified third party" in Both Procedures
10/27/16	241-243	Added "Annual By outside contractors" to Results/Remarks
10/27/16	246	Added "Also in CCR as with 245"
10/27/16	249	Added numbering to item 249
10/27/16	MSFDSD Page 60	Corrected Level/Space naming and Added Zone/Smoke numbers
12/5/16	71, 72, 73, & 75	Amended with the following: 71 is not a SHD, 72 alarms at 95, 73 changed procedure for test, and 75 added setpoint.
1/5/2017	71	Amended to demonstrate shutdown
1/5/2017	113, 114, & 115, 137,138	Added setpoint to RP trip test procedures per Dwg E2-1 ECR MSB: Removed procedure 137 and 138. The vessel is not equipped with an automatic bilge pump.
22 June 2020	Various	Amended Procedures 1,3,5,30,34,36,40,42,52,61,62,72,73,78-81,92,94,102,104,112,114,136,137,147,155-157,208, and 211 Deleted old procedures: # 63,129,226,236 as equipment was no OB. Procedure 236 redundant with #132 Inserted new Procedure #63, and 68. All procedures after these re-numbered.

ABBREVIATIONS	4
STANDARD TEST PROCEDURES	5
INTERNAL COMMUNICATIONS	9
<i>WATCHSTANDERS ALARMS AND WATCH CALL SYSTEM</i>	10
<i>PA AND SOUND POWERED PHONES</i>	12
MANEUVERING & STEERING CONTROLS	13
<i>MAIN ENGINE REMOTE CONTROLS</i>	14
<i>MAIN ENGINE REMOTE CONTROLS Cont'd</i>	15
<i>STEERING ALARMS</i>	17
<i>RUDDER ALARMS</i>	18
PROPULSION SYSTEMS	19
<i>MAIN ENGINE ALARMS</i>	20
<i>MAIN ENGINE AND VITAL AUXILIARIES – STANDBY PUMP OPERATION</i>	26
POWER GENERATION	27
<i>EMERGENCY DIESEL GENERATOR AUTOSTART AND SAFETY DEVICES</i>	28
<i>GENERATOR ENGINE REMOTE STARTS</i>	29
<i>#1 SERVICE GENERATOR ENGINE SAFETY DEVICES</i>	30
<i>#2 SERVICE GENERATOR ENGINE SAFETY DEVICES</i>	31
<i>#3 SERVICE GENERATOR ENGINE SAFETY DEVICES</i>	32
<i>GENERATOR SWITCHBOARD SAFETY DEVICES</i>	33
<i>SYSTEM POWER SUPPLIES</i>	35
FLOODING SAFETY	36
<i>ENGINE ROOM AUTO BILGE SYSTEM</i>	37
COMPRESSED AIR SYSTEMS & FUEL DELIVERY	38
<i>COMPRESSED AIR SYSTEMS</i>	39
<i>FO AND LO TANK TEMPERATURE AND LEVEL ALARMS</i>	41
<i>QUICK CLOSING FUEL & L/O VALVES</i>	44
<i>PURIFIERS & FO BOOSTER UNIT</i>	45
AUXILIARY BOILER	46
<i>AUXILIARY BOILER TEST PROCEDURE</i>	47
<i>COMPOSITE AUXILIARY BOILER TEST PROCEDURE</i>	49
FIRE DETECTION AND EXTINGUISHING	51
<i>FIREMAIN PUMP CONTROLS</i>	52
<i>FIRE DETECTION SYSTEM</i>	53
<i>FIXED FIRE EXTINGUISHING SYSTEMS</i>	54
<i>EMERGENCY STOP SYSTEM FOR VENTILATION AND MISC VITAL SYSTEMS</i>	57
<i>MACHINERY SPACE FIRE DETECTION SYSTEM DETECTORS</i>	59



ABBREVIATIONS

ACP	AutoChief Control Panel
A/E	Auxiliary Engine or generator
BCU	Bridge Control Unit
CB	Circuit Breaker
ECC	Engine Control Room console
ECR	Engine Control Room
EDG	Emergency Diesel Generator
EOT	Engine Order Telegraph
ESB	Emergency Switchboard
ESU	Main Engine Safety Unit
F.O.	Fuel Oil
EOT	Engine Order Telegraph (See LTU)
E/S	Engine side or local control panel
FDP	Fire Detection and Fire Repeater Panels
FDP/A	Fire detection panel on Navigational Bridge
H	Audible signal for alarm condition at Engine Control Room console (unless otherwise noted)
H & L	See “H” and “L” herein
L	Visual light Alarm at ECC or text Alarm on HMI (unless otherwise noted)
L.O.	Lube Oil
LTU	Lever Telegraph Unit
LVL	Level control or float switch
MCB	Miniature Circuit Breaker
MCCB	Molded Case Circuit Breaker
MCU	Main Control Unit or (Main Computer Unit)
M.E.	Main Engine
MSB	Main Switchboard
PRS	Pressure switch or pressure control device
PSC	Pressure Sensor Calibrator or Portable Pressure Hand Pump
S/G	Steering Gear
SHD	Shutdown
SLD	M.E. Safety Slowdown
STBY	Standby
TMP	Temperature control device, switch or analog signal
VAC	Voltage Alternating Current
VDC	Voltage Direct Current
W/H	Wheel House control station
WBU	Watch Bridge Unit
WCS	Bridge Wing Console – STBD
WCP	Bridge Wing Console – PORT
WCU	Watch Cabin Unit

NOTE: Set point values are given for guidance and should be interpreted as approximate. A tolerance of $\pm 10\%$ should be expected on most actuation points. For additional guidance concerning set point values, refer to the appropriate equipment instruction manual.

STANDARD TEST PROCEDURES

The following standard procedures outlined below will be used unless the U.S. Coast Guard Inspector authorizes alternate methods.

PRESSURE SWITCHES

Connect the test equipment to the test valve and raise or lower the test pressure above/below the switch setting and then slowly reduce/raise the pressure until the switch contacts function.

PRS-1 System where pressures can be adjusted to designated set point

1. Regulate system pressure to designated set point.
2. Observe sensor output signal and compare with instrument or gauge, if installed.
3. Observe resulting functional alarm response on MCC and conditional response on equipment i.e. shutdown, slowdown etc..).

PRS-2 Low pressure device fitted with 3-way test valves and calibrated pressure gauge

1. Connect drain line & bleed valve hose on installed 3-way valve at PRS and ensure drain line is closed.
2. Place system in normal operation.
3. Close flow to sensor with 3-way valve, which pressurizes drain line to bleed valve and closes flow from normal source.
4. Bleed pressure slowly using bleed valve on drain line.
5. Observe resulting functional alarm response on MCC and conditional response on equipment i.e. shutdown, slowdown etc..).
6. Restore system to normal operating arrangement.

PRS-3 Pressure device set beyond normal limits of the system

1. Connect portable PSC on installed 3-way valve test before PRS
2. Close flow to PRS with 3-way valve, which opens flow from PSC to sensor
3. Using PSC, pressurize sensor to operating parameters
4. Place system in normal operation
5. Using PSC raise pressure to above or below setpoint
6. Observe resulting functional alarm response on MCU and conditional response on equipment i.e. shutdown, slowdown etc..).
7. Restore the system to its normal operating arrangement.

PRS-4 For pump standby auto start if no block and bleed is available

1. Assure pumps are secured.
2. Disconnect pressure switch sensing line from system and connect PSC to switch input.
3. Confirm pressure switch activates at correct set point.
4. Close sensing line valve, bleed off pressure at PSC and confirm standby pump switches over.
5. Observe resulting functional alarm response on MCU and conditional response on equipment i.e. shutdown, slowdown etc..).
6. Restore system to normal operating arrangement.

TEMPERATURE SWITCHES

Remove sensor from protecting well and place sensor in wet-well or dry-well calibrator temperature raise or lower the temperature slowly until the temperature contact functions.

TMP-1 Temperature device in system where medium can be temperature controlled to designated set point

1. Provide an independent thermometer at sensor, if not installed.
2. Regulate the medium temperature to designated set point.
3. Observe the operation response.
4. Restore the system to its normal operating condition

TMP-2 Temperature device in system without temperature regulation

1. Observe current temperature value.
2. Remove sensor from wet¹ or dry well and place in wet or dry well temperature calibrator. Wiring should remain connected to system.
3. Adjust calibrator temperature to alarm set point
4. Observe resulting functional alarm response on MCC and conditional response on equipment i.e. shutdown, slowdown etc..).
5. Restore sensor to original condition.

TMP-3 Temperature device in Equipment without temperature regulation and sensing device is not removable (i.e., thermocouple, RTD, not in wet or dry well well etc..)

1. Place system in normal operation and verify a normal sensor output.
2. Disconnect the thermal detector at the console or some other accessible point.
3. Simulate sensor output (millivolt signal or resistance) with a signal generator and verify correlation between simulated signals and console display.
4. Increase simulated voltage or resistance to create an alarm condition. Verify proper set points.
5. Observe resulting functional alarm response on MCU and conditional response on equipment i.e. shutdown, slowdown etc..).
6. Remove the electrical simulators and reconnect the sensors.
7. Verify the proper polarity and that indicators are reading properly.

¹ If temperature switch is removed from a wet well then sensor hole must be plugged before starting test.

LEVEL SWITCHES

Remove sensor from protecting

LVL-1 Level sensors with system where the fluid level can be regulated

1. Place the machine or system in normal operation.
2. Adjust or regulate the flow to regulate fluid level to alarm set point.
3. Observe resulting functional alarm response on MCU and conditional response on equipment i.e. shutdown, slowdown etc..).
4. Verify the fluid level at time of alarm
5. Restore the system to its normal operating condition.

LVL-2 System containing pressure sensing level transmitters with 3-way test valve

1. Place system in normal operation.
2. Close flow to sensor with 3-way valve, which pressurizes drain line to bleed valve and closes flow from normal source.
3. Bleed pressure slowly from using bleed valve on drain line.
4. Observe resulting functional alarm response on MCU and conditional response on equipment i.e. shutdown, slowdown etc..).
5. Restore system to normal operating arrangement.

LVL-3 System or machine without fluid level control – level sensor internally mounted

1. Place system in normal operation.
2. Drain or pump tank level down or up to activate the level sensor to the designated level.
3. Observe resulting functional alarm response on MCU and conditional response on equipment i.e. shutdown, slowdown etc..).
4. For high level alarms and where tank levels cannot be raised to high level alarm points for safety reasons, remove high level indicator (float switch) and place in a liquid bath to activate switch and demonstrate float and sensor integrity. Test shall include ensuring float mechanism floats, float is not detached and float is not leaking.
5. Restore the system to its normal operating arrangement.

FIRE ALARM SENSORS

In lieu of completing these tests by the ships crew a service report from a qualified manufactures representative is considered as an acceptable alternative.

FIRE-1 Manually operated fire alarm detector

1. Assure that the manual station is not alarmed and fire detection system is active.
2. Remove glass cover for push button.
3. Activate push button.
4. Witness detector LED light and Fire Detection Panel on the Navigational Bridge annunciate the alarm for detector.
5. Restore the system to its normal operating condition.

FIRE-2 Smoke detector

1. Assure that the smoke detector is not alarmed and fire detection system is active.
2. Activate smoke detector by using the manufactures recommended test smoke sprayed into the detector head.
3. Witness detector LED light and Fire Detection Panel on the Navigational Bridge annunciate the alarm for detector.
4. Restore system to normal operating arrangement.

FIRE-3 Heat detector

1. Assure that the heat detector is not alarmed and fire detection system is active.
2. Activate heat detector by using heat gun² blowing into the detector head. Hand held thermometer may be used to verify temperature. **DO NOT USE AN OPEN FLAME!**
3. Witness detector LED light and Fire Detection Panel on the Navigational Bridge annunciate the alarm for detector.
4. Restore the system to its normal operating arrangement.

FIRE-4 Infrared flame detector

1. Assure that the flame detector is not alarmed and fire detection system is active.
2. Using a bright flashlight, flash the light across the flame detectors sensor to activate the flame detector head
3. Witness detector LED light and Fire Detection Panel on the Navigational Bridge annunciate the alarm for detector.
4. Restore the system to its normal operating arrangement.

² **UNDER NO CIRCUMSTANCES SHALL AN OPEN FLAME SUCH AS A LIGHTER OR MATCHES BE USED**

INTERNAL COMMUNICATIONS

WATCHSTANDERS ALARMS AND WATCH CALL SYSTEM

ITEM NO.	DESCRIPTION	PROCEDURE	SETPOINT	RESULTS/REMARKS	CHECK OFF	
					S	U
1.	<p>KONGBURG SAFETY SYSTEM (DEADMAN) ALARM</p> <p><i>The KONGBURG Engineers safety system (Dead man system) is a system for engineer fitness. When activated, the reset button must be pressed by the engineer within a pre-defined time period. If not, the system will indicate "Engineer fitness alarm"</i></p>	<p>1) Ensure Kongsberg Alarm system is set to <u>Bridge Watch</u> and any duty engineer is <u>selected</u></p> <p>2) Activate KONGBURG Safety System "Dead man" alarm by placing key in the "ON"</p> <p>3) When pre-alarm sounds do not reset timer.</p>	<p>27 Min: Pre-alarm</p> <p>3 Min from pre-alarm to deadman alarm</p>	<p>a) Placing system on starts time and the need to reset the dead man alarm timer at specified interval.</p> <p>b) Failure to reset timer triggers "Engineer Fitness Alarm" in the wheel house and throughout all remote watch call stations.</p>		
2.	ENGINEER NEEDS ASSISTANCE ALARM	<p>1) On extension alarm panel in engine room assign duty engineer (place system in UMS)</p> <p>2) Activate any alarm in engine room and do not acknowledge alarm in ECR</p>	5 minutes	<p>a) Accept duty from engineer's cabin</p> <p>b) Buzzer is activated on bridge and all common extension alarm panels and alarm LED flashes upon alarm activation.</p> <p>c) Failure to acknowledge at duty engineer's extension alarm panel after time period expires Alarm goes to "ALL CALL" or engineer needs assistance</p>		
3.	ENGINEERS' WATCH CALLING SYSTEM (DUTY ENG)	<p>1) Ensure Kongsberg Alarm system is set to <u>Bridge Watch</u> and any duty engineer is <u>selected</u></p> <p>2) Select "HOME" on C/R console</p> <p>3) Select "WCALL ENGINE"</p> <p>4) Select "CALL DUTY ENG"</p> <p><i>Note: The engineering watch calling system is a supplemental communication method for contacting the duty engineer or all engineers manually</i></p>		An indicator beside the called engineer(s) title on the Watch Calling Units starts to sound and is lit. The called engineer(s) signs the call by pushing the ACK button.		
4.	ENGINEERS' WATCH CALLING SYSTEM (ALL CALL)	<p>1) Normal operations UMS engine room</p> <p>2) Select "HOME" on C/R console</p> <p>3) Select "WCALL ENGINE"</p> <p>4) Select "ALL CALL ENG"</p> <p><i>See note above.</i></p>		An indicator beside on all engineer(s)] Watch Calling Units starts to sound and is lit.		

ITEM NO.	DESCRIPTION	PROCEDURE	SETPOINT	RESULTS/REMARKS	CHECK OFF		
					S	U	
5.	EXTENDED ALARMS ON WATCH CABIN UNITS	1) Ensure Kongsberg Alarm system is set to <u>Bridge Watch</u> 2) Select desired duty engineer 3) Initiate alarm (any) on ECU and do not reset alarm at the ECU during test. This initiates timer alarm timer. 4) Silence the alarm at the selected duty engineers WCU and allow alarm to repeat without resetting on the ECU. 5) Allow alarm to repeat a third time without resetting at the ECU. 6) After "All Call" reset alarm at ECU. 7) Repeat for each Qualified Engineering Watch standers WCU alarm panel:		a) H&L Alarm is relayed on selected duty engineers WCU b) Alarm is relayed on all public space WCU's c) If alarm remains unacknowledged after set period of time H&L alarm repeats d) If alarm remains unacknowledged H&L alarm repeats a third time and then sounds on all WCU's for all qualified engineers	Chief Eng Rm		
					1 st Assist		
					2 nd Eng.		
					3 rd Eng.		
					RM 502		
					RM 503		
					RM 504		
					D-Deck		
					Officers Smoke RM		
					Crews Day RM		
					Gym		
					Officers Mess		
					Crews Mess		
Duty Mess							
C/E Office							



PA AND SOUND POWERED PHONES

ITEM NO.	DESCRIPTION	PROCEDURE	SETPOINT	RESULTS/REMARKS	CHECK OFF	
					S	U
6.	Public Address & Sound Powered Phone Systems are used for emergency communications between the Bridge and the Engineering Staff					
	DIAL #200 ON THE VMP-430 TELEPHONE SYSTEM AND BROADCAST AN ANNOUNCEMENT FROM THE BRIDGE ON THE PA	Listen from ECR.		ECR can hear and understand.		
		Listen from C/E stateroom		Can hear and understand.		
		Listen from 1 A/E stateroom		Can hear and understand.		
		Listen from 2 A/E stateroom		Can hear and understand.		
		Listen from 3 A/E stateroom		Can hear and understand.		
Listen from CCR			Can hear and understand.			
7.	SOUND POWER PHONE COMMUNICATION BETWEEN BRIDGE AND ECR	Ring the ECR from the bridge		Can hear and understand from both locations.		
		Ring the bridge from the ECR		Can hear and understand from both locations.		
8.	SOUND POWER PHONE COMMUNICATION BETWEEN BRIDGE AND STEERING GEAR ROOM	Ring the bridge from the steering gear Room		Can hear and understand from both locations.		
		Ring the steering gear room from the bridge		Can hear and understand from both locations.		
9.	VMP-430 SHIPS TELEPHONE SYSTEM	On ECR VMP-430 phone, dial any of the following: Chief, 1st., 2nd. or 3rd Engr.		Phone rings in respective room Can hear and understand from both locations.		
10.	8. VMP-430 SHIPS TELEPHONE SYSTEM	On Bridge VMP-430 phone, dial main engine local control station (ELCS)		Phone rings in at engine local control station load speaker functions at ELCS, Can hear and understand from both locations.		

MANEUVERING & STEERING CONTROLS

MAIN ENGINE REMOTE CONTROLS


ITEM NO.	ALARM DESCRIPTION	PROCEDURE	SETPOINT	RESULTS/REMARKS	SAT	UNSAT
	CONTROL POSITION	CHANGE OVER TEST (M/E @ STOP)				
11.	LOCAL CONTROL TO ECR CONTROL TO BRIDGE CONTROL AND BACK TO ECR CONTROL	1) Engine stopped and in local control 2) Move fuel lever into Remote position		In ECR 1) ECR LED in LTU will start to flash and a buzzer is activated.		
		3) In ECR push "ECR" on "LTU"		LOCAL LED will become dark. ECR LED will become steady. Buzzer is silenced. ECR control is obtained.		
		In ECR: 4) Move switch from C/R Control to Bridge Control		In WH: BRIDGE LED will start flashing. Buzzer is activated.		
		In WH: 5) Press "Bridge" on "LTU"		ECR LED will become dark. BRIDGE LED will become steady. Buzzer is silenced. Bridge control is obtained.		
		In WH: 6). Press "ECR" on "LTU"		In ECR: ECR LED will start flashing. Buzzer is activated.		
		In ECR: 7) Move Switch from Bridge Control to C/R Control		BRIDGE LED will become dark. ECR LED will become steady. Buzzer is silenced. ECR control is obtained.		

Note: The engine control can be taken from the WH to the ECR at any time by pressing the "ECR" button on the "LTU" in the control room. The W/H then has to acknowledge the transfer by pressing the ECR button on the LTU on the Bridge. If the Bridge does not confirm transfer, ECR can force command transfer by pushing the "ECR" pushbutton on the LTU, until transfer is forced to occur (approx. 5 seconds). The engine control can be taken to the local control station at any time by moving the fuel lever out of the remote position.

MAIN ENGINE REMOTE CONTROLS Cont'd

ITEM NO.	DESCRIPTION	PROCEDURE	SETPOINT	RESULTS/REMARKS	CHECK OFF	
					S	U
12.	CHANGE CONTROL TO E/S (LOCAL) CONTROL	This test is to be completed U/W with the main engine secured		Transfer and control of engine accomplished locally		

- 1) Check that valve (105), which is the “telegraph handle” of the engine side control system, is in the required position. Note that reversing to a new direction is only possible when stop valve (102 is activated).
- 2) Turn Handle “A” counterclockwise to free the regulating hand wheel “B”
- 3) Place blocking arm in emergency position
- 4) Turn hand wheel “B” to move the innermost lever of the changeover mechanism “C” to a position where the impact hand wheel “P” is able to enter the tapered slots in both levers. Quickly, turn the impact wheel “P” counterclockwise; this causes disconnection of the governor and connection of the regulating hand wheel “B” to fuel pumps. *Note: When the governor is disengaged, the engine is still protected from overspeed by the electric overspeed*
- 5) Change position of valve “100” from Normal to Emergency. Now air supply is led to the valves of the maneuvering system for emergency running.
- 6) Check that valve “105”, which is the “telegraph handle” of the emergency control system, is in the required position.
- 7) Start: Move regulating hand wheel to “Start” position and push down on start valve. When the starting level r/min has been reached, release the start valve. Engine runs.
- 8) Increase speed by turning regulating hand wheel
- 9) Reversing and Start in New Direction: Activate stop valve “102-B6” and move valve “105-C5”, which reverses the rollers for the fuel pumps and the starting air distributor. The engine is now ready to start per item 6) above.



MAIN ENGINE REMOTE CONTROLS (continued)

ITEM NO.	ALARM DESCRIPTION	PROCEDURE	SETPOINT	RESULTS/REMARKS	SAT	UNSAT
	CONTROL POSITION	CHANGE OVER TEST (M/E @ STOP)				
13.	TURNING GEAR INTERLOCK	Main Engine in ECR control and ready to start.		C/R L on.		
		Without engaging turning gear, activate turning gear limit switch		Turning gear engaged lamp on @ C/R.		
		Move Engine controls slow ahead		Main engine remains stopped. M/E safety system abnormal alarm on ECC		
14.	EOT MISMATCH ALARM	1) M/E Start air secured 2) Move EOT on bridge to any desired command 3) On Engine room EOT move to any other position		H & L Miss match alarm		
15.	WRONG DIRECTION	Main engine in ECR control. Go to engine side controls and switch to local control. Have bridge give "Ahead" order. Start Engine in the "Astern" direction.		Bell & L at engine side. Bell @ W/H. Bell @ C/R.		
16.	ENGINE EMERGENCY STOPS	Activate emergency stop push button on appropriate engine control system. After test, Reset emergency Stop by pushing the E-stop button again. Then proceed to next test location	Binary	H & L Engine stops. If U/W convention stop is also activated and speed order to the rpm control system is set to zero.	Bridge	
					P Wing	
					S Wing	
					ECR	
	Local Control Box					
17.	SPEED AND THRUST INSTRUMENTATION	While at sea conducting pre-arrival tests verify speed and direction of propulsion instruments		Instrumentation shows revolutions of propeller shaft and direction of thrust is verified in each direction as called for on the EOT.		

Note: Item No. 9, 11, 12 & 14 shall be tested by crew for actual performance at sea and recorded in the ships log. These items can be demonstrated in port for general logic only.

STEERING ALARMS

ITEM NO.	ALARM DESCRIPTION	PROCEDURE	SETPOINT	RESULTS/REMARKS	SAT	UNSAT
18.	NO. 1 STEERING GEAR RUNNING	1) Ensure local control panels are in remote and power is in the on position 2) Start No. 1 steering gear motor from bridge		Steering gear starts		
19.	NO. 1 STEERING GEAR POWER & PHASE FAILURE	With No. 1 steering pump in remote 1) Open local controller in steering gear room 2) Open main power switch using hand tool.	Binary	No.2 steering gear starts automatically H & L Tag 1005 S/G Servo PP Loss Phase Tag 1001 S/G Control Power Failure on ECC, Bridge and W/H steering alarm panel flash with steering control Power and Phase No Volt indicators		
20.	NO. 2 STEERING GEAR RUNNING	1) Ensure local control panels are in remote and power is in the on position 2) Start No.2 steering gear motor from bridge		Steering gear starts		
21.	NO. 2 STEERING GEAR POWER & PHASE FAILURE	With No. 2 steering pump in remote 1) Open local controller in steering gear room 2) Open main power switch using hand tool.	Binary	No.1 steering gear starts automatically H & L Tag 1007 S/G Servo PP Loss Phase Tag 1002 S/G Control Power Failure on ECC, and Bridge and W/H steering alarm panel flash with steering control Power and Phase No Volt indicators		
22.	NO. 1 STEERING GEAR MOTOR OVERLOAD	Activate test button on motor overload module on (K4) contactor in motor controller	Binary	H & L in ECR and in W/H Tag 1003 S/G Servo PP Overload		
23.	NO. 2 STEERING GEAR MOTOR OVERLOAD	Activate test button on motor overload module on (K4) contactor in motor controller	Binary	H & L in ECR and in W/H Tag 1004 S/G Servo PP Overload		
24.	NO. 1 STEERING GEAR HYDRAULIC OIL LEVEL LOW	With S/G running remove the cover on the LL switch and lift the knob to activate the LL alarm. Do not to lift too high as damage to spring might occur.	Binary	No.2 steering gear starts automatically H & L Tag 1009 S/G Oil Tank Level Low Tag 1013 S/G STBY Unit Auto Cut In		
25.	NO. 2 STEERING GEAR HYDRAULIC OIL LEVEL LOW	With S/G running remove the cover on the LL switch and lift the knob to activate the LL alarm. Do not to lift too high as damage to spring might occur.	Binary	No.1 steering gear starts automatically H & L Tag 1011 S/G Oil Tank Level Low Tag 1012 S/G STBY Unit Auto Cut In		

RUDDER ALARMS

ITEM NO.	ALARM DESCRIPTION	PROCEDURE	SETPOINT	RESULTS/REMARKS	SAT	UNSAT
26.	RUDDER ANGLE REPEATER	With steering gear operating 1) Set rudder at mid-ships b) Move helm to 30° starboard c) Move helm to 30° port	0°	Confirm W/H rudder repeater is within ±1° of mid-ships		
			30° stbd	Confirm W/H rudder repeater is within ±1° of 30° port		
			30° port	Confirm W/H rudder repeater is within ±1° of 30° starboard		
27.	STEERING GEAR TEST	With steering gear operating Swing helm on bridge from 30° P to 35° S		Rudder responds 30° to 35° within 60 seconds		
28.	STEERING FAILURE	With the vessel at sea under normal propulsion, secure the steering pumps and steer a course greater than 5° off course.	binary	H & L at steering stand.		

Note: Item No. 25 to be performed at sea and logged in official log book. Assure that the vessel is in safe area before conducting test.

PROPULSION SYSTEMS

MAIN ENGINE ALARMS

ITEM NO.	DESCRIPTION	PROCEDURE	SETPOINT	RESULTS/REMARKS	SAT	UNSAT
29.	ENGINE SAFETY SYSTEM SLOWDOWN FUNCTIONAL TEST	U/W engine running <80% MCR in bridge control 1) Initial any SLD alarm on main engine 2) Depress "Cancel SLD" pushbutton on the bridge ACP unit 3) Repeat SLD alarm without depressing "Cancel SHD" pushbutton 4) Reset SHD after sensor is restored by setting maneuvering lever at the control stand in control stop position		1) H&L 2) Slowdown function is canceled 3) Engine slows down immediately		
30.	ENGINE SAFETY SYSTEM SHUTDOWN FUNCTIONAL TEST <i>Note: Slowdown function is available for 7 seconds During this time the Master can initiate a SLD for the safety of the ship.</i>	U/W engine running <80% MCR in bridge control 1) Initial any SLD alarm on ME 2) Depress "Cancel SLD" pushbutton on the bridge ACP unit 3) Repeat SLD alarm without depressing "Cancel SLD" pushbutton 4) Reset SLD after sensor is restored by setting maneuvering lever at the control stand in control stop position		1) H&L 2) Slowdown function is canceled 3) Engine Slowdown is initiated i		
31.	M.E. L.O. INLET PRESSURE ³	PRS-2	Alarm 0.2 MPa SLD: 0.14 MPa SHD: 0.12 MPa	H & L ME Slow down or shutdown Tag 3052 M.E. LO Inlet Pressure lo		
32.	M.E. T/C LO OUTLET HIGH TEMPERATURE	TMP-2 at dock with engine secured	95°C	H & L Tag 3039 M.E. T/C Outlet Temp		
33.	M.E. T/C LO INLET PRESSURE	PRS-2 at dock with engine secured	0.12Mpa	H & L Tag 3038 M.E. T/C LO Inlet Pressure		
34.	THRUST PAD HIGH TEMPERATURE	1. Using an infrared handheld thermometer, verify that the temperature reading on the Kongsburg reads at or near the temperature on the sensor bearing housing 2. Lower the setpoint to just below the temperature observed on the handheld thermometer.	75° C HI 80° C Slowdown 90° C Shutdown	H & L ME 2/Second time delay Tag 3079 Thrust bearing Hi		

³ Item 28 and 29 Shall be tested U/W and Logged for DNV/USCG to show slowdown and shutdown system functions other testes to be performed at dock with engine secured)



MAIN ENGINE ALARMS Cont'd

ITEM NO.	DESCRIPTION	PROCEDURE	SETPOINT	RESULTS/REMARKS	SAT	UNSAT
35.	M.E JACKET WATER COOLING LOW PRESSURE	PRS-2 at dock with engine secured	0.2 MPa LO 0.15 MPa SLD	H & L ME Slow Down W/2 second delay Tag 3014 M.E. JWC Lo Press		
36.	M.E. C.F.W DIFFERENTIAL PRESSURE ACROSS ENGINE	With cooling water pump running and engine secured PRS-2 on Sensor PS307	0.15 MPa	H & L Tag 3024 M.E. CFW Dift Press Across Eng.		
37.	M.E. L.O. HIGH INLET TEMPERATURE	TMP-2 at dock with engine secured	55° C HI 60° C Slowdown	H & L ME Slow down W/2 second delay Tag 3033 M.E. Hi Inlet Temp		
38.	M. E. PISTON COOLING OIL OUTLET TEMP CYLINDERS 1 THROUGH 6	TMP-2 at dock with engine secured	70° C HI 75° C Slowdown	H & L ME Slow Down W/2 second time delay Tags 3041 through 3046	1	
					2	
					3	
					4	
					5	
					6	
39.	M.E. EXHAUST VALVE AIR INLET TO AIR CYLINDER PRESSURE	PRS-2 at dock with engine secured	0.55 MPa LO	H & L ME Slow Down W/2 second TD		
40.	CYLINDER EXHAUST GAS HIGH CYLINDERS 1 THROUGH 6	TMP -2 at dock with engine secured	430° C HI 450° Slowdown	Activate alarm. Tags 3053 through 3058	1	
					2	
					3	
					4	
					5	
					6	
41.	EXHAUST GAS AFTER T/C TEMPERATURE HIGH	TMP-2	350° C HI	H&L Tag 3052 M.E. Gas after T/C Hi		
42.	EXHAUST GAS AFTER CYLINDER DEVIATION TEMP Cylinders 1 through 6	With engine in ½ ahead or with AutoChief simulating engine RPMs: `TMP -2	± 50° C HI ± 60° Slowdown	H & L ME Slow Down W/2 second delay Tags 3059 through 3064	1	
					2	
					3	
					4	
					5	
					6	

MAIN ENGINE ALARMS Cont'd

ITEM NO.	DESCRIPTION	PROCEDURE	SETPOINT	RESULTS/REMARKS	SAT	UNSAT
43.	M/E HIGH PRESSURE F.O. PIPE LEAK Cylinders 1 through 6	LVL-3 Apply air pressure to collector on the side of fuel pump. Diaphragm shifts relay air valve which activates pressure switch which sends alarm signal.	Binary	H & L ME Slow Down W/2 second delay Tags 3026 through 3031	1	
					2	
					3	
					4	
					5	
					6	
44.	M/E PISTON CYLINDER COOLING OIL OUTLET NO FLOW	Disconnect oil pipe which leads to the no-flow sensor	Binary	H & L ME Slow Down Tags 3046 through 3051	1	
					2	
					3	
					4	
					5	
					6	
45.	M/E F.O. INLET PRESSURE	PRS-2	0.65MPa	H&L Tag: 3025 M/E F.O. Inlet Pressure		
46.	MAIN LO AUTO FILTER DIFF PRESSURE HIGH	PRS-2	0.09MPa	H&L Tag: 4112 Main LO Auto Filter Diff Pressure High		
47.	FW EXPANSION TANK LOW LEVEL	LVL-3	400MM	H&L w/15 second delay Tag: 4243 F.W. Expansion Tank Low Level		
48.	M/E LO SUMP TANK LOW LEVEL	LVL-3	200MM	H&L w/15 second delay Tag: 4215 M/E LO Sump Tank Low Level		

MAIN ENGINE ALARMS Cont'd

ITEM NO.	DESCRIPTION	PROCEDURE	SETPOINT	RESULTS/REMARKS	SAT	UNSAT	
49.	ALPHA LUBRICATION SYSTEM CHACK	1) With engine secured 2) Depress PRE_LUBRICATION button on the HMI panel and inspect LED's on intermediate box	binary	All LED's for feedback indication on the intermediate boxes should flash indicating that the lubricators are functioning correctly			
50.	CRANK CASE OIL MIST (Bearing High Temp) M1-5		.05mg/L	H & L ME Slow down w/2 second delay Tag 3009 Crank case oil mist Hi			
PROCEDURE							
		<p>1) With engine secured & Graviner Mk6 on</p> <p>2) Cut a length of wick approximately 30 mm long. Assemble the smoke tester by pushing the wick into the wick holder fitted with the pipette bulb. Press the nylon pipe into the Pipe connector</p> <p>3) Push the nylon pipe of the smoke tester into the connector on the side of the detector base body</p> <p>4) Dip the wick into the bottle of smoke oil and reseal the bottle firmly</p> <p>5) Ignite the wick of the smoke tester and blow out the flame. Squeeze the pipette bulb to keep the wick smoking</p> <p>6) While the wick is still smouldering, insert it into the pipe connector and squeeze the pipette bulb.</p> <p>7) Observe the wick is still smouldering, insert nylon pipe into the pipe connector of the detector and squeeze the pipette bulb. Note results here.</p> <p>8) After tests are completed the Maximum Actual Average readings should be erased. This can be done in the Engineer Main Menu then configuration and then CLR. Maximum Average</p> <p>9) To release the pipe from the connector, press in the blue plastic collar on the end of the connector at the same time as pulling the pipe out.</p> <p>10) Remove the nylon pipe from the pipe connector for stowage purposes.</p> <p>11) The wick is reusable and can be left in the wick holder. Fully extinguish the wick after use at all times.</p> <p>12) Refer to the Material Safety Data Sheet in the event of health or safety issues.</p>					
							

MAIN ENGINE ALARMS Cont'd

ITEM NO.	ALARM DESCRIPTION	PROCEDURE	SETPOINT	RESULTS/REMARKS			SAT	UNSAT
51.	OIL MIST DETECTOR FAIL	1) With engine secured and Graviner Mk6 functioning remove the connector pin on any detector for 10 seconds 2) Re-install connector and reset Graviner by holding in reset button for 5 seconds	Binary	H & L on Graviner Panel and ECC 2/Second delay				
52.	LINE SHAFT BEARINGS HIGH TEMP BEARINGS 1 THROUGH 3	1. Using an infrared handheld thermometer, verify that the temperature reading on the Kongsburg reads at or near the temperature on the sensor bearing housing 2. Lower the setpoint to just below the temperature observed on the handheld thermometer.	Stern Tube AFT See remarks	H & L 2/Second delay Tag 3080 Aft Bearing Hi	60° C HI 65° C SLD	1		
			Stern Tube Fwd See Remarks	H & L 2/Second delay Tag 3081 Stern Tube Fwd bearing Hi	60° C HI 65° C SLD	2		
			Intermediate See Remarks	H & L 2/Second delay Tag 3081 Intermediate Bearing Hi	65° C HI 70° C SLD	3		

MAIN ENGINE ALARMS Cont'd

ITEM NO.	ALARM DESCRIPTION	PROCEDURE	SETPOINT	RESULTS/REMARKS	SAT	UNSAT
53.	MAIN ENGINE OVER SPEED (Test and Log for DNV/USCG)	1) Activate the Over Speed Test Level and set to 25 rpm. (ACP, Page Safety System/RPM Detector) 2.) Start engine. After test Deactivate the Over Speed Test Level. Enter 5 digit password		H & L Tag 3003 ME Overspeed Engine starts normally. After reaching the RPM limit, Shut-Down outputs are directly activated through the ESU. The engine stops.		
54.	M. E. JACKET WATER COOLING HIGH OUTLET CYLINDER TEMPERATURE CYLINDERS 1 THROUGH 6	TMP-2	85° C HI 90° C SLD	H & L Tag 3018 through 3023 ME Slow Down W/2 second time delay	1	
					2	
					3	
					4	
					5	
					6	
55.	SCAVENGING AIR HIGH TEMPERATURE	TMP-2; Each of 6 Cylinders.	80 °C HI 120 °C SLD	H & L; ME Slow Down Tag 3065 through 3070	1	
					2	
					3	
					4	
					5	
					6	
56.	SCAVENGE AIR WATER LEVEL	Engine secured On lower level of engine room starboard side under scavenge air box, remove float sensor from housing and activate float by lifting float mechanism	Binary	H & L 15 second time delay Tag 3072 M/E Scavenge Air Receiver W. Lev/H	SAT	UNSAT
57.	SCAVENGE AIR RECEIVER PRESSURE	PRS-2	0.039MPa	H&L Tag: 3071 M/E Scav. Air Receiver Pressure		
58.	FO/LO LEAKAGE TANK HIGH LEVEL ALARM	LVL-3	Binary	H & L 2 Second time delay		

MAIN ENGINE AND VITAL AUXILIARIES – STANDBY PUMP OPERATION

ITEM NO.	DESCRIPTION	PROCEDURE	SETPOINT	RESULTS/REMARKS	SAT	UNSAT
59.	M.E L.O PUMP #1 STANDBY START	Select # 2 ON; #1 STBY Trip Breaker for #2	0.16MPa	#1 Pump Starts H & L Tag 4001 M.E. LO Pump standby start		
60.	M.E L.O PUMP #2 STANDBY START	Select # 1 ON; #2 STBY Trip Breaker for #1	0.16Mpa	#2 Pump Starts H & L Tag 4001 M.E. LO Pump standby start		
61.	M.E SW. PUMP #1 STANDBY START	Set to Control System #1. Control System selects lead pump. TMP-2. Temp. Sensor in L.T. Outlet.	35°C	#1 Pump Starts after cooling water temperature reaches 35 degrees F		
62.	M.E SW. PUMP #2 STANDBY START	Set to Control System #1. Control System selects lead pump. TMP-2. Temp. Sensor in L.T. Outlet.	35°C	#2 Pump Starts after cooling water temperature reaches 35 degrees F		
63.	M.E SW. PUMP #3 STANDBY START	Set to Control System #1. Control System selects lead pump. TMP-2. Temp. Sensor in L.T. Outlet.	35°C	#2 Pump Starts after cooling water temperature reaches 35 degrees F		
64.	M.E H.T.F.W PUMP #1 STANDBY START	Select #2 ON; #1 STBY Trip breaker for #2	0.25Mpa	#1 Pump Starts H & L		
65.	M.E H.T.F.W PUMP #2 STANDBY START	Select #1 ON; #2 STBY Trip Breaker for #2	0.25Mpa	#2 Pump Starts H & L Tag: 4004 M/E LTFW ST/BY PP start		
66.	M.E L.T.F.W PUMP #2 STANDBY START	Select #2 ON; #1 STBY Trip breaker for #2	0.2Mpa	#1 Pump Starts H & L Tag: 4004 M/E LTFW ST/BY PP start		
67.	M.E L.T.F.W PUMP #2 STANDBY START	Select #1 ON; #2 STBY Trip breaker for #1	0.2Mpa	#2 Pump Starts H & L		
68.	M.E L.T.F.W PUMP #3 STANDBY START	Select #1 ON; #3 STBY Trip breaker for #1	0.2Mpa	#3 Pump Starts H & L		
69.	FO SUPPLY STANDBY PUMP START	Select #1 ON; #2 STBY PRS- 2	0.3MPa	Standby pump starts H&L Tag: 4110 FO Transf. ST/BY Pump Start		
70.	FO CIRC STANDBY PUMP START	Select #1 ON; #2 STBY PRS- 2	0.6MPa	Standby pump starts H&L Tag: 4111 FO Circ. ST/BY Pump Start		

POWER GENERATION

EMERGENCY DIESEL GENERATOR AUTOSTART AND SAFETY DEVICES

ITEM NO.	ALARM DESCRIPTION	PROCEDURE	SETPOINT	RESULTS/REMARKS	SAT	UNSAT
71.	EDG AUTOMATIC STARTUP	1) Begin with all loads on ESB being fed from main generator side. 2) Open emergency bus tie on MSB.	N/A	1) The circuit breaker on main bus tie on the ESB opens automatically. 2) The EDG starts and comes up to speed automatically. 3) The EDG breaker to the ESB closes automatically. 4) All loads on the ESB are being fed from the EDG side. 5) Confirm EDG comes online in less than 45 seconds.		
72.	OVER SPEED	Engine running without load. 1) On the engine control panel, displaying the main screen, press the Page button 2 times. 2) Press the down arrow 3 times to Engine Protect, Press Enter. 3) Press the down arrow 8 times to Overspeed, Press the Enter button 1 time. 4) Press the down arrow to change the set-point from 115% to 95% to initiate overspeed. 5) Reset the fault and reset the over speed set-point to 115%	2050 RPM	H & L; Engine Stops		
73.	L.O. INLET LOW PRESSURE	PRS-2	2.5 Bar	H & L;		
74.	CFW HIGH TEMPERATURE	TMP-2	95°C	Alarm only		
75.	FAILURE TO START	1) Hold governor stop solenoid in stopped position 2) Start the engine locally	Binary	After third attempt to start; H & L "Start Failure" alarm is given, and engine does not start.		
76.	FUEL LEAKAGE	LVL-3		Alarm only		
77.	CFW LOW PRESSURE	PRS-2	0.5 Bar	Alarm only		

GENERATOR ENGINE REMOTE STARTS

ITEM NO.	ALARM DESCRIPTION	PROCEDURE	SETPOINT	RESULTS/REMARKS		SAT	UNSAT
	CONTROL POSITION	ONE GENERATOR ON LINE					
78.	ECR GENERATOR START FUNCTION	1) Generator #1 on line 2) On "Syncro" panel on MSB select #2 generator as standby 3) On #2 generator panel on MSB depress the "start" button 4) Depress Auto Sync button 5) Single up on #2 and secure #1		Generator starts Generator parallels w/ bus			
79.	ECR GENERATOR START FUNCTION	1) Generator #2 on line 2) On "Syncro" panel on MSB select #3 generator as standby 3) On #3 generator panel on MSB depress the "start" button 4) Depress Auto Sync button 5) Single up on #3 and secure #2		Generator starts Generator parallels w/ bus			
80.	ECR GENERATOR START FUNCTION	1) Generator #3 on line 2) On "Syncro" panel on MSB select #1 generator as standby 3) On #1 generator panel on MSB depress the "start" button 4) Depress Auto Sync button 5) Single up on #1 and secure #3		Generator starts Generator parallels w/ bus			
81.	GENERATOR FAIL TO START	1) With generator off line close start air valve and activate start sequence MSB		H & L	A/E NO.1		
					A/E NO.2		
					A/E NO.3		
82.	GENERATOR LOCAL START	1) Start each generator locally at the generator local control panel.		H & L	A/E NO.1		
					A/E NO.2		
					A/E NO.3		
83.	GENERATOR "E-STOP"	With A/E running and off line depress appropriate "Stop button" switch on panel #3 of ECC.		H & L	A/E NO.1		
					A/E NO.2		
					A/E NO.3		

#1 SERVICE GENERATOR ENGINE SAFETY DEVICES

ITEM NO.	ALARM DESCRIPTION	PROCEDURE	SETPOINT	RESULTS/REMARKS	SAT	UNSAT
84.	OVERSPEED SHUTDOWN	1. Engine running at operating temperature and not online 2) Using a mechanical tool manually override governor actuator arm and slowly rise engine RPMS to set point.	1015 RPM	H&L Engine Stops Tag: 2011 No.1 A/E OVERSPEED SHD		
85.	LUBE OIL INLET PRESSURE LOW	1. Engine running at operating temperature and not online 2. PRS-2	0.4 Mpa LO 0.25 SHD	H & L Tag: 2006 No.1 D/G L.O. Inlet pressure Engine shuts down on LO-LO		
86.	FUEL OIL INLET PRESSURE LOW	PRS-2	0.4 Mpa LO	H & L Tag: 2030 No.1 D/G F.O. Inlet pressure		
87.	LUBE OIL INLET TEMPERATURE	TMP-2	75°C HI	H & L Tag: 2008 No.1 D/G L.O. Inlet Temp		
88.	C.F.W. INLET PRESSURE	PRS-2	0.08 MPa	H & L		
89.	CFW OUTLET TEMPERATURE	1) Engine running at operating temperature and not online 2) TMP-2	90°C HI 95°C SHD	H & L; Engine Stops Tag: 2009 No.1 D/G CFW Outlet Temp		
90.	F.O. FILTER HIGH DIEF PRESSURE		0.02~0.25 Mpa	H&L Tag 2038 No.1 A/E F.O. FILTER HI PRES.		
91.	DG EXHAUST GAS OUTLET TEMPERATURE	TMP-2	420°C	Tag: 2023 H & L (No.X Exh Gas	CYL 1	
				Tag: 2027 Temp Out)	CYL 2	
				Tag: 2029	CYL 3	
				Tag: 2032	CYL 4	
				Tag: 2034	CYL 5	
				Tag: 2036	CYL 6	
92.	DG EXHAUST GAS HT DEVIATION FROM AVERAGE Note: Deviation temperatures are inhibited when the generator is not on the bus	1) Engine running at operating temperature and connected to the buss 2) TMP-2	±50°C	Tag: 2026 H&L (No.1 A/E EXH	CYL 1	
				Tag: 2028 GAS HT DEIV FM	CYL 2	
				Tag: 2031 AVERAGE)	CYL 3	
				Tag: 2033	CYL 4	
				Tag: 2035	CYL 5	
				Tag: 2037	CYL 6	
93.	DG EXHAUST GAS T/C INLET TEMPERATURE HIGH	TMP-2	550°C	H&L Tag: 2066 No.2 D/G EXH GAS INLET T/C TEMP		
94.	TURNING GEAR INTERLOCK	Engage turning bar, Close start air valve and activate start sequence at local control panel.	Binary	Starter air solenoid does not engage and Engine does not attempt to start; Light on Generator Section of MSB illuminates: Turning Gear Interlock.		

#2 SERVICE GENERATOR ENGINE SAFETY DEVICES

ITEM NO.	ALARM DESCRIPTION	PROCEDURE	SETPOINT	RESULTS/REMARKS	SAT	UNSAT
95.	OVERSPEED SHUTDOWN	1. Engine running up to operating temperature. 2) Using a mechanical tool manually override governor actuator arm and slowly rise engine RPMS to set point.	1015 RPM	H&L Engine Stops Tag: 2061 No.2 A/E OVERSPEED SHD		
96.	LUBE OIL INLET PRESSURE LOW	PRS-2	0.4 Mpa LO 0.25 SHD	H & L Tag: 2056 No.2 D/G L.O. Inlet pressure Engine shuts down on LO-LO		
97.	FUEL OIL INLET PRESSURE LOW	PRS-2	0.4 Mpa LO	H & L Tag: 2080 No.2 D/G F.O. Inlet pressure LO		
98.	LUBE OIL INLET TEMPERATURE	TMP-2	75°C HI	H & L Tag: 2058 No.2 A/E D/G L.O. Inlet Temp		
99.	C.F.W. INLET PRESSURE	PRS-2	0.08 MPa	H & L Tag: 2057 No.2 A/E CFW Inlet Pressure		
100.	CFW OUTLET TEMPERATURE	TMP-2	90°C HI 95°C SHD	H & L; Engine Stops		
	F.O. FILTER HIGH DIEF PRESSURE		0.02~0.25 Mpa	H&L Tag 2088 No.2 A/E F.O. FILTER HI PRES.		
101.	DG EXHAUST GAS OUTLET TEMPERATURE	TMP-2	420°C	Tag: 2075 H&L (No.2 A/E EXH Tag: 2077 GAS HT DEIV FM Tag: 2079 AVERAGE) Tag: 2082 Tag: 2084 Tag: 2086	CYL 1 CYL 2 CYL 3 CYL 4 CYL 5 CYL 6	
102.	DG EXHAUST GAS HT DEVIATION FROM AVERAGE Note: Deviation temperatures are inhibited when the generator is not on the bus	1) Engine running at operating temperature and connected to the buss 2) TMP-2	±50°C	Tag: 2076 H&L (No.2 A/E EXH Tag: 2078 GAS HT DEIV FM Tag: 2081 AVERAGE) Tag: 2083 Tag: 2085 Tag: 2087	CYL 1 CYL 2 CYL 3 CYL 4 CYL 5 CYL 6	
103.	DG EXHAUST GAS T/C INLET TEMPERATURE HIGH	TMP-2	550°C	H&L Tag: 2066 No.2 D/G EXH GAS INLET T/C TEMP		
104.	TURNING GEAR INTERLOCK	Engage turning bar, Close start air valve and activate start sequence at local control panel.	Binary	Starter air solenoid does not engage and Engine does not attempt to start; Light on Generator Section of MSB illuminates: Turning Gear Interlock.		

#3 SERVICE GENERATOR ENGINE SAFETY DEVICES

ITEM NO.	ALARM DESCRIPTION	PROCEDURE	SETPOINT	RESULTS/REMARKS	SAT	UNSAT
105.	OVERSPEED SHUTDOWN	1. Engine running up to operating temperature. 2) Using a mechanical tool manually override governor actuator arm and slowly rise engine RPMS to set point.	1015 RPM	H&L Engine Stops Tag: 2111 No.3 A/E OVERSPEED SHD		
106.	LUBE OIL INLET PRESSURE LOW	PRS-2	0.4 Mpa LO 0.25 SHD	H & L Tag: 2106 No.3 D/G L.O. Inlet pressure Engine shuts down on LO-LO		
107.	FUEL OIL INLET PRESSURE LOW	PRS-2	0.4 Mpa LO	H & L Tag: 2130 No.3 D/G F.O. Inlet pressure LO		
108.	LUBE OIL INLET TEMPERATURE	TMP-2	75°C HI	H & L Tag: 2108 No.3 A/E D/G L.O. Inlet Temp		
109.	C.F.W. INLET PRESSURE	PRS-2	0.08 MPa	H & L Tag: 2107 No.3 A/E CFW Inlet Pressure		
110.	CFW OUTLET TEMPERATURE	TMP-2	90°C HI 95°C SHD	H & L; Engine Stops Tag: 2109 No.3 A/E CFW Outlet Temp		
	F.O. FILTER HIGH DIEF PRESSURE		0.02~0.25 Mpa	H&L Tag 2138 No.3 A/E F.O. FILTER HI PRES.		
111.	DG EXHAUST GAS OUTLET TEMPERATURE	TMP-2	420°C	Tag: 2125 H&L (No.3 A/E EXH Tag: 2127 GAS HT DEIV FM Tag: 2129 AVERAGE) Tag: 2132 Tag: 2134 Tag: 2136	CYL 1 CYL 2 CYL 3 CYL 4 CYL 5 CYL 6	
112.	DG EXHAUST GAS HT DEVIATION FROM AVERAGE Note: Deviation temperatures are inhibited when the generator is not on the bus	1) Engine running at operating temperature and connected to the buss 2) TMP-2	±50°C	Tag: 2126 H&L (No.3 A/E EXH Tag: 2128 GAS HT DEIV FM Tag: 2131 AVERAGE) Tag: 2133 Tag: 2135 Tag: 2137	CYL 1 CYL 2 CYL 3 CYL 4 CYL 5 CYL 6	
113.	DG EXHAUST GAS T/C INLET TEMPERATURE HIGH	TMP-2	550°C	H&L; Tag: 2116 No.3 D/G EXH GAS INLET T/C TEMP		
114.	TURNING GEAR INTERLOCK	Engage turning bar, Close start air valve and activate start sequence at local control panel.	Binary	Starter air solenoid does not engage and Engine does not attempt to start; Light on Generator Section of MSB illuminates: Turning Gear Interlock.		

GENERATOR SWITCHBOARD SAFETY DEVICES

ITEM NO.	ALARM DESCRIPTION	PROCEDURE	SETPOINT	RESULTS/REMARKS	SAT	UNSAT
115.	#1 G/E REVERSE POWER	1) #1 and #2 in parallel. 2) Place genset selector switches in manual 3) Reduce engine speed at governor control on MSB on #1 while raising speed on #2.	(10%/-91kW)	H & L 4 sec. delay; breaker opens; Preferential Trips activated		
116.	#2 G/E REVERSE POWER	1) #2 and #3 2) Place genset selector switches in manual. 3) Reduce engine speed at governor control on MSB on #2 while raising speed on #3	(10%/-91kW)	H & L 4 sec. delay; breaker opens; Preferential Trips activated		
117.	#3 G/E REVERSE POWER	1) #3 and #1 in parallel. 2) Place genset selector switches in manual. 3) Reduce engine speed at governor control on MSB on #3 while raising speed on #1.	(10%/-91kW)	H & L 4 sec. delay; breaker opens; Preferential Trips activated		
118.	MSB BUSS ABNORMAL (UNDER VOLTAGE)	1) With on line generator open generator panel on MSB 2) On the DIEF RMV-112D UV relay adjust the 80% - 100% dashpot to 100%	95% or 418VAC 5 seconds	H & L		
119.	MSB BUSS ABNORMAL (HIGH VOLTAGE)	1) With on line generator open generator panel on MSB 2) On the DIEF RMV-112D UV relay adjust the 106% - 120% dashpot to 100%	105% or 462VAC 5 seconds	H & L		
120.	MSB BUSS ABNORMAL (HIGH FREQUENCY)	1) With on line generator open generator panel on MSB 2) On the DIEF RMV-112D Over Frequency relay adjust the 100% - 110% dashpot to 100%	105% or 63Hz 5 seconds	H & L Tag: 5002 MSB Frequency High		
121.	MSB BUSS ABNORMAL (LOW FREQUENCY)	1) With on line generator open generator panel on MSB 2) On the DIEF RMV-112D under frequency relay adjust the 80% - 100% dashpot to 100%	95% or 57Hz 5 seconds	H & L		

GENERATOR SWITCHBOARD SAFETY DEVICES (Cont'd)

ITEM NO.	ALARM DESCRIPTION	PROCEDURE	SETPOINT	RESULTS/REMARKS	SAT	UNSAT
122.	Automatic Startup Black out start	1) This test can be completed with any one SSDG feeding the MSB and an alternate in standby 2) Advise crew of a impending power interruption 3) Open MCB for online generator		H&L 1) The standby generator starts and it's CB closes, restoring power 2) EDG starts 3) No loss of propulsion safety trip control system		
123.	Number 2 Generator auto-start	a) With #1 G/E online; #2 G/E in stand-by, increase the load. b) With both generators now online, decrease load.	95% or 864kW for 5 seconds	#2 G/E starts automatically and parallels #2 G/E automatically goes off-line and secures after cool down period.		
			80% or 728kW for 10 minutes			
124.	Number 3 Generator auto start	a) With #2 G/E online; #3 G/E in stand-by increase the load. b) With both generators now online, decrease load	95% or 864kW for 5 seconds	#3 G/E starts automatically and parallels #3 G/E automatically goes off-line and secures after cool down period.		
			80% or 728kW for 10 minutes			
125.	Number 1 Generator auto start	a) With #3 G/E online; #1 G/E in stand-by increase the load. b) With all both generators now online, decrease load.	95% or 864kW for 5 seconds	#1 G/E starts automatically and parallels. #1 G/E automatically goes off-line and secures after cool down period.		
			80% or 728kW for 10 minutes			
126.	PREFERENCE TRIP #1*	1) With two generators on line in parallel 2) Trip ACB to one breaker		H & L Preferential trips occur		

**Note: Preferential Trips will also occur when completing reverse power relay tests*

SYSTEM POWER SUPPLIES

ITEM NO.	ALARM DESCRIPTION	PROCEDURE	SETPOINT	RESULTS/REMARKS	SAT	UNSAT
127.	MCU AC POWER FAIL TO UPS U4 <i>Failure of Normal Power</i>	Open MCCB "EL21" located on ESB	Binary	H & L Power is supplied by redundant AC power supply U2 from MSB and 24 VDC "G1" battery backup		
128.	MCU AC POWER FAIL to UPS U2 <i>Failure of Backup Power</i>	Open MCCB "4P24" located on MSB	Binary	H & L Power is supplied by redundant AC power supply U4 from ESB and 24 VDC "G1" battery backup		
129.	DC 24V BATTERY "G1" FAILURE	Secure 24VDC power at FB switch	Binary	H & L		
130.	ECC BATTERY LOW VOLTAGE	Secure AC power from MSB "4P24" and ESB "EL21"	Binary	H & L 24 VDC Batteries assume load for a minimum of 30 minutes		
131.	ENGINE TELEGRAPH POWER FAILURE	Secure power to the C/R Maneuvering Unit & EOT by removing X10 DC power input on underside of the telegraph.		H & L No loss of control when in Bridge Control		
132.	BRIDGE TELEGRAPH POWER FAILURE	Secure power to the Bridge Maneuvering Unit & EOT by removing X10 DC power input on underside of the telegraph.		H & L Must operate on P/S bridge wing, ECR Control or in Local Control		
133.	FIRE ALARM AC POWER FAILURE	On MSB open MCCB "4P2"		H&L in ECR and W/H; Tag 13003 Fire Alarm AC Power		
134.	MSB POWER FAILURE TO BATTERY CHARGING AND DICHARGING PANEL	Open CB "M1" from MSB 1 on main NP control panel in Electric Equipment Room		H & L Tag: 5012 Battery Charger Panel Fail		
135.	ESB POWER FAILURE TO BATTERY CHARGING AND DICHARGING PANEL	Open CB "M2" from ESB on main NP control panel in Electric Equipment Room		H & L Tag: 5012 Battery Charger Panel Fail		
136.	220V POWER FAILURE TO A7-1 UPS <i>UPS FEEDS KONGSBURG ROS 1 COMPUTER A3 AND LCD DISPLAY</i>	Open CB 1F06 on 220 VAC panel board in section 3 of the ECC		H & L 220VAC UPS Fail PC A3, LCD remain operational on UPS		
137.	220V POWER FAILURE TO A7-2 UPS <i>UPS FEEDS KONGSBURG ROS 2 COMPUTER A3 AND LCD DISPLAY</i>	Open CB 1F07 on 220 VAC panel board in section 3 of the ECC		H & L 220VAC UPS Fail PC A6, LCD remain operational on UPS		

FLOODING SAFETY

ENGINE ROOM AUTO BILGE SYSTEM

ITEM NO.	DESCRIPTION	PROCEDURE	SETPOINT	RESULT/REMARKS	SAT	UNSAT
138.	BILGE WELL HIGH LEVEL ALARMS	Fill ER bilge well with water or LVL-1		H & L		
				ER Forward PS Bilge Well		
				ER Forward SB Bilge Well		
				ER Below ME		
				ER Aft bilge well		
				S/G Room		
				Bow Thruster		
139.	OILY WATER HIGH OIL CONTENT ALARM	Simulate high oil content shutdown	15 ppm	H & L 2 Second delay		
140.	DIRTY BILGE WATER TANK HIGH 90%	LVL-1 or LVL -3	300MM	H & L 2 Second delay		
141.	CLEAN BILGE WATER TANK HIGH 90%	LVL-1 or LVL -3	300MM	H & L 2 Second delay		
142.	EMERGENCY BILGE SUCTION VALVE OPERATIONAL TEST	Ensure system is secured and Cycle Emergency Bilge Suction Valve Open and Closed. <i>It is not necessary to pump water to accomplish this test</i>		Associated valve should open and close freely		

COMPRESSED AIR SYSTEMS & FUEL DELIVERY

COMPRESSED AIR SYSTEMS

ITEM NO.	ALARM DESCRIPTION	PROCEDURE	SETPOINT	RESULTS/REMARKS	SAT	UNSAT
143.	STARTING AIR COMPRESSORS	1) Place both start air compressors in Auto 2) Lower air pressure		Both compressors will run		
144.	NO. 1 MAIN AIR RECEIVER LOW	PRS-3	1.6 MPa	H & L Tag: 4120 Main Air Reservoir Pressure Engine remains capable of further starts per SOLAS Reg 31.2.9		
145.	NO. 2 MAIN AIR RECEIVER LOW	PRS-3	1.6 MPa	H & L Tag: 4121 Main Air Reservoir Pressure Engine remains capable of further starts per SOLAS Reg 31.2.9		
146.	AUXILIARY AIR RECEIVER LOW	PRS-3	1.6 MPa	H & L		
147.	CONTROL AIR INLET PRESSURE	PRS-3	0.55 MPa	H & L		
148.	M/E STARTING AIR INLET PRESSURE	PRS-3	1.5 MPa	H & L Tag: 3073 M/E Starting Air Pressure Low		
149.	#1 MAIN AIR COMPRESSOR ABNORMAL	Open CB 1P19 on MSB or PRS-3 or PRS-4	Binary	H & L Tag: 4116 No.1 Main Air Compressor abn Standby Compressor start automatically		
150.	#2 MAIN AIR COMPRESSOR ABNORMAL	PRS-3 or PRS-4	Binary Lag setpoint:	H & L Tag: 4117 No.2 Main Air Compressor abn Standby Compressor start automatically after air pressure reaches lag setpoint in switch [xxx]		
151.	QUICK CLOSING VALVE AIR PRESSURE LOW	PRS-3 or PRS-4	0.55 MPa	H & L		
152.	NO. 1 A/E STARTING AIR INLET PRESSURE	PRS-3 or PRS-4	0.7 MPa	H & L Tag: 2002 No.1 D/G Start. Air Inlet Press		
153.	NO. 2 A/E STARTING AIR INLET PRESSURE	PRS-3 or PRS-4	0.7 MPa	H & L Tag: 2052 No.1 D/G Start. Air Inlet Press		
154.	NO. 3 A/E STARTING AIR INLET PRESSURE	PRS-3 or PRS-4	0.7 MPa	H & L Tag: 2102 No.1 D/G Start. Air Inlet Press		

ITEM NO.	ALARM DESCRIPTION	PROCEDURE	SETPOINT	RESULTS/REMARKS	SAT	UNSAT
155.	NO. 1 A/E START FAIL	1) A/E #2 or #3 on line 2) Close air start valve on No.1 A/E 3) On "Syncro" panel on MSB select #1 generator as standby and in manual control 4) On #1 generator panel on MSB depress the "start" button	Binary 2 Second Delay	A/E #1 Fails to start H&L Tag:2001 No.1 A/E Start Fail		
156.	NO. 2 A/E START FAIL	1) A/E #1 or #3 on line 2) Close air start valve on No.2 A/E 3) On "Syncro" panel on MSB select #2 generator as standby and in manual control 4) On #2 generator panel on MSB depress the "start" button	Binary 2 Second Delay	A/E #2 Fails to start H&L Tag:2051 No.2 A/E Start Fail		
157.	NO. 3 A/E START FAIL	1) A/E #1 or #2 on line 2) Close air start valve on No.3 A/E 3) On "Syncro" panel on MSB select #3 generator as standby and in manual control 4) On #3 generator panel on MSB depress the "start" button	Binary 2 Second Delay	A/E #3 Fails to start H&L Tag:2101 No.1 A/E Start Fail		

FO AND LO TANK TEMPERATURE AND LEVEL ALARMS

ITEM NO.	ALARM DESCRIPTION Level Alarms	PROCEDURE	SETPOINT	RESULTS/REMARKS	SAT	UNSAT
158.	NO. 1 DO TANK HIGH	LVL-1 or LVL-3	350MM	H & L after 15s delay Tag: 4214 No.1 DO Tank High Level 95%		
159.	DO SERVICE TANK LOW	LVL-1 or LVL-3	900MM	H & L after 15s delay Tag: 4221 DO Service Tank Low Level		
160.	HFO SERVICE TANK LOW	LVL-1 or LVL-3	1500MM	H & L after 15s delay Tag: 4222 HFO Service Tank Low Level		
161.	HFO SETTLING TANK HIGH	LVL-1 or LVL-3	900MM	H & L after 15s delay Tag: 4223 HFO Settling Tank High Level		
162.	HFO SETTLING TANK LOW	LVL-1 or LVL-3	600MM	H & L after 15s delay Tag: 4224 HFO Settling Tank Low Level		
163.	L.S. FO SETTLING TANK HIGH	LVL-1 or LVL-3	900MM	H & L after 15s delay Tag: 4225 LSFO Settling Tank High Level		
164.	L.S. FO SETTLING TANK LOW	LVL-1 or LVL-3	600MM	H & L after 15s delay Tag: 4226 LSFO Settling Tank Low Level		
165.	HFO SLUDGE TANK HIGH	LVL-1 or LVL-3	200MM	H & L after 15s delay Tag: 4227 HFO Sludge Tank High Level		
166.	LO SLUDGE TANK HIGH	LVL-1 or LVL-3	200MM	H & L after 15s delay Tag: 4228 LO Sludge Tank High Level		
167.	HFO OVERFLOW TANK HIGH (90%)	LVL-1 or LVL-3	300MM	H & L after 15s delay Tag: 4229 HFO Overflow Tank High Level		
168.	OIL DRAIN TANK FOR LO AND FO HIGH LEVEL	LVL-1 or LVL-3	300MM	H & L after 15s delay Tag: 4230 Oil Drain TK for FO & LO High Level (90%)		
169.	NO. 1 PS HFO TANK HIGH 95%	LVL-1 or LVL-3	660MM	H & L after 15s delay Tag: 4246 No.1 PS HFO Tank High Level (95%)		
170.	NO. 1 SB HFO TANK HIGH 95%	LVL-1 or LVL-3	660MM	H & L after 15s delay Tag: 4247 No.1 SB HFO Tank High Level (95%)		
171.	NO. 2 PS HFO TANK HIGH 95%	LVL-1 or LVL-3	660MM	H & L after 15s delay Tag: 4248 No.2 PS HFO Tank High Level (95%)		
172.	LFSO STORAGE TANK HIGH 95%	LVL-1 or LVL-3	660MM	H & L after 15s delay Tag: 4249 LSFO Tank High Level (95%)		
173.	NO. 3 SB HFO TANK HIGH 95%	LVL-1 or LVL-3	660MM	H & L after 15s delay Tag: 4250 No.3 SB HFO Tank High Level (95%)		

FO AND LO TANK TEMPERATURE AND LEVEL ALARMS Cont'd

ITEM NO.	ALARM DESCRIPTION Level Alarms	PROCEDURE	SETPOINT	RESULTS/REMARKS	SAT	UNSAT
174.	LSFO SERVICE TANK LOW LEVEL	LVL-1 or LVL-3	1500MM	H & L after 15s delay Tag: 4265 LSFO Serv. Tank Low Level		
175.	D.O. TANK FOR IGG LOW	LVL-1 or LVL-3	400MM	H & L after 15s delay Tag: 4267 DO Tk. For IGG Low Level		
176.	EMERGENCY GENERATOR D.O. TANK LOW-LOW	LVL-1 or LVL-3	Binary	H & L after 2s delay		
177.	CYL OIL SERVICE TANK HIGH LEVEL	LVL-1 or LVL-3	200MM	H & L after 15s delay Tag: 4268 Cyl Oil Service Tank high Level		
178.	D.O. TANK FOR INCINERATOR LOW LEVEL	LVL-1 or LVL-3	LL	H & L after 15s delay Tag: 4269 DO TK For Incinerator Low Level		
179.	WASTE OIL SETTLING TANK HIGH LEVEL	LVL-1 or LVL-3	HL	H & L after 15s delay Tag: 4270 Waste Oil Settling Tank High Level		
180.	WASTE OIL SETTLING TANK LOW LEVEL	LVL-1 or LVL-3	LL	H & L after 15s delay Tag: 4270 Waste Oil Settling Tank Low Level		
181.	CYL OIL SERVICE TANK LOW LEVEL	LVL-1 or LVL-3	300MM	H & L after 15s delay Tag: 4245 Cyl Oil Service Tank Low Level		

FO AND LO TANK TEMPERATURE AND LEVEL ALARMS Cont'd

ITEM NO.	ALARM DESCRIPTION Temperature Alarms	PROCEDURE	SETPOINT	RESULTS/REMARKS	SAT	UNSAT
182.	FO SETTLING TANK HIGH TEMPERATURE		87°C	H & L after 2s delay Tag: 4201 FO Sett TK Temp High		
183.	FO SERVICE TANK HIGH TEMPERATURE		98°C	H & L after 2s delay Tag: 4202 FO SERV. TK Temp High		
184.	LSFO SETTLING TANK HIGH TEMPERATURE		80°C	H & L after 2s delay Tag: 4203 LSFO Sett TK Temp High		
185.	LSFO SERVICE TANK HIGH TEMPERATURE		98°C	H & L after 2s delay Tag: 4204 LSFO Serv. TK Temp High		
186.	NO.1 PS HFO TANK HIGH TEMPERATURE		65°C	H & L after 2s delay Tag: 4205 No.1 PS HFO TK Temp High		
187.	NO.1 SB HFO TANK HIGH TEMPERATURE		65°C	H & L after 2s delay Tag: 4206 No.1 SB HFO TK Temp High		
188.	NO.2 PS HFO TANK HIGH TEMPERATURE		65°C	H & L after 2s delay Tag: 4207 No.2 PS HFO TK Temp High		
189.	LSFO TANK HIGH TEMPERATURE		65°C	H & L after 2s delay Tag: 4208 LFSO TK Temp High		
190.	NO.3 SB HFO TANK HIGH TEMPERATURE		65°C	H & L after 2s delay Tag: 4209 No.3 SB HFO TK Temp High		

QUICK CLOSING FUEL & L/O VALVES

ITEM NO	DESCRIPTION	PROCEDURE	RESULT	REMARKS		SAT	UNSAT
				VALVE IDENTIFICATION	SERVING VALVES		
191.	QUICK CLOSING VALVES	1. In Cargo Control Room open cabinet and check to see that the QCV air reservoir has a working pressure of 0.7 MPa. 2. Open cabinet door and activate valves one at a time: 3. Locally inspect valve to ensure the valves fully close then reset each valve prior to moving to next test.	VALVE CLOSES	QCV FOR I.G.G. D.O. TK	I.G.G. Diesel Oil Tank to I.G.G F.O. Unit		
				QCV FOR INCINERATOR	Incinerator Waste Oil Service Tank to Incinerator		
				QCV FOR UPPER FLAT	A/E L.O. Storage Tank to A/E & L.O. Transfer Pumps		
					M/E L.O. Settling Tank to L.O. Purifier feed pumps		
					M/E L.O. Storage Tank to M/E L.O. Sump Tank		
					Cylinder Oil Tank to M/E		
					M/E Cyl. Oil Storage Tank No.1 to Cyl. O. Transfer pump		
					M/E CYL. Oil Storage Tank No.2 Cyl. O. Transfer pump		
				QCV FOR LOWER FLAT	M/E		
					F.O. Sett Tank to Boiler		
					F.O. Sett Tank to F.O. Purifier, feed pumps & transfer pump		
					F.O. Service TK to F.O. transfer pump		
					F.O. Service TK to F.O. supply unit		
					D.O Service TK to F.O. Supply unit		
					D.O Service TK to Boiler		
					D.O Service TK to D.O. Supply pump		
					D.O Service TK to D.O. Purifier Feed Pump & D.O. Transfer pump		
L.F.S.O Tank to F.O. Transfer pump							
L.F.S.O Tank to F.O Supply Unit							
L.F.S.O Sett Tank to Boiler							
L.F.S.O Sett Tank to Boiler F.O. Purifier Feed Pump & F.O. Transfer pump							

QUICK CLOSING VALVES Cont'd

ITEM NO	DESCRIPTION	PROCEDURE	RESULT	REMARKS		SAT	UNSAT
				VALVE IDENTIFICATION	SERVING VALVES		
	QUICK CLOSING VALVES		VALVE CLOSES	QCV FOR F.O. TK	No. 1 H.F.O. Tank Port		
					No. 2 H.F.O. Tank Port		
					No. 1 D.O. Tank Port		
					No. 3 H.F.O. Tank Starboard		
					No. 1 H.F.O. Tank Starboard		
					L.S.H. F.O. Tank		

PURIFIERS & FO BOOSTER UNIT

ITEM NO.	ALARM DESCRIPTION	PROCEDURE	SETPOINT	RESULTS/REMARKS	SAT	UNSAT
192.	NO. 1 FO PURIFIER ABNORMAL	Purifier online and running 1) Secure Power to purifier	Binary	H & L Tag 4101 No.1 FO Purifier Abnormal		
193.	NO. 2 FO PURIFIER ABNORMAL	Purifier online and running 1) Secure Power to purifier	Binary	H & L Tag 4102 No.1 FO Purifier Abnormal		
194.	DO PURIFIER ABNORMAL	Purifier online and running 1) Secure Power to purifier	Binary	H & L Tag 4103 DO Purifier Abnormal		
195.	No.1 M/E PURIFIER ABNORMAL	Purifier online and running 1) Secure Power to purifier	Binary	H & L Tag 4104 No.1 M/E Purifier Abnormal		
196.	No.2 M/E PURIFIER ABNORMAL	Purifier online and running 1) Secure Power to purifier	Binary	H & L Tag 4105 No.2 M/E Purifier Abnormal		
197.	A/E PURIFIER ABNORMAL	Purifier online and running 1) Secure Power to purifier	Binary	H & L Tag 4106 A/E Purifier Abnormal		
198.	FO AUTO FILTER HIGH DIFF PRESSURE	PRS-3	0.09MPa	H&L Tag: 4108 FO Auto Filter Diff Pressure High		
199.	FO VISCOSITY HIGHT/LOW		10/7Cst	H&L Tag: 4109 FO Viscosity High/Low		

AUXILIARY BOILER

AUXILIARY BOILER TEST PROCEDURE

ITEM NO.	ALARM DESCRIPTION	PROCEDURE	SETPOINT	RESULTS/REMARKS	SAT	UNSAT
200.	START SEQUENCE TEST & NORMAL AUTOMATIC OPERATION	Manually Start boiler and build pressure		Normal sequence will commence 1) pre-purge 2) ignition 3) Fuel 4) Flame		
201.	FLAME FAILURE	With boiler on line 1) Remove LAE10 flame scanner No.1 from holder and cover sensor 2) Reset all shut downs and repeat with flame scanner No.2	Binary	H & L Boiler trips Tag: 1101 Aux. Boiler Shut Down	FS No.1 FS No.2	
202.	GLOWING FURNACE	Boiler off line 1) LAE10 flame scanner removed 2) Point flash light directly into flame scanner and set burner to start.		H & L Boiler fails to start		
203.	HIGH WATER LEVEL	Set for Automatic Feed Regulation. Raise Drum water	150mm	H & L		
204.	LOW WATER LEVEL	With the boiler operating at pressure 1) Secure feed water to boiler and lower water level while observing sight glass	-120mm	H & L		
205.	LOW-LOW WATER LEVEL	Option A: With the boiler operating at pressure 1) Depress "Channel #1" test for more than 5 seconds Option B: With the boiler operating at pressure 1) Lower water level	-150mm	H & L Boiler secures 5 send time delay Tag: 1101 Aux. Boiler Shut Down		
206.	LOW OIL PRESSURE ALARM & STANDBY PUMP START	With the boiler operating at pressure 1) One pump running with one in standby 2) Slowly decrease pressure on pressure regulating valve until set point is reached		H & L Standby pump starts		
207.	LOW OIL PRESSURE SHUT DOWN AND TRIP FUNCTION	With the boiler operating at pressure 1) One pump running with one in standby 2) Slowly use manual bypass decrease pressure on pressure regulating valve until set point is reached		H & L Standby pump starts secures Boiler trips Tag: 1101 Aux. Boiler Shut Down		

		3) Continue to reduce pressure.				
--	--	---------------------------------	--	--	--	--

AUXILIARY BOILER TESTS Cont'd

ITEM NO.	ALARM DESCRIPTION	PROCEDURE	SETPOINT	RESULTS/REMARKS	SAT	UNSAT
208.	LOW COMBUSTION AIR PRESSURE	With the boiler operating at pressure 1) Open the installed vent valves on differential pressure transmitter.	5% of Airflow	H & L Boiler trips Tag: 1101 Aux. Boiler Shut Down		
209.	EMERGENCY STOP	With the boiler firing 1) Depress the "E-Stop". 2) Reset and then test alternate location		H&L Boiler trips Tag: 1101 Aux. Boiler Shut Down	ECR	
					Local	
					At PP	
210.	HIGH STEAM PRESSURE	With the burner in operation 1) Raise the steam pressure until set point is reached	7.5 Bar HI 8.5 Bar HI-HI	H & L Boiler trips Tag: 1101 Aux. Boiler Shut Down		
211.	AUX BOILER UPTAKE TEMPERATURE HIGH	TMP2	450°C	H & L Boiler trips		
212.	HIGH FUEL OIL INLET TEMPERATURE	TMP2	145°C	H & L		
213.	LOW FUEL OIL INLET TEMPERATURE	TMP2	110°C	H & L		
214.	BOILER POWER FAILURE	With the boiler operating at pressure 1) Secure main power to boiler controls	Binary	H&L Boiler Trips		
215.	STANDBY WATER PUMP START	Select # 1 ON; #2 STBY Trip Breaker for #1	0.9MPa	#2 Pump Starts H & L		



COMPOSITE AUXILIARY BOILER TEST PROCEDURE

Vertical Smoke Water Tube Boiler (Waste Heat)

ITEM NO.	ALARM DESCRIPTION	PROCEDURE	SETPOINT	RESULTS/REMARKS	SAT	UNSAT
216.	START SEQUENCE TEST & NORMAL AUTOMATIC OPERATION	Manually Start boiler and build pressure		Normal sequence will commence 1) pre-purge 2) ignition 3) Fuel 4) Flame		
217.	FLAME FAILURE	With boiler on line 1) Remove flame scanner No.1 from holder and cover sensor 2) Reset all shut downs and repeat with flame scanner No.2		H & L Boiler trips Tag: 1103 Composite Boiler Shut Down	FS No.1 FS No.2	
218.	GLOWING FURNACE	Boiler off line 1) Flame scanner removed 2) Point flashlight directly into flame scanner and set burner to start.		H & L Boiler fails to start		
219.	HIGH WATER LEVEL	Manually raise water level	150mm	H & L W/15 Sec Time Delay		
220.	LOW WATER LEVEL	With the boiler operating at pressure 1) Secure feed water to boiler and lower water level while observing sight glass	-135mm	H & L W/15 Sec Time Delay		
221.	LOW-LOW WATER LEVEL	Option A: With the boiler operating at pressure 1) Depress "Channel #1" test for more than 5 seconds Option B: With the boiler operating at pressure 1) Lower water level	-120mm	H & L W/15 Sec Time Delay Boiler secures 5 send time delay Tag: 1103 Composite Boiler Shut Down		
222.	STEAM PRESSURE HIGH	With the burner in operation 1) Raise the steam pressure until set point is reached	.75Mpa	H & L Boiler trips		
223.	WATER STANDBY PUMP START	Select # 1 ON; #2 STBY Trip Breaker for #1		H & L Standby pump starts		
224.	HIGH FUEL OIL TEMP	TMP2	160°C	H & L		
225.	LOW FUEL OIL TEMP	TMP2	80°C	H & L		

COMPOSITE AUXILIARY BOILER TESTS Cont'd

ITEM NO.	ALARM DESCRIPTION	PROCEDURE	SETPOINT	RESULTS/REMARKS	SAT	UNSAT
226.	EMERGENCY STOP	With the boiler firing 1) Depress the "E-Stop". 2) Reset and then test alternate location		H&L Boiler trips Tag: 1103 Aux. Boiler Shut Down	ECR Local At PP	

FIRE DETECTION AND EXTINGUISHING

FIREMAIN PUMP CONTROLS

ITEM NO.	ALARM DESCRIPTION	PROCEDURE	SETPOINT	RESULTS/REMARKS	SAT	UNSAT
	CONTROL POSITION					
227.	BRIDGE #1 FIRE PUMP CONTROLS	1. Depress #1 Fire pump start button 2. Secure pump		#1 Fire pump starts and local pressure gage shows pressure.		
228.	BRIDGE #2 FIRE PUMP CONTROLS	1. Depress No.2 Fire pump start button 2. Secure pump		#2 Fire pump starts and pressure gage shows pressure.		
229.	CARGO CONTROL ROOM #1 FIRE PUMP CONTROLS	1. Depress No.1 Fire pump start button 2. Secure pump		#1 Fire pump starts and pressure gage shows pressure.		
230.	CARGO CONTROL ROOM #2 FIRE PUMP CONTROLS	1. Depress No.2 Fire pump start button 2. Secure pump		#2 Fire pump starts and pressure gage shows pressure.		
231.	ECR #1 FIRE PUMP CONTROLS	1. Depress No.1 Fire pump start button 2. Secure pump		#1 Fire pump starts and pressure gage shows pressure.		
232.	ECR #2 FIRE PUMP CONTROLS	1. Depress No.2 Fire pump start button 2. Secure pump		#2 Fire pump starts and pressure gage shows pressure.		
233.	FOAM ROOM #1 FIRE PUMP CONTROLS	1. Depress No.1 Fire pump start button 2. Secure pump		#1 Fire pump starts and pressure gage shows pressure.		
234.	FOAM ROOM #2 FIRE PUMP CONTROLS	1. Depress No.2 Fire pump start button 2. Secure pump		Fire pump starts and pressure gage shows pressure.		

FIRE DETECTION SYSTEM

ITEM NO.	ALARM DESCRIPTION	PROCEDURE	SETPOINT	RESULTS/REMARKS	SAT	UNSAT
235.	FIRE DETECTION SYSTEM	FIRE 1,2,3 or 4 Test E/R fire detectors (page 60 - Machinery Space Fire Detect. SYS Detectors) This can be accomplished by a third party vendor on an annual basis	Binary	H & L in bridge, E/R and Accommodation space		

FIXED FIRE EXTINGUISHING SYSTEMS

ITEM NO.	ALARM DESCRIPTION	PROCEDURE	SETPOINT	RESULTS/REMARKS	SAT	UNSAT
236.	ENGINE ROOM FIXED HIGH PRESSURE CO2 FIRE EXTINGUISHING SYSTEM PERFORMANCE TEST	This test is completed on an annual basis by a <u>qualified third party</u> . <i>Due to Safety reasons Procedures 240 through 243 shall not be completed by the crew</i>		H & L in bridge, E/R and Accommodation space		
237.	CO2 BOTTLE WEIGHT	This test is completed on an annual basis by a <u>qualified third party</u> . Loosen the mounting clamps at the cylinder and weigh the cylinder.		The correct charge should be not less than 10% below the required weight.		
238.	DEMONSTRATE CO ₂ ACTUATION RELEASE TEST FOR THE E/R	At the CO ₂ storage bottles remove actuators from all CO ₂ cylinders and install spectacle flange at main CO ₂ discharge line.		Annual by outside contractor		
		At the activation control station in the ballast Control Room, remove the pilot line from the nitrogen charge bottles and connect a 15-lb test CO ₂ cylinder.				
		Ensure all E/R ventilation is running and that all personnel have been removed from E/R during test				
		Activate the test cylinder to simulate pressurize from one of the activation control cylinders to distribution valves				
		Open Door to E/r release box & Pull Handle Marked No.1		E/R Ventilation shuts down upon opening door. Alarm sounds and distribution valve opens after pulling handle No.1		
		Pull Handle Marked No.2		CO ₂ passes valve to timer. After 30 to 40 seconds the discharge pins in each actuator are activated.		

FIXED FIRE EXTINGUISHING SYSTEMS Cont'd

ITEM NO.	ALARM DESCRIPTION	PROCEDURE	SETPOINT	RESULTS/REMARKS	SAT	UNSAT
239.	DEMONSTRATE CO ₂ ACTUATION RELEASE TEST FOR THE ECC	At the CO ₂ storage bottles remove actuators from all CO ₂ cylinders and install spectacle flange at main CO ₂ discharge line.		Annual by outside contractor		
		At the activation control station in the ballast Control Room, remove the pilot line from the nitrogen charge bottles and connect a 15-lb test CO ₂ cylinder.				
		Activate the test cylinder to simulate pressurize from one of the activation control cylinders to distribution valves				
		Open Door to ECC release box & Pull Handle Marked No.1		Alarm sounds and distribution valve opens after pulling handle No.1		
		Pull Handle Marked No.2		CO ₂ passes valve to timer. After 30 to 40 seconds the discharge pins in each actuator are activated.		
240.	DEMONSTRATE CO ₂ ACTUATION RELEASE TEST FOR THE IGG ROOM	At the CO ₂ storage bottles remove actuators from all CO ₂ cylinders and install spectacle flange at main CO ₂ discharge line.		Annual by outside contractor		
		At the activation control station in the ballast Control Room, remove the pilot line from the nitrogen charge bottles and connect a 15-lb test CO ₂ cylinder.				
		Activate the test cylinder to simulate pressurize from one of the activation control cylinders to distribution valves				
		Open Door to IGG Room release box & Pull Handle Marked No.1		Alarm sounds and distribution valve opens after pulling handle No.1		
		Pull Handle Marked No.2		CO ₂ passes valve to timer. After 30 to 40 seconds the discharge pins in each actuator are activated.		
		Restore system to ready for use status.				

FIXED FIRE EXTINGUISHING SYSTEMS Cont'd

ITEM NO.	ALARM DESCRIPTION	PROCEDURE	SETPOINT	RESULTS/REMARKS	SAT	UNSAT
241.	DEMONSTRATE WATER MIST ACTUATION RELEASE TEST	Close all outlet valves and open test valves				
		Release one section manually by activating the "F1 or F2" button on the FCP, select a zone for release and press "OK"		Pump starts, correct valve opens for zone selected and water is discharged through drain valve, and display on the FCP indicates: Water Mist System Released" Alarm is actuated on the FCP		
		Reset the alarm on the FCP		Valve closes and pump stops		
		Close test valve and repeat procedures for all zones.				
				Protection Zones:		
				IGG		
				Aux Boiler		
				Main Engine		
				Incinerator		
				Composite Boiler		
				Aux Engine #1		
				Aux Engine #2		
				Aux Engine #3		
				FO/MDO Purifier		

EMERGENCY STOP SYSTEM FOR VENTILATION AND MISC VITAL SYSTEMS

ITEM NO.	ALARM DESCRIPTION	PROCEDURE	SETPOINT	RESULTS/REMARKS	SAT	UNSAT
242.	DEMONSTRATE VENTILATION EMERGENCY STOP SYSTEM ON SHIPS CONTROL CENTER AND ON WHEELHOUSE "ESS-1"	<ol style="list-style-type: none"> 1. In-port test only 2. Ensure all of the items listed in results/remarks are energized or are operationally tested just prior to test. 3. Open glass protective test on bridge console and depress "ESS-1" emergency stop button 4. RESET and ready to repeat test 5. Ensure all of the items listed in results/remarks are energized or are operationally tested just prior to second test. 6. Open glass protective test on FCR console and depress "ES-1" emergency stop button 		<p>Verify the following items are secured or no longer have power:</p> <p>No. 1 E/R Supply Fan No. 3 E/R Supply Fan No. 4 E/R Supply Fan No. 2 E/R Fan No. 1 ME Aux Blower No. 2 ME Aux Blower Packed Air Conditioning Unit for ER 45D Power Dist Board</p>		
243.	DEMONSTRATE EMERGENCY ACOMM VENT AND GALLEY EQUIP STOP SYSTEM ON SHIPS CONTROL CENTER "ESS-2"	<ol style="list-style-type: none"> 1. In-port test only 2. Ensure all of the items listed in results/remarks are energized or are operationally tested just prior to test. 3. Open glass protective test on bridge console and depress "ESS-2" emergency stop button 4. RESET (Also in CCR as with 245.) 		<p>Verify the following items are secured or no longer have power:</p> <p>22D Power Dist Board 23D Power Dist Board 47D Power Dist Board 4AD Power Dist Board C02 Room Fan Air Cond. Fan</p>		



FIXED FIRE EXTINGUISHING SYSTEMS Cont'd

ITEM NO.	ALARM DESCRIPTION	PROCEDURE	SETPOINT	RESULTS/REMARKS	SAT	UNSAT
244.	<p>DEMONSTRATE MACHINERY EMERGENCY STOP SYSTEM ON SHIPS CONTROL CENTER "ESS-3"</p> <p><i>ESS-3 is for the ships purifiers, aux boiler, ME and AE oil pumps & incinerator</i></p>	<ol style="list-style-type: none"> 1. In-port test only 2. Ensure all of the items listed in results/remarks are energized or are operationally tested just prior to test. 3. Open glass protective test on bridge console and depress "ESS-3" emergency stop button 4. RESET 		<p>Verify the following items are secured or no longer have power:</p> <p>43D Power Dist Board 44D Power Dist Board Aux Boiler Control Panel F.O. Feed Unit No.1 & No. 2 M.E L.O. Pumps D.O. Transfer Pump L.O. Transfer Pump H.F.O. Transfer Pump D/G D.O Supply Pump No.1 through No.3 Prime Pump Incinerator</p>		
245.	<p>DEMONSTRATE EMERGENCY A/E STOP SYSTEM ON SHIPS CONTROL CENTER "ESS-4"</p>	<ol style="list-style-type: none"> 1. In-port test only 2. A/E Engines running and ships power being supplied via EDG 3. Open glass protective test on Ships Control console and depress "ESS-4" emergency stop button 4. RESET 		<p>All A/E Engines stop</p>		
249.	<p>DEMONSTRATE EMERGENCY IGG STOP SYSTEM ON SHIPS CONTROL CENTER "ESS-5"</p>	<ol style="list-style-type: none"> 1. In-port test only 2. IGG System running 3. Open glass protective test on Ships Control console and depress "ESS-5" emergency stop button 4. RESET 		<p>Verify the following items are secured or no longer have power:</p> <p>No.1 and No.2 IGS Fan I.G.S. F.O. Pump</p>		

MACHINERY SPACE FIRE DETECTION SYSTEM DETECTORS

LEVEL	SPACE			TYPE & Number	PROCEDURE	SAT	UNSAT
B-DECK	Engine Casing	Zone 2	Smoke 50	AFSW 51			
A-Deck	Engine Casing	Zone 2	Smoke 48	AFSW 49			
A-Deck	IGG Space	Zone 2	Smoke 46	AFSW 48			
A-Deck	EDG Space	Zone 1	Smoke65	AFSW 50			
Upper Deck	Engine Casing	(No Smoke Detectors)		AFT26			
Upper Deck	Engine Casing			AFT25			
Upper Level	ECR	Zone 2	Smoke 2	AFS121			
Upper Level	Store Room	Zone 2	Smoke 5	AFSW22			
Upper Level	Electricians Workshop	Zone 2	Smoke 7	AFSW23			
Upper Level	Workshop	Zone 2	Smoke 3	AFSW21			
Upper Level	E/R Aft of A/C	Zone 2	Smoke 16	AFSW28			
Upper Level	E/R Near Reefer	Zone 2	Smoke 17	AFSW39			
Upper Level	E/R Fwd M/E	Zone 2	Smoke 19	AF F			
Upper Level	E/R Aft M/E	Zone	Smoke 21	AFSW31			
Upper Level	E/R Above M/E	(Not a Smoke Detector)		AFSW32			
Upper Level	Incinerator	Zone 2	Smoke 14	AFSW30			
Lower Platform	Generator #3	Zone 2	Smoke 27				
Lower Platform	Generator Room	Zone 2	Smoke 26	AFSW36			
Lower Platform	Air Compressor Room	Zone 2	Smoke 29	AFSW37			
Lower Platform	Air Compressor Room MSD	Zone 2	Smoke 28	AFSW38			
Lower Platform	E/R Aft	Zone 2	Smoke 31	AFSW39			
Lower Platform	E/R Fwd	Zone 2	Smoke 32	AFSW40			
Lower Platform	E/R Port	Zone 2	Smoke 33	AFSW41			
Lower Level	E/R Port	Zone 2	Smoke 39	AFSW42			
Lower Level	E/R Stbd	Zone 2	Smoke 37	AFSW43			
Lower Level	E/R Aft	Zone 2	Smoke 38	AFSW44			
Steering Gear	Steering Gear Room Port	Zone 2	Smoke 9	AFSW24			
Steering Gear	Steering Gear Room Stbd	Zone 2	Smoke 11	AFSW25			
Steering Gear	Steering Gear Room (P) Store	Zone 2	Smoke 8	AFSW26			
Steering Gear	Steering Gear Room (S) Store	Zone 2	Smoke 12	AFSW27			

REPORT of MARINE CASUALTY, COMMERCIAL DIVING CASUALTY, or OCS-RELATED CASUALTY**Section I - Reporting Vessel/Facility Information**

1. Vessel or Facility Name SLNC Goodwill		2. Vessel Official Number or IMO Number 9448334		3. Vessel Flag US	
4. Vessel Length 183.2 <input type="checkbox"/> Feet <input checked="" type="checkbox"/> Meters		5. Vessel Gross Tons 30241		6. Vessel Propulsion Type MOTOR	
7. Vessel or Facility Type TANKSHIP		8. Vessel or Facility Service or Occupation MSC FAR EAST CHARTER			
9. FOR TOWING ONLY	9a. Arrangement:	9b. Number of Vessels Towed:		9c. Maximum Size of Tow/Tow-Boat(s):	
	<input type="checkbox"/> Pushing Ahead <input type="checkbox"/> Towing Astern <input type="checkbox"/> Towing Alongside	Empty _____ Loaded _____ Total _____		Length _____ feet Width _____ feet	
9d. Did one or more of the barges in the tow cause or sustain damage in the marine casualty? <input type="checkbox"/> Yes <input type="checkbox"/> No (If Yes complete and attach one or more CG-2692A forms to this report)					

Section II - Reason for Submitting this Report (Check all that apply)

10. The above vessel was involved in a Marine Casualty consisting in (46 CFR 4.05-1 and 4.05-10):

1. Unintended grounding or an unintended strike of (allision with) a bridge

2. Intended grounding or intended strike of a bridge that created a hazard to navigation, the environment or the safety of the vessel, or that meets any of the criteria in 3 through 8 below

3. Loss of main propulsion, primary steering, or any associated component or control system that reduces the maneuverability of the vessel

4. Occurrence materially and adversely affected the vessel's seaworthiness or fitness for service or route

5. Loss of life

6. Injury that requires professional medical treatment (treatment beyond first aid) and, if the person is engaged or employed on board a vessel in commercial service, that renders the individual unfit to perform his or her routine duties

7. Occurrence causing property damage in excess of \$75,000

8. Occurrence involving significant harm to the environment

11. The above facility or vessel was involved in a Commercial Diving Casualty involving (46 CFR 197.484):

1. Loss of life

2. Diving-related injury to any person causing incapacitation for more than 72 hours

3. Diving-related injury to any person requiring hospitalization for more than 24 hours

12. The above facility or vessel was involved in an OCS Facility Casualty Resulting in (33 CFR 146.30 and 146.35):

1. Death

2. Injury to 5 or more persons in a single incident

3. Injury causing any person to be incapacitated for more than 72 hours

4. OCS Facility only - Damage affecting the usefulness of primary lifesaving or firefighting equipment

5. OCS Facility only - Damage to the facility exceeding \$25,000 resulting from a collision by a vessel with the facility

6. OCS Facility only - Damage to a floating OCS facility exceeding \$25,000

Section III - Associated Parties Information (Fill all fields that apply)

13. Name of Owner NORD GOODWILL LLC		Telephone		14. Name of Operator or Manager Schuyler Line Navigation Co		Telephone 14102166020	
Address 2711 CENTERVILL RD STE 400 WILMINGTON, DE 19808 United States		Email address		Address (b) (7)(C), (b) (6)		Email address (b) (6), (b) (7)(C)	
15. Name of Master or Person in Charge (Last, First, Middle) (b) (6), (b) (7)(C)		Telephone (b) (6), (b) (7)(C)		16. Name of Agent (Last, First, Middle)		Telephone	
Address Same as block 14		Email address (b) (6), (b) (7)(C)		Address		Email address	
17. Name of Dive Supervisor (Last, First, Middle)		Telephone		18. Name of Pilot (Last, First, Middle)		Telephone	
Address		Email address		Address		Email address	

Section IV - Casualty Information

19. Date/Time (local) of Occurrence 2020 August 5 1342		20. Location-Name of Body of Water or Waterway: Latitude: 32-29N Sea of Japan		River Mile Marker: OR	
21. Property Damage Estimated Damage Cost(s) to: Vessel: \$500000 Cargo: \$ _____ Facility: \$ _____ Other: \$ _____		Describe the Extent of Property Damage #1 SSDG loss, damage to ships systems and bulk heads above and below the #1 SSDG.			
22. Status of Involved Persons (If there are 1 or more injured, dead or missing persons complete and attach one or more CG-2692C forms to this Report)					
Total Number of Persons:		On Board the Vessel: 20		Injured: 0	
		Dead: 1		Missing: _____	

Section IV - Casualty Information (continued)

23. Was This Casualty a Serious Marine Incident (SMI) as Defined in 46 CFR 4.03-27

Yes No Not at this Time, But is Likely to Become an SMI (If Yes or is Likely to Become an SMI complete/attach one or more CG-2692B forms to this report)

24a. Is there any evidence of alcohol or drug use by or intoxication of individuals directly involved in the casualty?

Yes No (If Yes, identify those individuals for whom evidence has been obtained and specify the method to obtain such evidence in block 24c)

24b. Did any individual directly involved in a casualty refuse to submit to, or cooperate in, the administration of a timely chemical test, when directed by a law enforcement officer or by the marine employer?

Yes No (If Yes, note the individual(s) who refused in block 24c)

24c. Individuals with evidence of drug or alcohol use, evidence of intoxication, or who refused to submit/cooperate in a timely chemical test (if more space is needed, continue in block 25c)

NA

24d. Is there evidence that alcohol use contributed to this casualty?

Yes No (If Yes, discuss in block 25b)

25. Nature and Circumstance of the Casualty:

25a. Activity or Operation Being Conducted at the Time of the Casualty:

#1 SSDG was being returned to service by Chief Engineer, 1AE, and 3AE. The governor was being replaced with a shore reconditioned spare. During start up and testing, #1 SSDG started to over speed and runaway causing the flywheel to disintegrate. The electronic and mechanical over speed devices failed to stop the #1 SSDG. The debris from this caused fatal blunt force trauma to the 3AE, and a loss of ship's power, and damage to the surrounding spaces.

25b. Description of the Casualty (casualty events and the conditions and actions that were believed to be causal factors as well as any hazards created as a result of the casualty. Attach additional sheets if necessary.):

The #1 SSDG flywheel caused damage to the bulkheads and spaces above below and beside the 1/2 Generator room. 1342 LT (JST) the ship lost main power and propulsion. The ship's Emergency Diesel Generator went on-line. The ship's Fire and Emergency signal was sounded and crew mustered for response.

No fire was found in the E/R spaces. But structural damage to the bulkheads and a severely injured crewmember the 3AE. The 3AE was evacuated to the ship's hospital, Medical Alert Services activated, and medical treatment begun. Immediately the Master called Japan Coast Guard to report an casualty and emergency and request medical evacuation. Injured 3AE was medevac'd by Japanese Coast Guard Helicopter at 1725(JST).

The damage to the SSDG's and control systems left the vessel without power and adrift. The ship's crew worked to restore power to the #3 SSDG and then restore propulsion.

Attached timeline of events for the vessel:

Attached timeline of events from Medical Advisory Service:

Attached witness statement's already provided to USCG inspectors.

25c. Any other comments, including with respect to use of or need for emergency response equipment:

While vessel was adrift working to restore power the set of the vessel was bringing it towards land approximately 10nm away. Japanese Coast Guard dispatched a patrol cutter to our location. To provide emergency tow if necessary if the vessel was in imminent danger. A tug boat was dispatched at the master's request to aid the vessel and provide emergency towing if necessary. A favorable shift in currents provided the vessel's crew time to restore power and propulsion and proceed to a safe harbor. Once propulsion was restored the vessel proceeded to rendez-vous with the the dispatched tug boat, and proceed under escort to the nearest safe port

Section V - Person Making this Report

24. Name (PRINT) (Last, First, Middle) (b) (6), (b) (7)(C)	25. Signature: (b) (6), (b) (7)(C)	26. Date 8/09/2020
27. Title Master	28. Address (b) (6), (b) (7)(C)	United States
29. Telephone No. (b) (6), (b) (7)(C)	30. Email (b) (6), (b) (7)(C)	

INSTRUCTIONS FOR COMPLETION OF FORM CG-2692
REPORT OF MARINE CASUALTY, COMMERCIAL DIVING CASUALTY, OR OCS-RELATED CASUALTY

An agency may not conduct or sponsor, and a person is not required to respond to a collection of information unless it displays a valid OMB control number. The Coast Guard estimates that the average burden for this report is 1 hour. You may submit any comments concerning the accuracy of this burden estimate or any suggestions for reducing the burden to: Commandant (CG-INV), U.S. Coast Guard Stop 7501, 2703 Martin Luther King Jr Ave SE, Washington, DC 20583-7501 or Office of Management and Budget, Paperwork Reduction Project (1625-0001), Washington, DC 20503.

WHEN TO USE THIS FORM

1. This form satisfies the requirement for written reports of casualties and accidents found in the Code of Federal Regulations for vessels, commercial diving operations, and Outer Continental Shelf (OCS) facilities. Depending on the circumstances surrounding an incident, a written report may be required if it meets one or more of the conditions described in instructions 2 - 4.
2. **VESSELS.** If you are the owner, agent, master, operator, or person in charge of a vessel, other than a public vessel or an uninspected recreational or state-numbered vessel, you must submit a report if your vessel:
 - A. is involved in a marine casualty or accident that occurs upon the navigable waters of the United States, its territories or possessions and meets any of the criteria in block 10, or
 - B. is a United States vessel involved in a marine casualty or accident, wherever such casualty or accident occurs, that meets any of the criteria in block 10, or
 - C. is a foreign vessel engaged in OCS activities as defined in 33 CFR 140.10 and is involved in a marine casualty or accident that meets any of the criteria in block 10, or
 - D. is a foreign tank vessel operating in waters subject to the jurisdiction of the United States, including the Exclusive Economic Zone (EEZ), which involves significant harm to the environment or material damage affecting the seaworthiness or efficiency of the vessel.
3. **DIVING.**
 - A. **Commercial Diving.** If you are the master or person in charge of a vessel or facility from which a commercial diving operation is conducted: (1) at any deepwater port or the safety zone thereof as defined in 33 CFR Part 150; (2) from any artificial island, installation, or other device on the Outer Continental Shelf (OCS) and the waters adjacent thereto as defined in 33 CFR Part 147 or otherwise related to activities on the OCS; (3) from any vessel required to have a certificate of inspection issued by the Coast Guard, including mobile offshore drilling units, regardless of their geographic location; or (4) from any vessel connected with a deepwater port or within the deepwater port safety zone or from any vessel engaged in activities related to the OCS, you must submit a report if there is a diving casualty meeting the criteria in block 11, except if the diving operation is:
 1. performed solely for marine scientific research and development purposes by educational institutions,
 2. performed solely for research and development for the advancement of diving equipment and technology, or
 3. performed solely for search and rescue or related public safety purposes by or under the control of a governmental agency.
 - B. **All Other Diving.** Any occurrence of injury or loss of life to any person while diving from a vessel subject to instruction 2 and using underwater breathing apparatus must be reported under instruction 2.
4. **OUTER CONTINENTAL SHELF (OCS) FACILITIES.** If you are the owner, operator, or person in charge of an OCS facility engaged in OCS activities as defined in 33 CFR 140.10, you must submit a report if your facility is involved in a casualty or accident that meets any of the criteria in block 12.

COMPLETION OF THIS FORM

5. In accordance with 46 CFR §4.05-10, 46 CFR §197.486, and 33 CFR §146.35, this form shall be filled out as completely and accurately as possible. Please type or print clearly. Fill in all blanks that apply to the kind of accident that has occurred. If a block is not applicable, the abbreviation "NA" should be entered in that space. If the answer is unknown and cannot be obtained before the report has to be submitted (i.e. within 5 days of the accident), the abbreviation "UNK" should be entered in that block. If "NONE" is the correct response, enter it in the block.
6. Once completed, deliver, email, or fax this form within 5 days of the casualty to the Coast Guard Sector, Marine Safety Unit, or Activity nearest the location of the casualty or, if at sea, nearest the arrival port. <http://www.uscg.mil/top/units/>
7. Tugs or towboats with tows under their control shall complete blocks 9a through 9d and, if one or more barges in their tow causes or sustains damage or meets any other reporting criteria, use the "Barge Addendum," CG-2692A to report information on the barge(s) involved.
8. If an incident involves multiple barges suffering or causing damage while moored or anchored (such as in a fleeting area), or breaking away from their moorage and causing or sustaining damage, enter the location of the moorage in Block 1 of the CG-2692 and complete the form except for blocks 2-8. Details for the barges will be entered on the CG-2692A. If a single barge is involved in a marine casualty while moored or anchored, it shall be documented as any other vessel using the CG-2692.
9. If the casualty meets the criteria for a serious marine incident as defined in 46 CFR §4.03, use the "Chemical Drug and Alcohol Testing Addendum," CG-2692B to report information on required drug and alcohol testing following a serious marine incident.
10. If one or more persons on the vessel or facility were injured, killed, or missing as a result of the casualty, use the "Personnel Casualty" Addendum," CG-2692C to report information on the extent of all personnel casualties.
11. For facilities and vessels engaged in OCS activities who are reporting a casualty in accordance with 33 CFR §146.35 or 33 CFR §146.303, use the "Involved Persons and Witnesses Addendum," CG-2692D to provide a list of all involved persons and witnesses to the casualty being reported. The CG-2692D may also be used to provide data on persons involved or witnessing a marine casualty or commercial diving casualty.
12. **Block 20 - "Location":** Always identify the body of water or waterway. Latitude and longitude to the nearest tenth of a minute should always be entered except in those rivers and waterways where a mile marker system is commonly used. In those cases, the mile number to the nearest tenth of a mile should be entered. If the latitude and longitude, or mile number, are unknown, reference to a known landmark or object (buoy, light, etc.) with distance and bearing to the object is permissible.

Privacy Act Notice

(CG-2692, CG-2692A, CG-2692B, CG-2692C and CG-2692D)

Authority: Title 46, United States Code (U.S.C.) §5301, Title 46, Code of Federal Regulations (CFR), Parts 4 and 197, and Title 33, CFR Part 146 authorizes the collection of this information. Specifically, 46 CFR §4.05-10 mandates that vessel owners, agents, masters, operators, or persons in charge file a written report of any marine casualty required to be reported under 46 CFR §4.05-1, 46 CFR §197.486 mandates that persons in charge of vessels or facilities file a report of any diving casualty required to be reported under 33 CFR §197.484, and 46 CFR §146.35 mandates that owners, operators, or persons in charge of an OCS facility or vessel engaged in OCS activities file a report of any OCS-related casualty required to be reported under 33 CFR §146.30. For marine casualties, diving casualties when the diving installation is on a vessel, and The written report must be provided on Form CG-2692 (Report of Marine Casualty, Commercial Diving Casualty, or OCS-Related Casualty) supplemented as necessary by appended Forms CG-2692A (Barge Addendum), CG-2692B (Chemical Drug and Alcohol Testing Addendum), CG-2692C (Personnel Casualty Addendum), and CG-2692D (Involved Persons and Witnesses Addendum). The forms may be used for diving casualties when the diving installation is on a facility or for OCS-related casualties that are not also marine casualties under 46 CFR Part 4.

Purpose: The Coast Guard uses this information in gathering facts to determine causes surrounding reportable marine casualties. This information assists in promoting the safety of life, property, and the protection of the marine environment through preventing the recurrence of accidents.

Routine Uses: Reportable marine casualty information is needed for Coast Guard investigations of vessel casualties involving injury, death, property damage, environmental damage and dangerous conditions and for preparation and submission of data reports mandated by Congress (see 46 U.S.C. 6301). Information gathered is also used to determine whether new or revised safety laws, regulations, and policies are necessary. Additionally, chemical testing information is needed to improve Coast Guard detection and reduction of drug use by mariners. The information contained on forms CG-2692, CG-2692A, CG-2692B, CG-2692C, and CG-2692D may be disclosed under the Freedom of Information Act (FOIA) in response to a written FOIA request.

Disclosure: Furnishing this information is mandatory per 46 CFR §4.05-10. Failure to furnish the requested information for occurrences that are reportable marine casualties, diving casualties, or OCS-related casualties may result in civil penalty sanctions as outlined in 33 CFR Part 1. Coast Guard credentialed mariners may be subject to administrative adjudication per 46 CFR Part 5 for reporting failures. Some of the casualty information collected on this form may be made available for public inspection; however, information collected is protected from use in civil litigation per 46 U.S.C. §6308. Personal privacy information will not be disclosed routinely. Social Security numbers are not mandated on this form.

DEPARTMENT OF HOMELAND SECURITY
U.S. Coast Guard
PERSONNEL CASUALTY ADDENDUM

OMB No: 1625-0001
Exp. Date: 07/31/2022

Note: This form shall be used to report data on persons who were injured, killed, or are missing as a result of the marine casualty described on form CG-2692.
This form may only be used in addition to form CG-2692, never alone.

Section I - Reporting Vessel/Facility Information - Casualty Date/Time

1. Vessel or Facility Name SLNC GOODWILL	2. Date/Time (local) of Occurrence 2020AUG05 1342 LT
---	---

Section II - Injured, Dead, and Missing Person Details

3a. Name (Last, First, Middle) Lloyd-Rees, Trenton David	3b. Relationship to Vessel or Facility <input checked="" type="checkbox"/> Crew - Position: 3rd Assistant Engineer <input type="checkbox"/> Passenger <input type="checkbox"/> Other - Describe: _____	3c. Status <input type="checkbox"/> Injured <input checked="" type="checkbox"/> Dead <input type="checkbox"/> Missing
3d. Address (b) (6), (b) (7)(C)		

3e. Telephone 1-(b) (7)(C), (b) (6)	3f. Email Address	3g. For Crew - On Duty at Time? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	3h. Date of Birth (b) (7)(C), (b) (6)	3i. Date of Death 08/05/2020
--	-------------------	--	--	---------------------------------

3j. Activity of Person at Time of Casualty: Conducting Generator Repairs to #1 SSDG

3k. Location on Vessel or Facility Where Casualty Occurred: 1/2 AE Generator Room

3l. Extent of Injuries to Person (Parts of Body and Type of Injuries): Blunt force trauma to head and neck

4a. Name (Last, First, Middle)	4b. Relationship to Vessel or Facility <input type="checkbox"/> Crew - Position: _____ <input type="checkbox"/> Passenger <input type="checkbox"/> Other - Describe: _____	4c. Status <input type="checkbox"/> Injured <input type="checkbox"/> Dead <input type="checkbox"/> Missing
4d. Address		

4e. Telephone	4f. Email Address	4g. For Crew - On Duty at Time? <input type="checkbox"/> Yes <input type="checkbox"/> No	4h. Date of Birth	4i. Date of Death
---------------	-------------------	---	-------------------	-------------------

4j. Activity of Person at Time of Casualty:

4k. Location on Vessel or Facility Where Casualty Occurred:

4l. Extent of Injuries to Person (Parts of Body and Type of Injuries):

5a. Name (Last, First, Middle)	5b. Relationship to Vessel or Facility <input type="checkbox"/> Crew - Position: _____ <input type="checkbox"/> Passenger <input type="checkbox"/> Other - Describe: _____	5c. Status <input type="checkbox"/> Injured <input type="checkbox"/> Dead <input type="checkbox"/> Missing
5d. Address		

5e. Telephone	5f. Email Address	5g. For Crew - On Duty at Time? <input type="checkbox"/> Yes <input type="checkbox"/> No	5h. Date of Birth	5i. Date of Death
---------------	-------------------	---	-------------------	-------------------

5j. Activity of Person at Time of Casualty:

5k. Location on Vessel or Facility Where Casualty Occurred:

5l. Extent of Injuries to Person (Parts of Body and Type of Injuries):

6a. Name (Last, First, Middle)	6b. Relationship to Vessel or Facility <input type="checkbox"/> Crew - Position: _____ <input type="checkbox"/> Passenger <input type="checkbox"/> Other - Describe: _____	6c. Status <input type="checkbox"/> Injured <input type="checkbox"/> Dead <input type="checkbox"/> Missing
6d. Address		

6e. Telephone	6f. Email Address	6g. For Crew - On Duty at Time? <input type="checkbox"/> Yes <input type="checkbox"/> No	6h. Date of Birth	6i. Date of Death
---------------	-------------------	---	-------------------	-------------------

6j. Activity of Person at Time of Casualty:

6k. Location on Vessel or Facility Where Casualty Occurred:

6l. Extent of Injuries to Person (Parts of Body and Type of Injuries):

7a. Name (Last, First, Middle)	7b. Relationship to Vessel or Facility <input type="checkbox"/> Crew - Position: _____ <input type="checkbox"/> Passenger <input type="checkbox"/> Other - Describe: _____	7c. Status <input type="checkbox"/> Injured <input type="checkbox"/> Dead <input type="checkbox"/> Missing
7d. Address		

7e. Telephone	7f. Email Address	7g. For Crew - On Duty at Time? <input type="checkbox"/> Yes <input type="checkbox"/> No	7h. Date of Birth	7i. Date of Death
---------------	-------------------	---	-------------------	-------------------

7j. Activity of Person at Time of Casualty:

7k. Location on Vessel or Facility Where Casualty Occurred:

7l. Extent of Injuries to Person (Parts of Body and Type of Injuries):

Enclosure: CG-03 page 1 of 2
Case# 1229748
ECN 7025155-(b) (6), (b) (7)(C) 003

**INSTRUCTIONS FOR COMPLETION OF FORM CG-2692C
PERSONNEL CASUALTY ADDENDUM**

Note: This form shall be used to report data on persons who were injured, killed, or missing as a result of the marine casualty described on form CG-2692. This form may only be used in addition to form CG-2692, never alone.

An agency may not conduct or sponsor, and a person is not required to respond to a collection of information unless it displays a valid OMB control number. The Coast Guard estimates that the average burden for this report is .5 hours. You may submit any comments concerning the accuracy of this burden estimate or any suggestions for reducing the burden to: Commandant (CG-INV), U.S. Coast Guard Stop 7501, 2703 Martin Luther King Jr Ave SE, Washington, DC 20593-7501 or Office of Management and Budget, Paperwork Reduction Project (1625-0001), Washington, DC 20503.

WHEN TO USE THIS FORM

1. This form, when submitted in conjunction with a CG-2692, satisfies the requirement for written reports of casualties found in the Code of Federal Regulations for vessels. Specifically, it provides information on one or more persons who were injured, dead or missing as a result of their involvement in a reportable marine casualty, commercial diving casualty, or an OCS-related casualty. This form may only be used in addition to form CG-2692, never alone.

DEFINITIONS

2. Loss of Life - a life is considered lost when the person is known to be deceased (e.g. the body has been recovered), the person has been categorized as "presumed lost/dead" by agencies leading search and rescue efforts, or the circumstances of the occurrence make recovery of the person alive unlikely.

3. Injury - defined as damage or harm caused to the structure or function of the body as a result of an outside physical agent. Damage or harm caused exclusively by animal/insect bites/scratches is excluded. Pursuant to the Occupational Safety and Health Administration's (OSHA) definition of "injury or illness" in 29 CFR 1904.46, the Coast Guard considers injuries and illnesses as separate types of occurrences. As such, damage or harm caused by illness, including but not limited to: communicable illness (i.e. colds, flu, etc.), food poisoning, heart attack, stroke, or other pre-existing medical condition is not considered an injury and does not fall under this criterion.

COMPLETION OF THIS FORM

4. In accordance with 46 CFR §4.05-10, 46 CFR §197.486, and 33 CFR §146.35 this form shall be filled out as completely and accurately as possible. Please type or print clearly. Fill in all blanks that apply to the kind of casualty that has occurred. If a block is not applicable, the abbreviation "NA" should be entered in that space. If the answer is unknown and cannot be obtained before the report has to be submitted (i.e. within 5 days of the accident), the abbreviation "UNK" should be entered in that block. If "NONE" is the correct response, enter it in the block.

5. If more than 5 individuals were injured, dead, or missing as a result of the marine casualty additional CG2692Cs should be completed.

6. Once completed, deliver, email, or fax this form with a corresponding CG-2692 within 5 days of the casualty to the Coast Guard Sector, Marine Safety Unit, or Activity nearest the location of the casualty or, if at sea, nearest the arrival port. <https://www.uscg.mil/Units/Organization>

NOTICE: The information collected on this form is routinely available for public inspection. It is needed by the Coast Guard to carry out its responsibility to investigate marine casualties, to identify hazardous conditions or situations and to conduct statistical analysis. The information is used to determine whether new or revised safety initiatives are necessary for the protection of life or property in the marine environment.

MV SLAVE GOODWILL VOY NO. 338 MARSEC LVL: 1 FROM APRA HARBOR GUAM TOWARDS DANSAN, ROK DATE SAT 1 AUG 2020 ZD 10

HR	COURSE			WIND		SEA		SWELL		TEMPERATURES		BAR	SKY/WX
	BASE DEG	DYNO	STEER	DIR	FORCE	DIR	FEET	DIR	FEET	DRY	WET		
0100													
0200	318	317	316	E	4	E	2	NE	3	29	26	1005	M'CLDY
0300													
0400	318	320	320	EM	4	E	2	NE	3	29	26	1007	M'CLDY
0500													
0600	318	322	321	E	4	E	3	NE	2	30	27	1008	P'CLDY
0700													
0800	318	321	320	E	4	E	4	ENE	2	31	28	1008	P'CLDY
0900													
1000	318	321	316	E	4	E	4	ENE	3	33	29	1009	P'CLDY
1100													
1200	318	321	316	E	3	E	3	ENE	3	34	29	1009	M'CLDY
1300													
1400	318	322	316	E	3	E	3	E	3	31	29	1009	P'CLDY
1500													
1600	318	317	311	E	3	E	3	E	3	32	29	1008	P'CLDY
1700													
1800	318	321	321	E	3	E	3	ENE	3	32	28	1008	P'CLDY
1900													
2000	318	321	321	ENE	3	NE/E	3	SE/E	3	30	27	1007	P'CLDY
2100													
2200	318	320	321	E	4	E	2	E	3	29	25	1010	CLEAR SKY
2300													
2400	318	320	321	E	3	E	2	E	3	29	25	1010	CLEAR SKY

ARRIVAL/DEPARTURE MOON	NOON	POSITION	DRAFT	FWD	AFT	MEAN	DENSITY
L 16-50 39.4	141-30 22.6	LD 24	12.0	6.0	8.3	7.1	1.025

Running Time	TOTAL/PASSAGE		TIME ON/TIME OFF	DECK WATCH/LOOKOUT	
	DAILY	TOTAL		OFFICER	COOK
Observed Distance	176	170	0600/0400	(b) (6), (b) (7)(C)	
Average Speed	14.2	14.2	0400/0800	(b) (6), (b) (7)(C)	
Fuel Departure	-	-	201/120	(b) (6), (b) (7)(C)	
Fuel 0800/Noon	735.7	-	1200/1600	(b) (6), (b) (7)(C)	
Fuel Consumed	3.1	3.1	1600/2000	(b) (6), (b) (7)(C)	
Fuel Arrival	-	-	200/120	(b) (6), (b) (7)(C)	
Libres 0800/Noon	403.8	-		(b) (6), (b) (7)(C)	
Libres Consumed	130	130		(b) (6), (b) (7)(C)	
Water 0800/Noon	343	-		(b) (6), (b) (7)(C)	
Water Consumed	81	81		(b) (6), (b) (7)(C)	
Water Arrival	-	-		(b) (6), (b) (7)(C)	

TESTS, DRILLS & INSPECTIONS
 1200 IAW BR 215.1 AND 41 CFR 199.190 COMPLETED DAILY MORNING TEST OF THE SHIPS WHISTLES AND GENERAL ALARM CLOCKS SYNCED ALL IN GOOD ORDER (b) (6), (b) (7)(C)

EVENTS AND REMARKS
 Watch Condition 1 unless otherwise stated in this section

0000 3/m (b) (6), (b) (7)(C) ON WATCH IAW BPG 8-16 W/O EXCEPTION. FIRE SECURITY ROUND MADE PRIOR TO ASSUMING THE WATCH. 0400 VSL IN EASY MOTION LT ENELY WIND. SEA NEELY SWELL GOOD VIS NO TRAFFIC. WLT HELM IN AUTO SECURITY MAINTAINED. RLVD BY 3/m (b) (6), (b) (7)(C)

0400 2/m (b) (6), (b) (7)(C) ASSUMES THE WATCH IAW BPG 8-16 W/O EXCEPTIONS. FIRE AND SECURITY ROUND MADE PRIOR TO ASSUMING THE WATCH. 0800 VESSEL IN EASY MOTION IN LIGHT ELY SEAS AND WINDS WITH LOW ENELY SWELL. GOOD VISIBILITY W/ LT TRAFFIC. HELM IN AUTO. SECURITY MAINTAINED. RELIEVED PER SMS BY (b) (6), (b) (7)(C)

1200 3/m (b) (6), (b) (7)(C) UNDER THE WATCH IAW BPG 8-16 W/O EXCEPTION. FIRE AND SECURITY ROUND MADE PRIOR TO ASSUMING THE WATCH. 0444 LPU 101 RPM, A PER CAPT. 1256 LPU 120 RPM. 1200 VESSEL IN EASY MOTION WITH LIGHT ELY WINDS AND SEA. ENELY SWELL. GOOD VISIBILITY WITH NO TRAFFIC. WLT HELM IN AUTO. RELIEVED BY 3/m (b) (6), (b) (7)(C)

1200 3/m (b) (6), (b) (7)(C) ASSUMES THE WATCH IAW BPG 8-16 W/O EXCEPTION. FIRE SECURITY ROUND MADE PRIOR TO ASSUMING THE WATCH. 1600 VSL IN EASY MOTION LT ENELY WIND. SEA, ELY SWELL GOOD VIS NO TRAFFIC. WLT HELM IN AUTO. SECURITY MAINTAINED. RELIEVED BY 3/m (b) (6), (b) (7)(C)

1600 2/m (b) (6), (b) (7)(C) ASSUMES THE WATCH IAW BPG 8-16 W/O EXCEPTIONS. FIRE AND SECURITY ROUND MADE PRIOR TO ASSUMING THE WATCH. 1916 ↓ REDUCE SPEED TO FULL AHEAD. 2000 VESSEL ROLLING IN EASY MOTION IN LIGHT NEELY SEAS, ENELY WINDS AND LOW SEELY SWELL. GOOD VISIBILITY WITH NO TRAFFIC. HELM IN AUTO. SECURITY MAINTAINED. WLT. PROPERLY RELIEVED PER SMS BY 3/m (b) (6), (b) (7)(C)

2000 3/m (b) (6), (b) (7)(C) ASSUMES THE WATCH IAW BPG 8-16 W/O EXCEPTION. FIRE AND SECURITY ROUND MADE PRIOR TO ASSUMING THE WATCH. 2014 LPU 120 RPM'S. 2400 VESSEL IN EASY MOTION. TIMELY ROLL IN LIGHT ELY AND SEA. SEA AND SWELL. GOOD VISIBILITY WITH NO TRAFFIC. WLT HELM IN AUTO. SECURITY MAINTAINED. RELIEVED BY 3/m (b) (6), (b) (7)(C)

CHIEF OFFICER (b) (6), (b) (7)(C) PAGE NO. 001

HR	COURSE			ERROR		WIND		SEA		SWELL		TEMPERATURES		DAR	SKY/WX
	BASE DEG	GYRO	STEER	GYRO	DIR	FORCE	DIR	FEET	DIR	FEET	DRY	WET			
0100															
0200	318	310	317		E	2	ENE	2	ENE	3	29	35	1009	P'CLDY	
0300															
0400	318	320	324		E	3	ENE	3	ENE	3	29	25	1009	CLEAR	
0500															
0600	318	314	320		ESE	3	ESE	3	SSE	3	28	24	1005	P'CLDY	
0700															
0800	318	320	321		E	1	E	1	SW/NE	3/3	30	26	1010	P'CLDY	
0900															
1000	318	317	317		E	2	ENE	2	ENE	3	32	30	1010.5	O'CAST	
1100															
1200	318	317	317		ENE	2	ENE	2	NE	4	33	30	1010.5	O'CAST	
1300															
1400	318	320	322		E	3	E	3	E	4	32	27	1010	A'LLDY	
1500															
1600	318	320	322		ESE	3	E	3	E	4	32	27	1007	M'LAY Hazy	
1700															
1800	318	317	318		E	3	E	2	ESE	4	31	25	1010	HAZE/O'CAST	
1900															
2000	318	317	318		ENE	3-4	E	2	ESE	4	30	25	1010	HAZE/O'CAST	
2100															
2200	318	317	322		ENE	2	E	2	NE	3	29	25	1011	SHRZY O'CAST	
2300															
2400	318	317	322		NE	2	E	2	NE	3	29	25	1011.5	SHRZY O'CAST	

ARRIVAL/DEPARTURE/NOON	<u>NOON</u>	POSITION	DRAFT	PWD	AFT	MEAN	DENSITY
<u>L</u>	<u>21-12.17 N</u>	<u>137-25.58 E</u>	<u>LOD 24</u>	<u>6.0</u>	<u>8.3</u>	<u>2.1</u>	<u>1.025</u>

	DAILY		TOTAL/PASSAGE		DECK WATCH/DROKOUT	
	Running Time	Observed Distance	Observed Distance	Time On/Time Off	OFFICER	CREW
Running Time	24	43	350	0000/0400	(b) (6), (b) (7)(C)	(b) (6), (b) (7)(C)
Observed Distance	350	430	0400/0600			
Average Speed	14.6	14.4	0700/1200			
Fuel Departure			1200/1600			
Fuel 0600/Noon	692.6		1600/2000			
Fuel Consumed	433	74.4	2000/2400			
Fuel Arrival						
Lubes 0600/Noon	3848					
Lubes Consumed	190	320				
Water 0600/Noon	356					
Water Consumed	38	119				
Water Arrival						

TESTS, DRILLS & INSPECTIONS

1200 JAW BAI 2:15 AM 46 CFR 149.190 COMPLETED DAILY NOON TEST OF THE SHIPS WHISTLES AND GENERAL ALARM CLOCKS SYNCED. ALL IN GOOD ORDER **(b) (6), (b) (7)(C)**

1400 JAW BAI 2:30 AM 46 CFR 33.1015 VESSEL EDC WAS OILCAGED AND A VESSEL TEST OF RESISTANCE MANEUVER ALL IN GOOD ORDER **(b) (6), (b) (7)(C)**

1500 JAW 46 CFR 160.40 AND 160.41 WENT VESSEL TEST OF SURVIVAL EQUIP LIFEBOOT AND LIFELINE. ALL EQUIP OPERATIONAL AND IN GOOD ORDER

1500 JAW 46 CFR 160.40 AND 160.41 WENT VESSEL TEST OF SURVIVAL EQUIP LIFEBOOT AND LIFELINE. ALL EQUIP OPERATIONAL AND IN GOOD ORDER

1500 JAW 46 CFR 160.40 AND 160.41 WENT VESSEL TEST OF SURVIVAL EQUIP LIFEBOOT AND LIFELINE. ALL EQUIP OPERATIONAL AND IN GOOD ORDER

EVENTS AND REMARKS Watch Condition 1 unless otherwise stated in this section

0000 3/M **(b) (6), (b) (7)(C)** ASSUMES THE WATCH JAW BPG-BIG W/O EXCEPTION. FIRE + SECURITY ROUND MADE PRIOR TO ASSUMING THE WATCH. GOOD VESSEL IN EAST MOTION LT ELY

0400 **(b) (6), (b) (7)(C)** ASSUMES THE WATCH LAW BPG-BIG W/O EXCEPTIONS. FIRE AND SECURITY ROUND MADE PRIOR TO ASSUMING THE WATCH. GOOD VESSEL IN EAST MOTION LT ELY

0600 **(b) (6), (b) (7)(C)** ASSUMES THE WATCH LAW BPG-BIG W/O EXCEPTIONS. FIRE AND SECURITY ROUND MADE PRIOR TO ASSUMING THE WATCH. GOOD VESSEL IN EAST MOTION LT ELY

0800 **(b) (6), (b) (7)(C)** ASSUMES THE WATCH LAW BPG-BIG W/O EXCEPTIONS. FIRE AND SECURITY ROUND MADE PRIOR TO ASSUMING THE WATCH. GOOD VESSEL IN EAST MOTION LT ELY

1000 **(b) (6), (b) (7)(C)** ASSUMES THE WATCH LAW BPG-BIG W/O EXCEPTIONS. FIRE AND SECURITY ROUND MADE PRIOR TO ASSUMING THE WATCH. GOOD VESSEL IN EAST MOTION LT ELY

1200 **(b) (6), (b) (7)(C)** ASSUMES THE WATCH LAW BPG-BIG W/O EXCEPTIONS. FIRE AND SECURITY ROUND MADE PRIOR TO ASSUMING THE WATCH. GOOD VESSEL IN EAST MOTION LT ELY

1400 **(b) (6), (b) (7)(C)** ASSUMES THE WATCH LAW BPG-BIG W/O EXCEPTIONS. FIRE AND SECURITY ROUND MADE PRIOR TO ASSUMING THE WATCH. GOOD VESSEL IN EAST MOTION LT ELY

1600 **(b) (6), (b) (7)(C)** ASSUMES THE WATCH LAW BPG-BIG W/O EXCEPTIONS. FIRE AND SECURITY ROUND MADE PRIOR TO ASSUMING THE WATCH. GOOD VESSEL IN EAST MOTION LT ELY

1800 **(b) (6), (b) (7)(C)** ASSUMES THE WATCH LAW BPG-BIG W/O EXCEPTIONS. FIRE AND SECURITY ROUND MADE PRIOR TO ASSUMING THE WATCH. GOOD VESSEL IN EAST MOTION LT ELY

2000 **(b) (6), (b) (7)(C)** ASSUMES THE WATCH LAW BPG-BIG W/O EXCEPTIONS. FIRE AND SECURITY ROUND MADE PRIOR TO ASSUMING THE WATCH. GOOD VESSEL IN EAST MOTION LT ELY

2200 **(b) (6), (b) (7)(C)** ASSUMES THE WATCH LAW BPG-BIG W/O EXCEPTIONS. FIRE AND SECURITY ROUND MADE PRIOR TO ASSUMING THE WATCH. GOOD VESSEL IN EAST MOTION LT ELY

2400 **(b) (6), (b) (7)(C)** ASSUMES THE WATCH LAW BPG-BIG W/O EXCEPTIONS. FIRE AND SECURITY ROUND MADE PRIOR TO ASSUMING THE WATCH. GOOD VESSEL IN EAST MOTION LT ELY

1015 (Rev. 6/18)
PROforma (100) 524-9837

MV SLMC GOODWILL VOY NO. 238 MARSEC LVL: 1 FROM APRA HARBOR, GUAM TOWARDS O/SAN, ROK DATE MON 3 AUG 2020 ZD 10

HR	COURSE			ERROR		WIND		SEA		SWELL		TEMPERATURES		BAR	SKY/WX	EVENTS AND REMARKS
	BASE	CRS	GYRO	GYRO	DR	DR	DR	FEET	DR	FEET	DRY	WET				
0100																
0200	318	319	322			N	2	E	1	E	3	28	24	1011	P'CLDY	0000 3M (b) (6), (b) (7)(C) ON WATCH PER 1326 HRZ ^M B-16 W/O EXCEPTION. FIRE & SECURITY ROUND
0300																
0400	318	321	323			N	3	E	1	E	3	28	24	1010	P'CLDY	MADE PRIOR TO ASSUMING THE WATCH 0400 VSL IN EASY MOTION. LT NNE'LY WIND
0500																
0600	318	321	323			ESE	3	E	1	E	3	28	24	1010	P'CLDY	E'LY SEA/SWELL GOOD VLS NO TRAFFIC W/2 HELM IN AUTO SECURITY MAINT. RVD BY (b) (6), (b) (7)(C)
0700																
0800	318	319	322			SE	3	SE	1	E	3	30	26	1010	P'CLDY	0400 (b) (6), (b) (7)(C) ASSUMES THE WATCH IAW BRG-B16 W/O EXCEPTIONS. FIRE AND SECURITY
0900																
1000	318	319	323			ESE	4	SE	3	S	3	33	26	1010.5	P'CLDY	ROUND MADE PRIOR TO ASSUMING THE WATCH. 0800 VESSEL IN EASY MOTION IN LIGHT
1100																
1200	318	319	323			E	4	E	4	SW	3	35	25	1011	P'CLDY	SE'LY WINDS AND SEAS AND LOW E'LY SWELL. GOOD VISIBILITY WITH NO TRAFFIC. HELM IN AUTO.
1300																
1400	318	319	323			ESE	4	E	3	E	3	36	20	1010.5	P'CLDY	SECURITY MAINTAINED. RELIEVED AS PER SMS BY (b) (6), (b) (7)(C)
1500																
1600	318	319	323			SE	4	E	3	SE	3	35	29	1010	P'CLDY	0800 (b) (6), (b) (7)(C) ON WATCH IAW BRG-B16 W/O EXCEPTION. 1200 VESSEL IN EASY MOTION IN
1700																
1800	318	315	318			ESE	3-4	ESE	3	ESE	3	33	27	1010	P'CLDY	LIGHT E'LY WINDS AND SEAS WITH LOW SWELL MIX. GOOD VISIBILITY. NO TRAFFIC.
1900																
2000	318	320	322			ESE	4	ESE	3	SW	3	32	27	1010.5	P'CLDY	HELMS IN AUTO. SECURITY MAINTAINED. RELIEVED AS PER SMS BY 3M M (b) (6), (b) (7)(C)
2100																
2200	318	321	324			SE	4	ESE	3	SW	3	29	25	1012	P'CLDY	1200 3M (b) (6), (b) (7)(C) ON WATCH PER BRG B-16 W/O EXCEPTION. FIRE & SECURITY ROUND MADE
2300																
2400	318	320	322			SE	4	ESE	3	SW	4	27	25	1011.5	P'CLDY	PRIOR TO ASSUMING THE WATCH 1330 REDUCE TO HALF AND 1400 VSL IN EASY MOTION
ARRIVAL/DEPARTURE/NOON																
M'DON POSITION DRAFT FWD AFT MEAN DENSITY																
1 25.0955 = 133-3871 E LWD 24 1200 6.0 8.3 7.1 1.025																
DECK WATCH/LOOKOUT																
Running Time 24 17 TIME ON/TIME OFF OFFICER CREW																
Observed Distance 316 936 0000/0400 (b) (6), (b) (7)(C)																
Average Speed 13.2 13.9 0400/0800 (b) (6), (b) (7)(C)																
Fuel Departure 0800/1200 (b) (6), (b) (7)(C)																
Fuel 0600/Noon 670.3 1200/1600 (b) (6), (b) (7)(C)																
Fuel Consumed 22.3 96.7 1600/2000 (b) (6), (b) (7)(C)																
Fuel Arrival 2000/2400 (b) (6), (b) (7)(C)																
Lubes 0600/Noon 372.8 (b) (6), (b) (7)(C)																
Lubes Consumed 12.0 44.0 (b) (6), (b) (7)(C)																
Water 0600/Noon 34.9 (b) (6), (b) (7)(C)																
Water Consumed 7 12.6 (b) (6), (b) (7)(C)																
Water Arrival (b) (6), (b) (7)(C)																
TESTS, DRILLS & INSPECTIONS																
1200 IAW BRG 2.15.1 AND 4.6 CFR 199.140 COMPLETED DAILY NOON TEST OF THE SHIPS																
WHISTLES AND GENERAL ALARM CLOCKS SYMLED. ALL IN GOOD ORDER (b) (6), (b) (7)(C)																
CHIEF OFFICER (b) (6), (b) (7)(C) (6), (b) (7)(C)																

MV SLNG GOODWILL VOY NO. 336 MARSEC LVL: 1 FROM APRA HARBOR, GUAM TOWARDS ONSAN, ROK DATE TUE 4 AUG 2020 20-9

HR	COURSE			ERROR		WIND		SEA		SWELL		TEMPERATURES		BAR	SKY/WX
	BASE	CRS	STBR	DRG	FRG	DIR	FRG	DIR	FEET	DIR	FEET	DRY	WET		
0100															
0200	315	314	315	SE	3	SE	3	SW	4	28	26	1011	P'CLDY		
0300															
0400	315	316	317	SE	3	SE	3	S	4	28	26	1011	P'CLDY		
0500															
0600	000	000	000	ESE	4	ESE	3	SW	4	29	25	1011	P'CLDY		
0700															
0800	040	040	048	ESE	4	SE	4	SW	7	30	26	1011	P'CLDY		
0900															
1000	302	298	303	ESE	4-5	SE	3	SW	5	30	26	1012	P'CLDY		
1100															
1200	302	295	298	SE	4	SE	3	SW	4	31	26	1012.5	P'CLDY		
1300															
1400	302	298	303	SE	4	SE	3	SW	4	31	28	1013	P'CLDY		
1500															
1600	302	300	303	SE	4	SE	3	SW	5	35	29	1013	P'CLDY		
1700															
1800	305	309	310	SE	4	SE	3	W	6	34	28	1012	P'CLDY		
1900															
2000	305	303	305	SSE	4-5	SE	3	WSW	6	31	27	1012	P'CLDY		
2100															
2200	312	300	300	SE	4	SE	3	SW	6	29	26	1012.5	P'CLDY		
2300															
2400	340	337	344	SSE	4	SE	3	SW	5	27	25	1015	P'CLDY		

ARRIVAL/DEPARTURE/NOON		N/GON	POSITION	DRAFT	FWD	AFT	MEAN	DENSITY
L 28-15.67'N		131-19.67'E	100 25	12.00	6.0	8.3	7.1	1.035

DAILY		TOTAL/PASSAGE	DECK WATCH/LOOKOUT		
Running Time	25	42	TIME ON/TIME OFF	OFFICER	CREW
Observed Distance	283	1219	0000 / 0400	(b) (6), (b) (7)(C)	(b) (6), (b) (7)(C)
Average Speed	11.3	13.5	0400 / 0800		
Fuel Departure			0800 / 1200		
Fuel 0800/Noon	648.9		1200 / 1600		
Fuel Consumed	21.4	118.1	1600 / 2000		
Fuel Arrival			2000 / 2400		
Lubes 0800/Noon	3619				
Lubes Consumed	110	550			
Water 0800/Noon	344				
Water Consumed	5	131			
Water Arrival					

TESTS, DRILLS & INSPECTIONS
 1100: R 28-01.2'N 131-22.2'E JAW 46 CFR 194.190 AND SOLAS II 2072 COMPLETED.
 1200: JAW 46 CFR 194.190 AND BR 2151 COMPLETED DAILY NOW TEST OF THE SHIP'S WHISTLES AND GEMERAL ARM CLOCKS SYNCED ALL IN GOOD ORDER (b) (6), (b) (7)(C)
 1130: HELM POSITIONED 28-06.25'N 131-27.27'E SECURITY DRILL CONDUCTED
 JAW 28 CFR 114.230(b)(4), ISPS 18.4, COMSINST 5530.3 CH2 (1)(C), AND
 VSP 10.5 COMPLETELY SECURITY DRILL WAS CONDUCTED, ALL CREW TRAINED, SEE
 DRILL 2. POINT FOR DETAILS. (b) (6), (b) (7)(C)

EVENTS AND REMARKS
 Watch Condition 1 unless otherwise stated in this section
 0000 3/4 (b) (6), (b) (7)(C) WATCH PER BPG B-16 W/O EXCEPTION. FIRE - SECURITY ROUND
 MADE PRIOR TO ASSUMING THE WATCH 0200 CLOCKS RETARDED 30 MIN, SET 20-9
 0400 VSL IN EASY MOTION LT SE'LY WIND/SEA S'LY SWELL GOOD VIS LT TRAFFIC
 WLG HELM IN AUTO SECURITY MAINTAINED RLVN BT 3/4 ATTN (b) (6), (b) (7)(C)
 0400 (b) (6), (b) (7)(C) ASSUMES THE WATCH JAW BPG-B16 W/O EXCEPTIONS, FIRE AND SECURITY
 ROUNDS MADE PRIOR TO ASSUMING THE WATCH. 0518 POS L27-44.6'N 131-05.9'E
 0/6 TO 000° PGC 353° T 008° PSC. 0630 POS L27-58.9'N 131-05.7'E 0/6 TO
 090° PGC 098° PSC. 0636 ↑ INCREASE SPEED TO FULL AHEAD 101 RPM. 0643 POS
 L27-59.3'N 131-08.5'E COMMENCE ODM E OPS, 62NM FROM LAND. 0718 ↓ DECREASE
 SPEED TO HALF AHEAD 85 RPM. 0728 ↓ DECREASE SPEED TO SLOW AHEAD 75 RPM.
 0800 VESSEL IN EASY MOTION IN LIGHT SE'LY SEAS AND ESE'LY WINDS AND SW'LY (LW)
 SWELL. GOOD VISIBILITY W/LT TRAFFIC. WLT - HELM IN AUTO. SECURITY MAINTAINED.
 RELIEVED AS PER SMS BY (b) (6), (b) (7)(C) (b) (6), (b) (7)(C)
 0800 3/4 (b) (6), (b) (7)(C) ASSUMES THE WATCH JAW BPG-B16 W/O EXCEPTIONS, FIRE AND SECURITY ROUNDS MADE PRIOR TO
 ASSUMING WATCH 0805 CONFIRMED FOLLOWING COURSE L: 28° 02.5' N A: 01° 27.2' E, 80NM FROM COAST LAND, 8.1 kts
 0827 ↑ HALF AHEAD, AS PER CAPTAIN. 0837 ↑ FULL AHEAD AS PER CAPTAIN. 0950 0/6 L: 28° 02.0' N A: 131° 44.8' E
 2000 3/4 (b) (6), (b) (7)(C) ASSUMES THE WATCH JAW BPG-B16 W/O EXCEPTIONS, FIRE AND SECURITY ROUNDS MADE PRIOR TO ASSUMING
 WATCH. 2039 C/C ENTER 12NM N 004.2 AT 12.5 NM. 3170L, 3170S, 2301 C/C RECM 12NM / 05.7' AT 13.8 NM
 332° BE 338° REL 375.7. 2400 VESSEL IN EASY MOTION, HOLDING POSITION THROUGH LIGHT SE'LY WIND AND SEA SW'LY
 SWELL GOOD VISIBILITY WITH LAND IN SIGHT, LIGHT TRAFFIC. WLT HELM IN AUTO. SECURITY MAINTAINED. RELIEVED BY (b) (6), (b) (7)(C)
 2000 3/4 (b) (6), (b) (7)(C) ASSUMES THE WATCH JAW BPG-B16 W/O EXCEPTIONS, FIRE AND SECURITY ROUNDS MADE PRIOR TO ASSUMING
 WATCH. 2039 C/C ENTER 12NM N 004.2 AT 12.5 NM. 3170L, 3170S, 2301 C/C RECM 12NM / 05.7' AT 13.8 NM
 332° BE 338° REL 375.7. 2400 VESSEL IN EASY MOTION, HOLDING POSITION THROUGH LIGHT SE'LY WIND AND SEA SW'LY
 SWELL GOOD VISIBILITY WITH LAND IN SIGHT, LIGHT TRAFFIC. WLT HELM IN AUTO. SECURITY MAINTAINED. RELIEVED BY (b) (6), (b) (7)(C)
 CHIEF OFFICER (b) (6), (b) (7)(C) (7)(C)

MV SLMC GOODWILL VOY NO. 738 MARSEC LVL: I FROM APRA HARBOR, GUAM TOWARDS DANSAV, ROK DATE WED 5 AUG 2020 ZD 9

HR	COURSE			ERROR		WIND		SEA		SWELL		TEMPERATURES		BAR	SKY/WX
	BASE CSE	GYRO	STEER	GYRO	DIR	FORCE	DIR	FEET	DIR	FEET	DRY	WET			
0100															
0200	346	342	349		35E	4	SE	3	SW	5	28	25	1013	P'CLDY	
0300															
0400	346	342	349		S	4	S	3	SW	5	28	25	1013	P'CLDY	
0500															
0600	354	350	358		SSE	4	S	3	SW	6	28	25	1013	M'CLDY	
0700															
0800	354	350	358		SSE	4	SSE	3	SW	6	27	26	1014	M'CLDY	
0900															
1000	354	350	358		SSE	4	SSE	4	SW	6	27	26	1013	S/LT MORE CLDY	
1100															
1200	348	348	327		SSE	4	SSE	5	SW	6	27	27	1013.2	S/LT MORE CLDY	
1300															
1400	N/A UNCL				SSE	6	SSE	6	SW	6	27	27	1013	M'CLDY	
1500															
1600	N/A UNCL				S	6	SSE	5	SW	6	27	27	1013	D'CAST	
1700															
1800	N/A UNCL				S	6	SSE	5	SW	6	27	26	1013	D'CAST	
1900															
2000															
2100															
2200	150	26			SSE	6	S	6	SW	6	27	26	1012.5	HUMID CLEAR	
2300															
2400	05:18				SSE	6	S	5	SW	5	28	25	1012.5	FAVORABLE CLEAR	

ARRIVAL/DEPARTURE/MOON	NOON	POSITION	DRAFT	FWD	AFT	MEAN	DENSITY
L 32-15.09'N	128-38.54'E	LD 24	1200	6.0	8.3	7.1	1.035

	DAILY		TOTAL/PASSAGE		DECK WATCH/LOOKOUT	
	PLANNING TIME	OBSERVED DISTANCE	AVERAGE SPEED	FUEL DEPARTURE	FUEL CONSUMED	FUEL ARRIVAL
Planning Time	24	1520	13.1	141.0	2000/1200	
Observed Distance	301					
Average Speed	13.5					
Fuel Departure						
Fuel Consumed	22.9					
Fuel Arrival						
Lubes Consumed	160					
Water Consumed	15					

TESTS, DRILLS & INSPECTIONS

1030 2-410 A DECK IG ROOM SMOKE ISOLATED, 2-411 A DECK IG ROOM DET EXT NOT ISOLATED, FOCALING

1130 ALL DISCONNECTS BACK ONLINE, FIRE DETECTION ALL SYSTEMS NORMAL.

1300 IAW 46 CFR 199.190 AND BPT 9.15.1 COMPLETED DAILY MOON TEST OF SHIPS WHISTLES AND GENERAL ALARM. CLOCKS STARTED ALL IN GOOD ORDER (b) (6), (b) (7)(C)

This is to certify that the vessel is maintained by Japanese Coast Guard (b) (6), (b) (7)(C)

EVENTS AND REMARKS Watch Condition 1 unless otherwise stated in this section

0000 (b) (6), (b) (7)(C) ON WATCH PER BPG B-16 W/O EXCEPTIONS. FIRE SECURITY ROUND MADE PRIOR TO ASSUMING THE WATCH 0400 VSL ROLLING EAST IN MODERATE SWLY SWELL LT S/LT WINDS GOOD VISIBILITY, LIGHT TRAFFIC. WGT HELM IN AUTO SECURITY MAINTAINED. RND BY 3m ATTEND (b) (6), (b) (7)(C)

0400 (b) (6), (b) (7)(C) ASSUMES THE WATCH IAW BPG-B16 W/O EXCEPTIONS. FIRE AND SECURITY ROUND MADE PRIOR TO ASSUMING THE WATCH. 0518 POS L30-55.0N X 128-55.3'E WLP AS PER VOYAGE PLAN. C/G TO 354°T 352°PGC 000 PGC. 0800 VESSEL IN EASY MOTION TO SLIGHT SSE BY SEAS, WINDS, AND SWLY SWELL, GOOD VISIBILITY W/ LT TRAFFIC. HELM IN AUTO, SECURITY MAINTAINED, PROPERLY BELIEVED PER SMS BY (b) (6), (b) (7)(C)

0800 3m R. BEGGI ASSUMES THE WATCH IAW BPG-B16 W/O EXCEPTIONS. FIRE AND SECURITY ROUND MADE PRIOR TO ASSUMING THE WATCH. 0859 IN POS L: 32°04.2'N X 128°46.2'E WITH E 261°T AT 18750M C/L 3.5T 318.5 323.5 1700 VESSEL ROLLING THROUGH LIGHT S/LT WIND AND SEA MODERATE S/LT SWELL. GOOD VISIBILITY WITH LIGHT TRAFFIC AND WGT HELM IN AUTO. SECURITY MAINTAINED. RND BY 7m (b) (6), (b) (7)(C)

1200 3m (b) (6), (b) (7)(C) ON WATCH PER BPG R-16 W/O EXCEPTIONS. FIRE SECURITY ROUND MADE PRIOR TO ASSUMING THE WATCH 1342 NOISE HEARD FROM BELOW, SMOKE/HEAT DETECTOR ALARM IN MULTIPLE G/R SPACES. 1343 MASTER ON BRIDGE SOUND GENERAL ALARM POS 32-35.2N X 128-25.1E SET NUC 1348 3AE REATED DOWN IN E/R G/R SPACE 1350 COMMS EST. WITH MOJI CG RADIO. 1400 VESSEL REPORTS MEDICAL EMERGENCY TO JAPAN COAST GUARD (46) ALL ELEVATOR STAIRS GEARED. LIFELINE ON FIRE GROUP. ALL LIFELINE EVACUATED. 1402 MEDICAL HELICOPTER REQUESTED 1403 PORT CAPTAIN NOTIFIED OF EMERGENCY ABOARD 1405 MEDICAL MBS CONTACTED FOR INJURED CREWMEMBER. FOR FURTHER DETAILS SEE VESSEL INCIDENT REPORT 1538 HOSPITAL REPORTS NO PULSE, REGAIN CPR. 1700 JAPAN COAST GUARD HELICOPTER ON STATION 1707 HELO CREW ON DECK 1725 3AE AWAY ON JAPAN COAST GUARD HELICOPTER 1731 ALL HELICOPTER CREW AWAY, HELO PROCEEDING TO HOSPITAL 1800 VESSEL NOT UNDER COMMAND AFTER EVACUATE IMMUNITY DRIFTING NORTHLY IN DEEP WATER APPROX 10NM FROM SHORE, VESSEL INCIDENT REPORT UPDATED WITH FURTHER DETAILS. GOOD VISIBILITY, MODERATE S/LT WIND, SEA SWELL. BRIDGE WATCH RND BY (b) (6), (b) (7)(C)

1800 3m (b) (6), (b) (7)(C) ASSUMES THE WATCH IAW BPG-B16 AND SMS W/O EXCEPTIONS. 1902 JAPAN COAST GUARD CUTTER ON STATION. 1931 CONFIRM WITH MOJI COAST GUARD THAT VESSEL IS NO LONGER IN IMMEDIATE DANGER. IF VESSEL DRIFTS WITHIN 6NM, WILL ACCEPT TOW. 1934 MOJI COAST GUARD INFORM SHIP HAS POWER CUT NO PROPULSION, 2000 VESSEL DRIFTING, NOT UNDER COMMAND RELIEVED BY (b) (6), (b) (7)(C)

2000 3m (b) (6), (b) (7)(C) ASSUMES WATCH IAW BPG-B16, VESSEL NUC PEARL LIGHTS ILLUMINATED. VESSEL DRIFTING IN N/WLY DIRECTION APPROX 6NM FROM JAPANESE COASTING POS L: 32° 33.15'N X 128° 26.50'E. COMMUNICATIONS ESTABLISHED WITH MOJI COAST GUARD. 2050 MOJI COAST GUARD ADVISED OF VESSEL'S UPDATED STATUS, APPROX 1 HOUR REMAINING TO ARRIVE AND 1 TUG INBOUND APPROX 2 HOURS. 2145 E/C CONDUCTING PIR-SMALL TUGS. 2150 WGT HELM IN AUTO. 2158 3AE BY 2200 MOJI COAST GUARD WITH AID OF VESSEL'S UPDATED STATUS VESSEL W/L ENROUTE TO SAVANAH TUG AND PROCEED FURTHER FROM SHORE. 2219 STEAM 180°X 140°PGC. WGT HELM IN EASY MOTION THROUGH MODERATE S/LT WIND W/MT S/LT SEA AND SWELL. GOOD VISIBILITY WITH LIGHT TRAFFIC. COAST GUARD CUTTER NOT AT VESSEL W/ ENROUTE TO SAVANAH TUGS. VESSEL NOT UNDER COMMAND RELIEVED BY 14m (b) (6), (b) (7)(C)

CHEF OFFICER (b) (6), (b) (7)(C)

MV SASEBO VOY NO. 2123 MARSEC LVL: 1 FROM APPA TOWARDS SASEBO, JAPAN DATE THURS 6 AUG 2020 ZD -9

HR	COURSE			WIND	SEA	SWELL	TEMPERATURES		BAR	SKY/WX	EVENTS AND REMARKS				
	BASE DEG	GYRO	STEER				DRY	WET							
0100															
0200	080	080	080	S	S-G	S	5	6	1013	M CLDY	0000 3m (b) (6), (b) (7)(C) WATCH FOR SWELL. 1/2 EXCEPTION FIRE. SECURITY ROUND MADE PRIOR TO ASSUMING THE WATCH.				
0300															
0400	090	075	080	S	S	S	5	6	1012	M CLDY	USE MULLER IN LIT POSITION W/ 7MM CONT. WARD CUTTER EXPT. 1042 HELM IN AUTO. CUSH HELM IN HAND. EAST EXPT. TURN "TURN" OF SAIKOU 0400 USE HOLLANDT. TOWARDS GIBERT. JAP W/ CONT. WARD AND THUNDER EXPT. WOOD VES. MUSTATE 5/17.				
0500															
0600	083	087	097	S	H	S	4	5	1011	M CLDY	WARD/SWELL. LE-036 4. TO 0807 JAP POS 32-22.4, 138-36.6. 2. REPAIR TO V. OVER WEL HELM IN.				
0700															
0800	009	008	012	SSE	4	SSG	3	SW	3	29	27	1012	OVCST	ARRV SECURITY MAINTAINED RVD BY 3m ATTNW (b) (6), (b) (7)(C).	
0900															
1000	009	004	010	SSE	5	S	4	W	4	29	26	1011.5	HAZE OCAST	0400 (b) (6), (b) (7)(C) ASSUMES THE WATCH IAW BRG-BIG AND SMS. NO EXCEPTIONS. FIRE AND SECURITY	
1100															
1200	AS PER DIRECT			SSE	5	E	2	UR	2	31	27	1011.0	OCAST	ROUND MADE PRIOR TO ASSUMING THE WATCH. 0706 L33-30.3N 138-24.6E 1/2 TO 0807	
1300															
1400				S	4	E	1	-	-	34	28	1010	OCAST	008 PGC, 018 PSC, 0800 VSL IN EASY MOTION TO SLIGHT SSE LT SEAS. WINDS AND LOW SWELL.	
1500															
1600	SASEBO	0	G-1	SSW	4	SSW	2	-	-	31	28	1009	HAZE	GOOD VISIBILITY, WCI. HELM IN AUTO. LT TRAFFIC SECURITY MAINTAINED. RECEIVED PER SMS (b) (6), (b) (7)(C).	
1700															
1800	SASEBO	0	G-1	SSW	3	SSW	1	-	-	29	24	1009	OCAST HAZE	0800 3m K. BERTINI ASSUMES WATCH IAW BRG-BIG WITH EXPT TUG STEERING BRIDGE OF VESSEL. FIRE AND SECURITY	
1900															
2000	SASEBO	0	G-1	SSW	3	SSW	1	-	-	29	24	1009	OCAST HAZE	ROUND MADE PRIOR TO ASSUMING WATCH NO EXCEPTIONS. 1000 WARD ON SWELL. WEL 1028 IN POS L 32-57.9N	
2100															
2200	SASEBO	0	G-1	SSW	3	SSW	1	-	-	28	24	1009.5	WT HAZE	L 179-24.6E 32-22.4N 1042 A/C 0306 040 POC 1058 POC 1100 ARRIVE 1130 22 33 10 4 1 17 3	
2300															
2400	SASEBO	0	G-1	SSW	3	S	2	W	2	29	28	1009.5	CLDY. HAZE	1000 MASTER CANNING. HAND STEERING. 1147 POC. 10 3000 Y. KAWASHIMA 1150 MASTER. 1157 EXCHANGE. 1158	

ARRIVAL/DEPARTURE/NOON NOON POSITION 33-06.37N 129-38.43E DRAFT LOD 24 FWD AFT WIND DENSITY

	DAILY	TOTAL/PASSAGE	DECK WATCH/LOOKOUT	
			OFFICER	CREW
Running Time			TIME ON/TIME OFF	
Observed Distance			0000/0400	(b) (6), (b) (7)(C)
Average Speed			0400/0800	(b) (6), (b) (7)(C)
Fuel Departure			1200/1200	
Fuel 0800/Noon			1200/1600	
Fuel Consumed			1000/2000	
Fuel Arrival			2000/2400	
Lubes 0800/Noon				
Lubes Consumed				
Water 0800/Noon				
Water Consumed				
Water Arrival				

TESTS, DRILLS, & INSPECTIONS

0102 WINDS BEING MONITORED BY USUAL AND ELECTRONIC MEANS. POSITION MONITORED BY USUAL AND ELECTRONIC MEANS. SECURITY MAINTAINED. RVD BY (b) (6), (b) (7)(C).

0200 (b) (6), (b) (7)(C) ASSUMES THE WATCH IAW BRG-BIG AND OPS 2.1.69 1/2 EXCEPTIONS. FIRE AND SECURITY ROUND MADE PRIOR TO ASSUMING THE WATCH. 2000 VESSEL RIDING EASY 7 SHOTS. PORT ANCHOR AT THE WATER'S EDGE IN LIGHT SWELL. WINDS AND SEAS W/ NO SWELL. GOOD VIS. POSITION CONTINUOUSLY MONITORED USUALLY AND ELECTRONICALLY. SECURITY MAINTAINED. RECEIVED PER SMS BY 3m (b) (6), (b) (7)(C).

2000 3m (b) (6), (b) (7)(C) ASSUMES THE WATCH IAW BRG-BIG AND OPS 2.1.9 1/2 EXCEPTION FIRE AND SECURITY ROUND MADE PRIOR TO ASSUMING WATCH. 2000 WARD HELM IN AUTO 7 SHOTS PORT ANCHOR AT WATER'S EDGE IN CLDY WIND SEA SWELL. GOOD VISIBILITY WITH PASSING SWELL. POSITION CONTINUOUSLY MONITORED BY USUAL AND ELECTRONIC MEANS. SECURITY MAINTAINED. FREQUENT ROUNDS MADE. NO POLLUTANTS OBSERVED. RELIEVED BY 3m ATTNW (b) (6), (b) (7)(C).

CHIEF (b) (6), (b) (7)(C) (b) (7)(C)

- 1342 Noise heard from below decks, Smoke/heat detectors activated multiple spaces in ER
- 1343 Master on bridge, General alarm sounded in POS 32-28.7N 128- 25.1E *NAC*
- 1348 3AE Reported down in Engine Room Generator Space
- 1350 Comms established with Moji Coast Guard Radio on VHF 16
- 1400 Declare medical emergency to Moji Coast Guard Radio
- 1401 All engineering space cleared, confirm no fire onboard. All crewmembers accounted for
- 1402 Vessel requests helicopter medivac for injured crewmember, Moji Coast Guard Radio confirms
- 1403 Port captain notified of emergency onboard
- 1405 Medical Advisory Service contacted for injured crewmember
- 1410 Moji Coast Guard Radio confirms helicopter dispatch with doctor onboard, eta 1730
- 1516 Contact Moji Coast Guard on Inmarsat phone
- 1528 Hospital reports no pulse, begin CPR
- 1545 Contact made with Sasebo port agent, request salvage tugboat
- 1552 Contact made with MSC CTF73 Battle Watch Officer to inform of situation
- 1620 Per MAS and Master CPR suspended
- 1626 Moji Coast Guard Radio requests CPR resume per Japanese Doctor
- 1635 Fire wire towing arrangement rigged on the bow per Moji Coast Guard
- 1700 Moji Coast Guard Helicopter on station
- 1705 Helicopter hovering over forward deck
- 1706 First helicopter crewmember on deck
- 1707 Second helicopter crewmember on deck
- 1708 Stretcher lowered from helicopter to deck
- 1710 Helicopter crew proceeding to hospital to assess patient
- 1713 Helicopter crew start use AED and automatic CPR on patient outside hospital
- 1715 Begin moving patient to stern for extraction per helicopter crew request
- 1721 Patient on helicopter stretcher preparing for lift to helicopter
- 1722 Helicopter in position over stern preparing for extraction
- 1725 3AE away on helicopter
- 1731 All helicopter crew off the ship and onboard helicopter

1735 #3 Generator started

1815 Return to emergency generator power, #3 Gen stopped for high temperatures

1820 CM and Bosun on the preparing for emergency towing

1845 #3 Generator running and on-line

1902 Japan Coast Guard cutter on station

1921 Vessel confirms with Moji Coast Guard that vessel is no longer in an immediately dangerous situation. Coast Guard asks for vessel to inform them if vessel drifts within 6nm of land

1924 Moji Coast Guard informed that #3 generator is on line and vessel has power but no navigational propulsion

		GENERATOR 1		CURRENT HOURS			43821
		DONE LAST		SINCE DONE			
SPINNER	43821	24-Jul-20	0				100 hours
TURBO WRAP	43562	23-May-20	259				As Needed
WATER WASH	43562	23-May-20	259				150 hours
LO CARTRIDGE					Hours Switched Over	Service Hours	
LEFT	42781	11-Feb-20	1040			43821	As Needed
RIGHT	40672	31-Jan-19	3149		40880	2941	
GREEN OIL FILT	43567	5-Jun-20	254				every 2 months
VALVE LASH	42620	23-Dec-19	1201				2000 hours
		GENERATOR 2		CURRENT HOURS			40902
		DONE LAST		SINCE DONE			
SPINNER	40878	24-Jul-20	24				100 hours
TURBO WRAP	40902	25-Jul-20	0				As Needed
WATER WASH	40272	22-May-20	630				150 hours
LO CARTRIDGE					Hours Switched Over	Service Hours	
LEFT	39561	20-Mar-20	1341		38385	2517	As Needed
RIGHT	39561	20-Mar-20	1341			40902	
GREEN OIL FILT	40360	5-Jun-20	542				Every 2 Months
VALVE LASH	38848	15-Jan-20	2054				2000 hours
		GENERATOR 3		CURRENT HOURS			50256
		DONE LAST		SINCE DONE			
SPINNER	50210	13-Jun-20	46				100 hours
TURBO WRAP	50256	25-Jul-20	0				As Needed
WATER WASH	50210	21-Jul-20	46				150 hours
LO CARTRIDGE					Hours Switched Over	Service Hours	
LEFT	49573	13-Jun-20	683		0	50256	As Needed
RIGHT	47553	27-Jan-20	2703		46825	3431	
GREEN OIL FILT	49415	5-Jun-20	841				Every 2 Months
VALVE LASH	50210	19-Oct-19	46				2000 hours

CURRENT DATE	7/22/2020
---------------------	-----------

Gen 1

	INJECTORS			PUMPS			TYPE
	DONE LAST	SINCE DONE		DONE LAST	SINCE DONE		
1	43790	22-Jul-20	31	40964	23-Apr-19	2857	New Plunger and Bar
2	43790	22-Jul-20	31	40964	23-Apr-19	2857	New Plunger and Bar
3	43790	20-Jul-20	31	40964	23-Apr-19	2857	New Plunger and Bar
4	43790	22-Jul-20	31	40964	23-Apr-19	2857	New Plunger and Bar
5	43790	22-Jul-20	31	40964	23-Apr-19	2857	New Plunger and Bar
6	43790	22-Jul-20	31	40964	23-Apr-19	2857	New Plunger and Bar

Gen 2

	INJECTORS			PUMPS			TYPE
	DONE LAST	SINCE DONE		DONE LAST	SINCE DONE		
1	39630	1-Apr-20	1272	35417	15-Jul-19	5485	New Plunger and Bar
2	39630	1-Apr-20	1272	40446	27-Jun-20	456	New Plunger and Bar
3	39630	1-Apr-20	1272	26325	17-Sep-17	14577	New Plunger and Bar
4	39630	1-Apr-20	1272	26203	10-Sep-17	14699	New Plunger and Bar
5	39630	1-Apr-20	1272	26674	15-Oct-17	14228	New Plunger and Bar
6	39630	1-Apr-20	1272	39814	13-Apr-20	1088	New Plunger and Bar

Gen 3

	INJECTORS			PUMPS			TYPE
	DONE LAST	SINCE DONE		DONE LAST	SINCE DONE		
1	48838	1-May-20	1418	40543	16-Feb-19	9713	New Plunger and Bar
2	48838	1-May-20	1418	40543	28-May-18	9713	New Plunger and Bar
3	48838	1-May-20	1418	35108	20-Feb-17	15148	New Plunger and Bar
4	48838	1-May-20	1418	43119	11-Feb-19	7137	New Plunger and Bar
5	48838	1-May-20	1418	48907	6-May-20	1349	New Plunger and Bar
6	48838	1-May-20	1418	49609	18-Jun-20	647	New Plunger and Bar

PUMP SEALS (REWORKED)		OIL CHANGE	AIR COOLER
DONE LAST	SINCE DONE	DATE	DATE
40964	23-Apr-19	2857	23-Apr-19
40964	23-Apr-19	2857	HOURS DONE
40964	23-Apr-19	2857	40964
40964	23-Apr-19	2857	SINCE LAST
40964	23-Apr-19	2857	2857
40964	23-Apr-19	2857	

NEW TURBO	WATER PUMP	L.O.THERMOSTATS
DATE	DATE	DATE
23-Apr-19		
HOURS DONE	HOURS DONE	HOURS DONE
40964		
SINCE LAST	SINCE LAST	SINCE LAST
2857		

PUMP SEALS (REWORKED)		OIL CHANGE	AIR COOLER
DONE LAST	SINCE DONE	DATE	DATE
35417	15-Jul-19	5485	15-Dec-19
30753	25-Jul-18	10149	DONE LAST
39262	17-Feb-20	1640	38385
26203	10-Sep-17	14699	SINCE LAST
26674	15-Oct-17	14228	2517
39814	13-Apr-20	1088	5485

NEW TURBO	WATER PUMP	L.O.THERMOSTATS
DATE	DATE	DATE
7/15/2019	7/15/2019	12/15/2019
HOURS DONE	HOURS DONE	HOURS DONE
35417	35417	38385
SINCE LAST	SINCE LAST	SINCE LAST
5485	5485	2517

PUMP SEALS (REWORKED)		OIL CHANGE	AIR COOLER
DONE LAST	SINCE DONE	DATE	DATE
40543	16-Feb-19	9713	?
40543	28-May-18	9713	HOURS DONE
35108	20-Feb-17	15148	?
43119	11-Feb-19	7137	SINCE LAST
48907	6-May-20	1349	#VALUE!
n/a		#VALUE!	

NEW TURBO	WATER PUMP	L.O.THERMOSTATS
DATE	DATE	DATE
	4/10/2020	
HOURS DONE	HOURS DONE	HOURS DONE
	48567	
SINCE LAST	SINCE LAST	SINCE LAST
	1689	

FUEL PUMP CAM ROLLERS		
Cylinder	Hours	Date
1		
2		
3		
4	43119	8-Feb-19
5	48907	6-May-20
6		

Junma Services Pte Ltd

7-Tuas South Ave 10
Singapore 637011

Tel: +96-698636523
Fax: +65-698636524

service@junma.biz
spares@junma.biz



Vessel: **SLNC GOODWILL**

Customer: **American Ship Management**

Junma Job No. **JS-SVC-2019-03-006a**

Date of Inspection: **31.03.2019**



Document Title: **Connecting rod calibration report (Initial)**

Engine Maker: **ZJMD-MAN B&W**

Engine Model: **6L23/30H**

Engine Serial No: **08365**


Calibration Tools Used:



	Piston and oil scraper ring, Nominal size	New ring grooves, Tolerances	Ring grooves, Max. wear limit
Piston ring 1	New 4.0 mm	4.0 mm +0.14 +0.12	4.43 mm
Piston ring 2	New 4.0 mm	4.0 mm +0.11 +0.09	4.43 mm
Piston ring 3	New 4.0 mm	4.0 mm +0.11 +0.09	4.43 mm
Scraper ring	New 7.0 mm	7.0 mm +0.10 +0.08	7.43 mm

Position	Unit.1				Unit.2				Unit.3			
	F	P	A	S	F	P	A	S	F	P	A	S
Top groove	4.41	4.42	4.37	4.38	4.24	4.23	4.26	4.24	4.31	4.35	4.32	4.35
2 nd groove	4.17	4.17	4.15	4.16	4.16	4.14	4.16	4.15	4.12	4.10	4.08	4.10
3 rd groove	4.17	4.14	4.13	4.13	4.13	4.14	4.16	4.13	4.09	4.09	4.08	4.09
Oil ring groove	7.06	7.06	7.06	7.06	7.06	7.06	7.06	7.06	7.06	7.06	7.06	7.06
REMARKS	Top groove found worn and near to max limit											

Position	Unit.4				Unit.5				Unit.6			
	F	P	A	S	F	P	A	S	F	P	A	S
Top groove	4.38	4.36	4.39	4.39	4.19	4.19	4.20	4.20	4.24	4.26	4.21	4.20
2 nd groove	4.13	4.13	4.14	4.16	4.16	4.15	4.15	4.16	4.26	4.15	4.16	4.13
3 rd groove	4.10	4.09	4.10	4.10	4.14	4.10	4.10	4.16	4.15	4.13	4.10	4.12
Oil ring groove	7.06	7.06	7.06	7.06	7.06	7.06	7.06	7.06	7.06	7.06	7.06	7.06
REMARKS	Top groove found worn and near to max limit, cavitation erosion on combustion surface						Cavitation erosion on combustion surface					



Position	Unit.1				Unit.2			
	FWD		AFT		FWD		AFT	
	T-B	P-S	T-B	P-S	T-B	P-S	T-B	P-S
	98.03	98.03	98.03	98.03	98.03	98.02	98.03	98.02
Remarks								

Position	Unit.3				Unit.4			
	FWD		AFT		FWD		AFT	
	T-B	P-S	T-B	P-S	T-B	P-S	T-B	P-S
	98.03	98.03	98.03	98.03	98.03	98.03	98.03	98.03
Remarks								

Position	Unit.5				Unit.6			
	FWD		AFT		FWD		AFT	
	T-B	P-S	T-B	P-S	T-B	P-S	T-B	P-S
	98.03	98.03	98.03	98.03	98.03	98.03	98.03	98.03
Remarks								

Remarks (if any): a). Renewed piston no.1, 4 & 6 from onboard spares.

JUNMA SERVICE ENGINEER

(b) (6), (b) (7)(C)



CUSTOMER REPRESENTATIVE

VESSEL STAMP

Name: (b) (6), (b) (7)(C)


Name:

Junma Services Pte Ltd

7-Tuas South Ave 10
Singapore 637011

Tel: +65-6863 6523
Fax: +65-6863 6524

service@junma.com.sg
sales@junma.com.sg



Vessel: **SLNC GOODWILL**

Customer: **American Ship Management**

Junma Job No. **JS-SVC-2019-03-006a**

Date of inspection: **31.03.2019**


Document Title: **Connecting rod calibration report (Initial)**

Engine Maker: **ZJMD-MAN B&W**

Engine Model: **6L23/30H**

Engine Serial No: **08365**

Calibration Tools Used:



Connecting rod
Ident. No


Big end bearing bore

Hydraulic pressure **750** Bar
Nominal Diameter **195** mm

Small End bush mounted


Nominal Diameter **98** mm
Maximum allowable diameter mm

Aux Engine No.1									
Big end bearing bore (Measurement given in mm)									
		Unit #1	Unit #2	Unit #3	Unit #4	Unit #5	Unit #6		
A	FWD	Cracked on serration area	-0.11	Cracked on serration area	-0.01	-0.08	Cracked on serration area		
	AFT		-0.10		0	-0.08			
B	FWD		-0.21		-0.01	-0.17			
	AFT		-0.22		+0.01	-0.17			
C	FWD		-0.20		-0.01	-0.18			
	AFT		-0.19		0	-0.16			
D	FWD		+0.04		0	+0.04			
	AFT		+0.04		+0.01	+0.04			
E	FWD		+0.08		-0.01	+0.07			
	AFT		+0.08		0	+0.07			
Max. deviation			0.30mm		0.02	0.25mm			
Remarks			beyond limit		Acceptable	beyond limit			



Small end bush

Small end bush mounted (Measurement given in mm)							
		Unit #1	Unit #2	Unit #3	Unit #4	Unit #5	Unit #6
T-B	FWD	+0.20	+0.20	+0.20	+0.20	+0.20	+0.20
	AFT	+0.20	+0.20	+0.20	+0.20	+0.20	+0.20
P-S	FWD	+0.20	+0.20	+0.20	+0.20	+0.20	+0.20
	AFT	+0.20	+0.20	+0.20	+0.20	+0.20	+0.20
Remarks							



Gudgeon pin

Gudgeon Pin Diameter							
		CYL1	CYL2	CYL3	CYL4	CYL5	CYL6
1	T-B	97.96	97.97	97.96	97.96	97.97	97.97
	P-S	97.96	97.97	97.96	97.96	97.97	97.97
2	T-B	97.96	97.97	97.96	97.96	97.97	97.97
	P-S	97.96	97.97	97.96	97.96	97.97	97.97
3	T-B	97.96	97.97	97.96	97.96	97.97	97.97
	P-S	97.96	97.97	97.96	97.96	97.97	97.97
Manufact. No.							
Remarks							

Remarks (if any): Finally renewed all 6pcs connecting rod onboard ship with owner supplied new spare.
no. 4 connecting rod return onboard and to be kept as emergency spare.

(b) (6), (b) (7)(C)
ENGINEER
(b) (6), (b) (7)(C)




CUSTOMER REPRESENTATIVE

VESSEL STAMP

Name: _____

Junma Services Pte Ltd

Company Reg. No.: 200709388D
 48Toh Guan Road East Enterprise Hub, #05-120/121.
 Singapore 608586



Tel: (65) 6863 6523
 Fax: (65) 6863 6524
 Email: service@junma.biz
 Website: www.junma.biz




Vessel:	SLNC Goodwill
Customer:	keppel shipyard Tuas
Junma Job No.	JS-SVC-2019-04-05
Date of Inspection:	27.03.2019

Document Title: Liner Calibration & Visual Inspection Report (initial) Before Honing

Engine Maker: ZJMD MAN B&W Engine Model: 6L23/30H Engine Serial No: 08365

Calibration Tools Used: Inside micrometer



Nominal Diameter: Ø225mm

Max. Wear Limit: +0.5mm

(Unit for measuring : mm)

AUXILIARY ENGINE NO. 1												
Point of Measurement	Cyl No.1		Cyl No.2		Cyl No.3		Cyl No.4		Cyl No.5		Cyl No.6	
	P-S	F-A	P-S	F-A	P-S	F-A	P-S	F-A	P-S	F-A	P-S	F-A
D1	+0.13	+0.10	+0.14	+0.12	+0.12	+0.11	+0.12	+0.11	+0.10	+0.11	+0.13	+0.14
D2	+0.12	+0.09	+0.12	+0.10	+0.11	+0.10	+0.11	+0.10	+0.11	+0.10	+0.12	+0.12
D3	+0.09	+0.09	+0.12	+0.09	+0.10	+0.09	+0.10	+0.11	+0.09	+0.09	+0.11	+0.09
REMARKS												

AUXILIARY ENGINE												
Point of Measurement	Cyl No.1		Cyl No.2		Cyl No.3		Cyl No.4		Cyl No.5		Cyl No.6	
	P-S	F-A	P-S	F-A	P-S	F-A	P-S	F-A	P-S	F-A	P-S	F-A
D1												
D2												
D3												
D4												
REMARKS												

Remarks (if any): Cylinder liner was found all units look very shining there was No sign of running surface wave roughness for oil film

Strongly recommended for Honing all units

Liner top flame ring to be renewed after the honing process

JUNMA SERVICE ENGINEER

CUSTOMER REPRESENTATIVE

VESSEL STAMP

Name: Siva

Name:

Junma Services Pte Ltd

Company Reg. No.: 200709388D
 48Toh Guan Road East Enterprise Hub, #05-120/121.
 Singapore 608586



Tel: (65) 6863 6523
 Fax: (65) 6863 6524
 Email: service@junma.biz
 Website: www.junma.biz





Vessel:	SLNC Goodwill
Customer:	keppel shipyard Tuas
Junma Job No.	JS-SVC-2019-04-05
Date of Inspection:	31.03.2019

Document Title: Liner Calibration & Visual Inspection Report (After Honing)

Engine Maker: ZJMD MAN B&W	Engine Model: 6L23/30H	Engine Serial No: 08365
----------------------------	------------------------	-------------------------

Calibration Tools Used: Inside micrometer



Nominal Diameter: Ø225mm

Max. Wear Limit: +0.5mm

(Unit for measuring : mm)

AUXILIARY ENGINE NO. 1												
Point of Measurement	Cyl No.1		Cyl No.2		Cyl No.3		Cyl No.4		Cyl No.5		Cyl No.6	
	P-S	F-A	P-S	F-A	P-S	F-A	P-S	F-A	P-S	F-A	P-S	F-A
D1	+0.13	+0.13	+0.14	+0.13	+0.12	+0.12	+0.13	+0.12	+0.12	+0.12	+0.14	+0.14
D2	+0.12	+0.11	+0.12	+0.12	+0.11	+0.10	+0.11	+0.11	+0.11	+0.11	+0.13	+0.12
D3	+0.09	+0.09	+0.12	+0.10	+0.10	+0.10	+0.12	+0.12	+0.10	+0.11	+0.11	+0.10
REMARKS												

AUXILIARY ENGINE												
Point of Measurement	Cyl No.1		Cyl No.2		Cyl No.3		Cyl No.4		Cyl No.5		Cyl No.6	
	P-S	F-A	P-S	F-A	P-S	F-A	P-S	F-A	P-S	F-A	P-S	F-A
D1												
D2												
D3												
D4												
REMARKS												

Remarks (if any): Cylinder liner was done honing in order and found satisfactory required roughness on the running surface for station of oil film

Honing was done all units

Liner top flame ring was renewed all units after the honing process

JUNMA SERVICE ENGINEER

CUSTOMER REPRESENTATIVE

VESSEL STAMP

Name: Siva

Name:

Junma

7-Tuas South Ave10, T99 Building, Singapore 637011
 Tel: (65) 6863 6523 Fax: (65) 6863 6524
 Email: service@junma.biz Website: www.junma.biz

Authorized Sales and Service Agent for:



Name//Engine: 6L23/30 - Aux Engine No-1 (Before)		Draught fore										Draught aft			
Temp. 30°												Date, time: 23/3/2019			
Normal Max. Deflection		0.05 mm (See Instruction Manual)										Engine Running hr 40,964 Hrs			
Max. Deflection value Flywheel crank throw		0.09 mm (See Instruction Manual)													
Max. Deflection value ABS(C-D)		0.05 mm (See Instruction Manual)													
Unit: 1/100 mm.		Fore order No & deflections													
Crank position			1	2	3	4	5	6	7	8	9	10	11	12	Att
Near bottom, camshaft side		B1	0	0	0	0	0	0							
Port side		P	0	-1	0	1	0	1							
Top		T	0	-1	0	1	1	1							
Starboard side		S	2	-1	1	1	1	2							
Near bottom, exhaust side		B2	-1	-1		1	1	2							
Bottom 1/2(B1+B2)		B	-0.5	-0.5	0.5	0.5	0.5	1	0	0	0	0	0	0	
Top - Bottom (T-B)		V	Calculated vertical deflection values												
Maximum deflection values, vertically			0.5	-0.5	-0.5	0.5	0.5	0							
OK = Inside limit, OUT = Outside limit			OK	OK	OK	OK	OK	OK							Result Inside limit
Exhaust - Cam side (S-P)		H	Calculated horizontal deflection values												
Maximum deflection values, horizontally			-2	0	1	0	1	1							
OK = Inside limit, OUT = Outside limit			OK	OK	OK	OK	OK	OK							Result Inside limit
Top + Bottom (T+B)		C	Calculated ovality deflection values												
Port side + Starboard side (P+S)		D	-0.5	-1.5	0.5	1.5	1.5	2							
Maximum deflection values, ovality		C-D	1.5	0.5	-0.5	-0.5	0.5	-1							
OK = Inside limit, OUT = Outside limit			OK	OK	OK	OK	OK	OK							Result Inside limit

Figure 1

JUNMA SERVICE ENGINEER: (b) (6), (b) (7)(C) CUSTOMER REPRESENTATIVE: VESSEL STAMP:

0160100

Junma Services Pte Ltd

Company Reg. No.: 200709388D
 48Toh Guan Road East Enterprise Hub, #05-120/121,
 Singapore 608586



Tel: (65) 6863 6523
 Fax: (65) 6863 6524
 Email: service@junma.biz
 Website: www.junma.biz



Vessel:

SLNC Goodwill

Customer:

SLNC

Junma Job No.

JS-SVC-2019-04-05

Date of Inspection:

12 April 2019

Document Title: **Piston Ring Groove Vertical clearance Report**



Engine Maker: **ZJMD MAN B&W**

Engine Model: **6L23/30H**

Engine Serial No: **08365**

Calibration Tools Used: **Feeler Gauge**

Engine Running hrs: **40,964**



H1 Standard Height:

H1 Max. Height Limit:

H2 Standard Height:

H2 Max. Height Limit:

H3 Standard Height:

H3 Max. Height Limit:

H4 Standard Height:

H4 Max. Height Limit:

	UNIT NO.1				UNIT NO.2				UNIT NO.3			
	P	A	S	F	P	A	S	F	P	A	S	F
H1	0.50	0.50	0.50	0.50	0.35	0.35	0.35	0.35	0.30	0.30	0.30	0.30
H2	0.25	0.25	0.25	0.25	0.20	0.20	0.20	0.20	0.15	0.15	0.15	0.15
H3	0.15	0.15	0.15	0.15	0.15	0.15	0.15	0.15	0.15	0.15	0.15	0.15
H4	0.15	0.15	0.15	0.15	0.15	0.15	0.15	0.15	0.10	0.10	0.10	0.10
REMARKS												

	UNIT NO.4				UNIT NO.5				UNIT NO.6			
	P	A	S	F	P	A	S	F	P	A	S	F
H1	0.30	0.30	0.30	0.30	0.30	0.30	0.30	0.30	0.30	0.30	0.30	0.30
H2	0.15	0.15	0.15	0.15	0.15	0.15	0.15	0.15	0.15	0.15	0.15	0.15
H3	0.15	0.15	0.15	0.15	0.15	0.15	0.15	0.15	0.15	0.15	0.15	0.15
H4	0.10	0.10	0.10	0.10	0.10	0.10	0.10	0.10	0.10	0.10	0.10	0.10
REMARKS												

Remarks (if any): Ring groove size is 1 to 3 4.0 mm

Ring groove size 4th groove is 7.0 mm

Max wear limit 0.43 to 0.45mm

Unit No-1 top ring groove was found already exceeding wear limit, we have renewed with new piston crown

unit No-4-5-6 was renewed with New Piston crown supplied by ship

JUNMA SERVICE ENGINEER

CUSTOMER REPRESENTATIVE

VESSEL STAMP

Name

Name:

Junma

Authorized Sales and Service Agent for:

7-Tuas South Ave 10, T99 Building, Singapore 637011
 Tel: (65) 6863 6523 Fax: (65) 6863 6524
 Email: service@junma.biz Website: www.junma.biz



Name//Engine: 6L23/30 - Aux Engine No-2 (Barora)		Draught fore				Draught aft				Date, time: 23/3/2019				
Temp. 32°		(See Instruction Manual)				Engine Running hr 34,574 Hrs								
Normal Max. Deflection 0.05 mm		(See Instruction Manual)												
Max. Deflection value Flywheel crank throw 0.09 mm		(See Instruction Manual)												
Max. Deflection value ABS(C-D) 0.05 mm		(See Instruction Manual)												
Units: 1/100 mm.		Fore order No & deflections										Aft		
Crank position														
Near bottom, camshaft side		B1	1	2	3	4	5	6	7	8	9	10	11	12
Port side		P	0	-1	0	-1	0	-1	0	0	0	0	0	0
Top		T	-1	1	0	-1	0	1	0	2	0	0	0	0
Starboard side		S	1	-1	-1	0	1	1	0	0	0	0	0	0
Near bottom, exhaust side		B2	1	0	-1	-1	1	1	0	0	0	0	0	0
Bottom 1/2(B1+B2)		B	-0.5	0	-0.5	-0.5	0.5	0.5	0	0	0	0	0	0
Calculated vertical deflection values														
Top - Bottom (T-B)		V	-0.5	1	0.5	-0.5	-0.5	1.5	0	0	0	0	0	0
Maximum deflection values, vertically			5	5	5	5	5	9	0	0	0	0	0	0
OK = Inside limit, OUT = Outside limit			OK	OK	OK	OK	OK	OK	0	0	0	0	0	0
Calculated horizontal deflection values														
Exhaust - Cam side (S-P)		H	1	0	-1	1	1	2	0	0	0	0	0	0
Maximum deflection values, horizontally			5	5	5	5	5	5	0	0	0	0	0	0
OK = Inside limit, OUT = Outside limit			OK	OK	OK	OK	OK	OK	0	0	0	0	0	0
Calculated ovality deflection values														
Top + Bottom (T+B)		C	-1.5	1	-0.5	-1.5	0.5	2.5	0	0	0	0	0	0
Port side + Starboard side (P+S)		D	1	-2	-1	-1	1	0	0	0	0	0	0	0
Maximum deflection values, ovality		C-D	-2.5	3	0.5	-0.5	-0.5	2.5	0	0	0	0	0	0
OK = Inside limit, OUT = Outside limit			OK	OK	OK	OK	OK	OK	0	0	0	0	0	0
Result			Inside limit											
Result			Inside limit											
Result			Inside limit											

Figure 1


JUNMA SERVICE ENGINEER: (b) (6), (b) (7)(C)

CUSTOMER REPRESENTATIVE:

VESSEL STAMP:

Junma Services Pte Ltd

Company Reg. No.: 200709388D
 48Toh Guan Road East Enterprise Hub, #05-120/121.
 Singapore 608586



Tel: (65) 6863 6523
 Fax: (65) 6863 6524
 Email: (b) (6), (b) (7)(C)
 Website: www.junma.biz



Vessel: SLNC Goodwill

Customer: SLNC

Junma Job No. JS-SVC-2019-04-05

Date of Inspection: 31.Mar.2019


Document Title: Crankpin calibration Report

Engine Maker: ZJMD MAN B&W

Engine Model: 6L23/30H

Engine Serial No: 08365

Calibration Tools Used: Outside Micrometer Crank Pin Dia 185.0 mm



POSITION OF MEASUREMENT	CYL. NO.1		CYL. NO.2		CYL. NO.3	
	T-B	P-S	T-B	P-S	T-B	P-S
F	-0.02	-0.02	-0.03	-0.03	-0.02	-0.03
M	-0.02	-0.02	-0.04	-0.04	-0.02	-0.03
M	-0.01	-0.02	-0.03	-0.04	-0.03	-0.03
REMARKS						

POSITION OF MEASUREMENT	CYL. NO.4		CYL. NO.5		CYL. NO.6	
	T-B	P-S	T-B	P-S	T-B	P-S
F	-0.04	-0.04	-0.04	-0.04	-0.04	-0.04
M	-0.04	-0.04	-0.03	-0.04	-0.05	-0.04
M	-0.04	-0.04	-0.03	-0.04	-0.04	-0.04
REMARKS						

Remarks (if any): Crank pin was found all units around the Lube oil hole got wear ridge,
it was polished with emery special film paper before installed the New bearing
all units crank pin surface was checked with straight edge blue paste inspection before and after

JUNMA SERVICE ENGINEER

CUSTOMER REPRESENTATIVE

VESSEL STAMP

(b) (6), (b) (7)(C)

Name

Name:



Authorized Sales and Service Agent for:

7-Tuas South Ave10, T99 Building, Singapore 637011
 Tel: (65) 6863 6523 Fax: (65) 6863 6524
 Email: service@junma.biz Website: www.junma.biz



Name//Engine: 6L23/30 - Aux Engine No-1 (Arter)		Draught fore		Draught aft										
Temp. 32°				Date, time: 16/4/2019										
Normal Max. Deflection 0.05 mm		(See Instruction Manual)		Engine Running hr 40,964 Hrs										
Max. Deflection value Flywheel crank throw 0.09 mm		(See Instruction Manual)												
Max. Deflection value ABS(C-D) 0.05 mm		(See Instruction Manual)												
Unit: 1/100 mm.		Fore order No & deflections										Aft		
Crank position														
Near bottom, camshaft side		B1	1	2	3	4	5	6	7	8	9	10	11	12
Port side		P	0	0	0	0	0	0	0	0	0	0	0	0
Top		T	0	-1	1	1	1	2						
Starboard side		S	-1	0	1	1	0	2						
Near bottom, exhaust side		B2	-1	-1	2	0	1	1						
Bottom 1/2(B1+B2)		B	-0.5	-0.5	1	0	0.5	0.5	0	0	0	0	0	0
Calculated vertical deflection values														
Top - Bottom (T-B)		V	0.5	-0.5	0	1	0.5	1.5						
Maximum deflection values, vertically			5	5	5	5	5	9						
OK = Inside limit, OUT = Outside limit			OK	OK	OK	OK	OK	OK						
Calculated horizontal deflection values														
Exhaust - Cam side (S-P)		H	-1	0	1	-1	0	1						
Maximum deflection values, horizontally			5	5	5	5	5	5						
OK = Inside limit, OUT = Outside limit			OK	OK	OK	OK	OK	OK						
Calculated ovality deflection values														
Top - Bottom (T+B)		C	-0.5	-1.5	2	1	1.5	2.5						
Port side + Starboard side (P+S)		D	-1	0	1	3	0	3						
Maximum deflection values, ovality		C-D	0.5	1.5	1	-2	1.5	-0.5						
OK = Inside limit, OUT = Outside limit			OK	OK	OK	OK	OK	OK						
Result Inside limit														
JUNMA SERVICE ENGINEER: (b) (6), (b) (7)(C)		CUSTOMER REPRESENTATIVE:				VESSEL STAMP:								

0160100

Authorized Sales and Service Agent for: **CSE** **QMD** **DMD** **YMD** **SXD** *Junma*

Service and genuine spares provider for: **CSSC** **HMM** **CS** 上海中船三井造船柴油机有限公司
CSSC-MES Diesel Co., Ltd.

The following inspection report is enclosed with this service report:

01. Deflection report (Crank shaft)
02. Crank pin big end brg clearance report
03. Cylinder liner calibration report
04. Crank pin dia calibration report
05. Piston ring groove inspection report
06. Con rod big end bore inspection report
07. Piston pin small end pin & bush inspection report

As per the supt requirement Sea trial has attended and all parameters found to be in normal

(b) (6), (b) (7)(C)

Service Engineer

Junma

25/4/2019

Chief Engineer

SLNC GOODWILL

(b) (6), (b) (7)(C)

Authorized Sales and Service Agent for:



Service and genuine spares provider for:



Service Report

Ship Name: SLNC GOODWILL

Customer Name: SLNC

23 April 2019

Authorized Sales and Service Agent for:



Service and genuine spares provider for:



Engine Maker: ZJMD MAN B&W	Engine No: AE No1 08365
Engine Type: 6L23/30H	Newbuilding yard: ZJMD
Hull No:	IMO No: 9448334
Place: SINGAPORE	Reason: Drydocking Repair
Visit by: (b) (6), (b) (7)(C)	Location: KEPPEL SHIPYARD TUAS
Owner: SLNC	Supt: (b) (7)(C), (b) (6)
Job order No: JS-SVC-2019-04-05	Engine Running Hrs: 40,964
Period From: 21.MAR.2019	To:23.APL.2019

GENERATOR ENGINE OVERHAULING (No-1)

01. Generator engine crank shaft deflection Check (Before No-1 & 2 and After No-1)
 - a. As per the owner request crank shaft deflection was carried out and the readings taken as well. Deflection gauge was provided by junma
02. Removed AE 1 engine cylinder head with Rocker arm & all mountings 6 Nos
 - a. Dismantled cylinder head all mountings hydraulic nut with 750 bar
 - b. Removed the cylinder head to shore work shop for overhauling
 - c. Removed inlet & Exhaust valve spindle and valve guide & valve seat as well, after the supt inspection renewed with ship spares accordingly.
 - d. Cylinder head Combustion chamber surface DPI were checked found all 6 units were corroded at liner and cooling water jacket seating surface, valve seat surface was Dye checked for crack free.
 - e. Injector were removed and overhauled as well and pressure tested 320 bar (6 pcs)
 - f. New Nozzle were renewed in order, upon inspection boxed back as well
 - g. Cooling water jacket space were cleaned and Dpi checked.
 - h. Cylinder head related mountings were removed & cleaned & renewed gasket
 - i. Upon completion of overhauling, cylinder head was assembled with cooling jacket and Cylinder liner together then pressure tested in order (7 bar)
 - j. Fuel injector pocket were cleaned thoroughly and lapping as well
 - k. Cylinder head & Exhaust manifold mounting coupling surface were cleaned as well
 - l. All valve seat/guide/spindle/spring were renewed with new spares

Authorized Sales and Service Agent for:



Service and genuine spares provider for:



03. Removed Connecting rod Big end bearing 6 Nos

- a. Dismantled connecting rod bearing, and cleaned the big end & small end bore as well
- b. Calibrate big end bore as per the manual instructions with tight Torque value (750 bar)
- c. Calibrate small end bush bearing and piston pin as well, found small end bush some hard contact and scoring marks. Based on the running hours all 6 pcs were polished as well
- d. Con rod big end serration and contact surface were dye checked found 5 pcs crack, also Big end bore was found Ovality 5 pcs
- e. Con rod serration part was Found crack 5 pcs (DPI checked)
- f. Con rod tightened as per the maintenance manual procedure 750 bar
- g. Con rod all Bearing were renewed with ship spares. Clearance were checked before and after overhauling. Spec: 0.15mm to 0.2mm found 0.15 mm
- h. Upon completion of overhaul all parts assembled back in order

04. Removed Piston 6 Nos

- a. To cleaned piston ring groove with cold wash & calibrate as well
- b. Piston crown top land was checked DPI (2 units was found eroded marks and one unit was found Top ring groove clearance overlimit)
- c. To informed supt for inspection as well, as per his instructions renewed 3 piston with new spares
- d. Piston Crown Ring groove vertical clearance were checked with new piston rings

05. Cylinder liner clean /Honing/ calibrate 6 Nos

- a. To cleaned cylinder liner top surface carbon particles
- b. Calibrate the cylinder liner in order and readings are recorded, found the liner bore readings within limit, but liner surface was found very shine condition.
- c. Liner inner surface were found very shining without roughness cross marks, recommend to Honing all 6 nos in-situ, it was done as well
- d. Cylinder liner Flame ring seating surface were cleaned as well
- e. Upon cleaned liner surface, calibrate liner as well, it is usable condition

06. Removed Charging Air cooler 1 unit

- a. Dismantled Charging air cooler from the engine to shore work shop
- b. To cleaned the Air cooler inner space dirt and corroded part as well
- c. Air Cooler was cleaned and dye checked as well
- d. Air cooler was Pressure tested as well
- e. Supplied Air cooler gasket 2 Nos together with cooler

07. Removed Fuel pump 6 Nos

- a. Dismantled all fuel pumps and sent to shore ws in order

Authorized Sales and Service Agent for:



Service and genuine spares provider for:



- b. To cleaned all parts with cold wash and diesel oil as well
- c. Plunger and barrel clearance were calibrated
- d. Housing and timing gears were checked
- e. Delivery valve and spring were checked and renewed
- f. Plunger and barrel were renewed 6 Nos

08. Crank pin polishing were carried out AE #1 engines (All units)

- a. Upon removal of crank pin bearing, crank journal were cleaned as well
- b. Found scoring marks ridge wear on the journal and around the journal part
- c. Informed to owner about this issue
- d. As per the owner instructions crank pin was carried out wear ridge removal with special consumable parts and material as well as MAN service letter requirement.
- e. Crank pin diameter was calibrated as well, found readings with in limit
- f. Surface roughness were measured as well, found in order

09. Crank case sump were cleaned thoroughly at AE#1 & #2 engine

- a. To removed out sump dirt and Oil as well
- b. After cleaned informed to CE for inspection as well
- c. Upon inspection filled new Lube oil into sump accordingly

10. AUX engine crank shaft deflection was checked (AE No-1 After)

- b. AE #1 crank shaft deflection was carried out and the readings taken as well. Deflection gauge was provided by junma.

11. AE engine Rocker arm Tappet clearance were checked according to Firing Order

Inlet valve 0.5 mm
Exhaust valve 0.9 mm

12. AE No-1 Turbo charger overhauling

- a. Removed T/C to shore work shop
- b. Dismantle and cleaned/Dynamic balancing as well
- c. Upon overhaul return back to ship in order


13. Leak Test:

- a. Upon completion of Aux engine overhauling and installation, to run the system check for leaks, found in normal. (Water, Air, fuel oil, Lube oil)
- a. Upon completion of AE #1 engines have checked the all parameters were found in order and Engine Load tested found in normal.
- b. SEA Trial was performed as well

Authorized Sales and Service Agent for:



Service and genuine spares provider for:




SERVICE PHOTOS:

A close-up photograph of a black metal nameplate for a MAN B&W GEN01 engine. The nameplate lists technical specifications such as 'ENG. NO.', 'O. R.', 'NET WT.', and 'MAN B&W DIESEL'.	A photograph showing a large industrial engine in a compartment. A technician is working on the side, and an aircooler and turbocharger assembly is being removed from the engine.
A photograph showing several cylindrical crank pin bearings laid out on a workbench. The bearings are arranged in two rows, with some showing signs of wear.	A photograph showing an aircooler and turbocharger assembly being removed from an engine. The components are placed on a workbench next to the engine.
<p>Crank pin bearing after removal</p> A photograph showing a cylinder liner being honed in situ. A honing tool is being used to finish the inner surface of the liner while it remains in the engine block.	<p>Aircooler & Turbo charger being removed</p> A photograph showing a crank shaft being measured for deflection. A dial indicator is being used to measure the deflection of the crank shaft while it is in the engine.
<p>Liner honing at insitu</p>	<p>Crank shaft Deflection being taken</p>

Authorized Sales and Service Agent for:



Service and genuine spares provider for:



Crank pin Before polish condition



Crank pin with wear ridge condition



Crank pin found Wear ridge



Crank pin found Wear ridge



Crank pin found Wear ridge



Crank pin found Wear ridge

Authorized Sales and Service Agent for:



Service and genuine spares provider for:




Crank pin being polished



Cp wear ridge being checked with blue paste



Cp being polished



Cp being polished



Crank pin after polished




Crank pin before polish

Authorized Sales and Service Agent for:









Service and genuine spares provider for:



	
Crank pin after polished #1	Crank pin after polished #2
	
Crank pin after polished #3	Crank pin after polished #4
	
Crank pin after polished #5	Crank pin after polished #6

Authorized Sales and Service Agent for: **CSE** **QMD** **DMD** **YMD** **SYD** *Junma*

Service and genuine spares provider for: **CSSC** **HMM** **CS** 上海中船三井造船柴油机有限公司
CSSC-MES Diesel Co., Ltd.

	
<p>Piston crown #4 condition (found cavitation)</p>	<p>Piston crown #6 condition (found cavitation)</p>
 <p>0.5mm GE unit No1</p>	
<p>Cylinder liner condition Before honing</p>	<p>New Connecting rod being cleaned</p>
 <p>#4 #5 #6 New spare</p>	
<p>Piston crown New spare used</p>	<p>Crank pin being checked dimensions</p>

Authorized Sales and Service Agent for: **CSE** **GMD** **DMD** **YMD** **SXD** *Junma*


Service and genuine spares provider for: **CSSC** **HMM** **W** 上海中船三井透船柴油有限公司
CSSC-MES Diesel Co., Ltd.



Before honing




Before honing



Before honing



Before honing









Before honing



Before honing


Authorized Sales and Service Agent for: **CSE** **GMD** **DMD** **YMD** **SXD** *Junma*

Service and genuine spares provider for: **CSSC** **HMM** **CS** 上海中船三井造船柴油机有限公司
CSSC-MES Diesel Co., Ltd.

 <p>GE1 unit 1 after</p>	 <p>GE1 unit 2 after</p>
Liner After Honing	Liner After Honing
 <p>Unit #3 After</p>	 <p>GE1 unit 4 after</p>
Liner After Honing	Liner After Honing
 <p>GE1 unit 5 after</p>	 <p>Unit #5 After</p>
Liner After Honing	Liner After Honing

Authorized Sales and Service Agent for: **CSE** **QMD** **DMD** **YMD** **SXD** *Junma*

Service and genuine spares provider for: **CSSC** **HHK** **W** 上海中船三井造船柴油机有限公司
CSSC-MES Diesel Co., Ltd.



Authorized Sales and Service Agent for:




Junma

Service and genuine spares provider for:



上海中船三井造船柴油机有限公司
CSSC-MES Diesel Co., Ltd.





Junma Services Pte Ltd

7-Tan South Ave 10
Singapore 637011


Tel: +65-6863 6523
Fax: +65-6863 6524

(b) (6), (b) (7)(C)



Work Done Report (Workshop)

Vessel Name	SLNC GOODWILL
IMO No.	9448334
Customer	American Ship Management
Junma Job Number	JS-SVC-2019-03-006a
Engine Maker/Model	ZJMD-MAN B&W 6L23/30H, E/No: 08365
Date	01.04.2019



This work done report is regarding below component of aux engine no.1

1. Cylinder head: 6 units
2. Rocker arm assembly: 6 units
3. Indicator valve: 6 pcs
4. Piston with connecting rod: 6 units
5. Fuel injection pump: 5 units
6. Fuel injector: 6 units
7. Turbocharger
8. Charge air cooler

1. Cylinder head: 6 units

Work done:

- Complete disassembled, clean all components.
- Extract out all valve seats due to corroded with worn step. Performed Dye Penetrant Inspection valve seat pockets and combustion surface, no crack detected. Inserted new valve seats inlet 12pcs & exhaust 12pcs.
- Extract out all 24pcs existing valve guides and inserted new valve guides.
- Removed all 6pcs cooling water jacket, cleaned and Dye checked. Refitted all cooling water jacket with new o-rings.
- Removed unit no.5 injector sleeve to renew o-ring
- Carried out hydro-test all 6 cylinder head at pressure 7kg/cm², no leak detected.
- Renewed all 24pcs valve due to worn at lid surface.
- 5pcs of valve rotators were renewed due to wear on ball seat, remaining 19pcs reused. All 24 sets of valve springs were reused.
- Assembled components as per maker's specification.



Extracted all valve seats



Valve seat pockets and combustion surface crack test





Junma Services Pte Ltd

7-Tuas South Ave #01
Singapore 627011


Tel: +65 - 6863 8023
Fax: +65 - 6863 8528

Service Junma for
American Ship Management




Work Done Report (Workshop)

Vessel Name	SLNC GOODWILL
IMO No.	9448334
Customer	American Ship Management
Junma Job Number	JS-SVC-2019-03-006a
Engine Maker/Model	ZJMD-MAN B&W 6L23/30H, E/No: 08365
Date	01.04.2019



Valve seat pocket



Jacket and coaming after clean



New valve guide insert

2. Rocker arm assembly: 6 units

Work done:

- Disassembled rocker arm, clean and inspect bearings and shaft. All the shaft journal found slightly worn at bottom, however clearance found within limit, 0.13-0.15 mm by feeler gauge.

Note: Maximum clearance between rocker arm bush and rocker arm shaft 0.30mm



Rocker arm after disassembly



Bottom of the shaft journal



Bush

3. Indicator valve: 6 pcs

Work done:

- Disassembled, cleaned and inspect components.
- Carried out lapping on seat and lid surface and reassembled.



Indicator valve

Work Done Report (Workshop)


Vessel Name	SLNC GOODWILL
IMO No.	9448334
Customer	American Ship Management
Junma Job Number	JS-SVC-2019-03-006a
Engine Maker/Model	Z/JMD-MAN B&W 6L23/30H, E/No: 08365
Date	01.04.2019

4. Piston with connecting rod: 6 units

Work done:


- Disassembled piston connecting rods, cleaned and inspect components.
- **Piston:** Carried out dye check on piston combustion surface, unit no.4 and 6 combustion surface found excessively corroded with cavitations. Unit no.1 piston ring groove height found worn and at max wear limit. Renewed no.1, 4 and 6 piston onboard ship from vessel spares.
- **Gudgeon pin:** All 6 pcs gudgeon pin found within wear limit, super polished all 6 pcs gudgeon pin using micro film.
- **Connecting rods:** Clean & inspect all 6 pcs connecting rod. Dye checked serration area, found cracked no.1, 3, and 6. No.2 & 5 big end bore diameter beyond maximum deviation. Only unit no.4 connecting rod found acceptable and return onboard as emergency spare.

Note: all 6 pcs connecting rod were renewed onboard with new spares.



Crack test of pistons

Corrosion cavitations on piston no. 4 & 6



Cracked con rod unit no.1

Cracked con rod unit no.3

Cracked con rod unit no.6



Junma Services Pte Ltd

7-Utas South Ave 10
Singapore 637011


Tel: +65-6963 6523
Fax: +65-6963 6524

service@junma.biz
junma@junma.biz



Work Done Report (Workshop)

Vessel Name	SLNC GOODWILL
IMONo.	9448334
Customer	American Ship Management
Junma Job Number	JS-SVC-2019-03-006a
Engine Maker/Model	ZJMD-MAN B&W 6L23/30H, E/No: 08365
Date	01.04.2019





Calibration of big end bore

Gudgeon pin before super polished

5. Fuel injection pump: 5 units (unit no. 2-6)

Work done:

- Disassembled, cleaned and inspect all components.
- Renewed 5 sets of plunger-barrels with owner supplied new spares.
- Lapped mating surfaces.
- Renewed all deliver valve springs.
- Renewed all o-rings, seals and gaskets.
- Reassembled as per maker's specification.



Components after disassembled and cleaned

New plunger-barrels

6. Fuel injector: 6 units

Work done:

- Disassembled, cleaned and inspect all components.
- Grinding Fuel injector surface, thrust spindle surface, nozzle cap nut surface.
- Set opening pressure at 320 bar

	Renewed spares	QTY	
a)	Fuel Nozzle	6 nos	Owner supplied
b)	Pressure adjusting rod washer	12 nos	Supplied by Junma
c)	Injector body external upper O-ring	12 nos	Supplied by Junma
d)	Injector body external lower O-ring	6 nos	Supplied by Junma




Junma Services Pte Ltd

7 Tuas South Ave 10
Singapore 637011

Tel: +65-6861 0329
Fax: +65-6863 0324

Service Junma Ltd
www.junma.biz



Work Done Report (Workshop)

Vessel Name	SLNC GOODWILL
IMO No.	9448334
Customer	American Ship Management
Junma Job Number	JS-SVC-2019-03-006a
Engine Maker/Model	ZJMD-MAN B&W 6L23/30H, E/No: 08365
Date	01.04.2019

e)	Nozzle cap landing face washer	6 nos	Supplied by Junma
f)	Vent plug washer	6 nos	Supplied by Junma
g)	Nozzle steel guide pin	4 nos	Supplied by Junma

7. Turbocharger (N20/R, Serial No. 7024941)



Work done:

- Disassembled turbocharger including removing of gas inlet casing and compressor wheel.
- Fly ash blasting of turbine blades
- Dynamic balancing of rotorshaft
- Removed nozzle ring from gas inlet casing and inspect
- Fly ash blasting of nozzle ring
- Fly ash blasting of cover ring
- Chemical cleaning of gas inlet casing, gas outlet casing and bearing casing
- Supplied bearing bush (P-N20/R-517.002), Qty 2pcs
- Supplied oil outlet gasket, Qty 1pc
- Supplied Copper ring, Qty 2pcs
- Supplied Copper gasket for GOC, Qty 1pc
- Supplied Copper gasket for gas admission casing, Qty 1pc
- Supplied Gasket for air casing, Qty 1pc
- Assembled TC as per maker's specification

8. Charge air cooler

Work done:

- Removed end covers, high pressure washed and applied a coat of coal tar epoxy.
- Airside ultrasonic degreased, seawater side descaled, high pressure washed, neutralized & blow dry.
- Vacuum leak tested on all tubes
- Close up end cover with new gaskets & cooler pressure tested on tube side at 4 kg/cm²

Sign of representative Junma Services Pte Ltd	Sign of Master/Chief Eng. & Vessel Stamp	
  <p>Date: 19.04.2019</p>		Junma Services
		Master/Chief Eng.
		Yard

TURBO SERVICES

JB 1903-0020


Service Report

NR20R / 172
SLNC GOODWILL

JUNMA SERVICES PTE LTD


Clearances

ANNEX 1



Position		Top	Right	Bottom	Left	Min	Max
1	C/W-Insert Radial gap	Before	0.3	0.3	0.4	0.40	0.70
		After	0.5	0.6	0.6		
2	C/W-Insert Axial gap					0.25	0.90
3	Rotor-Insert Radial gap	Before	0.55	0.55	0.60	0.40	0.70
		After	0.60	0.60	0.60		
4	Rotor-Insert Axial gap					0.55	1.25
5	Loc.Bearing-Lab.Ring Axial Clearance	Measured value before = 0.22				0.22	0.36
		Measured value after = 0.22					
6	C/W face run out	Measured value after = 0.03				0.06	

	TURBOCHARGER Inspection Report		Date: 14/04/2019
	Rotor complete		Type: NR20/R 172
Job no: JB 1903 - 0020	Vessel: SLNC GOODWILL		



Compressor wheel no:


Rotor shaft no:

	Dia. 1 (mm)	Dia 2 (mm)	Dia 3 (mm)	TOLERANCES
Labyrinth ring 'DA'	Ø 64.88	Ø 64.86	Ø 69.89	Ø ≤64.85
Locating ring 'DT'	Ø 64.92	Ø 64.87	Ø 64.86	Ø ≤64.85
Thrust length 'L'	118.25			118.25-0.03

Remarks :

All parts of satisfactory condition , all to be reused

Reported by (b) (6), (b) (7)(C)

	<h1>CHECK LIST</h1>	Date : 14 / 04 / 2019
With Engineer's Report dtd. _____		Turbocharger : NR20/R.172
Name of customer : JUNMA SERVICES	Address : _____	Serial No. : _____
Site/ship's name : SLNC GOODWILL	_____	Job No. : JB 1903-0020
_____	_____	Engine type : _____
_____	_____	Serial No. : _____

Turbocharger inspected - on _____ by _____

Reason _____

Last inspection - overhaul on _____ by _____

Service hours since the last inspection - overhaul _____ h

Service hours since commissioning _____ h

CONDITION OF COMPONENTS

Silencer +

Air-intake casing +

condition of felt plates _____

<input type="checkbox"/>	clean
<input type="checkbox"/>	dusty
<input checked="" type="checkbox"/>	oily
<input type="checkbox"/>	sooty
<input checked="" type="checkbox"/>	satisfactory
<input type="checkbox"/>	bad

Compressor casing, Insert piece + _____

traces of rotor contact _____

<input type="checkbox"/>	clean
<input type="checkbox"/>	dusty
<input checked="" type="checkbox"/>	oily
<input type="checkbox"/>	sooty
<input checked="" type="checkbox"/>	no
<input type="checkbox"/>	local _____ (clock)
<input type="checkbox"/>	total circumference
<input type="checkbox"/>	radial <input type="checkbox"/> axial
<input checked="" type="checkbox"/>	reused
<input type="checkbox"/>	replaced

Diffusor _____

<input checked="" type="checkbox"/>	satisfactory
<input type="checkbox"/>	bent
<input type="checkbox"/>	cracked
<input type="checkbox"/>	Slight eroded
<input checked="" type="checkbox"/>	reused
<input type="checkbox"/>	replaced

Turbine nozzle ring _____

<input checked="" type="checkbox"/>	satisfactory
<input type="checkbox"/>	new
<input type="checkbox"/>	cracked
<input type="checkbox"/>	scaled
<input type="checkbox"/>	eroded
<input type="checkbox"/>	loose
<input type="checkbox"/>	damaged by foreign matter
<input checked="" type="checkbox"/>	reused
<input type="checkbox"/>	replaced

Gas-admission casing, Insert piece + _____

Gas exit diffusor + _____

Trace of Contact _____

<input type="checkbox"/>	clean
<input type="checkbox"/>	rusty
<input checked="" type="checkbox"/>	sooty
<input type="checkbox"/>	worn
<input type="checkbox"/>	cracked
<input checked="" type="checkbox"/>	satisfactory
<input type="checkbox"/>	broken
<input checked="" type="checkbox"/>	no
<input type="checkbox"/>	local _____ (clock)
<input type="checkbox"/>	Total circumference
<input type="checkbox"/>	radial <input type="checkbox"/> axial
<input checked="" type="checkbox"/>	reused
<input type="checkbox"/>	replaced

Cartridge in assembled state

Turbine side _____

Vanes slight thin _____

Turbine rotor (blades) _____

<input type="checkbox"/>	clean
<input type="checkbox"/>	oil traces
<input checked="" type="checkbox"/>	carbon residue of oil
<input type="checkbox"/>	heavy fuel coating
<input checked="" type="checkbox"/>	satisfactory
<input type="checkbox"/>	bent


Damaged by foreign matter _____

traces of contact _____

<input type="checkbox"/>	cracked
<input type="checkbox"/>	on leading edges
<input type="checkbox"/>	on blades
<input checked="" type="checkbox"/>	no
<input type="checkbox"/>	local
<input type="checkbox"/>	total circumference
<input type="checkbox"/>	radial <input type="checkbox"/> axial

Compressor side _____

<input type="checkbox"/>	clean
<input type="checkbox"/>	dusty
<input type="checkbox"/>	sooty
<input checked="" type="checkbox"/>	oily



compressor wheel (blades)	<input checked="" type="checkbox"/>	satisfactory
damaged by foreign matter	<input type="checkbox"/>	slight dented
traces of contact	<input checked="" type="checkbox"/>	cracked on leading edges blades
	<input type="checkbox"/>	no <input type="checkbox"/> yes
	<input type="checkbox"/>	local
	<input type="checkbox"/>	total circumference
	<input type="checkbox"/>	radial <input type="checkbox"/> axial
Cartridge (599.001)	<input type="checkbox"/>	reused
	<input type="checkbox"/>	replaced
	<input checked="" type="checkbox"/>	disassembled

Gaps and clearances (section 1, sheet 52)

Transverse play of rotor _____ mm

Axial runout of compressor wheel _____ mm

Radial gap	1	_____ mm
Axial gap	2	_____ mm
Radial gap	3	_____ mm
Axial gap	4	_____ mm
Axial clearance	5	_____ mm

Refer to annex 1

CONDITION OF SINGLE PARTS OF CARTRIDGE

Bearing casing(517.001)

lock air passages	<input checked="" type="checkbox"/>	reused
oil passages	<input type="checkbox"/>	replaced
	<input type="checkbox"/>	clean
	<input checked="" type="checkbox"/>	carbon covered
	<input checked="" type="checkbox"/>	clean
	<input type="checkbox"/>	restricted
	<input type="checkbox"/>	clogged

Sealing cover, compressor side (517.017) or (517.087) + reused replaced

reason: _____

Turbine rotor (520.001)

Frictional oxidation	<input checked="" type="checkbox"/>	reused
	<input type="checkbox"/>	replaced
	<input checked="" type="checkbox"/>	no
	<input type="checkbox"/>	yes

reason: _____

Bearing bush (517.002)

<input checked="" type="checkbox"/> turbine side	<input type="checkbox"/> reused
<input checked="" type="checkbox"/> compressor side	<input checked="" type="checkbox"/> replaced

Compressor wheel (520.005)

quality of fit	<input checked="" type="checkbox"/>	reused
	<input type="checkbox"/>	replaced
	<input checked="" type="checkbox"/>	satisfactory
	<input type="checkbox"/>	medium
	<input type="checkbox"/>	poor

reason: _____

reason: _____

Distance sleeve (517.003)

<input checked="" type="checkbox"/>	reused
<input type="checkbox"/>	replaced

Labyrinth ring (520.006)

	<input checked="" type="checkbox"/>	reused
	<input type="checkbox"/>	replaced

reason: _____

reason: _____

Holding sleeve (517.004)

<input checked="" type="checkbox"/>	reused
<input type="checkbox"/>	replaced

reason: _____

Rotor (520.000)

rebalanced	<input type="checkbox"/>	no
	<input checked="" type="checkbox"/>	yes
condition before rebalancing	<input checked="" type="checkbox"/>	satisfactory
	<input type="checkbox"/>	bad

Cover (517.009)+

<input type="checkbox"/>	reused
<input type="checkbox"/>	replaced

reason: _____

Sealing cover, turbine side (517.017)+

<input checked="" type="checkbox"/>	reused
<input type="checkbox"/>	replaced

reason: _____

Seals

<input type="checkbox"/>	reused
<input checked="" type="checkbox"/>	replaced

+ if provided
Remarks: _____

Inspected by: (b) (6), (b) (7)(C)

		TURBOCHARGER Inspection Report	Date: 14 / 04 / 2019
		PHOTO	Type: NR20/R 172
Job no: JB 1903-0020	Vessel: SLNC GOODWILL		



Condition of turbocharger before overhaul



Dent on turbocharger foundation




Clearance taken during dismantling



Air casing before cleaning



Inspected by: (b) (6), (b) (7)(C)

	TURBOCHARGER Inspection Report	Date: 14 / 04 / 2019
	PHOTO	Type: NR20/R 172
Job no: JB 1903-0020	Vessel: SLNC GOODWILL	



Clearance taken during dismantling




View of compressor side cartridge



View of turbine side cartridge



Cover ring disk before ash blasting



Rotor shaft before ash blasting



Inspected by: (b) (6), (b) (7)(C)

TURBOCHARGER
Inspection Report

Date: 14 / 04 / 2019

PHOTO

Type: NR20/R 172

Job no: JB 1903-0020

Vessel: SLNC GOODWILL




Guide bush OD satisfactory – to reused




Labyrinth ring OD satisfactory – to reused



Intermediate ring before ash blasting




Nozzle ring good condition – to ash blast



Inspected by (b) (6), (b) (7)(C)


	TURBOCHARGER Inspection Report	Date: 14 / 04 / 2019
	PHOTO	Type: NR20/R 172
Job no: JB 1903-0020	Vessel: SLNC GOODWILL	



New bearing bush



Bearing casing after cleaning



Intermediate ring after ash blasting

Inspected by: (b) (6), (b) (7)(C)

TURBOCHARGER
Inspection Report


Date: 14 / 04 / 2019

PHOTO


Type: NR20/R 172

Job no: JB 1903-0020


Vessel: SLNC GOODWILL



Bearing casing after cleaning




Assembling of rotor shaft to bearing casing




Clearance taken during assembling

Dynamic balancing of rotor shaft

Inspected by: (b) (6), (b) (7)(C)


	TURBOCHARGER Inspection Report	Date: 14 / 04 / 2019
	PHOTO	Type: NR20/R 172
Job no: JB 1903-0020	Vessel: SLNC GOODWILL	



Nozzle ring after ash blasting



Air casing after cleaning



Filter silencer after chemical clean and new air filter mat

Inspected by: (b) (6), (b) (7)(C)

Spare Parts Renewal

SN	PART NAME	PART NO.	QTY	RECOMMENDATION
1	Bearing Bush	517.002	2	Due for renewal – Discoloured and worn
2	Copper gasket for gas outlet casing	-	1	Due for renewal
3	Gasket	517.068	1	Due for renewal
4	Seal ring	517.064	2	Due for renewal
5	Seal	517.018	1	Due for renewal
6	Copper gasket for gas inlet casing	-	1	Due for renewal
7	Gasket for air casing	-	1	Due for renewal
8	Air filter mat	-	2.2 M	
9				
10				
11				
LABOUR				
1	Bearing casing	517.001	1	Chemical clean
2	Turbine casing	501.001	2	Chemical clean
3	Compressor wheel	520.005	1	Chemical clean
4	Filter silencer		1	Chemical clean
Remarks :				
			Report By:	(b) (6), (b) (7)(C)

Balancing Print Screen

Before



After



Balancing Report

User

(b) (6), (b) (7)(C)

Type data


Rotor type
Last change
Set speed
ABC geometry

SLNC GOODWILL*
3/27/2019 2:18 PM
1200 rpm

Position of correction planes

Distance a
Distance b
Distance c
Radius 1
Radius 2

42 mm
175 mm
38 mm
83 mm
56 mm



Tolerance

Tolerance
Selected planes
Dynamic Tolerance of Unbalance
Correction Plane 1
Correction Plane 2

User defined
Correction planes
14.5 g-mm
21.0 g-mm

Measuring Results, Run: 1

Rotor ID
Measuring speed
Correction
Correction Plane 1 - Mass (Remove)
Correction Plane 2 - Mass (Remove)

NR20/R #1
1219 rpm
690 mg
331 mg
162 °
332 °
3.9 ° Tol
In Tol

3/27/2019

Measuring Results, Run: 6

Rotor ID
Measuring speed
Correction
Correction Plane 1 - Mass (Remove)
Correction Plane 2 - Mass (Remove)

NR20/R #1
1216 rpm
48.1 mg
95.4 mg
310 °
11 °
In Tol
In Tol

3/27/2019

WORK ORDER/SERVICE REQUISITION FORM

Ship Name : SLNC GOODWILL

WO/SR No : 8052986

Performed By : WO/Crew

Title : AUXILIARY ENGINE 01 2000 HR PM

SCHEDULING DATA

Scheduled : 05/11/2019

Event :

Completed : 07/23/2020 goodwill, 3ae

Canceled :

Next Due Date : 12/13/2020

Interval : 2000 H

ADMINISTRATIVE DATA

Created By : (b) (6), (b) (7)(C)

On : 05/09/2020

Auth. By:

On :

Apprvd. By:

On :

Account No:

Project No:

Priority :D

Job Catg: PREVENTATIVE MAINTENANCE

Class Job No :

Sugg Vend:

Dept.: ENGINE

EQUIPMENT PARTICULARS

Name: AUXILIARY ENGINE 01

Class Equipment Name :

Class Eq Code:

Equip Code : NGOO01U2MA5

Manufacturer : ZHENJIANG MARINE AUX

Model : L23/30

Serial No : 08365

Size : 960KW@900RPM

Type : 6L23/30

Equip. Location :

Criticality: B

SPACE PARTICULARS

RESOURCES & COST DATA

Estimated Cost : 0.00

Estimated Man-Hrs : 8

Std. Job Cost :

Actual. Man-Hrs : 8

Resource : 3RD ASST ENG , OILER

WO DESCRIPTION

AE #1 2000 hour maintenance

Check of valve rotators' rotation during engine rotation.
Fuel injection valve - adjustment of opening pressure
Fuel oil high-pressure pipe - dismantling and check
Check sleeve for injector and lap if necessary
Camshaft - inspection of gear wheels, bolts, connections etc.
Lubrication of camshaft bearing and roller running surfaces- check
Change Governor Oil
PSTP – alarm testing, shut downs, over speed and pressure alarms
Function test - main starting valve, starting valve, main valves and emergency start valve

WO FINDINGS

PTSP Testing conducted 13 JULY 2020 see WO# 8053518 at 43794hrs

7/21/2020 - Cylinder #3 injector replaced with new nozzle, set 320 hold 300. MAN nozzle. Off going nozzle failed the drip test as per MAN manual.
 7/22/2020 - Remaining five injectors removed, pressure recalibrated, cleaned and reinstalled. Cylinder 5 injector nozzle fails drip test. Replaced with MAN new nozzle, replaced thrust spindle and washer. Other nozzles all passed atomization test and drip test.

Cam spaces inspected. Some marring of cam lobes noted, specifically a loss of polished coating on cylinder 2 intake push rod lobe. See attached photo. No ridges, bumps or otherwise disruptive wear noted.
 Prelube energized, lubrication found on each fuel cam and in each camshaft bearing, observed as well on each crankshaft/connecting rod and upper cylinder assembly.

Governor lube oil changed.

Valve rotators marked, engine blown over on air and rotation observed.

Engine test run, no deficiencies noted.

3 A/E T. Lloyd-Rees

Perform By:

Tested By:

Signature:

Designation:


MATERIALS REQUIRED & USED

Equip Code Main PartNo	Reference Equipment/ Part name/ Spares Location	Required	Used	Requisitioned Required / Used
NGOO01U2MD8 AE 1 CYLINDER COVERS W/VALVES				
50510-01H, ITEM 075	GASKET F. TOP COVER #075 H*ENG STORE	0.00PC	1.00PC	
Equip Code Main PartNo	Reference Equipment/ Part name/ Spares Location	Required	Used	Requisitioned Required / Used
AE 1 FO INJECTORS				
51420-01H-033	AEM NOZZLE #033, PLATE 51402-01 J*ENG STORE	0.00EA	2.00EA	/
51402-01H-069	THRUST SPINDLE #069, PLATE 51402-01 J*ENG STORE	0.00EA	1.00EA	/
51402-01H-189	WASHER #189, PLATE 51402-01 J*ENG STORE	0.00EA	1.00EA	/

IMAGES

IMAGES

Screenshot_20200724-012509.png11



OTHER ATTACHMENTS

NSE Generator Jobs to Create.docx

JOB SAFETY ANALYSIS


JSA Required : NO

Use Template :

M3-1

INSTRUCTION BOOK

ZHENJIANG MARINE DIESEL WORKS



Instruction Book

L23/30H

Shipyard :

Ship name :

Hull No. :

Rule :

Add: 250 Guangtang Road Zhenjiang

Jiangsu Province P.R.China

Tel: [REDACTED]

Fax: +86 511 451 0033

IndexPage 1 (1)	Engine Data	500
--------------------	--------------------	------------

Description	Document no	Notes
Warning	<u>000.00</u>	
Description	Document no	Notes
Main data for engine	<u>500.00</u>	
Introduction	<u>500.01 (02)</u>	
Safety	<u>500.02 (01H)</u>	
Cross section	<u>500.05 (06H)</u>	
Key for engine designation	<u>500.10 (02)</u>	
Designation of cylinders	<u>500.11 (01H)</u>	
Engine rotation clockwise	<u>500.12 (02H)</u>	
Code identification for instruments	<u>500.20 (01H)</u>	
Introduction to planned maintenance programme	<u>500.24 (02H)</u>	
Planned maintenance programme	<u>500.25 (19H)</u>	
Planned maintenance programme	<u>500.25 (22H)</u>	
Operation data and set points	<u>500.30 (35H)</u>	
Data for pressure and tolerance	<u>500.35 (15H)</u>	
Data for tightening torque	<u>500.40 (21H)</u>	720/750 rpm
Data for tightening torque	<u>500.40 (22H)</u>	900 rpm
Declaration of weight	<u>500.45 (01H)</u>	
Ordering of spare parts	<u>500.50 (01H)</u>	
Service letters	<u>500.55 (01H)</u>	
Conversion table	<u>500.60 (01H)</u>	
Basic symbols for piping	<u>500.65 (01H)</u>	

Description Page 1 (1)	Warning	000.00
---------------------------	---------	--------

General

Warning !

(Marine engines only)

It is important that all MAN B&W Diesel A/S engines are operated within the given specifications and performance tolerances specified in the engines' Technical Files and are maintained according to the MAN B&W Diesel A/S maintenance instructions in order to comply with given emissions regulations.

In accordance with Chapter I of the Code of Federal Regulations, Part 94, Subpart C, §94.211 NOTICE is hereby given that Chapter I of the Code of Federal Regulations, Part 94, Subpart K, §94.1004 requires that the emissions related maintenance of the diesel engine shall be performed as specified in MAN B&W Diesel A/S instructions including, but not limited to, the instructions to that effect included in the Technical File.

08028-0D/H6250/94.08.12

L23/30H

General

The overhaul intervals are based on operation on a specified fuel oil quality at normal service output, which means 70-100% of MCR.

In the long run, it is not possible to obtain a secure and optimal economical running without an effective maintenance system.

With the structure and amount of information in the maintenance programme, it can be integrated in the entire ship's/power station's maintenance system or it can be used separately.

The crux of the maintenance system is the key diagram, see page 500.25, indicating the inspection intervals for the components/systems, so that the crew can make the necessary overhauls, based on the engines' condition and/or the time criteria.

The stated recommended intervals are only for guidance as different service conditions, the quality of the fuel oil and the lubricating oil, treatment of the cooling water, etc, will decisively influence the actual service results and thus the intervals between necessary overhauls.

Experience with the specific plant/crew is to be used for adjustment of time between overhaul. Further it is to be used for adjusting the timetable stated for guidance in the working cards.

Working Cards

Each of the working cards can be divided into two: a front page and one or several pages, describing and illustrating the maintenance work.

The front page indicates the following:

1. Safety regulations, which MUST be carried out before the maintenance work can start.
2. A brief description of the work.
3. Reference to work, which must be carried out, if any, before the maintenance work can start.

4. Related procedures - indicates other works, depending on this work - or works which would be expedient to carry out.

5. Indicates x number of men in x number of hours for accomplishing the work.

The stated consumption of hours is only intended as a guide.

Experience with the specific station/crew may lead to a bringing up-to-date.

6. Refers to data, which are required for carrying out the work.

7. Special tools, which must be used. Please note that not all tools are standard equipment.

8. Various requisite hand tools.

9. Indicates the components/parts, which it is advisable to replace during the maintenance work. Please note, that this is a condition for the intervals stated.





Fig 1. Guidance instruction for working cards.

0802B-0D/H/5250/94.08.12



Description Page 1 (4)	Planned Maintenance Programme	500.25 Edition 19H
---------------------------	--------------------------------------	------------------------------

L23/30H
900 RPM

Description	Check new/overhauled parts after hours	Time Between Overhaul							Working Card No				
		50	200	2000	6000	12000	24000	Daily		Weekly	Monthly	3rd month	Observations
Operating of Engine: Readings of data for engine and alternor, with reference to "Engine Performance Data", section 502.01													502-01.00
Cylinder Head: Inlet and exhaust valve - overhaul and regrinding of spindel and valve seat Inspection of inlet, exhaust valves and valve guide Check of valve rotators' rotation during engine rotation . Sleeve for fuel injector Safety valve - overhaul and adjustment of opening pressure Indicator valve Cylinder head cooling water space - inspection Cylinder head nut - retightening	200												505-01.10 505-01.05 505-01.05 505-01.30 505-01.25 505-01.26 505-01.45 505-01.40
Piston, Connecting Rod and Cylinder Liner: Inspection of piston Piston ring and scraper ring Piston pin and bush for connecting rod - check of clearance Connecting rod - measuring of big-end bore Inspection of big-end bearing shells Connecting rod - retightening Cylinder liner - cleaning, honing and measuring Cylinder liner removed - check the water space and wear ring in frame	200												506-01.10 506-01.10 506-01.15 506-01.15 506-01.16 506-01.25 506-01.35 506-01.40
Camshaft and Camshaft Drive: Camshaft - inspection of gear wheels, bolts, connections etc. Camshaft bearing - inspection of clearance Camshaft adjustment - check the condition Lubrication of camshaft bearing - check	200												507-01.00 507-01.05 507-01.20 507-01.00

08028-0D/H5250/94.08.12

500.25 Edition 19H	Planned Maintenance Programme	Description Page 2 (4)
------------------------------	--------------------------------------	---------------------------

L23/30H
900 RPM

Description ● = Overhaul to be carried out ■ = Check the condition	Check new/overhauled parts after hours	Time Between Overhaul							Working Card No			
		50	200	2000	6000	12000	24000	Daily		Weekly	Monthly	3rd month
Operating Gear for Inlet Valves, Exhaust Valves and Fuel Injection Pumps:												
Roller guide for valve gear				■								508-01.00
Valve gear - valve bridge, spring, push rod, etc				■								508-01.10
Roller guide for fuel injection pump				■								508-01.05
Roller guide housing				■								508-01.10
Inlet and exhaust valve - check and adjustment of valve clearance		■										508-01.10
Lubricating of operating gear - check				■								508-01.00 508-01.05
Control and Safety System, Automatics and Instruments:												
Safety, alarm and monitoring equipment										■		509-01.00
Lambda controller - adjustment										■		509-10.00
Governor - check oil level, see governor instruction book, section 509										■		
Crankshaft and Main Bearing:												
Checking of main bearings alignment, (autolog)				■								510-01.00
Inspection of main bearing				■								510-01.05
Inspection of guide bearing				■								510-01.10
Vibration damper - check the condition					■							510-04.00
Lubricating of gear wheel for lub. oil pump and cooling water pump etc.												
Counterweight - retightening, see page 500.40	900*			■								
Main- and guide bearing cap - retightening	200			■								510-01.05 510-01.10
<i>* If screw can be tightened then the screw have to be loosened and retightened after page 500.40.</i>												

08028-0D/H5250/94.08.12



Description Page 3 (4)	Planned Maintenance Programme	500.25 Edition 19H
---------------------------	--------------------------------------	------------------------------

L23/30H
900 RPM

Description	● = Overhaul to be carried out ■ = Check the condition	Time Between Overhaul							Working Card No					
		Check new/overhauled parts after hours	50	200	2000	6000	12000	24000		Daily	Weekly	Monthly	3rd month	Observations
Engine Frame and Baseframe:														
Holding down bolts - retightening, see page 500.40		200												
Bolts between engine frame and base frame - retightening, see page 500.40		200												
For flexible mounted engines - check anti-vibration mountings		200												519-03.00
Safety cover - function test														511-01.00
Turbocharger System:														
Wet cleaning of turbine side											●			512-15.00
Water washing of compressor side			●											512-05.00
Cleaning of air filter - compressor side (see turbo-charger instruction book)														
Turbocharger complete - dismantling, cleaning, inspection etc. (see turbocharger instruction book)														
Charging air cooler - cleaning and inspection												■		512-01.00
Charging air cooler housing - draining												●		
Exhaust pipe - compensator												■		
Compressed Air System:														
Air starter motor - dismantling and inspection													■	513-01.30
Function test - main starting valve, starting valve, main valves and emergency start valve													■	513-01.40
Dirt separator - dismantling and cleaning												●		
Muffler - dismantling and cleaning												●		
Compressed air system - draining												●		513-01.90
Compressed air system - check of the system													■	513-01.90

08028-0D/H5250/94.08.12

500.25 Edition 19H	Planned Maintenance Programme	Description Page 4 (4)
-----------------------	--------------------------------------	---------------------------

L23/30H
900 RPM

Description	Check new/overhauled parts after hours	Time Between Overhaul								Working Card No		
		50	200	2000	6000	12000	24000	Daily	Weekly		Monthly	3rd month
Fuel Oil System and Injection Equipment:												
Fuel oil filter - dismantling and cleaning												● 514-01.15
Fuel oil feed pump												● 514-10.00
Fuel oil injection pump - dismantling and cleaning												● 514-01.05
Fuel injection valve - adjustment of opening pressure ...	200		■									514-01.10
Fuel oil high-pressure pipe - dismantling and check			■									514-01.05
Adjustment of the maximum combustion pressure												● 514-05.01
Fuel oil system - check the system											■	514-01.90
Nozzle cooling system - check the system if installed											■	514-01.90
Fuel oil - oil samples after every bunkering, see sec.504												
Lubricating Oil System:												
Lubricating oil pump - engine driven						■						515-01.00
Lubricating oil filter - cleaning and exchange												● 515-01.10
Lubricating oil cooler												● 515-06.00
Prelubricating pump - el.-driven						■						515-01.05
Thermostatic valve											■	515-01.20
Centrifugal filter - cleaning and exchange of paper												● 515-15.00
Hand pump												● 515-10.00
Lubricating oil - oil samples, see section 504											■	
Lubricating oil system - check the system											■	515-01.90
Cooling Water System:												
Cooling water pump - engine-driven (sea water and fresh water)						■						516-04.00
Thermostatic valve											■	516-04.00
Cooling water system - check the system											■	516-01.90
Cooling water system - water samples, see sec. 504											■	

08028-0D/H5250/94.08.12



Description Page 1 (5)	Planned Maintenance Programme	500.25 Edition 22H
---------------------------	--------------------------------------	------------------------------

L23/30H
720/750 RPM

Description	Check new/overhauled parts after hours	Time Between Overhaul						Working Card No					
		50	200	2000	* 6000	** 12000	*** 24000		Daily	Weekly	Monthly	3rd month	Observations
Operating of Engine: Readings of data for engine and alternator with reference to "Engine Performance Data", section 502.01													502-01.00
Cylinder Head: Inlet and exhaust valve - overhaul and regrinding of spindle and valve seat Inspection of inlet, exhaust valves and valve guide Check of valve rotators' rotation during engine rotation Sleeve for fuel injector Safety valve - overhaul and adjustment of opening pressure Indicator valve Cylinder head cooling water space - inspection Cylinder head nut - retightening	200			■	●	●	●						505-01.10 505-01.05 505-01.05 505-01.30 505-01.25 505-01.26 505-01.45 505-01.40
Piston, Connecting Rod and Cylinder Liner: Inspection of piston Piston ring and scraper ring Piston pin and bush for connecting rod - check of clearance Connecting rod - measuring of big-end bore Inspection of big-end bearing shells Connecting rod - retightening Cylinder liner - cleaning, honing and measuring Cylinder liner removed - check the water space and wear ring in frame	200			■	●	●	●						506-01.10 506-01.10 506-01.15 506-01.15 506-01.16 506-01.25 506-01.35 506-01.40
Camshaft and Camshaft Drive: Camshaft - Inspection of gear wheels, bolts, connections etc. Camshaft bearing - inspection of clearance Camshaft adjustment - check the condition Lubrication of camshaft bearing - check	200			■	●	●	●						507-01.00 507-01.05 507-01.20 507-01.00

Overhaul to be repeated:

- * Repeat 2.000 hours maintenance, with activities mentioned under 6.000 hours maintenance.
- ** Repeat 6.000 hours maintenance, with activities mentioned under 12.000 hours maintenance.
- *** Repeat 12.000 hours maintenance, with activities mentioned under 24.000 hours maintenance.

08028-0D/H5250/94.08.12


500.25 Edition 22H	Planned Maintenance Programme	Description Page 2 (5)
------------------------------	--------------------------------------	---------------------------

L23/30H
720/750 RPM

Description ■ = Off-line check of condition (engine shutdown) □ = On-line check of condition (engine running) ● = Off-line service / overhaul (engine shutdown) ○ = On-line service / overhaul (engine running)	Check new/overhauled parts after hours	Time Between Overhaul							Working Card No			
		50	200	2000	6000	12000	24000	Daily		Weekly	Monthly	3rd month
Operating Gear for Inlet Valves, Exhaust Valves and Fuel Injection Pumps: Roller guide for valve gear Valve gear - valve bridge, spring, push rod, etc Roller guide for fuel injection pump Roller guide housing Inlet and exhaust valve - check and adjustment of valve clearance Lubricating of operating gear - check				■	■	■						508-01.00 508-01.10 508-01.05 508-01.10 508-01.10 508-01.00 508-01.05
Control and Safety System, Automatics and Instruments: Safety, alarm and monitoring equipment Lambda controller - adjustment Governor - check oil level, see governor instruction book, section 509												509-01.00 509-10.00
Crankshaft and Main Bearing: Checking of main bearings alignment, (autolog) Inspection of main bearing Inspection of guide bearing Vibration damper - check the condition Lubricating of gear wheel for lub. oil pump and cooling water pump etc. Counterweight - retightening, see page 500.40 Main- and guide bearing cap - retightening <i>* If screw can be tightened then the screw have to be loosened and retightened after page 500.40.</i>	900* 200			■	■	■					510-01.00 510-01.05 510-01.10 510-04.00 510-01.05 510-01.10	

38028-0D/H5250/94.08.12

- Overhaul to be repeated:**
- * Repeat 2.000 hours maintenance, with activities mentioned under 6.000 hours maintenance.
 - ** Repeat 6.000 hours maintenance, with activities mentioned under 12.000 hours maintenance.
 - *** Repeat 12.000 hours maintenance, with activities mentioned under 24.000 hours maintenance.





Description Page 3 (5)	Planned Maintenance Programme	500.25 Edition 22H
---------------------------	--------------------------------------	------------------------------

L23/30H
720/750 RPM

Description <input checked="" type="checkbox"/> = Off-line check of condition (engine shutdown) <input type="checkbox"/> = On-line check of condition (engine running) <input checked="" type="checkbox"/> = Off-line service / overhaul (engine shutdown) <input type="checkbox"/> = On-line service / overhaul (engine running)	Check new/overhauled parts after hours	Time Between Overhaul							Working Card No			
		50	200	2000	6000	12000	24000	Daily		Weekly	Monthly	3rd month
Engine Frame and Baseframe:												
Holdingdown bolts - retightening, see page 500.40	200			<input checked="" type="checkbox"/>								
Bolts between engine frame and base frame - retightening, see page 500.40	200			<input checked="" type="checkbox"/>								
For flexible mounted engines - check anti-vibration mountings	200			<input type="checkbox"/>								519-03.00
Safety cover - function test				<input checked="" type="checkbox"/>								511-01.00
Turbocharger System:												
Dry cleaning of turbine side		<input type="checkbox"/>										512-10.00
Water washing of compressor side		<input checked="" type="checkbox"/>										512-05.00
Cleaning of air filter - compressor side (see turbocharger instruction book)												
Turbocharger complete - dismantling, cleaning, inspection etc. (see turbocharger instruction book)											<input checked="" type="checkbox"/>	512-01.00
Charging air cooler - cleaning and inspection											<input type="checkbox"/>	
Charging air cooler housing - draining											<input type="checkbox"/>	
Exhaust pipe - compensator											<input checked="" type="checkbox"/>	
Compressed Air System:												
Air starter motor - dismantling and inspection											<input checked="" type="checkbox"/>	513-01.30
Function test - main starting valve, starting valve, main valves and emergency start valve											<input checked="" type="checkbox"/>	513-01.40
Dirt separator - dismantling and cleaning											<input checked="" type="checkbox"/>	
Muffler - dismantling and cleaning											<input checked="" type="checkbox"/>	
Compressed air system - draining											<input type="checkbox"/>	513-01.90
Compressed air system - check of the system											<input type="checkbox"/>	513-01.90

Overhaul to be repeated:

- * Repeat 2.000 hours maintenance, with activities mentioned under 6.000 hours maintenance.
- ** Repeat 6.000 hours maintenance, with activities mentioned under 12.000 hours maintenance.
- *** Repeat 12.000 hours maintenance, with activities mentioned under 24.000 hours maintenance.

08028-0D/H5250/94.08.12

500.25 Edition 22H	Planned Maintenance Programme	Description Page 4 (5)
------------------------------	--------------------------------------	---------------------------


L23/30H
720/750 RPM

Description	Check new/overhauled parts after hours	Time Between Overhaul							Working Card No				
		50	200	2000	6000	12000	24000	Daily		Weekly	Monthly	3rd month	Observations
Fuel Oil System and Injection Equipment:													
Fuel oil filter - dismantling and cleaning												☉	514-01.15
Fuel oil feed pump												☉	514-10.00
Fuel oil injection pump - dismantling and cleaning												☉	514-01.05
Fuel injection valve - adjustment of opening pressure ...	200			☐									514-01.10
Fuel oil high-pressure pipe - dismantling and check				☐									514-01.05
Adjustment of the maximum combustion pressure												☉	514-05.01
Fuel oil system - check the system												☐	514-01.90
Nozzle cooling system - check the system												☐	
Fuel oil - oil samples after every bunkering, see sec.504													
Lubricating Oil System:													
Lubricating oil pump - engine-driven													515-01.00
Lubricating oil filter - cleaning and exchange												☉	515-01.10
Lubricating oil cooler												☉	515-06.00
Prelubricating pump - el. driven													515-01.05
Thermostatic valve												☐	515-01.20
Centrifugal filter - cleaning and exchange of paper												☉	515-15.00
Lubricating oil - oil samples, see section 504													515-01.90
Lubricating oil system - check the system													
Cooling Water System:													
Cooling water pump - engine-driven (sea water and fresh water)													516-04.00
Thermostatic valve												☐	516-04.00
Cooling water system - check the system													516-01.90
Cooling water system - water samples, see sec. 504													

Overhaul to be repeated:

- * Repeat 2.000 hours maintenance, with activities mentioned under 6.000 hours maintenance.
- ** Repeat 6.000 hours maintenance, with activities mentioned under 12.000 hours maintenance.
- *** Repeat 12.000 hours maintenance, with activities mentioned under 24.000 hours maintenance.

08028-0D/H5250/94.08.12





Description Page 5 (5)	Planned Maintenance Programme	500.25 Edition 22H
---------------------------	--------------------------------------	------------------------------

L23/30H
720/750 RPM

Auxiliary equipment

The precondition of the reliability and operating economy of the GenSet will to a great extent depend on correct operation and proper maintenance of all equipment in the Power Plant.

All auxiliary equipment in the Power Plant must be operated as described in the operation- and maintenance instructions from the manufacturer of the components.

It is also essential that the engine room personnel is fully acquainted with the functions and mode of operation of the auxiliary equipment.

08028-0D/H5250/94.08.12

Description Page 1 (2)	Operation Data & Set Points	500.30 Edition 35H
---------------------------	--	------------------------------

L23/30H

	Normal Value at Full load		Alarm Set point		Autostop of engine	
Lubricating Oil System						
Temp. before cooler (outlet engine)	SAE 30 SAE 40	TI 20 TI 20	60-75° C 65-82° C	TAH 20 TAH 20	90° C 100° C	
Temp. after cooler (inlet engine)	SAE 30 SAE 40	TI 22 TI 22	45-65° C 50-72° C	TAH 22 TAH 22	75° C 85° C	TSH 22 TSH 22
Pressure after filter (inlet eng)		PI 22	3-4 bar	PAL 22	3 bar	PSL 22
Elevated pressure i.g. when centrifugal filter installed		PI 22	4-5 bar	PAL 22	4 bar	PSL 22
Pressure drop across filter		PDAH 21-22	0.5-1 bar	PDAH 21-22	1.5 bar	
Prelubricating pressure		PI 25	0.1-0.5 bar	LAL 25	level switch	
Pressure inlet turbocharger		PI 23	1.5 ± 0.2 bar			
Lub. oil, level in base frame				LAL 28/LAH 28	low/high level	
Temp. main bearings		TE 29	75-85° C	TAH 29	95° C	
Fuel Oil System						
Pressure after filter	MDO HFO	PI 40 PI 40	2-3 bar (A)	PAL 40 PAL 40	1.5 bar 4 bar	
Leaking oil				LAH 42	leakage	
Press. nozz. cool. oil, inlet eng.		PI 50	2-3 bar	PAL 50	1.5 bar (C)	
Temp. nozz. cool. oil, outlet eng.		TI 51	80-90° C		(C)	
Cooling Water System						
Press. LT-system, inlet engine		PI 01	1-2.5 bar	PAL 01	0.4 bar + (B)	
Press. HT-system, inlet engine		PI 10	1-3.0 bar	PAL 10	0.4 bar + (B)	
Temp. HT-system, inlet engine		TI 10	60-75° C			
Temp. HT-system, outl. cyl. units		TI 11	70-85° C			
Temp. HT-system, outlet engine				TAH 12 TAH 12-2	90° C 93° C	TSH 12
Temp. raise across cyl. units			max. 10° C			95° C
Exhaust Gas and Charge Air						
Exh. gas temp. before TC		TI 62	425-475° C	TAH 62 TAH 62-2	550° C 600° C	
Exh. gas temp. outlet cyl. Diff. between individual cyl.		TI 60	280-390° C	TAH 60 TAD 60	420° C average ± 50° C	
Exh. gas temp. after TC		TI 61 TI 61	275-350° C* 320-390° C**	TAH 61	500° C	
Ch. air press. after cooler		PI 31	2-2.5 bar			
Ch. air temp. after cooler		TI 31	35-55° C	TAH 31	65° C	
Compressed Air System						
Press. inlet engine		PI 70	7-9 bar	PAL 70	7 bar	
Speed Control System						
Engine speed						
Mechanical		SI 90	720 rpm	SAH 81	815 rpm	SSH 81
Elec.		SI 90	750 rpm	SAH 81	850 rpm	SSH 81
Mechanical		SI 90	750 rpm	SAH 81	850 rpm	SSH 81
Elec.		SI 90	900 rpm	SAH 81	1015 rpm	SSH 81
Mechanical		SI 90	900 rpm	SAH 81	1015 rpm	SSH 81
Elec.		SI 90	900 rpm	SAH 81	1015 rpm	SSH 81
Turbocharger speed		SI 89		SAH 89	(D)	

Specific plants will not comprise alarm equipment and autostop for all parameters listed above. For specific plants additional parameters can be included. For remarks to some parameters, see overleaf.

* for 720/750 rpm


** for 900 rpm.

08028-0D/H5250/94.08.12

M3-1

INSTRUCTION BOOK

ZHENJIANG MARINE DIESEL WORKS



Instruction Book

L23/30H

..... Shipyard :

Ship name :

Hull No. :

Rule :

Add: 250, Guangtangqiao Zhenjiang

Jiangsu Province P.R.China

Tel: [REDACTED]

Fax: +86 511 451 0033

IndexPage 1 (1)	Engine Data	500
--------------------	--------------------	------------

Description	Document no	Notes
Warning	<u>000.00</u>	
Description	Document no	Notes
Main data for engine	<u>500.00</u>	
Introduction	<u>500.01 (02)</u>	
Safety	<u>500.02 (01H)</u>	
Cross section	<u>500.05 (06H)</u>	
Key for engine designation	<u>500.10 (02)</u>	
Designation of cylinders	<u>500.11 (01H)</u>	
Engine rotation clockwise	<u>500.12 (02H)</u>	
Code identification for instruments	<u>500.20 (01H)</u>	
Introduction to planned maintenance programme	<u>500.24 (02H)</u>	
Planned maintenance programme	<u>500.25 (19H)</u>	
Planned maintenance programme	<u>500.25 (22H)</u>	
Operation data and set points	<u>500.30 (35H)</u>	
Data for pressure and tolerance	<u>500.35 (15H)</u>	
Data for tightening torque	<u>500.40 (21H)</u>	- 720/750 rpm
Data for tightening torque	<u>500.40 (22H)</u>	- 900 rpm
Declaration of weight	<u>500.45 (01H)</u>	
Ordering of spare parts	<u>500.50 (01H)</u>	
Service letters	<u>500.55 (01H)</u>	
Conversion table	<u>500.60 (01H)</u>	
Basic symbols for piping	<u>500.65 (01H)</u>	

Description Page 1 (1)	Warning	000.00
---------------------------	---------	--------

General

Warning !

(Marine engines only)

It is important that all MAN B&W Diesel A/S engines are operated within the given specifications and performance tolerances specified in the engines' Technical Files and are maintained according to the MAN B&W Diesel A/S maintenance instructions in order to comply with given emissions regulations.

In accordance with Chapter I of the Code of Federal Regulations, Part 94, Subpart C, §94.211 NOTICE is hereby given that Chapter I of the Code of Federal Regulations, Part 94, Subpart K, §94.1004 requires that the emissions related maintenance of the diesel engine shall be performed as specified in MAN B&W Diesel A/S instructions including, but not limited to, the instructions to that effect included in the Technical File.

08028-0D/H6250/94.08.12


Description Page 1 (3)	Disturbances during Running	503.03 Edition 01H
---------------------------	------------------------------------	------------------------------

L23/30H

Trouble	Possible Cause	Trouble Shooting
Exhaust temperature(s) increase(s)	<p>(All cyls.) Increased charging air temperature due to ineffective air coolers.</p> <p>(All cyls.) Fouling or air and gas passages.</p> <p>(All cyls.) Insufficient cleaning of fuel oil or changed combustion characteristics.</p> <p>(All cyls.) Wrong position of camshaft (maladjustment).</p> <p>(single cyls.) Fuel valve or valve nozzle defective.</p> <p>(Single cyls.) Leaky exhaust valves (1).</p> <p>(Single cyls.) Blow-by leaky combustion chamber (2).</p> <p>(Single cyls.) Damaged fuel pump cam.</p>	<p>See Working Card 512-01.00.</p> <p>Reduce load and water-wash turbine. Clean air filters and coolers.</p> <p>See Description 504.25.</p> <p>Check P_{max}. Check camshaft adjustment.</p> <p>See Working Card 514-01.10.</p> <p>Check the valve clearance. Replace cyl. head with defective valve.</p> <p>See Working Card 506-01.00.</p> <p>Replace the single camshaft section.</p>
Exhaust temperature(s) decrease(s)	<p>(All cyls.) Decreased charging air temperature.</p> <p>(Single cyls.) Air in fuel pump(s) and fuel injection valve(s).</p> <p>(Single cyls.) Spindle in fuel valve sticking (3).</p> <p>(Single cyls.) Fuel pump plunger sticking or leaking.</p>	<p>Check that thermostatic valve (bypass valve) in cold water system is working properly and correctly set.</p> <p>Venting of fuel pump(s) until fuel without air bubbles appears. Check feed pump pressure.</p> <p>Change and overhaul defective fuel valve.</p> <p>Change fuel pump plunger/barrel assembly.</p>
Engine RPM decreases	<p>Pressure before fuel pumps too low.</p> <p>Fuel valve or fuel pump defective.</p> <p>Water in the fuel.</p> <p>Governor defective (4).</p> <p>Increased internal friction in engine (5).</p>	<p>Raise fuel oil feed pump pressure to normal. Check filter.</p> <p>Change defective valve or pump.</p> <p>Drain off water and vent the fuel pumps.</p> <p>Replace defective governor.</p> <p>See "Ignition in Crankcase".</p>

Cont.

08028-0D/H5250/94.08.12



503.03 Edition 01H	Disturbances during Running	Description Page 2 (3)
-----------------------	------------------------------------	---------------------------

L23/30H

Trouble	Possible Cause	Trouble Shooting
Engine stops.	Shutdown.	Check pressure and temperatures. If OK, check for faults in shutdown devices. See also Starting Failures.
Smoky exhaust.	Turbine RPM lagging behind engine RPM. Air supply too low. Fuel valves or nozzles defective. "Trumpets" at nozzle holes. Failure of cooling (especially during heavy-oil operation) (6).	Reasonably smoke is normal when RPM increases; no measures called for. If smoky exhaust during normal running, clean turbine(s) and check valves. Fouling of air and gas passages, see section 512. See Working Card 514-01.10. Overhaul fuel valves.
Exhaust valve knocking.	Adjusting screw for valve setting loose. Push rod thrust disc damaged.	Inspect and replace defective parts as necessary.
Rising cooling water temperature.	Pump stopped. Increased friction (7).	Stop the engine. Check the cooling water. Find cause of increased friction and remedy fault.
Lubricating oil pressure fails.	Lubricating oil pump defective. Filters/cooler fouled.	Stop the engine. For further details, see "Ignition in crankcase". See also Working Card 515-01.00 for lub. oil pump and Working Card 515-01.10 for the lub. oil filter

Remarks

1) This manifests itself by the exhaust temperature rising and falling of the compression and maximum combustion pressure of the respective cylinder dropping.

To limit the damage to the valves these should be changed immediately, if possible, or the fuel pump of the cylinder concerned should be put out of operation by moving the index to stop and locking it in this position.

2) Blow-by means a serious danger of piston seizure, and the engine must, if possible, be stopped and the piston in question pulled. If this is not possible, the fuel pump index must, as described above, be moved to stop. Leaky piston rings will normally result in a heavy excess pressure in the crankcase.

08028-0D/H5250/94.08.12

L23/30H

3) If this happens the fuel pump barrel and plunger must be changed, and if, it is necessary to increase the fuel pump index by more than 10 index degrees, to obtain full load of the respective cylinder, the fuel pump is worn out in most cases. Usually this is confirmed by inspection of the fuel pump plunger on which the helical cut-off edge will show a pitted and corroded area where material is plucked out. In that case the pump can be provided with a new barrel and plunger.

4) The governor will not reduce the fuel pump delivery to zero in case of, for instance, failure of the governor oil pump, but the engine speed will start fluctuating.

When the governor is defective the engine is protected against racing by the overspeed trip, i.e. the engine is stopped automatically in case of excessive speed. It is therefore, essential, that the overspeed trip is kept in perfect order. Regarding governor failure, see special instruction book.

5) Usually a bearing failure will not slow down the engine appreciably, but the seizure of a piston in the cylinder liner might do so. Repair is necessary before starting the engine again. Feelover and look out for oil mist.

6) If the cooling water temperature for the entire engine has risen to 90-100° C, it should be checked whether steam has developed by opening the test cocks, if fitted on the discharge from cylinders. If this is the case, there is no water on the cooling surfaces, which may therefore be heated unduly. To avoid heat stresses arising in cylinder liners and cylinder heads, if the water returns too early, the engine should be stopped and left to cool, while the discharge valve is closed. After 15 minutes it is opened a little to allow the water to rise slowly in the cooling jackets. Check filling at test cocks. Make crankcase inspection to ascertain that internal water leakage has not arisen. Remember slow turning with open indicator valves at subsequent starting-up.


7) If the lubricating oil pressure drops below the minimum mentioned in "Data" find the cause of the pressure drop and remedy the defect before re-starting the engine. Feel over 5-15-30 minutes after starting, and again when full load is obtained. See section 502.

M3-1

INSTRUCTION BOOK

(b) (7) (C), (b) (7) (D)

ZHENJIANG MARINE DIESEL WORKS



Instruction Book

L23/30H

..... Shipyard :

Ship name :

Hull No. :

Rule :

Add: 250, Guangtangqiao Zhenjiang

Jiangsu Province P.R.China

Tel: [REDACTED]

Fax: +86 511 451 0033

IndexPage 1 (1)	Engine Data	500
--------------------	--------------------	------------

Warning	Description	Document no	Notes
		<u>000.00</u>	
Main data for engine	Description	Document no	Notes
	Introduction	<u>500.01 (02)</u>	
	Safety	<u>500.02 (01H)</u>	
	Cross section	<u>500.05 (06H)</u>	
	Key for engine designation	<u>500.10 (02)</u>	
	Designation of cylinders	<u>500.11 (01H)</u>	
	Engine rotation clockwise	<u>500.12 (02H)</u>	
	Code identification for instruments	<u>500.20 (01H)</u>	
	Introduction to planned maintenance programme	<u>500.24 (02H)</u>	
	Planned maintenance programme	<u>500.25 (19H)</u>	
	Planned maintenance programme	<u>500.25 (22H)</u>	
	Operation data and set points	<u>500.30 (35H)</u>	
	Data for pressure and tolerance	<u>500.35 (15H)</u>	
	Data for tightening torque	<u>500.40 (21H)</u>	720/750 rpm
	Data for tightening torque	<u>500.40 (22H)</u>	900 rpm
	Declaration of weight	<u>500.45 (01H)</u>	
	Ordering of spare parts	<u>500.50 (01H)</u>	
	Service letters	<u>500.55 (01H)</u>	
	Conversion table	<u>500.60 (01H)</u>	
	Basic symbols for piping	<u>500.65 (01H)</u>	

Description Page 1 (1)	Warning	000.00
---------------------------	---------	--------

General

Warning !

(Marine engines only)

It is important that all MAN B&W Diesel A/S engines are operated within the given specifications and performance tolerances specified in the engines' Technical Files and are maintained according to the MAN B&W Diesel A/S maintenance instructions in order to comply with given emissions regulations.

In accordance with Chapter I of the Code of Federal Regulations, Part 94, Subpart C, §94.211 NOTICE is hereby given that Chapter I of the Code of Federal Regulations, Part 94, Subpart K, §94.1004 requires that the emissions related maintenance of the diesel engine shall be performed as specified in MAN B&W Diesel A/S instructions including, but not limited to, the instructions to that effect included in the Technical File.

08028-0D/H6250/94.08.12

L23/30H

General

The overhaul intervals are based on operation on a specified fuel oil quality at normal service output, which means 70-100% of MCR.

In the long run, it is not possible to obtain a secure and optimal economical running without an effective maintenance system.

With the structure and amount of information in the maintenance programme, it can be integrated in the entire ship's/power station's maintenance system or it can be used separately.

The crux of the maintenance system is the key diagram, see page 500.25, indicating the inspection intervals for the components/systems, so that the crew can make the necessary overhauls, based on the engines' condition and/or the time criteria.

The stated recommended intervals are only for guidance as different service conditions, the quality of the fuel oil and the lubricating oil, treatment of the cooling water, etc, will decisively influence the actual service results and thus the intervals between necessary overhauls.

Experience with the specific plant/crew is to be used for adjustment of time between overhaul. Further it is to be used for adjusting the timetable stated for guidance in the working cards.

Working Cards

Each of the working cards can be divided into two: a front page and one or several pages, describing and illustrating the maintenance work.

The front page indicates the following:

1. Safety regulations, which **MUST** be carried out before the maintenance work can start.
2. A brief description of the work.
3. Reference to work, which must be carried out, if any, before the maintenance work can start.

4. Related procedures - indicates other works, depending on this work - or works which would be expedient to carry out.

5. Indicates x number of men in x number of hours for accomplishing the work.

The stated consumption of hours is only intended as a guide.

Experience with the specific station/crew may lead to a bringing up-to-date.

6. Refers to data, which are required for carrying out the work.

7. Special tools, which must be used. Please note that not all tools are standard equipment.

8. Various requisite hand tools.

9. Indicates the components/parts, which it is advisable to replace during the maintenance work. Please note, that this is a condition for the intervals stated.





Fig 1. Guidance instruction for working cards.

0802B-0D/H/5250/94.08.12



Description Page 1 (4)	Planned Maintenance Programme	500.25 Edition 19H
---------------------------	--------------------------------------	------------------------------

L23/30H
900 RPM

Description	Check new/overhauled parts after hours	Time Between Overhaul							Working Card No
		50	200	2000	6000	12000	24000	Daily Weekly Monthly 3rd month Observations	
Operating of Engine: Readings of data for engine and alternor, with reference to "Engine Performance Data", section 502.01								☐	502-01.00
Cylinder Head: Inlet and exhaust valve - overhaul and regrinding of spindle and valve seat Inspection of inlet, exhaust valves and valve guide Check of valve rotators' rotation during engine rotation . Sleeve for fuel injector Safety valve - overhaul and adjustment of opening pressure Indicator valve Cylinder head cooling water space - inspection Cylinder head nut - retightening	200			☐	☐	☐	☐	☐	505-01.10 505-01.05 505-01.05 505-01.30 505-01.25 505-01.26 505-01.45 505-01.40
Piston, Connecting Rod and Cylinder Liner: Inspection of piston Piston ring and scraper ring Piston pin and bush for connecting rod - check of clearance Connecting rod - measuring of big-end bore Inspection of big-end bearing shells Connecting rod - retightening Cylinder liner - cleaning, honing and measuring Cylinder liner removed - check the water space and wear ring in frame	200			☐	☐	☐	☐	☐	506-01.10 506-01.10 506-01.15 506-01.15 506-01.16 506-01.25 506-01.35 506-01.40
Camshaft and Camshaft Drive: Camshaft - inspection of gear wheels, bolts, connections etc. Camshaft bearing - inspection of clearance Camshaft adjustment - check the condition Lubrication of camshaft bearing - check	200			☐	☐	☐	☐	☐	507-01.00 507-01.05 507-01.20 507-01.00


08028-0D/H5250/94.08.12

500.25 Edition 19H	Planned Maintenance Programme	Description Page 2 (4)
------------------------------	--------------------------------------	---------------------------

L23/30H
900 RPM

Description ● = Overhaul to be carried out ■ = Check the condition	Check new overhauled parts after hours	Time Between Overhaul							Working Card No				
		50	200	2000	6000	12000	24000	Daily		Weekly	Monthly	3rd month	Observations
Operating Gear for Inlet Valves, Exhaust Valves and Fuel Injection Pumps:													
Roller guide for valve gear				■									508-01.00
Valve gear - valve bridge, spring, push rod, etc				■									508-01.10
Roller guide for fuel injection pump				■									508-01.05
Roller guide housing				■									508-01.10
Inlet and exhaust valve - check and adjustment of valve clearance			■										508-01.10
Lubricating of operating gear - check				■									508-01.00 508-01.05
Control and Safety System, Automatics and Instruments:													
Safety, alarm and monitoring equipment											■		509-01.00
Lambda controller - adjustment											■		509-10.00
Governor - check oil level, see governor instruction book, section 509											■		
Crankshaft and Main Bearing:													
Checking of main bearings alignment, (autolog)				■									510-01.00
Inspection of main bearing				■									510-01.05
Inspection of guide bearing				■									510-01.10
Vibration damper - check the condition					■								510-04.00
Lubricating of gear wheel for lub. oil pump and cooling water pump etc.													
Counterweight - retightening, see page 500.40	900*			■									
Main- and guide bearing cap - retightening	200			■									510-01.05 510-01.10
<i>* If screw can be tightened then the screw have to be loosened and retightened after page 500.40.</i>													

08028-0D/H5250/94.08.12



Description Page 3 (4)	Planned Maintenance Programme	500.25 Edition 19H
---------------------------	--------------------------------------	------------------------------

L23/30H
900 RPM

Description	● = Overhaul to be carried out ■ = Check the condition	Check new/overhauled parts after hours	Time Between Overhaul							Working Card No		
			50	200	2000	6000	12000	24000	Daily		Weekly	Monthly
Engine Frame and Baseframe:												
Holding down bolts - retightening, see page 500.40		200										
Bolts between engine frame and base frame - retightening, see page 500.40		200										
For flexible mounted engines - check anti-vibration mountings		200										519-03.00
Safety cover - function test												511-01.00
Turbocharger System:												
Wet cleaning of turbine side										●		512-15.00
Water washing of compressor side			●									512-05.00
Cleaning of air filter - compressor side (see turbo-charger instruction book)												
Turbocharger complete - dismantling, cleaning, inspection etc. (see turbocharger instruction book)												
Charging air cooler - cleaning and inspection											■	512-01.00
Charging air cooler housing - draining											●	
Exhaust pipe - compensator											■	
Compressed Air System:												
Air starter motor - dismantling and inspection											■	513-01.30
Function test - main starting valve, starting valve, main valves and emergency start valve											■	513-01.40
Dirt separator - dismantling and cleaning											●	
Muffler - dismantling and cleaning											●	
Compressed air system - draining											●	513-01.90
Compressed air system - check of the system											■	513-01.90

08028-0D/H5250/94.08.12

500.25 Edition 19H	Planned Maintenance Programme	Description Page 4 (4)
-----------------------	--------------------------------------	---------------------------

L23/30H
900 RPM

Description	● = Overhaul to be carried out ■ = Check the condition	Check new/overhauled parts after hours	Time Between Overhaul								Working Card No	
			50	200	2000	6000	12000	24000	Daily	Weekly		Monthly
Fuel Oil System and Injection Equipment:												
Fuel oil filter - dismantling and cleaning												● 514-01.15
Fuel oil feed pump												● 514-10.00
Fuel oil injection pump - dismantling and cleaning												● 514-01.05
Fuel injection valve - adjustment of opening pressure ...		200		■								514-01.10
Fuel oil high-pressure pipe - dismantling and check				■								514-01.05
Adjustment of the maximum combustion pressure												● 514-05.01
Fuel oil system - check the system												■ 514-01.90
Nozzle cooling system - check the system if installed												■ 514-01.90
Fuel oil - oil samples after every bunkering, see sec.504												
Lubricating Oil System:												
Lubricating oil pump - engine driven												■ 515-01.00
Lubricating oil filter - cleaning and exchange												● 515-01.10
Lubricating oil cooler												● 515-06.00
Prelubricating pump - el.-driven												■ 515-01.05
Thermostatic valve												■ 515-01.20
Centrifugal filter - cleaning and exchange of paper												● 515-15.00
Hand pump												● 515-10.00
Lubricating oil - oil samples, see section 504												■ 515-01.90
Lubricating oil system - check the system												
Cooling Water System:												
Cooling water pump - engine-driven (sea water and fresh water)												■ 516-04.00
Thermostatic valve												■ 516-04.00
Cooling water system - check the system												■ 516-01.90
Cooling water system - water samples, see sec. 504												■ 516-01.90

08028-0D/H5250/94.08.12



Description Page 1 (5)	Planned Maintenance Programme	500.25 Edition 22H
---------------------------	--------------------------------------	------------------------------

L23/30H
720/750 RPM

Description <input checked="" type="checkbox"/> = Off-line check of condition (engine shutdown) <input type="checkbox"/> = On-line check of condition (engine running) <input checked="" type="checkbox"/> = Off-line service / overhaul (engine shutdown) <input type="checkbox"/> = On-line service / overhaul (engine running)	Check new/overhauled parts after hours	Time Between Overhaul						Working Card No				
		50	200	2000	* 6000	** 12000	*** 24000		Daily	Weekly	Monthly	3rd month
Operating of Engine: Readings of data for engine and alternator with reference to "Engine Performance Data", section 502.01												502-01.00
Cylinder Head: Inlet and exhaust valve - overhaul and regrinding of spindle and valve seat Inspection of inlet, exhaust valves and valve guide Check of valve rotators' rotation during engine rotation Sleeve for fuel injector Safety valve - overhaul and adjustment of opening pressure Indicator valve Cylinder head cooling water space - inspection Cylinder head nut - retightening	200											505-01.10 505-01.05 505-01.05 505-01.30 505-01.25 505-01.26 505-01.45 505-01.40
Piston, Connecting Rod and Cylinder Liner: Inspection of piston Piston ring and scraper ring Piston pin and bush for connecting rod - check of clearance Connecting rod - measuring of big-end bore Inspection of big-end bearing shells Connecting rod - retightening Cylinder liner - cleaning, honing and measuring Cylinder liner removed - check the water space and wear ring in frame	200											506-01.10 506-01.10 506-01.15 506-01.15 506-01.16 506-01.25 506-01.35 506-01.40
Camshaft and Camshaft Drive: Camshaft - Inspection of gear wheels, bolts, connections etc. Camshaft bearing - inspection of clearance Camshaft adjustment - check the condition Lubrication of camshaft bearing - check	200											507-01.00 507-01.05 507-01.20 507-01.00

Overhaul to be repeated:

- * Repeat 2.000 hours maintenance, with activities mentioned under 6.000 hours maintenance.
- ** Repeat 6.000 hours maintenance, with activities mentioned under 12.000 hours maintenance.
- *** Repeat 12.000 hours maintenance, with activities mentioned under 24.000 hours maintenance.

08028-0D/H5250/94.08.12


500.25 Edition 22H	Planned Maintenance Programme	Description Page 2 (5)
------------------------------	--------------------------------------	---------------------------


L23/30H
720/750 RPM

Description ■ = Off-line check of condition (engine shutdown) □ = On-line check of condition (engine running) ● = Off-line service / overhaul (engine shutdown) ○ = On-line service / overhaul (engine running)	Check new/overhauled parts after hours	Time Between Overhaul							Working Card No			
		50	200	2000	6000	12000	24000	Daily		Weekly	Monthly	3rd month
Operating Gear for Inlet Valves, Exhaust Valves and Fuel Injection Pumps: Roller guide for valve gear Valve gear - valve bridge, spring, push rod, etc Roller guide for fuel injection pump Roller guide housing Inlet and exhaust valve - check and adjustment of valve clearance Lubricating of operating gear - check				■	■	■						508-01.00 508-01.10 508-01.05 508-01.10 508-01.10 508-01.00 508-01.05
Control and Safety System, Automatics and Instruments: Safety, alarm and monitoring equipment Lambda controller - adjustment Governor - check oil level, see governor instruction book, section 509												509-01.00 509-10.00 □
Crankshaft and Main Bearing: Checking of main bearings alignment, (autolog) Inspection of main bearing Inspection of guide bearing Vibration damper - check the condition Lubricating of gear wheel for lub. oil pump and cooling water pump etc. Counterweight - retightening, see page 500.40 Main- and guide bearing cap - retightening <i>* If screw can be tightened then the screw have to be loosened and retightened after page 500.40.</i>	900* 200			■	■	■					510-01.00 510-01.05 510-01.10 510-04.00 510-01.05 510-01.10	

38028-0D/H5250/94.08.12

- Overhaul to be repeated:**
- * Repeat 2.000 hours maintenance, with activities mentioned under 6.000 hours maintenance.
 - ** Repeat 6.000 hours maintenance, with activities mentioned under 12.000 hours maintenance.
 - *** Repeat 12.000 hours maintenance, with activities mentioned under 24.000 hours maintenance.





Description Page 3 (5)	Planned Maintenance Programme	500.25 Edition 22H
---------------------------	--------------------------------------	------------------------------

L23/30H
720/750 RPM

Description <input checked="" type="checkbox"/> = Off-line check of condition (engine shutdown) <input type="checkbox"/> = On-line check of condition (engine running) <input checked="" type="checkbox"/> = Off-line service / overhaul (engine shutdown) <input type="checkbox"/> = On-line service / overhaul (engine running)	Check new/overhauled parts after hours	Time Between Overhaul							Working Card No			
		50	200	2000	6000	12000	24000	Daily		Weekly	Monthly	3rd month
Engine Frame and Baseframe:												
Holdingdown bolts - retightening, see page 500.40	200			<input checked="" type="checkbox"/>								
Bolts between engine frame and base frame - retightening, see page 500.40	200			<input checked="" type="checkbox"/>								
For flexible mounted engines - check anti-vibration mountings	200			<input type="checkbox"/>								519-03.00
Safety cover - function test				<input checked="" type="checkbox"/>								511-01.00
Turbocharger System:												
Dry cleaning of turbine side		<input type="checkbox"/>										512-10.00
Water washing of compressor side		<input checked="" type="checkbox"/>										512-05.00
Cleaning of air filter - compressor side (see turbocharger instruction book)												
Turbocharger complete - dismantling, cleaning, inspection etc. (see turbocharger instruction book)											<input checked="" type="checkbox"/>	512-01.00
Charging air cooler - cleaning and inspection											<input type="checkbox"/>	
Charging air cooler housing - draining											<input type="checkbox"/>	
Exhaust pipe - compensator											<input checked="" type="checkbox"/>	
Compressed Air System:												
Air starter motor - dismantling and inspection											<input checked="" type="checkbox"/>	513-01.30
Function test - main starting valve, starting valve, main valves and emergency start valve											<input checked="" type="checkbox"/>	513-01.40
Dirt separator - dismantling and cleaning											<input checked="" type="checkbox"/>	
Muffler - dismantling and cleaning											<input checked="" type="checkbox"/>	
Compressed air system - draining											<input type="checkbox"/>	513-01.90
Compressed air system - check of the system											<input type="checkbox"/>	513-01.90

Overhaul to be repeated:

- * Repeat 2.000 hours maintenance, with activities mentioned under 6.000 hours maintenance.
- ** Repeat 6.000 hours maintenance, with activities mentioned under 12.000 hours maintenance.
- *** Repeat 12.000 hours maintenance, with activities mentioned under 24.000 hours maintenance.

08028-0D/H5250/94.08.12

500.25 Edition 22H	Planned Maintenance Programme	Description Page 4 (5)
------------------------------	--------------------------------------	---------------------------

L23/30H
720/750 RPM

Description	Check new/overhauled parts after hours	Time Between Overhaul							Working Card No	
		50	200	2000	6000	12000	24000	Daily Weekly Monthly 3rd month Observations		
Fuel Oil System and Injection Equipment:										
Fuel oil filter - dismantling and cleaning									<input checked="" type="checkbox"/>	514-01.15
Fuel oil feed pump									<input checked="" type="checkbox"/>	514-10.00
Fuel oil injection pump - dismantling and cleaning									<input checked="" type="checkbox"/>	514-01.05
Fuel injection valve - adjustment of opening pressure ...	200		<input checked="" type="checkbox"/>							514-01.10
Fuel oil high-pressure pipe - dismantling and check			<input checked="" type="checkbox"/>							514-01.05
Adjustment of the maximum combustion pressure									<input checked="" type="checkbox"/>	514-05.01
Fuel oil system - check the system									<input checked="" type="checkbox"/>	514-01.90
Nozzle cooling system - check the system									<input checked="" type="checkbox"/>	
Fuel oil - oil samples after every bunkering, see sec.504										
Lubricating Oil System:										
Lubricating oil pump - engine-driven						<input checked="" type="checkbox"/>				515-01.00
Lubricating oil filter - cleaning and exchange									<input type="checkbox"/>	515-01.10
Lubricating oil cooler									<input checked="" type="checkbox"/>	515-06.00
Prelubricating pump - el. driven						<input type="checkbox"/>				515-01.05
Thermostatic valve									<input checked="" type="checkbox"/>	515-01.20
Centrifugal filter - cleaning and exchange of paper									<input type="checkbox"/>	515-15.00
Lubricating oil - oil samples, see section 504									<input type="checkbox"/>	
Lubricating oil system - check the system									<input type="checkbox"/>	515-01.90
Cooling Water System:										
Cooling water pump - engine-driven (sea water and fresh water)						<input checked="" type="checkbox"/>				516-04.00
Thermostatic valve									<input checked="" type="checkbox"/>	516-04.00
Cooling water system - check the system									<input type="checkbox"/>	516-01.90
Cooling water system - water samples, see sec. 504									<input type="checkbox"/>	

Overhaul to be repeated:

- * Repeat 2.000 hours maintenance, with activities mentioned under 6.000 hours maintenance.
- ** Repeat 6.000 hours maintenance, with activities mentioned under 12.000 hours maintenance.
- *** Repeat 12.000 hours maintenance, with activities mentioned under 24.000 hours maintenance.

08028-0D/H5250/94.08.12

Description Page 5 (5)	Planned Maintenance Programme	500.25 Edition 22H
---------------------------	--------------------------------------	------------------------------

L23/30H
720/750 RPM

Auxiliary equipment

The precondition of the reliability and operating economy of the GenSet will to a great extent depend on correct operation and proper maintenance of all equipment in the Power Plant.

All auxiliary equipment in the Power Plant must be operated as described in the operation- and maintenance instructions from the manufacturer of the components.

It is also essential that the engine room personnel is fully acquainted with the functions and mode of operation of the auxiliary equipment.

Description Page 1 (2)	Operation Data & Set Points	500.30 Edition 35H
---------------------------	--	------------------------------

L23/30H

	Normal Value at Full load		Alarm Set point		Autostop of engine	
Lubricating Oil System						
Temp. before cooler (outlet engine)	SAE 30 SAE 40	TI 20 TI 20	60-75° C 65-82° C	TAH 20 TAH 20	90° C 100° C	
Temp. after cooler (inlet engine)	SAE 30 SAE 40	TI 22 TI 22	45-65° C 50-72° C	TAH 22 TAH 22	75° C 85° C	TSH 22 TSH 22
Pressure after filter (inlet eng)		PI 22	3-4 bar	PAL 22	3 bar	PSL 22
Elevated pressure i.g. when centrifugal filter installed		PI 22	4-5 bar	PAL 22	4 bar	PSL 22
Pressure drop across filter		PDAH 21-22	0.5-1 bar	PDAH 21-22	1.5 bar	
Prelubricating pressure		PI 25	0.1-0.5 bar	LAL 25	level switch	
Pressure inlet turbocharger		PI 23	1.5 ± 0.2 bar			
Lub. oil, level in base frame				LAL 28/LAH 28	low/high level	
Temp. main bearings		TE 29	75-85° C	TAH 29	95° C	
Fuel Oil System						
Pressure after filter	MDO HFO	PI 40 PI 40	2-3 bar (A)	PAL 40 PAL 40	1.5 bar 4 bar	
Leaking oil				LAH 42	leakage	
Press. nozz. cool. oil, inlet eng.		PI 50	2-3 bar	PAL 50	1.5 bar (C)	
Temp. nozz. cool. oil, outlet eng.		TI 51	80-90° C		(C)	
Cooling Water System						
Press. LT-system, inlet engine		PI 01	1-2.5 bar	PAL 01	0.4 bar + (B)	
Press. HT-system, inlet engine		PI 10	1-3.0 bar	PAL 10	0.4 bar + (B)	
Temp. HT-system, inlet engine		TI 10	60-75° C			
Temp. HT-system, outl. cyl. units		TI 11	70-85° C			
Temp. HT-system, outlet engine				TAH 12 TAH 12-2	90° C 93° C	TSH 12
Temp. raise across cyl. units			max. 10° C			95° C
Exhaust Gas and Charge Air						
Exh. gas temp. before TC		TI 62	425-475° C	TAH 62 TAH 62-2	550° C 600° C	
Exh. gas temp. outlet cyl. Diff. between individual cyl.		TI 60	280-390° C	TAH 60 TAD 60	420° C average ± 50° C	
Exh. gas temp. after TC		TI 61 TI 61	275-350° C* 320-390° C**	TAH 61	500° C	
Ch. air press. after cooler		PI 31	2-2.5 bar			
Ch. air temp. after cooler		TI 31	35-55° C	TAH 31	65° C	
Compressed Air System						
Press. inlet engine		PI 70	7-9 bar	PAL 70	7 bar	
Speed Control System						
Engine speed						
Mechanical		SI 90	720 rpm	SAH 81	815 rpm	SSH 81
Elec.		SI 90	750 rpm	SAH 81	850 rpm	SSH 81
Mechanical		SI 90	750 rpm	SAH 81	850 rpm	SSH 81
Elec.		SI 90	900 rpm	SAH 81	1015 rpm	SSH 81
Mechanical		SI 90	900 rpm	SAH 81	1015 rpm	SSH 81
Elec.		SI 90	900 rpm	SAH 81	1015 rpm	SSH 81
Turbocharger speed		SI 89		SAH 89	(D)	

Specific plants will not comprise alarm equipment and autostop for all parameters listed above. For specific plants additional parameters can be included. For remarks to some parameters, see overleaf.

* for 720/750 rpm


** for 900 rpm.

08028-0D/H5250/94.08.12

M13-2

(b) (7)(C), (b) (7)(D)

ZHENJIANG CME CO., LTD



ZJMD-MAN B&W 6L23/30H

MAIN DIESEL GENERATING-SETS

DRAWING FOR FINAL

Shipyard : GUANGZHOU SHIPYARD INTERNATIONAL CO., LTD. / 50500DWT

Subject : 3 × 6L23/30H Gensets/Ship

Rule : ABS

Fuel oil : HFO, 380cSt/50°C

Power : 3 × 910 kW

Speed : 900 r/min

DATE: Jan. 30, 2008

ZHENJIANG CME CO., LTD

1609517-6.7 Page 1 (1)	Main Particulars	B 10 01 1
---------------------------	-------------------------	------------------

L23/30H

Cycle	:	4-stroke
Configuration	:	In-line
Cyl. Nos. available	:	5-6-7-8
Power range	:	650-1280 kW (885-1740 BHP)
Speed	:	720/750/900 rpm
Bore	:	225 mm
Stroke	:	300 mm
Stroke/bore ratio	:	1.33:1
Piston area per cyl.	:	398 cm²
Swept volume per cyl.	:	11.9 ltr.
Compression ratio	:	13:1
Max. combustion pressure	:	130 bar*
Turbocharging principle	:	Constant pressure system and intercooling
Fuel quality acceptance	:	HFO up to 700 cSt/50° C (BSMA 100-M9)



Power-lay-out		MCR version		
Speed	rpm	720	750	900
Mean piston speed	m/sec.	7.2	7.5	9.0
Mean effective pressure	bar	18.2	18.1	17.9
Max. combustion pressure	bar	130	130	130*
Power per cylinder	kW/cyl.	130	135	160
	BHP/cyl.	175	185	217

Overload rating (up to 10%) allowable in 1 hour for every 12 hours				
Power per cylinder	kW/cyl.	145	150	176
	BHP/cyl.	190	205	239

*For L23/30H-900 rpm version a pressure of 135 bar measured at the indicator cock correspond to 130 bar in the combustion chamber.

SPECIFICATION OF GENERATOR

USE:	DIESEL ENGINE GENERATOR	QUANTITY / SHIP:	3SETS / SHIP		
TYPE OF ENCLOSURE:	IP44	APPLIED CLASS:	ABS		
COOLING SYSTEM:	AIR TO WATER	AMBIENT TEMP.	45 °C		
EXCITING SYSTEM:	SELF EXCITING BRUSHLESS	INSULATION CLASS:	F		
COUPLING METHOD	DIRECT RIGID	TEMPERATURE RISE:	F		
SPECIFICATION		BEARING			
TYPE	HFJ6 508-84K	TYPE OF BEARING	ROLLER BEARING		
OUTPUT CAPACITY	1137.5KVA	LOCATION	DRIVE END	NON DRIVE END	
RATING	CONTINUOUS	SIZE	-	NU326 C3	
PHASES, WIRE, CONN.	3PH, 3W, Y (DAMPER WINDING)	OIL QUANTITY	-	456g	
VOLTAGE	AC 450 V	LUB. SYSTEM	-	GREASE LUB.	
CURRENT	1459.4A	OIL GRADE	ZL-3		
FREQUENCY	60 Hz	INLET PRESSURE	-		
POLES	8 POLE	INLET TEMP.	-		
SPEED	900 RPM	AIR COOLER			
POWER FACTOR	0.8 LAGGING	CAPACITY	60 KW		
GD ² / J	232.4 Kg.m ² / 58.1 Kg.m ²	FULID	FRESH WATER		
ROTOR WEIGHT	1718Kg	QUANTITY	15m ³ /h		
TOTAL WEIGHT	5.2 ton	INLET TEMP.	36°C		
CHARACTERISTICS		TEMP. RISE	4°C		
OVER CURRENT	150 % / 2 min	PRESSURE DROP			
VARIATION OF GENERATOR VOLTAGE	± 2.5%	DRY WEIGHT	-kg		
OVER SPEED	120 % / 2 min	DETECTING SYSTEM			
VOLTAGE ADJUST	± 5.0%	WINDING TEMP.	PT100 OHM x 2EA / PHASE		
MOUNTING METHOD	B16	AIR FILTER			
		BEARING TEMP.	PT100 OHM		
REACTANCE & TIME CONSTANT (calculated value)		COOLING AIR TEMP.	PT100 OHM		
		LEAKAGE DETECTOR	N/C CONTACT: 2EA/SET		
X _d : 335% (UNSATURATED)	T' _d : 0.0784 SEC.	CONFIRMED ITEM BY OWNER			
X' _d : 18.4% (SATURATED)	T'' _d : 0.0026 SEC.	* LOCATION OF TERMINAL BOX.			
X'' _d : 10.3% (SATURATED)	T _a : 0.0216 SEC.	(VIEWED FROM PRIME MOVER)			
RA : 1.27%		* CABLE ENTRY			
NOTE		SPACE HEATER	1PH, 230V, 315W		
		PAINTING COLOR			
		LOCATION OF AIR COOLER FLANGE (VIEWED FROM PRIME MOVER)			
		ROTATING DIRECTION (VIEWED FROM PRIME MOVER)	C. C. W		
REV.	CONTENTS	DATE	REMARK: THE SPECIFICATION OF * MARK SHOULD BE INFORMED ON YOUR APPROVED DRAWING.		
			HFJ6 508-84K		
			DATE	DESIGN	CHECKED
				张茂玲	方甫根
					姚立元
					APPROVED




- ① Air inlet with door open (for emergency operating)
- ② Air outlet with door open (for emergency operating)
- ③ Center of gravity
- ④ Cover for rotating rectifier
- ⑤ Connection for cooling water (JIS-65A)
- ⑥ Cover for voltage regulator
- ⑦ Cover for terminals and excitation equipment
- ⑧ Cable gland box
- ⑨ Free space of fitting bolts 190mm
- ⑩ Ball bearing
- ⑪ Dimension for removing the rotor
- ⑫ AIR Temp. sensor (PT100 ohm:option)

- ⑬ 12-φ21 pre drilled
- ⑭ Cover for space heater
- ⑮ Leakage water detector(2st)
- ⑯ In case of emergency operation with the doors open put in the air-stop plate furnished before the closed-circuit cooler
- ⑰ Clearance for fitting the air-stop plate in case of emergency operation
- ⑱ Dimension for removing the air cooler
- ⑲ Leakage water drain R3/B"
- ⑳ PT100 TEMP.SENSOR

Weight of machine	Weight of rotor	Moment of inertia of rotor(J)
Approx. 5.2 ton	1718 kg	68.1 kgm ²
Type of const : B16		Type of protection : IP44
		No. of poles : 8

					OUTLINE OF GENERATOR		镇江中船现代发电设备有限公司
标记	处数	分区	更改文件号	签名	年月日	TYPE	HFJ6 508-84K
设计			标准化			REF NO	
制图	张茂玲		批准			DWG NO	XD-W060137
校对	法尚根						
审核							

图号	
图名	
比例	
日期	
设计	
制图	
审核	



校核	
设计	
制图	
审核	
日期	
比例	
重量	
数量	
材料	
备注	

图号				
图名				
设计				
制图				
审核				
日期				


L23/30H
 ENG. AUTOMATIC
 STARTBOX & TERMINALBOX
 柴油机接线箱&起动机

L23-663-00XLt81			
材料	数量	重量(公斤)	比例
共 14 页	第 6 页		
镇江船用柴油机厂			

M3-1

INSTRUCTION BOOK

ZHENJIANG MARINE DIESEL WORKS



Instruction Book

L23/30H

..... Shipyard :

Ship name :

Hull No. :

Rule :

Add: 250, Guangtangqiao Zhenjiang

Jiangsu Province P.R.China

Tel: [REDACTED]

Fax: +86 511 451 0033

IndexPage 1 (1)	Engine Data	500
--------------------	--------------------	------------

Description	Document no	Notes
Warning	<u>000.00</u>	
Description	Document no	Notes
Main data for engine	<u>500.00</u>	
Introduction	<u>500.01 (02)</u>	
Safety	<u>500.02 (01H)</u>	
Cross section	<u>500.05 (06H)</u>	
Key for engine designation	<u>500.10 (02)</u>	
Designation of cylinders	<u>500.11 (01H)</u>	
Engine rotation clockwise	<u>500.12 (02H)</u>	
Code identification for instruments	<u>500.20 (01H)</u>	
Introduction to planned maintenance programme	<u>500.24 (02H)</u>	
Planned maintenance programme	<u>500.25 (19H)</u>	
Planned maintenance programme	<u>500.25 (22H)</u>	
Operation data and set points	<u>500.30 (35H)</u>	
Data for pressure and tolerance	<u>500.35 (15H)</u>	
Data for tightening torque	<u>500.40 (21H)</u>	- 720/750 rpm
Data for tightening torque	<u>500.40 (22H)</u>	- 900 rpm
Declaration of weight	<u>500.45 (01H)</u>	
Ordering of spare parts	<u>500.50 (01H)</u>	
Service letters	<u>500.55 (01H)</u>	
Conversion table	<u>500.60 (01H)</u>	
Basic symbols for piping	<u>500.65 (01H)</u>	

Description Page 1 (1)	Warning	000.00
---------------------------	---------	--------

General

Warning !

(Marine engines only)


It is important that all MAN B&W Diesel A/S engines are operated within the given specifications and performance tolerances specified in the engines' Technical Files and are maintained according to the MAN B&W Diesel A/S maintenance instructions in order to comply with given emissions regulations.

In accordance with Chapter I of the Code of Federal Regulations, Part 94, Subpart C, §94.211 NOTICE is hereby given that Chapter I of the Code of Federal Regulations, Part 94, Subpart K, §94.1004 requires that the emissions related maintenance of the diesel engine shall be performed as specified in MAN B&W Diesel A/S instructions including, but not limited to, the instructions to that effect included in the Technical File.

08028-0D/H6250/94.08.12

Plate Page 1 (2)	Flywheel with Flexible Coupling and Gear Rim	51003-01H
---------------------	--	-----------

L23/30H



08028-0D/H5250/94.08.12



51003-01H

Flywheel with Flexible Coupling and Gear Rim

Plate
Page 2 (2)

L23/30H

Item No.	Qty.	Designation	Benævnelse	Item No.	Qty.	Designation	Benævnelse
010	1/E	Gear rim	Tandkrans				
022	14/E	Screw	Skruer				
034	12/E	Self locking nut, for item no. 046	Selvlåsende møtrik for item nr. 046				
046+	12/E	Fitted bolt	Pasbolt				
058	1/E	Flywheel	Svinghjul				
071+	12/E	Fitted bolt	Pasbolt				
083	1/E	Flexible coupling, complete	Fleksibel kobling, komplet				
095	24/E	Rubber element	Gummielement				
105	2/E	Screw	Skruer				
117	12/E	Self locking nut, for item no. 071	Selvlåsende møtrik for item nr. 071				
		+ Item 046 and 071 require an individual matching, before mounting.	+ Item nr. 046 and 071 kræver en individuel tilpasning, før monteringen.				

When ordering spare parts, see also page 500.50.

* = Only available as part of a spare parts kit.
Qty./E = Qty./Engine


Ved bestilling af reservedele, se også side 500.50.

* = Kun tilgængelig som en del af et reservedelssæt.
Qty./E = Antal/Motor

08028-0D/H45250/94.08.12

Plate Page 1 (2)	Flywheel with Gear Rim	51003-02H
---------------------	------------------------	-----------

L23/30H



08028-0D/H5250/94.08.12



51003-02H

Flywheel with Gear Rim

Plate
Page 2 (2)

L23/30H

Item No.	Qty.	Designation	Benævnelse	Item No.	Qty.	Designation	Benævnelse
010	1/E	Gear rim	Tandkrans				
022	14/E	Screw	Skrue				
034	12/E	Self locking nut, for item no. 046	Selvlåsende møtrik for item nr. 046				
046+	12/E	Fitted bolt	Pasbolt				
058	1/E	Flywheel	Svinghjul				
105	2/E	Screw	Skrue				
		+ Item 046 require an individual matching before mounting.	+ Item nr. 046 kræver en individuel tilpasning før montering.				

When ordering spare parts, see also page 500.50.

Ved bestilling af reservedele, se også side 500.50.


* = Only available as part of a spare parts kit.
Qty./E = Qty./Engine* = Kun tilgængelig som en del af et reservedelssæt.
Qty./E = Antal/Motor

08028-00/H/5250/94.08.12

M3-1

INSTRUCTION BOOK

ZHENJIANG MARINE DIESEL WORKS



Instruction Book

L23/30H

..... Shipyard :

Ship name :

Hull No. :

Rule :

Add: 250, Guangtangqiao Zhenjiang

Jiangsu Province P.R.China

Tel: [REDACTED]

Fax: +86 511 451 0033

IndexPage 1 (1)	Engine Data	500
--------------------	--------------------	------------

Description	Document no	Notes
Warning	<u>000.00</u>	
Description	Document no	Notes
Main data for engine	<u>500.00</u>	
Introduction	<u>500.01 (02)</u>	
Safety	<u>500.02 (01H)</u>	
Cross section	<u>500.05 (06H)</u>	
Key for engine designation	<u>500.10 (02)</u>	
Designation of cylinders	<u>500.11 (01H)</u>	
Engine rotation clockwise	<u>500.12 (02H)</u>	
Code identification for instruments	<u>500.20 (01H)</u>	
Introduction to planned maintenance programme	<u>500.24 (02H)</u>	
Planned maintenance programme	<u>500.25 (19H)</u>	
Planned maintenance programme	<u>500.25 (22H)</u>	
Operation data and set points	<u>500.30 (35H)</u>	
Data for pressure and tolerance	<u>500.35 (15H)</u>	
Data for tightening torque	<u>500.40 (21H)</u>	- 720/750 rpm
Data for tightening torque	<u>500.40 (22H)</u>	- 900 rpm
Declaration of weight	<u>500.45 (01H)</u>	
Ordering of spare parts	<u>500.50 (01H)</u>	
Service letters	<u>500.55 (01H)</u>	
Conversion table	<u>500.60 (01H)</u>	
Basic symbols for piping	<u>500.65 (01H)</u>	

Description Page 1 (1)	Warning	000.00
---------------------------	---------	--------

General

Warning !

(Marine engines only)

It is important that all MAN B&W Diesel A/S engines are operated within the given specifications and performance tolerances specified in the engines' Technical Files and are maintained according to the MAN B&W Diesel A/S maintenance instructions in order to comply with given emissions regulations.

In accordance with Chapter I of the Code of Federal Regulations, Part 94, Subpart C, §94.211 NOTICE is hereby given that Chapter I of the Code of Federal Regulations, Part 94, Subpart K, §94.1004 requires that the emissions related maintenance of the diesel engine shall be performed as specified in MAN B&W Diesel A/S instructions including, but not limited to, the instructions to that effect included in the Technical File.

08028-0D/H6250/94.08.12

IndexPage 1 (1)	Operation of Engine	501
--------------------	----------------------------	------------

Description	Document no	Notes
Operating	<u>501.01 (01H)</u>	-
Out of service	<u>501.05 (01H)</u>	-
Starting-up after out of service periods	<u>501.10 (01H)</u>	-
Guidelines for longterm low-load operation on HFO	<u>501.15 (02H)</u>	-
Operating a diesel engines at low frequency	<u>501.25 (01H)</u>	only stationary engines

L23/30H

Preparations for Starting

The following describes what to do before starting, when the engine has been out of service for a longer period of time, or if major overhauls have been made.

1. Check the oil level in the base frame (or in the lub. oil tank, if the engine is with dry sump), air lubricator and in the governor.

Start-up the prelubricating pump.

The engine shall be prelubricated at least 2 minutes prior to start.

Check oil pressures before and after the filter.

2. Open the cooling water supply, start separate cooling water pumps where installed, and check the cooling water pressure.

Note: To avoid shock effects owing to large temperature fluctuations just after the start, it is recommended:

a) to preheat the engine. Cooling water of at least 60 °C should be circulated through the frame and cylinder head for at least 2 hours before start:

- either by means of cooling water from engines which are running or by means of a built-in preheater (if installed).

or

b) When starting without preheated cooling water, the engine must only be started on MDO (Marine Diesel Oil).

The engine should not be run up to more than 50% load to begin with, and the increase to 100% should take place gradually over 5 to 10 minutes.

Note: When starting on HFO (Heavy Fuel Oil), only item "a" applies.

3. Open the fuel oil supply to the feed pump.

Starting on HFO: circulate preheated fuel through the pumps until correct working temperatures have been obtained. This normally takes 30-60 minutes.

4. Check the pressure in the starting air receiver(s) and open the starting air supply (blow-off water, if any, and drain the starting air system before opening.

5. Regulating gear - please check:

- that all fuel pumps are set at index "0" when the regulating shaft are in STOP position.

- that each fuel pump can be pressed by hand to full index when the regulating shaft are in STOP position, and that the pumps return automatically to the "0" index when the hand is removed.

- that the spring-loaded pull rod is working correctly.

- that the stop cylinder for regulating the shaft works properly, both when stopping normally and at overspeed and shut down.

- that testing is made by simulating these situations.

6. Open the indicator valves and turn the engine some few revolutions, check that no liquid is flowing out from any of the indicator valves during the turning.

Slow-turning must always be carried out, before the engine is started after prolonged out of-service periods and after overhauls, which may involve a risk of liquid having collected in the cylinders.

7. Close the indicator valves.

8. Disengage the turning gear, if fitted. Check that it is locked in the "OUT" position.

Starting

1. Start the engine by activating the start button.

2. Check the lubricating oil pressure, cooling water pressure, fuel oil feed pressure. Check that the prelubricating oil pump is stopped.

3. Check that all alarms are connected.

See also "checks after starting-up".



501.01

Edition 01H

Operating

Description
Page 2 (2)

L23/30H

Testing during Running

When the engine is running, the planned maintenance programme and the following should be checked:

1. The lubricating oil pressure must be within the stated limits and must not fall below the stated minimum pressure. The paper filter cartridges must be replaced before the pressure drop across the filter reaches the stated maximum value, or the pressure after the filter has fallen below the stated minimum value. Dirty filter cartridges cannot be cleaned for re-use.

2. The lubricating oil temperature must be kept within the stated limits indicated on the data sheet.

3. The fuel oil pressure must be kept at the stated value, and the filter must be cleaned before the pressure drop across the filter reaches the stated maximum value.

4. The cylinder cooling water temperature must be kept within the limits indicated and the temperature rise across the engine should not exceed 10°C.

5. The cooling water temperature at the charging air cooler inlet should be kept as low as possible; however, not as low as to produce condensation water in the charging air space.

Adjustment takes place in the external system outside the engine, and the amount of cooling water must be adjusted so that the temperature rise across the charging air cooler is 3 - 5 °C.

6. The exhaust gases should be free from smoke at all loads. For normal exhaust temperatures, see the test report from shop and sea trials.

7. Keep the charging air pressure and temperature under control. For normal values, see the test report from shop and sea trials.

8. Recharge the starting air receivers when the pressure has dropped to about 20 bar. Stop recharging at 30 bar.

9. To ensure full operational liability, the condition of the engine should be continuously observed in order for preventive maintenance work to be carried out before serious breakdowns occur.

Stopping

1. Before stopping, it is recommended to run the engine at reduced load, or to idle for about 5 minutes for cooling-down purposes.

2. The engine is stopped by keeping the fuel pump delivery rate at "0", by turning the "load-limit" knob on the governor to "0", or by activating the remote stopping device.

Start and Stop on HFO

Start and stop of the engine should take place on HFO in order to prevent any incompatibility problems by change-over to MDO.

MDO should only be used in connection with maintenance work on the engine or longer periods of engine standstill.

Before starting on HFO the engine must be properly preheated as described in "Preparations for Starting" and as described below.

Stopping the engine on HFO is no problem, but it should be ensured that the temperature of fuel pipes are not reduced to a level below the pour point of the fuel, otherwise, reestablishing of the circulation might cause problems.

Starting on MDO

For starting on MDO there are no restrictions except lubricating oil viscosity may not be higher than 1500 cSt (5° C SAE 30, or 10° C SAE 40).

Initial ignition may be difficult if the engine and ambient temperatures are lower than 5° C and 15° C cooling water temperature.

08028-0D/H5250/94.08.12

L23/30H

1. Stand-by Engines

During engine standstill in stand-by position the media cooling water and fuel oil should be continuously circulated at temperatures similar to the operation conditions.

The engine shall be prelubricated 2 minutes prior to start, if there is not intermittent or continuous prelubricating installed. intermittent prelub. is 2 min every 10 minutes.

2. Maintenance during Standstill

In periods during stand-still of the engine (not in stand-by position) it is recommended to start the prelubricating oil pump minimum 10 minutes once every week and totum the engine during the prelubricating period by 2-3 revolutions.

3. Laid-up Vessels

During the lay-up period (and also when laying-up the vessel) we recommend that our special instructions for preservation of the engines are followed.

4. Work before Major Repairs

4.1 After stopping the engine, while the oil is still warm, start the el-driven prelub. pump, open up the crankcase and camshaft housings and check that the oil is flowing freely from all bearings. Also, take off the top covers on the cylinder heads and make sure that oil is not supplied for lubrication of rocker arms, as non-return valves are fitted which do not open until the oil pressure at the inlet to the rocker arms exceeds 1 bar.

After overhaul of pistons, bearings, etc. this check should be repeated before starting the engine.

4.2. After stopping the prelub. pump, check the bottom of the oil sump for fragments of babbitt from bearings

4.3. Open up all filters to check that filter elements are intact. Filter cartridges in the lub. oil filter is to be replaced before start, after repair, or after excessive differential pressure. After removal, dirty elements can be examined for particles of bearing metal at the bottom of the paper lamella. (the elements can not be used again).

4.4. Check the cylinder walls.

4.5. Take deflection measurements of the crankshaft.

4.6. A lubricating oil sample should be sent to a laboratory for immediate analysis.

4.7. Drain plugs are unscrewed from the bottom of turbochargers, or the drain cock is opened. If drain facilities are installed in the exhaust gas system this should be opened.

5. Work during Repairs

The following should be made during major repairs.

5.1. Retighten all bolts and nuts in the crankcase and check their locking devices. Also, retighten foundation bolts.

5.2. Check the various gear wheel drives for the camshaft(s).

5.3. Remedy leakages of water and oil in the engine, and blow through blocked-up drain pipes.

5.4. Drain starting air pipes of water.

5.5. Empty the oil sump of lubricating oil and remove the sludge, if not done within a period of one year. Clean the sump very thoroughly and subsequently coat with clean lubricating oil.

6. Work after Repairs

6.1. If an opening-up of engine or lubricating oil system may have caused ingress of impurities, cleaning should be carried out very carefully before starting the engine.



501.05

Edition 01H

Out-of Service

Description
Page 2 (2)

L23/30H

The differential pressure across the lub. oil filter must be watched very carefully after cleaning and starting-up the engine. Be sure to replace filter cartridges in due time.

6.2. After restoring normal lubricating oil circulation, turn the engine at least two revolutions by means of the turning rod to check the movability of the relevant parts of the engine.

6.3. Close the drain cocks in the turbocharger (or in the exhaust gas system, if mounted).

6.4. Lubricate the bearings and rod connections in the manoeuvring gear. Disconnect the governor and move the rod connections by hand to check that the friction in bearings and fuel pumps is sufficiently low. If repair of bearings or alignment of engine has been made, check no 1, 2, and 5 should be repated.

6.5. Checks to be made just before starting of the engine are mentioned under 501.01.

6.6. Add cooling water and check the leakage pressure system on at the upper and lower cylinder liner sealings and at cooling water connections.

6.7. Check the governor as follows:

Start up the engine and run it at the synchronous number of revolutions.

6.7 a) Speed-setting: Before switching-in the alternator on the switchboard please check that the servomotor adjusts the rpm with a suitable quickness after actuation of the synchronizer knob on the switchboard. The range from - 5% to + 5% from the synchronous rpm should be tested.

6.7 b) Adjustment speed: Switch-in the alternator on the switchboard and set the load to about 40%. On reaching normal oil temperatures in governor and engine, increase the load instantly to about 80% (by starting the major pump or compressor). This must not cause the frequency to fall by more than some 8%, and the engine must return to a constant no rpm after about 3 seconds (although this rpm will be a little lower than before owing to the speed droop of the governor). If the engine is operated in parallel with other engines, an even sharing of load shall be established within about 3 seconds. If the governor reacts too slowly, compensating adjustment is effected as indicated in Woodward's instruction manual (Compensating Adjustment).

Note: It is a condition for this test that the engine and turbocharger are in perfect operating condition, so that possible sources of error immediately can be eliminated

6.7 c) Hunting: Run the engine at synchronous rpm, and without load. Provided the governor oil is warm, the regulating lever must not perform any major periodical movements, and neither must there be any variation in the engine speed. If that is the case, repeat the compensating adjustment according to Woodward's instruction manual.

6.7 d) Speed droop: in case of unsatisfactory load sharing between two or more engines this can be rectified by increasing the speed droop of the engine that is subject to the greatest load (or by reducing the setting of the other engines).

The setting should not normally be increased beyond 70 on the scale, and satisfactory parallel operation can generally be obtained at settings between 40 and 60.

08028-0D/H5250/94.08.12

Description Page 1 (1)	Starting-up after Out of Service Periods	501.10 Edition 01H
---------------------------	---	------------------------------

L23/30H

The following enumerate checks are to be made immediately after starting, during load increase, and during normal running.

In the following it is assumed that the engine has been out of service for some time, for instance due to repairs and that checks during out of service periods have been carried out as described in the previous chapter.

When starting after such an out-of-service period, the following checks must be made in the stated order in addition to normal surveillance and recording.

1. To be Checked immediately after Starting:

- 1.1. Check that the turbocharger is running.
- 1.2. Check that the lubricating oil pressure is in order.
- 1.3. Check that all cylinders are firing (see exhaust temperatures).
- 1.4. Check that everything is normal for the engine speed, fuel oil, cooling water and system oil.
- 1.5. Check by simulation of the overspeed shut-down device that the engine stops. The overspeed setting should be according to " Set Points and Operation Data " section 500.

2. To be Checked during Starting-up, but only if Required after Repairs or Alterations:

- 2.1. If the condition of the machinery is not well-known, especially after repairs or alterations, the "feel-over sequence" should always be followed, i.e.:

After 5-15 and 30 minutes' idle running, open the crankcase and the camshaft housing and perform feel-over on the surfaces of all moving parts where friction may arise and cause undue heating.

Feel: Main, crankpin, (alternator), and camshaft bearings, piston pins, cylinder liners, roller guides and gear wheels.

After the last feel-over, repeat check 4 page 501.05, see also **Ignition in Crankcase** page 503.04 in section 503.

After repair or renewal of cylinder liners, piston rings or bearings, allowance must be made for a running-in period, i.e. the engine load should be increased gradually as indicated in the tables below. The engine output is determined on the basis of the fuel index and the load on the electric switchboard. The turbocharger speed gives some indication of the engine output, but is not directly proportional to the output throughout the service period.

Begin the starting-up sequence at a reduced engine speed, e.g. 400 rpm, until it can be known for certain that there are no hot spots in the engine. Then, increase the speed to the normal rpm and connect to the switchboard and put on load.

The load increase during the starting-up sequence may, for instance, be:

- 25 % load for 2 hours
- 50 % load for 2 hours
- 75 % load for 2 hours
- 100 % load may be put on.

The pump index indicated in the tables has been given as a percentage of the index at full load. To enable the index to be read directly off the fuel pumps, the following formula can be employed:

$$I = \frac{I\%}{100} \times I_f$$

I_f = Index at full load (from testbed table)

$I\%$ = Index expressed as % of full load index (stated in the preceding starting-up sequence).

Following the alteration of the pump index of the one or two cylinders concerned it must be checked that when in STOP position the governor is able to move all the fuel pumps to an average pump index not exceeding 2 or 3.

After completing the starting-up sequence, make sure that all fuel pumps are set at the same index and that the governor can cause all fuel pumps to move to "0" index.

08028-0D/H5250/94.08.12

General

Part load/low load operation

In certain ship operation situations the diesel-generator sets are sometimes exposed to part load/low load operation.

During manoeuvring all diesel-generator sets are often started up for safety reasons, resulting in low load conditions for all sets.

During harbour stay even one diesel-generator running could be lowloaded when hotel purposes are the only electricity consumers.

At part load/low load it is important to maintain constant media temperatures, i.e. for cooling water, lubricating oil and fuel oil, in order to ensure adequate combustion chamber temperature and thus complete combustion.

At loads lower than 20% MCR there is risk of time-dependant retardation of the engine performance condition due to fouling of gas- and air channels, combustion chambers and the turbocharger.

HFO-operation at loads lower than 20% MCR should therefore only take place within certain time limitations according to the curves.

After a certain period of HFO-operation at a load lower than 20% MCR, a change to MDO should take place in order to prevent further retardation of the engine performance condition, or the engine load should over a period of 15 minutes be raised to 70% MCR and maintained here for a certain period of time in order to burn off the carbon deposits, thus reestablishing adequate performance condition. After such "cleanburning period" low-load operation on HFO can be continued.

However the operator must be aware of the fact that fouling in the air inlet channels, if any, will not be cleaned with high load running. Extensive low-load running can therefore result in necessity of manual cleaning of the inlet channels.

If special application conditions demand continuous HFO-operation at loads lower than 20% MCR, and occasionally performed "clean-burning" periods are inconvenient or impossible, special equipment and arrangements must be established.




Fig 1 Low-load operation.

Description Page 1 (1)	Operating a Diesel Engine at Low Frequency	501.25 Edition 01H
---------------------------	---	------------------------------

General

Description

At land-based power stations the diesel generator is often connected to a common electrical grid with more than one power producer.

Further the diesel engine is often small compared to the rest of the grid. Under these circumstances the diesel engine cannot control the frequency of the grid, because the other producers are dominating.

If the diesel engine is delivering full 100% power at lower speed (lower frequency), this is equal to overload on the engine. Thus, if the engine is designed for 50 Hz at 750 rpm and the actual running conditions are 100%, 45 Hz (675 rpm), this corresponds to 10% overload.

Running the diesel engine at overload condition for a long period is not recommendable, it will damage the engine and is therefore not acceptable. Such operating will immediately interrupt all guarantee obligations on the engine from MAN B&W, Høleby.

Therefore it is advisable to reduce the allowable max output of the diesel generator, in case of lower frequency/speed.

Maximum output should be lowered with the same percentage as the frequency/speed drop.

If the engine is controlled by an automatic power management system, the program of the system should take care of this output reduction.

In case of no automatic power management, the output reduction must be performed manually by the operator.

Furthermore, it is not advisable to operate the alternator at frequency lower than 6% under nominal frequency.

The alternator over/under frequency protection is normally:

$$f_N \pm 6\%, 5 \text{ sec delay}$$

Below is illustrated a power curve for 50/60 Hz engines.





Fig 1 Power curve for 50/60 Hz engines.

08028-0D/H5250/94.08.12

ZHENJIANG CME CO., LTD



ZJMD-MAN B&W 6L23/30H

MAIN DIESEL GENERATING-SETS

DRAWING FOR FINAL

Shipyard : GUANGZHOU SHIPYARD INTERNATIONAL CO., LTD. / 50500DWT

Subject : 3 × 6L23/30H Gensets/Ship

Rule : ABS

Fuel oil : HFO, 380cSt/50°C

Power : 3 × 910 kW

Speed : 900 r/min

DATE: Jan. 30, 2008

ZHENJIANG CME CO., LTD

1699106-9.0 Page 1 (2)	Overhaul Recommendations	D 10 35 0
---------------------------	---------------------------------	------------------

L23/30H

Component	900 RPM	Hours Between Overhauls	Expected Service Life
Turbocharger	Dry cleaning of turbine side	every second day	
	or Wet cleaning of turbine side		
	Water washing of compressor side	every week 25-75	
	Air filter cleaning : Based on observations.		
	Inspection: Check all mounting screws, casing screws and pipe line connections for tight fit by tapping, retighten if necessary	with new or overhauled turbocharger once aft 1000	
	Compressor cleaning in dismantled condition: compressor inner components, final diffusor, compressor wheel	6.000	
	Silencer cleaning in dismantled condition: silencer felt linings ..	6.000	
Regulating system	Major overhaul: Dismantling, cleaning, inspection, checking and cleaning cartridge, checking bearing clearances, checking gaps and clearances on reassembly	12.000	
	Function check of overspeed and shutdown devices. Check that the control rod of each individual fuel pump can easily go to "stop" position	monthly	
Cylinder head			
Fuel injection valve	Checking and adjustment of valve clearance	2.000	
Exhaust valve	Checking, cleaning and adjustment of opening pressure	2.000	24.000
	Overhaul and regrinding of spindle and valve seat	12.000	
Air inlet valve	Function check of rotocap	monthly	
Valve guide			
	Overhaul in connection with exhaust valve overhaul	12.000	24.000
Cylinder head nuts	Measuring of inside diameter in connection with valve overhaul	12.000	24.000
	Retightening 200 hours after new or overhaul		
Compressed air system	Check of compressed air system	12.000	
	Refill of air lubricator : Based on observations.		
Main bearings	Inspection according to classification survey, normally after 24.000 running hours or 4 years of service	24.000	36.000
	Retightening of main bearing cap. 200 hours after new or overhaul and every	6.000	
	Retightening of screws for counterweights. 200 hours after new or overhaul and every	6.000	
Supporting chocks and bolt connections	Retightening of holding-down bolts. 200 á 1000 hours after new or overhaul and every	6.000	
	Retightening of bolts between engine frame and base frame	6.000	
	For flexible mounted engines. Check anti-vibration mountings	6.000	
Autolog reading	Crankshaft deflection and main bearing clearance reading. Should be carried out in connection with retightening of main bearing and holding-down bolts	6.000	
Big-end bearing	Retightening and checking of bearing clearance. 200 hours after new or overhaul and every	6.000	24.000
	Inspection in connection with piston overhaul	12.000	
Piston	Overhaul, replacement of compression rings and scraper rings, measuring of ring grooves, inspection of big-end bearing and inspection of cylinder liner condition	12.000	60.000

08028-0D/H5250/94.08.12

D 10 35 0	Overhaul Recommendations	1699106-9.0 Page 2 (2)
-----------	--------------------------	---------------------------

L23/30H

Component	900 RPM	Hours Between Overhauls	Expected Service Life
Cylinder liner	Inspection, measuring and reconditioning of running surface condition: In connection with piston overhaul	12.000	60.000
	Overhaul and reconditioning of surface between liner and frame and cleaning of surface in cooling water space	24.000	
Fuel pump	Fuel pump barrel/plunger assembly. Overhaul based on operational observations		24.000
Torsional vibration dampers	Overhaul A sample of silicone fluid must be taken and analysed in between.	36.000	
Lub. oil filter cartr.	Replacement based on observations of pressure drop		1.500
Filter cartridges	Replacement based on observations		1.500

08028-0D/AE250/94.08.12



TANKER VESSEL OPERATIONS MANUAL (VOM)



Procedures adopted as Schuyler Line Navigation Company
Policy to Adhere to MARPOL Annex VI Requirements

**Schuyler Line Navigation Co.
130 Severn Avenue, Suite 201
Annapolis, Maryland 21403**

TKR-VOM-08 - PART 08-008 PLANNED PREVENTATIVE MAINTENANCE SYSTEM

1.0 Description of PPM System

1.1 In accordance with The International Safety Management Code (ISM) **SLNC** has established procedures in the Ship Management System, (SMS), to identify equipment and technical systems, the sudden operational failure of which may result in hazardous situations. The SMS provides for specific measures aimed at promoting the reliability of such equipment or systems. The measures include the regular testing of stand-by arrangements and equipment or technical systems that are not in continuous use. The procedures utilized by **SLNC** and its vessels are incorporated within a formal preventative maintenance program.

SLNC utilizes the ABS approved “NS5” system for its preventative maintenance tracking and reporting program. The system has made many changes over the years, and currently is known as “NS5.” It should be noted that a critical equipment test & inspection reporting system is contained within this NS5 Program. NS5 incorporates an integrated information system which is generated at each company site (offices and ships). Each site is provided with its own database to store information and data received from the other sites. NS5’s has a built in communications facility which performs data transfer automatically and on demand using satellite, mobile, or land-lines. The data is automatically loaded into the end user’s work station. Continuous synchronicity is maintained between the central office and each remote location. See diagram 2.2. Further description of the system follows after 2.2.

1.2 Critical Equipment

The vessel's operating systems have been analyzed to identify a list of critical equipment, for which the failure of same would result in a critical or hazardous situation on the vessel. The vessel and the crew are protected from these critical failures by a combination of alarms, testing, inspections, fail-safe conditions, redundancy of hardware, critical spare parts and other devices or systems which warn of failures, ensuring the reliability of the ships operating systems and/or providing for the rapid restoration of critical functions in the event of a failure.

1.3 In the analysis of system failures, the following vital vessel systems were determined to be essential to the vessel’s safe operation:

- Cargo Systems
- Safety Systems
- Navigation Systems
- Communications Systems
- Propulsion Systems
- Electrical Systems

1.4 The critical equipment list is a separate part of the M&R section and shall be specially treated as priority. This list will identify the system or component, the frequency of inspection or testing and the location of the record of the event. The critical equipment list shall be completed by the Chief Engineer. Procedures for reporting critical failures are outlined in the Emergency

Controlled Copy

Tank Vessel Operations Manual (VOM)/Version:1.0/Revision: 0

Revision Date: 01/Jan/2019

Page **435** of **646**

Procedures section of this manual. As such, the Master is required to notify the ship manager of all failures to critical equipment via satellite phone, cell phone, or email. The reporting shall include the component nomenclature, the specific failure, the cause (if known), repairs made or recommended shore side follow up. An entry shall be made in the equipments maintenance and repair record. This procedure shall be inclusive of specific failures, and unplanned maintenance to critical equipment. The Critical Equipment list *FORM SLNC-022* provides for the item component or system, the interval of test or inspection, the “log” location, and date of inspection. The Critical Inspection Report is to be sent to the **SLNC** office each quarter. It will show the last date of the test or inspection for each component or system.

For routine planned maintenance of critical equipment, a dialogue will be established between the Master, Chief Engineer and Ship Manager to provide a risk assessment of shutting-down a particular piece of equipment or component. An assessment shall be made to determine use of back-up systems, modifications to operational procedures, or any additional safety procedures to be employed while that piece of equipment is secured. Any requirement for the use of outside vendors or contractors shall also be discussed and (if necessary) arranged.


If the maintenance of the critical equipment cannot be carried out, a further assessment shall be made between the Master, Chief Engineer, and Ship Manager. This may be due to environmental conditions (sea state etc), or crew fatigue (STCW hour parameters), or any outside forces. Communication and approval shall be made by the ship manager. The item shall be dealt with at the next opportune time and results recorded.

Controlled Copy

2.0 Shipboard Maintenance Programs

2.1 The Company has established a comprehensive maintenance program for each vessel. The maintenance program shall be carried out and documented by the Chief Engineer. The maintenance program shall be maintained in “ABS NS5” and reviewed by the Engineering Department ashore. NS-5 is an integrated information network that addresses every element of the ship management’s day to day business functions and is supported by the ABS classification society. A complete suite of NS-5 modules handle the aspects of operational management including regulatory requirements, planned preventative maintenance, purchasing, payroll, and crew management.

The interface connections of NS5 are primarily a “hub and spoke” topology where the central database acts as the communications hub for the entire system as illustrated in the diagram below:



2.2 The preventive maintenance component records, schedules, and manages all data pertaining to the work performed on a vessel by the crew or an outside contractor / vendor. This includes, planned and scheduled maintenance items, which shall be performed on specified equipment or systems at specific intervals and under stipulated procedures.

The computerized NS5 system replicates with the company daily or as otherwise deemed necessary. This replication enables the company to see ongoing and completed maintenance, repair and inspection of all equipment onboard the vessel (critical and non-critical).

Controlled Copy

SLNC has a permanently assigned 'system administrator' who is responsible for maintaining the entire system. The administrator is assisted by other trained individuals for period where the administrator is unavailable. The administrator monitors and performs many actions and responsibilities:

- data entry and data modifications
- timely back-up of information
- oversight of all transmission of data
- system maintenance and upgrades

There are many modules within the NS5 system including:

- maintenance & repairs
- purchasing
- crew management
- crew payroll
- quality & compliance
- general data
- replication

For the purpose of this chapter we will discuss the maintenance and repair module and some aspects of the purchasing module as related to M&R.

- 2.3 Maintenance performed on the vessel's structure, its machinery or systems that is the result of a failure or damage to that element is considered to be corrective in nature. Corrective maintenance encompasses the maintenance, which falls outside the parameters of the preventive maintenance system. Any deficiencies found and repairs made to systems or machinery while performing preventive maintenance tasks become corrective maintenance items. The function of the corrective maintenance component of the maintenance program is primarily a record keeping procedure. The Chief Engineer establishes crew work orders and maintains the reporting system to record maintenance of a corrective nature. These work orders shall be completed and become a part of the ship's machinery history.
- 2.4 The documentation component ensures the timely completion of all Preventive Maintenance tasks required by the program.
- 2.5 The system is established and provides for a preventive and corrective maintenance program for the engine, deck and stewards departments. This maintenance program contains elements dealing with periodic inspection and testing of machinery and equipment, navigation and communication gear, tanks and compartments, decks, superstructures, accommodations the maintenance of safety related equipment and any other items of specific concern.
- 2.6 The vessels maintenance program shall ensure that maintenance tasks, repairs and relevant surveys are carried out in a well-planned, safe and timely manner.

Controlled Copy

- 2.7 A major benefit of the system is that it provides a menu to track surveys and certificates for classification, USCG, and other regulatory bodies and inspectors.

This will ensure that there will be no delay or disruption to the vessel due to outstanding conditions of class. The surveys and / or inspections can be scheduled in a timely and organized manner consistent with class regulations and charterer's requirements.

NS5 provides a back-up system to monitor certificates and surveys. Additionally **SLNC** maintains a duplicate set of certificates in the "Sharepoint" directory. The Sharepoint directory is an on-line database which stores information and is available to users in the office and users through a web- based access.

Sharepoint has true copies (scanned images) of all certificates as well as a "due date timeline". This is only one feature of sharepoint. It additionally contains vessel schedules, vessel data, voyage data, chartering data. ESQA safety and quality statistics, and a number of other items.

- 2.8 The system produces a maintenance plan for each vessel that includes all work to be performed, and sorted by specific predetermined categories. The system allows for the generation of shipboard work orders or service requisitions. The work order section is the area that deals with crew work and crew tasks. The service requisition section is the area that documents work to be carried out by outside contractors or company vendors. Each work order or service requisition includes details of the task to be accomplished, who is to do the tasks, and a listing of parts that are to be used. This, in turn allows the on board engineers and office staff to determine what parts and services may be needed in the future.

The reporting of specific defects and maintenance tasks will be recorded in the M&R module of NS5. As discussed previously, it is maintained and held in the computer system for ease in use and editing. The basic criteria for the maintenance tasks are based on equipment manufacturer's recommendations.


As the majority of work tasks are either hourly or time cycle based, any items coming due are highlighted and those jobs which are overdue are detected through the reports section of the NS5 program. Any overdue maintenance evolutions are listed in a concise report. This procedure is built into the program and is automatically brought to the attention of the vessel's chief engineer and the office staff. The ship manager has the capability to monitor the system from the office or remotely through internet access when traveling.

- 2.9 The NS5 system tracks ongoing projects. (i.e. drydockings or out of service periods). The project module will track and record all associated maintenance tasks, vendors, spare parts used etc. The project module will track and record costs for both service contractors and purchasing events. The project section of the M&R module allows for tracking and drydock work lists and out of service period work lists. These can be reviewed and edited as necessary by ship manager. This list is maintained in NS5 and as such available at all times for shore based and shipboard personnel.
- 2.10 Replication Manager Component

Controlled Copy

The centerpiece of the NS5 system is the Replication Manager. The replication manager is a built in communications facility that performs automatic data transfer (or on demand transfer) of information to and from the vessel and office. The data can be transmitted by satellite, cell phones, or land line. Once transmitted, the data is automatically distributed and loaded into each site's database and displayed at each user's personal computer. In this way the shore based management can monitor vessel status and in turn provide any assistance that may be required.

The benefit of the replication manager is that it provides consistent terminology and standards throughout each vessel. The basic system is illustrated below:



(It should be noted that **SLNC** does not employ a centralized warehouse (per the example) but maintains inventory through individual vessel class databases.

2.11 Spares inventory

The on-board spares inventory is monitored on board the vessel through the purchasing module. The system tracks the minimum and maximum levels of spares and equipment that is to be kept on board the vessel. The level for parts and equipment has been established using manufacturer's recommendations as well as established procedures and practices. The critically level of each part is evaluated and spares levels adjusted as necessary. Critical spares are maintained (where possible) on board each vessel. Any shortages are replenished through the purchasing system. A description of which is covered in a later chapter of this manual. However, the basic system is provided as follows:

- spare part or component used on board and inventory checked
- if needed, a requisition is prepared for the part and sent to chief engineer for verification
- requisition is approved by chief engineer or master
- requisition is replicated and sent to office
- requisition is distributed to ship manager

Controlled Copy

Tank Vessel Operations Manual (VOM)/Version:1.0/Revision: 0

Revision Date: 01/Jan/2019

Page **440** of **646**

- requisition is either approved, edited, or deleted
- a record of the above is replicated to the vessel
- if approved or edited, the requisition is replicated to purchasing buyer
- the requisition may also be annotated that pricing is required for approval. in this case the buyer provides pricing to ship manager and the approval process begins again
- the buyer send out RFQs for prices of parts using **SLNC** purchasing guidelines (bid – no bid)
- prices are received and the best valued offer is provided with a purchase order
- the item is delivered to the vessel, and confirmation of receipt is provided to the purchasing department for invoice approval

As discussed previously, **SLNC** does not employ a centralized warehouse but maintains shore side inventory through individual vessel class databases. **SLNC** maintains warehouses in Houston, Texas and Portland, Oregon. A list of after hour contacts are maintained by the ship manager (should a particular part be urgently required after business hours).

2.12 Vessel Attendance

SLNC has stipulated that ship managers, (superintendents, port engineers, port captains) will attend the vessel at various times through the year and report on same. A guideline has been established that a recommendation of six (6) visits will be required annually. This may vary depending on drydock schedules and major out of service periods. Each ship manager will visit with the Captain and Chief Engineer (as a minimum) and inspect the vessel to ensure that safe and quality standards are being upheld. The inspection shall be limited to those spaces that can be safely and readily accessed. A review of vessel logs and work book shall be made as well as a review of the maintenance and repair program (NS5). The attendee shall prepare a “Vessel attendance Report” which shall contain certain inspection criteria and reporting of events as well as quality issues. A permanent record shall be kept of the attendance report in the **SLNC** offices.

The ship manager may also (as appropriate), sail on any of the vessels, to confirm that standards are being maintained. This is commonly done prior to shipyards for the preparation of work plans and shipyard specifications.

3.0 Preventive Maintenance

3.2 The system shall include applicable inspections, testing, lubrication and maintenance procedures as recommended or required in the equipment manufacturers operating manuals. Assigned tasks shall normally be performed at the interval recommended by the manufacturer. The Chief Engineer may specify alternative maintenance frequencies or procedures if appropriate for his particular vessel, if agreeable with **SLNC** Engineering staff.

3.3 The system shall include any additional maintenance requirements, which are required by regulatory statute or rule. Also include, any additional inspections, testing or maintenance which good engineering practice or experience dictates is necessary to maintain the dependability of the machinery or system.

Controlled Copy

Tank Vessel Operations Manual (VOM)/Version:1.0/Revision: 0

Revision Date: 01/Jan/2019

Page **441** of **646**

- 3.4 Maintenance work orders are outlined and included in the NS5 Program for each vessel. Maintenance work orders are to be designed and carried out ensuring that the work will not impede the sea worthiness or overall operation of the vessel.
- 3.5 The primary goals of the NS5 System is to provide a well designed, preventive maintenance system and achieve a balance in the quantity of work required in each month's work cycle. The workload tasks for each month shall consist of tasks required to be performed on a monthly basis and a portion of the quarterly, semi-annual and annually scheduled tasks so as to obtain an equal distribution. Special attention needs to be given to special maintenance items, which are due at or around shipyard periods.
- 3.6 Preventive maintenance work orders for each month shall be printed and distributed to department heads for action.

4.0 Preventive Maintenance Procedures and Work Orders

- 4.1 Preventive maintenance procedures and work orders are established for the following systems and equipment:

- Main and Auxiliary Machinery
- Steering Gear
- Inert Gas and Vapor Recovery Systems
- Automation and Control Systems
- Cargo Loading and Discharging Equipment
- Anchoring and Mooring Equipment
- Waste Disposal and Sewage Treatment Systems
- Pipelines and Valves
- Safety and Fire Fighting Equipment
- Pollution Control Equipment
- Navigation Equipment
- Communications Equipment
- Lifting Gear
- Periodic Tank and Compartment Inspections
- Decks
- Accommodations
- Machinery Spaces
- Service Spaces
- Cargo Tanks
- Machinery and Piping Systems

5.0 Follow Up

- 5.1 The individual items on the Work Order shall be checked off as they are completed. The Work Order schedule shall then be signed and dated.

Controlled Copy

- 5.2 If for any reason an individual item on the Work Order is not completed by the end of that month, an explanation shall be given and signed before returning to the 1st Engineer and/or Chief Officer.
- 5.3 The 1st Engineer shall collect the Work Order's that have not already been turned in at the end of each month and provide a copy of the work order to the Chief Engineer for his/her review and comments.
- 5.4 Monthly Work Orders shall be completed in "ABS NS5" and reviewed by **SLNC** Engineering.
- 5.5 Uncompleted Work Orders shall be reissued on the 1st day of the following month. These items shall be completed at the earliest opportunity.

6.0 Corrective Maintenance (Repairs)

- 6.1 A Work Order report form shall be issued for corrective maintenance. This report shall detail the machinery or system name, the date of repair, the nature of the repair, materials used or components replaced in completing repairs, and any photographic documentation (if necessary) relevant to maintaining a permanent record.
- 6.2 The machinery history file in "ABS NS5" will be populated once the Work Order has been completed.
- 6.3 Corrective maintenance Service Requisition shall be prepared to record work or repairs carried out by contractors on vessel's machinery or equipment. Copies of the contractor's service reports shall be kept in a separate machinery history file.
- 6.4 Corrective maintenance Work Orders may be used for Class continuous survey purposes in order to obtain credit for overhauls and inspections performed by the crew while at sea.

7.0 Corrective Actions requiring shore side support contractors

- 7.1 There will be situations when the vessel's crew will not be able to handle to scope or magnitude of repairs needed. When a situation as this develops, the Chief Engineer shall contact the vessel's ship manager or superintendent to notify of such a request. The notification may be made via telephone, email, or through the NS5 system. The severity and timeliness and urgency of scheduling will be the factor to decide how the request is transmitted.
- 7.2 For routine requests, the NS5 system will track and monitor requests and follow up. The ship will generate a work order and then the chief engineer shall either approve or disapprove the request. For approved requests requiring outside contractors or vendors, then the work order will be transmitted through replication to the superintendent. The superintendent will either approve or disapprove the work order. This will be noted in the NS5 system - so that the chief engineer will be made aware of the denial.

Any approved work order requests shall be made into a Purchase Order The PO shall be written or edited and sent to a vendor or a number of vendors (if pre-pricing is required). The

Controlled Copy

Tank Vessel Operations Manual (VOM)/Version:1.0/Revision: 0

Revision Date: 01/Jan/2019

Page **443** of **646**

superintendent is required to contact the vendor or contractor and make suitable arrangements for the work to be carried out at the earliest possibility or as expeditiously as possible. The superintendent is required to schedule the work so that there is as little disruption to the vessel's schedule and operational commitments. The superintendent shall also ensure that the vendor or contractor has suitable insurance as required in the company procedures. Arrangements shall be made through the vessel's agents to provide port or gate passes so that the vendors can gain access to the vessel.

If any hot work is required (in port) - a certified marine chemist shall inspect the vessel and determine suitability of hot work. Certificates shall be issued and signed by the Master of the vessel prior to any hot work taking place.

After the work is completed, the vessel shall 'sign off' the work in the NS5 system by "completing" the purchase order. This will be an indication to all that the work was satisfactorily completed and /or all goods and services were received and accounted for. Upon receipt of the "completion", the superintendent shall "complete" the final phase of the purchase order indicating the final price and agreement that the invoice may be paid.

- 7.3 The NS5 system will provide an entry into the particular vessel machinery or equipment and indicate what work was carried out as a historical reference.

Controlled Copy



TANKER VESSEL OPERATIONS MANUAL (VOM)



Procedures adopted as Schuyler Line Navigation Company
Policy to Adhere to MARPOL Annex VI Requirements

**Schuyler Line Navigation Co.
130 Severn Avenue, Suite 201
Annapolis, Maryland 21403**

TKR-VOM-03 - PART 03-022 THIRD ASSISTANT ENGINEER

- 8.1 Stand watch in accordance with the established watch schedule.
- 8.2 Assist in the maintenance and repair of equipment as directed by the Chief Engineer or 1st Assistant Engineer.
- 8.3 Maintain the electrical systems, distilling plant and Lubricating oil systems, lube oil purifiers and MSDS on the ship as directed by the Chief Engineer or 1st Assistant Engineer.
- 8.4 Obtain the consent of the 1st Assistant or Chief Engineer for any absence from the vessel.

The 3AE shall report to the First Assistant Engineer. The 1AE will assign the 3AE to duties, both at sea and in port.

Controlled Copy

Tank Vessel Operations Manual (VOM)/Version:1.0/Revision: 0

Revision Date: 01/Jan/2019

Page 92 of 646



TANKER VESSEL OPERATIONS MANUAL (VOM)



Procedures adopted as Schuyler Line Navigation Company
Policy to Adhere to MARPOL Annex VI Requirements

**Schuyler Line Navigation Co.
130 Severn Avenue, Suite 201
Annapolis, Maryland 21403**

TKR-VOM-08 - PART 08-005 ENGINE DEPARTMENT EMERGENCY PROCEDURES

1.0 Emergency Preparedness

- 1.1 It is the responsibility of individuals aboard **SLNC** vessels to be prepared for emergency situations.
- 1.2 The licensed Engineer on watch shall record emergency events and times of such events in the Engine room Log Book.

2.0 Emergency Events

- 2.1 The following emergency events describe the responsibilities and actions to be taken by the engineering department when such an event occurs. This is not meant to limit the individual's responsibility to assess each situation and modify the actions taken based on the specific circumstances of each situation. These events shall be the focus of drills that shall be scheduled at the discretion of the Master as prescribed by regulatory requirements.

Abandon Ship

- 2.2 All personnel shall muster at their station as per the Station Bill and follow directions of the Master, personnel assigned to the Engine room shall:
- Maintain propulsion and steering until directed otherwise.
 - Secure machinery, if time permits, so as to facilitate safe abandonment.
 - Notify Bridge when evacuating the engine room.

Bridge Control Failure / Engine Order Telegraph Failures

- 2.3 The watch stander shall:
- Establish communication with the Bridge.
 - Switch to Engine room Control.
 - Notify Chief and 1st Engineer and activate engineer's assistance alarm.
 - Maintain communication with the Bridge.

Collision

- 2.4 The watch stander, upon notification, shall do the following;
- Maintain the watch at the Control Station.
 - Prepare to respond to communications from the Bridge.
 - Ensure that the fire main is pressurized.
 - Standby to take maneuvering orders if required.
 - Close all watertight doors.

Controlled Copy

2.5 Non-watch standing personnel shall:

- Go to their Emergency Station.
- Complete muster.
- Follow directions of the Master.

2.6 The Chief Engineer, under the direction of the Master, shall be in charge of the Engine room to direct all engine related operations and procedures.

Fire (other than engine room)

2.7 The watch stander, upon activation of the General Alarm, shall:

- Prepare to respond to communications from the Bridge.
- Ensure that the fire main is pressurized.
- Standby to take maneuvering orders if required.
- Maintain their watch at the Control Station until properly relieved by the Chief or 1st Engineer.

2.8 Non-watch standing personnel shall:

- Go to their Emergency Station.
- Complete muster.
- Follow directions of the Master.

2.9 The Chief Engineer, under direction of the Master, shall be in charge of the Engine room to ensure the following:

- Fire main pressure is established and maintained.
- The engine room is adequately manned.
- That maneuvering orders are followed.

Engine room Fire

2.10 The watch stander, upon discovering fire in the Engine room, shall do the following:

- Report the fire to the Bridge & Chief Engineer.
- Respond as appropriate to contain and/or extinguish fire.
- Notify Bridge when evacuating engine room.

2.11 Non-watch standing personnel shall:

- Go to their Emergency Station.
- Complete muster.
- Follow directions of the Master.

Controlled Copy

Tank Vessel Operations Manual (VOM)/Version:1.0/Revision: 0

Revision Date: 01/Jan/2019

Page **424** of **646**

- The Chief Engineer, under direction of the Master, shall be in charge of the Engine room.

Engine room Flooding

2.12 The watch stander, upon detecting flooding in the Engine room, shall:

- Report the condition of the Engine Room to the Bridge & Chief Engineer.
- Activate the Engineers assistance alarm.
- Take appropriate actions to stop source of flooding.
- Align emergency bilge suction for use, if so directed.
- Close all watertight doors (as applicable).

2.13 Non-watch standing personnel shall:

- Assemble at the Engine room Control Station.
- Follow directions of the Chief Engineer.
- The Chief Engineer, under the direction of the Master, shall be in charge of carrying out damage control measures as appropriate.

Abnormal Engine room Oil Leakage

2.14 The watch stander upon detecting oil leakage in the Engine room, shall:

- Report the condition to the Bridge & Chief Engineer.
- Activate the Engineers assistance alarm
- Attempt to secure the source of leakage and/or mitigate as appropriate.
- Non-watch standing personnel shall respond and assist in the containment as directed by the Chief Engineer.
- The Chief Engineer and 1st Engineer shall proceed to the Engine room.
- The Chief Engineer shall keep the Master advised of the conditions.

Helicopter Operations

2.15 Helicopter operations are assumed to be a planned event. The engine room watch stander shall be prepared to take maneuvering orders for positioning the vessel during the event.

2.16 The Chief Engineer shall evaluate the need for and assign additional watch personnel as appropriate for the conditions during the event.

Heavy Weather Operation

2.17 The watch stander or duty engineer, during heavy weather, shall make more frequent inspections of equipment and systems for the purpose of ascertaining adverse impacts that weather conditions may be having.

Controlled Copy

Tank Vessel Operations Manual (VOM)/Version:1.0/Revision: 0

Revision Date: 01/Jan/2019

Page **425** of **646**

- 2.18 The watch stander or duty engineer, in the event that a given piece of equipment and/or system are being adversely affected by heavy weather, shall notify the Bridge and the Chief Engineer of the condition.

Propulsion Failure

- 2.19 The watch stander or duty engineer, when propulsion failure is detected, shall:
- Report the failure to the Bridge & Chief Engineer.
 - Activate the Engineers assistance alarm.
- 2.20 Non-watch standing personnel shall:
- Assemble at the Engine room Control Station.
 - Follow directions of the Chief Engineer.
- 2.21 The Chief Engineer, when in an unrestricted sea way, shall:
- Diagnose and repair the problem.
 - Keep the Master apprised of the situation.
 - Maintain other systems to the extent possible.
- 2.22 The Chief Engineer, in confined waters or while maneuvering, shall determine the immediate course of action in consultation with the Master.

Man Overboard

- 2.23 The watch stander, upon receiving information of a man overboard shall:
- Maintain the watch at the Control Station.
 - Prepare the plant for maneuvering.
 - Call the Chief Engineer for assistance in the Engine room.
 - Standby to take maneuvering orders as required.
 - Non-watch standing personnel shall assist as directed by the Master, if requested.

Search & Rescue

- 2.24 Search & Rescue operations are assumed to be a planned event. The engine room watch stander shall be prepared to take maneuvering orders for positioning the vessel during the event.
- 2.25 The Chief Engineer shall evaluate the need for and assign additional watch personnel, as appropriate, for the conditions during the event.

Controlled Copy

Steering Failure

- 2.26 For vessels constructed with two (2) separate Steering Gear rooms, if the steering gear failure is confined to either the port or starboard steering gear, then the watch engineer shall notify Chief Engineer; proceed to the location of the malfunction and follow procedures as defined to switch over control to the operable steering gear. Should both steering gears fail simultaneously, then the Watch Engineer shall proceed to the STARBOARD steering station and the First Assistant Engineer shall report to the PORT steering station and follow procedures as defined.
- 2.27 The Engine room watch stander, when notified by the Bridge of a Steering Failure:
- Activate the Engineers assistance alarm.
 - Proceed directly to the Steering Gear room.
 - Take corrective action and report to the Bridge or establish local control of the steering gear, if possible and notify the Bridge of readiness to take helm orders.
- 2.28 The Chief Engineer shall:
- Proceed to the Steering Gear room.
 - Make an assessment of the condition and take corrective action.
 - Assign personnel to appropriate duties for local steering of the vessel and watch keeping.
 - Notify the Bridge of steering capabilities of the vessel.

Stranding or Grounding

- 2.29 The watch stander or duty engineer, upon notification by the Bridge of a stranding or grounding, shall:
- Maintain the watch at the Control Station.
 - Activate the Engineers Assistance Alarm.
 - Ensure that the fire main is pressurized.
 - Assume maneuvering mode.
 - Standby to take maneuvering orders as required.
 - The Chief Engineer shall make an engine room inspection to assess integrity and condition of the engine room and report conditions found to the Master.
- 2.30 Non-watch standing personnel shall, upon activation of the Engineers Assistance Alarm:
- Assemble at the Engine Room Control Station.
 - Follow directions of the Master or Chief Engineer.

Loss of Ships Service Electrical Power - Emergency Diesel Generator Power Available. Ship Service Generator Failure - Emergency Generator Starts.

- 2.31 The watch stander shall:

Controlled Copy

- Detect and report failure to the Bridge & Chief Engineer.
- Stop the Main Engine.
- Activate the Engineers assistance alarm.

2.32 The watch Engineer shall re-establish electrical power and stabilize the plant by means of the following:

- Initiate feedback from the Emergency Buss.
- Start the standby Ship Service Generator and transfer load from the Emergency Generator.
- The Chief Engineer shall investigate cause of failure.
- Undertake measures to re-establish full normal plant operation.

Ship Service Generator Failure/Emergency Battery Lighting Only

2.33 With the Emergency Generator in the “auto start” mode and the standby generator fails to start and the emergency lighting batteries take the lighting load, the watch Engineer shall follow procedures as defined and establish electrical power, as follows:

- Start Emergency Air Compressor for Ship Service Generator starting.

Start the standby Ship Service Generator and re-establish power to the Main Switchboard.

- Off watch Personnel, when notified, shall muster and assist in damage control as directed by the Master.

Breakaway from Dock

2.34 The watch stander, upon receiving information of a breakaway from a dock shall:

- Maintain the watch at the Control Station.
- Prepare the plant for maneuvering.
- Call the Chief Engineer for assistance in the Engine room.
- Standby to take maneuvering orders as required.
- Secure cargo pumps.
- Ensure that the fire main is pressurized.
- Non-watch standing personnel shall assist as directed by the Master, if requested.

Unmanned Engine Room Operations

2.35 Should there be any emergencies as referenced above, then unmanned operations shall stop and full manned engine room status shall resume. The Chief Engineer shall assign duties to members of the engineering staff as necessary to assist in the emergency situation.

Controlled Copy

Tank Vessel Operations Manual (VOM)/Version:1.0/Revision: 0

Revision Date: 01/Jan/2019

Page **428** of **646**

- Prepare towing equipment if required

3.0 Engine Room Fire

3.1 Use of fixed system should be considered in the first few minutes of a machinery space fire if it is not extinguished immediately with portable extinguishers.

- Inform Master
- Sound general alarm
- Muster crew – account for all hands
- If in port – advise terminal/port authority
- Secure all cargo/ballast/bunker operations – utilize emergency shoreside shut-down system (if available)
- Secure cross – ship’s passageway and water tight doors as directed
- Secure fuel oil valves as directed by Chief Engineer
- Secure ventilation/dampers as required
- Isolate electrical power to affected areas
- Ensure fire pump is lined up and ready - start fire pump when requested
- Prepare foam pump as required
- Ensure emergency generator is ready for use – start if requested
- At sea – alert all traffic in the area and notify the local port state as required
- Sound appropriate signals
- Advise emergency teams of known situation/prepare plan of attack
- Commence boundary cooling
- Brief fire party prior to entering space – means of escape and anticipated firefighting requirements
- Contain and work to control and extinguish fire
- Commence fire patrols for flash back watch and to protect against fires in adjacent spaces
- At sea – prepare to transmit safety and/or distress message as needed
- Prepare lifesaving appliances for use
- Ensure back up equipment is available at the scene – recharge SCBA’s bottles as needed
- Pump water out of affected spaces
- Maintain escape route throughout
- Consider use of fixed CO2 system
- Evacuate all personnel prior to use of fixed system
- Batten down all openings prior to use of fixed system
- Re-muster crew prior to use of fixed system
- After release leave space secured for adequate time to ensure fire is extinguished.
- Re-entry into enclosed spaces following CO2 activation requires prior notification and consultation with **SLNC** Operations Department. Where practical space re-entry will be cleared “safe for personnel” by a certified Marine Chemist.
- Transmit distress call if required
- Follow VRP (as applicable)
- Prepare emergency towing equipment as required

Controlled Copy

Tank Vessel Operations Manual (VOM)/Version:1.0/Revision: 0

Revision Date: 01/Jan/2019

Page **566** of **646**

4.0 Machinery Space Fire

4.1 Use of fixed system should be considered in the first few minutes of a machinery space fire if it is not extinguished immediately with portable extinguishers.

4.2 Consider using foam.

- Sound general alarm
- Inform Master
- Muster crew – account for all hands
- If in port – advise terminal/port authority
- At sea – alert all traffic in the area and notify the local port state as required
- Sound appropriate signals
- Secure all cargo/ballast/bunker operations – utilize shore side emergency shut-down system (if available)
- Secure all appropriate emergency fuel shut-off valves
- Secure ventilation/dampers
- Consider use of fixed CO2 system or foam system
- Space evacuated
- Space secured
- Electrical power secured
- After release leave space secured for adequate time to ensure fire is extinguished.
- Re-entry into enclosed spaces following CO2 activation requires prior notification and consultation with **SLNC** Operations Department. Where practical space re-entry will be cleared “safe for personnel” by a certified Marine Chemist.
- Utilize tug fire pump for boundary cooling and additional fire protection

5.0 Deck Fire

5.1 Cargo Fire

- Inform Master
- Sound general alarm
- Muster crew – all hands accounted for
- If in port – advise terminal / port authority
- Secure all cargo/ballast/bunker operations – utilize emergency shoreside shut-down system (if available)
- Ensure fire pump is lined up and ready - start fire pump when requested
- Prepare foam pump
- Ensure emergency generator is ready for use – start if requested
- Start/utilize deck monitors
- At sea – consider course alteration for wind (vapor dispersal) and the avoidance of any prevailing dangers to navigation
- At sea alert all traffic in the area and notify the local port state as required
- Advise engine room and emergency teams of situation

Controlled Copy

Tank Vessel Operations Manual (VOM)/Version:1.0/Revision: 0

Revision Date: 01/Jan/2019

Page **567** of **646**

TKR-VOM-11 - PART 11-030 INJURY OR ILLNESS

Recognizing that each emergency injury/illness case is unique, the following procedures shall be followed as conditions relative to a specific case allow:

1.0 First Aid

1.1 If an injury/illness requires no more attention than first aid, such aid may be rendered by crewmembers under the Master's supervision or by the Master. If it is determined that a treated injury/illness requires a follow-up visit to a clinic or doctor's office at the next port-of-call, such a visit (transportation, etc.) shall be scheduled through the Master via Agent next available port.

2.0 Injury/Illness Requiring Care Beyond First Aid

2.1 Injury/Illness requiring care beyond first aid, not necessarily requiring immediate professional medical attention (e.g., incapacitating, but not life-threatening illness). If the injury/illness requires a doctor's care, the employee shall be taken to the nearest medical facility. If at sea MAS (Medical Advisory Service) shall be contacted for guidance. The Master shall also consult the Operations office for guidance and, if necessary, deviation instructions.

3.0 Injury/Illness Requiring Immediate Doctor's Care

3.1 The Master (or crewman designated by the Master) shall apply the appropriate first aid measures that are possible without aggravating the patient's condition (remove patient from hazardous conditions, control bleeding, etc.) and monitor vital signs. In cases of patient bleeding, the Bloodborne Pathogens Kit shall be used to protect caregivers. The Master shall answer questions in the MAS (Medical Advisory Service) Manual pertaining to the patient's case, consult the MAS duty physician, and follow the physician's instructions. As soon as possible following the MAS consultation, the Master shall contact Operations personnel, and provide an appropriate briefing. Deviation or evacuation actions shall proceed, based on MAS physician recommendations. If helicopter evacuation is required, refer to Part Y of this section.

Controlled Copy

TKR-VOM-11 - PART 11-025 HELICOPTER EVACUATION

The following was prepared for use in evacuations carried out by USCG helicopters. Its applicability extends to helicopter operations conducted by private operators, as well as military helicopters. Helicopter evacuation is a hazardous operation to all concerned and shall be attempted only when life or health is gravely threatened.

1.0 Requesting Helicopter Assistance

- 1.1 Give accurate position, time, speed, course, weather conditions, wind direction and velocity.
- 1.2 If not already provided, give complete medical information, including whether or not the patient is ambulatory.
- 1.3 If beyond helicopter range, advise of diversion intentions so a rendezvous point may be selected.
- 1.4 If there are any changes, advise immediately.

2.0 Preparation Prior to Arrival of the Helicopter

- 2.1 Provide continuous radio guard on 2182 kHz, or specified voice frequency, if possible.
- 2.2 Select and clear the most suitable hoist area with the maximum clear deck area. This includes the securing of loose gear, antenna wires.
- 2.3 If the hoist is at night, light the pickup area as well as possible. Be sure to avoid shining lights on the helicopter, as that could blind the pilot. Put a light on any obstructions in the vicinity so the pilot will be aware of their positions.
- 2.4 Point searchlights vertically to provide the pilot an aid in locating the vessel, and secure them after the helicopter is on the scene.
- 2.5 Advise location of pickup area before the helicopter arrives so it may make best approach.
- 2.6 There will be a high noise level under the helicopter, making voice communications almost impossible. Arrange a set of hand signals among the assisting crew.

3.0 Hoist Operations

- 3.1 If possible, move the patient to a position as close to the hoist area as his condition permits - **TIME IS IMPORTANT.**
- 3.2 Normally, if a litter is required, it will be necessary to move the patient to a special litter, which will be lowered by the helicopter. Be prepared to do this as quickly as possible. Be sure the patient is strapped in, face up, wearing a life jacket, if conditions permit.
- 3.3 Be sure the patient is tagged to indicate what medication, if any was administered, and when.

Controlled Copy

- 3.4 Have information on the patient's medical status and necessary papers in an envelope or package ready for transfer with him.
- 3.5 Change course so the vessel rides as easily as possible with the wind on the bow, preferably on the port bow. Try to choose a course to keep stack gases clear of the hoist area.
- 3.6 Reduce speed if necessary to ease vessel's motion, but maintain steerageway.
- 3.7 If radio contact with the helicopter has not been established when the vessel is ready for the hoist, signal the helicopter in with a "come on" by hand, or at night, with a flashlight.
- 3.8 **Allow basket or stretcher to touch deck prior to handling in order to avoid static shock.**
- 3.9 Place the patient into the basket, sifting with hands clear of sides, or in the litter as described above. Signal the helicopter hoist operator when ready for the hoist. Patient should signal by nodding his or her head, if able. Deck personnel should signal thumbs up.
- 3.10 If it is necessary to take the litter away from the hoist point, unhook the hoist cable and keep free for the helicopter to haul in. Do not secure cable to vessel or attempt to move stretcher without unhooking.
- 3.11 When the patient is strapped onto the stretcher, signal the helicopter to lower the cable, hook up, and signal the hoist operator when ready to hoist. Steady the stretcher to keep it from swinging or turning.
- 3.12 If a tag line is attached to the basket or stretcher, use it to steady the hoist. Keep feet clear of line.

- Request helicopter assistance giving the accurate position, time, speed, course, weather conditions, wind direction and velocity.
- Chose a rendezvous point and prepare for arrival.
- Establish hand signals to be used by crew to maintain communication when the helicopter is in auditory range.
- Retrieve the patient's medical paperwork.
- Change course so the vessel rides as easily as possible with the wind on the bow, preferably on the port bow. Try to choose a course to keep stack gases clear of the hoist area.
- Work quickly to move the patient to the hoist area.
- Establish contact with the helicopter to direct a safe hoist.

Reference: ICS Helicopter/Ship Operations

Controlled Copy

Tank Vessel Operations Manual (VOM)/Version:1.0/Revision: 0


Revision Date: 01/Jan/2019

Page **600** of **646**

M3-1

INSTRUCTION BOOK

ZHENJIANG MARINE DIESEL WORKS



Instruction Book

L23/30H

..... Shipyard :

Ship name :

Hull No. :

Rule :

Add: 250, Guangtangqiao Zhenjiang

Jiangsu Province P.R.China

Tel: [REDACTED]

Fax: +86 511 451 0033

IndexPage 1 (1)	Engine Data	500
--------------------	--------------------	------------

Description	Document no	Notes
Warning	<u>000.00</u>	
Description	Document no	Notes
Main data for engine	<u>500.00</u>	
Introduction	<u>500.01 (02)</u>	
Safety	<u>500.02 (01H)</u>	
Cross section	<u>500.05 (06H)</u>	
Key for engine designation	<u>500.10 (02)</u>	
Designation of cylinders	<u>500.11 (01H)</u>	
Engine rotation clockwise	<u>500.12 (02H)</u>	
Code identification for instruments	<u>500.20 (01H)</u>	
Introduction to planned maintenance programme	<u>500.24 (02H)</u>	
Planned maintenance programme	<u>500.25 (19H)</u>	
Planned maintenance programme	<u>500.25 (22H)</u>	
Operation data and set points	<u>500.30 (35H)</u>	
Data for pressure and tolerance	<u>500.35 (15H)</u>	
Data for tightening torque	<u>500.40 (21H)</u>	- 720/750 rpm
Data for tightening torque	<u>500.40 (22H)</u>	- 900 rpm
Declaration of weight	<u>500.45 (01H)</u>	
Ordering of spare parts	<u>500.50 (01H)</u>	
Service letters	<u>500.55 (01H)</u>	
Conversion table	<u>500.60 (01H)</u>	
Basic symbols for piping	<u>500.65 (01H)</u>	

Description Page 1 (1)	Warning	000.00
---------------------------	---------	--------

General

Warning !

(Marine engines only)

It is important that all MAN B&W Diesel A/S engines are operated within the given specifications and performance tolerances specified in the engines' Technical Files and are maintained according to the MAN B&W Diesel A/S maintenance instructions in order to comply with given emissions regulations.

In accordance with Chapter I of the Code of Federal Regulations, Part 94, Subpart C, §94.211 NOTICE is hereby given that Chapter I of the Code of Federal Regulations, Part 94, Subpart K, §94.1004 requires that the emissions related maintenance of the diesel engine shall be performed as specified in MAN B&W Diesel A/S instructions including, but not limited to, the instructions to that effect included in the Technical File.

08028-0D/H6250/94.08.12

IndexPage 1 (2)	Control and Safety Systems, Automatics and Instruments	509
-------------------------------	--	------------

Description	Document no	Notes
Control and safety systems	<u>509.01 (01H)</u>	-
Instrument and automatics	<u>509.05 (01H)</u>	-
Lambda controller	<u>509.10 (02H)</u>	-
Starting box	<u>509.35 (01H)</u>	-
Converter for engine- and turbocharger RPM signal	<u>509.40 (01H)</u>	-

Working card	Document no	Notes
Functional test and adjustment of safety, alarm and monitoring equipment	<u>509-01.00 (01H)</u>	-
Function test and adjustment of overspeed trip	<u>509-01.05 (01H)</u>	-
Adjustment and test of ON/OFF pressostate	<u>509-05.00 (01H)</u>	-
Adjustment and test of ON/OFF thermostate	<u>509-05.01 (01H)</u>	-
Function and test of level switch (LAL 25)	<u>509-05.02 (01H)</u>	-
Adjustment and test of analogous pressure transmitter	<u>509-05.03 (01H)</u>	-
Adjustment and test of analogous temperature transmitter	<u>509-05.04 (01H)</u>	-
Adjustment of lambda controller	<u>509-10.00 (08H)</u>	-

Plates	Document no	Notes
Governor and governor drive	<u>50901-22H</u>	optional
Governor and governor drive	<u>50901-21H</u>	standard
Governor and governor drive	<u>50901-23H</u>	-
Regulating device	<u>50902-06H</u>	optional
Regulating device	<u>50902-07H</u>	standard
Overspeed device	<u>50903-02H</u>	-
Fuel oil leakage alarm (LAH 42)	<u>50905-02H</u>	-
Prelubricating oil alarm (LAL 25)	<u>50905-03H</u>	-

IndexPage	Control and Safety Systems,	509
2 (2)	Automatics and Instruments	

Plates	Document no	Notes
Level switch in oil sump (LAL 28)	<u>50905-05H</u>	-
Instrument panel	<u>50905-07H</u>	-
Level switch in oil sump (LAL/LAH 28)	<u>50905-09H</u>	-
Level switch in oil sump (LAL/LAH 28)	<u>50905-10H</u>	-
Instrument panel	<u>50905-11H</u>	-
Pressostate, thermostate, difference pressostate and pressure transmitter	<u>50907-01H</u>	-
Thermometer	<u>50907-02H</u>	-
Pick-up	<u>50908-01H</u>	-
Lambda controller	<u>50910-02H</u>	-
Starting box	<u>50935-01H</u>	-

Description Page 1 (2)	Control and Safety Systems	509.01 Edition 01H
---------------------------	-----------------------------------	------------------------------

L23/30H

Governor

The engine speed is controlled by a hydraulic governor. The purpose of the governor is to regulate the rate of delivery from the fuel pumps, so that the engine speed is kept within certain limits, independent on the load.

Information about the design, function and operation of the governor is found in the special governor instruction book.

The governor is mounted on the flywheel end of the engine and is driven from the camshaft via a cylindrical gear wheel and a set of bevel gears.

Pick-up for Engine RPM

The pick-up for transfer of signal to the tachometer instrument for engine RPM is mounted on the flywheel end cover of the engine.

A signal varying proportionally to engine RPM is created in the pick-up by the rotating toothed impulse wheel mounted on the camshaft end.

Pick-up for Turbocharger RPM

See turbocharger instruction book, section 512.

Regulating Shaft

The governor movements are transmitted through a spring-loaded pull rod to the fuel pump regulating shaft which is fitted along the engine.

The spring-loaded pull rod permits the governor to give full deflection even if the stop cylinder of the manoeuvring system keeps the fuel pump regulating shaft at "no fuel" position.

Each fuel pump is connected to the common, longitudinal regulating shaft by means of a two-piece, spring-loaded arm.

Should a fuel pump plunger seize in its barrel, thus blocking the regulating guide, governing of the remaining fuel pumps may continue unimpeded owing to the spring-loaded linkage between the blocked pump and the regulating shaft.

Stop Screw for Max. Delivery Rate

The bracket for stop cylinder/limiting cylinder is fitted with a stop screw which prevents the fuel pumps from being set to a higher delivery rate than what corresponds to the permissible overload rating.

This is effected by the arm on the regulating shaft being stopped by the stop screw, *see fig. 1*.

Mechanical Overspeed (SSH 81)

The engine is protected against overspeeding in the event of, for instance, governor failure by means of an overspeed trip.

The engine is equipped with a stopping device which starts to operate if the maximum permissible revolution number is exceeded.

The overspeed tripping device is fitted to the end cover of the lubricating oil pump and is driven through this pump.

If the pre-set tripping speed is exceeded, the spring-loaded flyweight (1), *see fig. 1*, will move outwards and press down the arm (2).

The arm is locked in its bottom position by the lock pin (3) which is pressed in by the spring (4).

At the same time the arm (2) presses down the spindle (5), and the pneumatic valve (6) opens, whereby compressed air will be led to the Lambda cylinder, *see description 509.10*, in which the piston is pressed forward and, through the arm, turns the fuel pump regulating rod to STOP position, thereby the engine stops, the spring-loaded pull rod connection to the governor being compressed.

08028-0D/H5250/94.08.12

L23/30H

The engine can be stopped manually by pressing down the button (7), see fig. 1, which will activate the spring-loaded fly weight (1) through the lever (8).

If the overspeed has been activated the overspeed must be reset before the engine can be started. Reset is done by means of the button (10).

The overspeed alarm (SAH. 81) is activated by means of the micro switch (9).




Fig 1. Mechanical overspeed (SSH 81).

08028-0D/H5250/94.08.12

Description Page 1 (3)	Instruments and Automatics	509.05 Edition 01H
---------------------------	-----------------------------------	------------------------------

L23/30H

Main Instrument Panel

As standard the engine is equipped with an instrument panel, comprising instruments for visual indication of the most essential pressures. Illustrated on *fig. 1*.

The instrument panel is mounted flexibly on rubber elements and all manometer connections are connected to the panel by means of flexible hoses, as shown on *fig. 2*.




Fig. 1. Lay-out of instrument panel




Fig. 2. Cross section of instrument panel

The connecting pipes to the manometers are equipped with valves which make it possible to replace the manometers during operation.

08028-0D/H5250/94.08.12

L23/30H

Instrumentation

As standard the engine is supplied with the following instrumentation mounted local on the engine:

Thermometer	TI 01	LT water - inlet air cooler
Thermometer	TI 02	LT water - outlet from air cooler
Thermometer	TI 03	LT water - outlet from lub. oil cooler
Thermometer	TI 10	HT fresh water - inlet to engine
Thermometer	TI 11	HT fresh water - outlet each cylinder
Thermometer	TI 20	Lubricating oil - inlet to cooler
Thermometer	TI 22	Lubricating oil - outlet from filter
Thermometer	TI 30	Charge air - inlet to cooler
Thermometer	TI 31	Charge air - outlet from cooler
Thermometer	TI 40	Fuel oil - inlet to engine
Thermometer	TI 60	Exhaust gas - outlet each cylinder
Thermometer	TI 61	Exhaust gas - outlet turbocharger

The actual number of the instrumentation for the plant can be seen on the diagrams for the specific plant in the sections 512-513-514-515-516.
For code identification see 500.20.

Pressostates and Thermostates

The engine is supplied with a number of alarm- and shut-down functions. The alarms shall via the alarm panel warn against an abnormal working condition, which can lead to break down and the shut-down functions shall stop the engine before a break down. I.e. a shut-down is "worse" than an alarm because a shut-down is given if the engine could be severe damage by running on these conditions.

As standard the engine is equipped with:

Shut-down Switches for

- too low lubricating oil pressure - inlet engine
- too high HT FW temperature - outlet engine
- too high engine speed (over speed)

Alarm Switches for

- leaking fuel oil
- too low lubricating oil pressure - inlet engine
- too low prelubricating oil pressure (level alarm)

- too high press. drop across lub. oil filter
- too high HT FW temperature - outlet engine
- too low starting air pressure - inlet engine
- too high engine speed (overspeed)

The actual number and type of the alarm- and shut-down switches for the plant can be seen in the list "Engine Automatic part list" in this section.

Leakage Alarm (LAH 42)

Waste and leak oil from the comparement, for the injection equipment, fuel valves, high-pressure pipes and engine feed pump (if mounted) is led to a fuel leakage alarm unit.




Fig. 4. Fuel oil leakage alarm.

Description Page 3 (3)	Instruments and Automatics	509.05 Edition 01H
---------------------------	-----------------------------------	------------------------------

L23/30H

The alarm unit consists of a box with a float switch for level monitoring, *see fig. 4*.

The supply fuel oil to the engine is led through the unit in order to keep heated up, thereby ensuring free drainage passage even for high-viscous waste/leak oil.

Under normal conditions there will always be a smaller amount of waste/leak oil from the compement, this will be led out through the bore "A" in the pipe "B" as illustrated.

In case of a larger than normal leakage, the level in the box will rise and the level switch "C" will be activated. The larger amount of leak oil will be lead out through the top of the pipe "B".

Alarm for Prelubricating (LAL 25)

Alarm for missing prelubricating, when the engine is stopped is given by means of a level switch (LAL 25) mounted in the main lubricating oil pipe.

Alarm and Shut-down for Overspeed

When the mechanical overspeed is activated, *see 509.01 fig. 2*, a micro-switch will release the alarm for overspeed (SAH 81) and activate the shut-down solenoid in the governor.

The latter function is a back-up for the mechanical overspeed.

Description Page 1 (1)	Lambda Controller	509.10 Edition 02H
---------------------------	--------------------------	------------------------------

L23/30H

Purpose

The purpose with the lambda controller is to prevent injection of more fuel in the combustion chamber than can be burned during a momentary load increase. This is carried out by controlling the relation between the fuel index and the charge air pressure.

The Lambda controller is also used as stop cylinder.

Advantages

The lambda controller has the following advantages:

- Reduction of visible smoke in case of sudden momentary load increases.
- Improved load ability.
- Less fouling of the engine's exhaust gas ways.
- Limitation of fuel oil index during starting procedure.

Principles for functioning

Figure 1 illustrates the controller's operation mode. In case of a momentary load increase, the regulating device will increase the index on the injection pumps and hereby the regulator arm (1) is turned, the switch (2) will touch the piston arm (3) and be pushed downwards, whereby the electrical circuit will be closed.

Thus the solenoid valve (4) opens. The jet system is activated, the turbocharger accelerates and increases the charge air pressure, thereby pressing the piston (3) backwards in the lambda cylinder (5). When the lambda ratio is satisfactory, the jet system will be deactivated.

At a 50% load change the system will be activated for about 3-8 seconds.

If the system is activated more than 10 seconds, the solenoid valve will be shut off and there will be a remote signal for "system failure".

Fuel oil limiting during start procedure

During the start procedure the lambda controller is used as an index limiter.

Hereby heavy smoke formation is prevented during start procedure and further the regulating device cannot over-react.

The jet system is blocked during the starting procedure until the engine has reached 710 RPM.




Fig 1 Principle drawing of lambda controller.

08028-0D/H5250/94.08.12

Description Page 1 (1)	Starting Box	509.35 Edition 01H
---------------------------	---------------------	------------------------------

L23/30H

Description

The starting box is mounted on the engine's control side. On front of the box there are the following indications/pushbuttons:

- Indication of engine or turbocharger RPM
- Indication of electronic overspeed
- Pushbutton for "Manual Start"
- Pushbutton for "Manual Stop"
- Pushbutton for "Remote" *
- Pushbutton for "Local" *
- Pushbutton for "Blocking" *
- Pushbutton for change-over between engine and turbocharger RPM

* The function chosen is indicated in the pushbutton. See fig 1.

Manual Start

The engine can be started by means of the start button, but only if the button "Local" is activated.

The manual, local start is an electrical, pneumatic start, i.e. when activating the start button a solenoid valve opens for air to the air starter, thereby engaging the starter and starting the diesel engine. Throughout the starting cycle the start button must be activated.

The air starter is automatically disengaged when the diesel engine exceeds 140 RPM. If the start button is disengaged before the diesel engine has exceeded 140 RPM, further starting cycles are blocked, until 5 sec. after the engine is at standstill.

Remote Start

Remote start can only take place if the pushbutton for "Remote" is activated.

Manual Stop

The "Manual Stop" button is connected to the stop coil on the governor.

Blocking

If "Blocking" is activated, it is not possible to start the diesel engine.

Engine / Turbocharger RPM

By activating the "Engine RPM/TC RPM" button, the indication is changed.

Engine RPM indication is green light-emitting diodes and turbocharger RPM indication is red light-emitting diodes.

External Indications

There are output signals for engine RPM and turbocharger RPM.

Engine: 0 - 1200 RPM ~ 4-20 mA
TC: 0 - 60000 RPM ~ 4-20 mA

The pushbuttons for "Remote", "Local" and "Blocking" have potential free switches for external indication.

All components in the starting box are wired to the built-on terminal box.




Fig 1. Starting box

08028-0D/H5250/94.08.12

L23/30H

Engine RPM signal

For measuring the engine's RPM, a pick-up mounted on the engine is used giving a frequency depending on the RPM. To be able to show the engine's RPM on an analogue tachometer, the frequency signal is sent through an f/I converter (frequency/current converter), where the signal is transformed into a proportional 4-20 mA ~ 0-1200 RPM signal.

Further, the converter has following signals:

- overspeed
- engine run
- safe start
- tacho fail




Fig 1. Converter for engine RPM.

Overspeed

When the engine speed reach the setpoint for electronic overspeed the converter gives a shutdown signal and a alarm signal through a relay.

Engine run

When the engine speed reach 710 RPM or 200 RPM + 10 seconds the converter gives a "engine run" signal.

The engine run signal will be deactivated when the speed is 640 RPM. If the engine speed haven't been over 710 RPM the signal will be deactivated at 200 RPM.

The "engine run" signals will be given through a relay. One for synchronizing and one for start/stop of pre. lub. oil pump or alarm blocking at start/stop.

Safe start

When the safe start signal is activated the engine can start. When the engine reach 140 RPM the air starter will be shut-off.

Further, the safe start signal is a blocking function for the air starter during rotation.

Tacho fail

The tacho fail signal will be on when everything is normal. If the pick-up or the converter fails the signal will be deactivated. E.g. if there is power supply failure.

The converter for engine RPM signal is mounted in the terminal box on the engine.

Turbocharger RPM signal

For measuring the turbocharger RPM, a pick-up mounted on the engine is used giving a frequency depending on the RPM. To be able to show the turbocharger's RPM on an analogue tachometer, the frequency signal is sent through a f/I converter (frequency/current converter), where the signal is transferred into a proportional 4-20 mA ~ 0-60000 RPM.




Fig 2. Converter for TC RPM.

The converter is mounted in the terminal box on engine.

08028-0D/H5250/94.08.12

Working Card Page 1 (2)	Functional Test and Adjustment of Safety, Alarm and Monitoring Equipment	509-01.00 Edition 01H
----------------------------	---	---------------------------------

L23/30H

<p>Safety precautions</p> <ul style="list-style-type: none"> <input type="checkbox"/> Stopped engine <input type="checkbox"/> Shut-off starting air <input type="checkbox"/> Shut-off cooling water <input type="checkbox"/> Shut-off fuel oil <input type="checkbox"/> Shut-off cooling oil <input type="checkbox"/> Stopped lub. oil circul. <p>Description</p> <p>Function test and adjustment of safety, alarm and monitoring equipment.</p> <p>Starting position</p> <p>Related procedure</p> <table style="width: 100%; border: none;"> <tr><td>Overspeed trip</td><td style="text-align: right;">509-01.05</td></tr> <tr><td>Pressostate</td><td style="text-align: right;">509-05.00</td></tr> <tr><td>Thermostate</td><td style="text-align: right;">509-05.01</td></tr> <tr><td>Level switch (LAL 25)</td><td style="text-align: right;">509-05.02</td></tr> <tr><td>Analog pressure transmitter</td><td style="text-align: right;">509-05.03</td></tr> <tr><td>Analog temperature transmitter</td><td style="text-align: right;">509-05.04</td></tr> </table> <p>Man power</p> <table style="width: 100%; border: none;"> <tr><td>Working time</td><td>:</td><td>hours</td></tr> <tr><td>Capacity</td><td>:</td><td>man</td></tr> </table> <p>Data</p> <table style="width: 100%; border: none;"> <tr><td>Data for pressure and tolerance</td><td>(Page 500.35)</td></tr> <tr><td>Data for torque moment</td><td>(Page 500.40)</td></tr> <tr><td>Declaration of weight</td><td>(Page 500.45)</td></tr> </table>	Overspeed trip	509-01.05	Pressostate	509-05.00	Thermostate	509-05.01	Level switch (LAL 25)	509-05.02	Analog pressure transmitter	509-05.03	Analog temperature transmitter	509-05.04	Working time	:	hours	Capacity	:	man	Data for pressure and tolerance	(Page 500.35)	Data for torque moment	(Page 500.40)	Declaration of weight	(Page 500.45)	<p>Special tools</p> <table style="width: 100%; border: none;"> <tr><td>Plate No</td><td>Item No</td><td>Note.</td></tr> <tr><td colspan="3" style="text-align: center;">See Related Procedure</td></tr> </table> <p>Hand tools</p> <p style="text-align: center;">See Related Procedure</p> <p>Replacement and wearing parts</p> <table style="width: 100%; border: none;"> <tr><td>Plate No</td><td>Item No</td><td>Qty. /</td></tr> </table>	Plate No	Item No	Note.	See Related Procedure			Plate No	Item No	Qty. /
Overspeed trip	509-01.05																																	
Pressostate	509-05.00																																	
Thermostate	509-05.01																																	
Level switch (LAL 25)	509-05.02																																	
Analog pressure transmitter	509-05.03																																	
Analog temperature transmitter	509-05.04																																	
Working time	:	hours																																
Capacity	:	man																																
Data for pressure and tolerance	(Page 500.35)																																	
Data for torque moment	(Page 500.40)																																	
Declaration of weight	(Page 500.45)																																	
Plate No	Item No	Note.																																
See Related Procedure																																		
Plate No	Item No	Qty. /																																

08028-0D/H5250/94.08.12

L23/30H

Maintenance of monitoring and safety systems

One of the most important parameters in the preventive work is that the alarm system as well as the shutdown and overspeed devices are functioning 100%.

If some of these functions are out of operation, they have to be repaired immediately. If this is not possible because of the present working situation, the engine has to be under constant observation until it can be stopped.

It is recommended that all functions are tested every three months according to the mentioned working cards.

The extent of the alarm and safety functions is variable from plant to plant.

For check of these functions use the working cards mentioned under related procedure on page 1.

Alarm System

It is important that all alarms lead to prompt investigation and remedy of the error.

No alarm is insignificant. It is therefore important that all engine crew members are familiar with and well trained in the use and importance of the alarm system.

The most serious alarms are equipped with slowdown and/or shutdown functions.

Working Card Page 1 (2)	Functional Test and Adjustment of Overspeed Trip	509-01.05 Edition 01H
----------------------------	---	---------------------------------

L23/30H

<p>Safety precautions:</p> <ul style="list-style-type: none"> <input type="checkbox"/> Stopped engine <input type="checkbox"/> Shut-off starting air <input type="checkbox"/> Shut-off cooling water <input type="checkbox"/> Shut-off fuel oil <input type="checkbox"/> Shut-off cooling oil <input type="checkbox"/> Stopped lub. oil circul. <p>Description:</p> <p>Functional test and adjustment of overspeed trip.</p> <p>Starting position:</p> <p>Functional test and adjustment of safety alarm and monitoring equipment, 509-01.00</p> <p>Related procedure:</p> <p>Manpower:</p> <p>Working time : 1 hour Capacity : 1 man</p> <p>Data:</p> <p>Data for pressure and tolerance (Page 500.35) Data for torque moment (Page 500.40) Declaration of weight (Page 500.45)</p>	<p>Special tools:</p> <table border="1" style="width: 100%; border-collapse: collapse; margin-top: 10px;"> <thead> <tr> <th style="width: 25%;">Plate no</th> <th style="width: 25%;">Item no</th> <th style="width: 50%;">Note</th> </tr> </thead> <tbody> <tr> <td style="text-align: center;">52009</td> <td style="text-align: center;">016</td> <td></td> </tr> </tbody> </table> <p>Hand tools:</p> <p>Allen key, 4 mm. Allen key, 2 mm.</p> <p>Replacement and wearing parts:</p> <table border="1" style="width: 100%; border-collapse: collapse; margin-top: 10px;"> <thead> <tr> <th style="width: 25%;">Plate no</th> <th style="width: 25%;">Item no</th> <th style="width: 50%;">Qty/</th> </tr> </thead> <tbody> <tr> <td> </td> <td> </td> <td> </td> </tr> </tbody> </table>	Plate no	Item no	Note	52009	016		Plate no	Item no	Qty/			
Plate no	Item no	Note											
52009	016												
Plate no	Item no	Qty/											

08028-0D/HS250/94.08.12

L23/30H

1) The engine is run up manually, (on governor "synchronizer") and at no load, while watching the tachometer.

On reaching the revolution number indicated on page 500.30 or in "Test Report", the overspeed tripping device must function, thus actuating the stop cylinders. The fuel injection pump control rods are now moved to zero index, and the engine stops.

2) If the overspeed device trip at a revolution number different from that stated on page 500.30 or in the "Test Report" the overspeed device must be adjusted.




Fig 1.

Adjustment of Overspeed Trip.

3) Remove both covers on the housing of the overspeed tripping device, see fig 1.

Turn the engine until the adjusting screw is opposite the opening on the side of the housing. Now loosen the lock screw and turn the adjusting screw, using the tubular pin spanner supplied, see fig 2.




Fig 2.

Turn the adjusting screw outwards (slacken flyweight spring) to reduce the revolution number. Be careful not to screw the adjusting screw so far out that it may touch the release arm. Tighten the lock screw and test the overspeed device again.

4) Refit the covers when the overspeed device functions at correct revolution number.

5) The overspeed device can be tested manually by depressing the button on top of the housing, see fig 1. This will activate the flyweight and the arm for release of the air valve for the stop cylinders and the engine should thus stop. (This test must also be carried out without load).

6) It is recommended now and then, while the engine is at a standstill, to move the flyweight by means of the push button to ensure that the flyweight can always move with sufficient ease.

08028-0D/H/5250/94.08.12

Working Card Page 1 (2)	Adjustment and Test of On/Off Pressostate	509-05.00 Edition 01H
----------------------------	--	---------------------------------

L23/30H

<p>Safety precautions:</p> <ul style="list-style-type: none"> <input checked="" type="checkbox"/> Stopped engine <input checked="" type="checkbox"/> Shut-off starting air <input checked="" type="checkbox"/> Shut-off cooling water <input checked="" type="checkbox"/> Shut-off fuel oil <input checked="" type="checkbox"/> Shut-off cooling oil <input checked="" type="checkbox"/> Stopped lub. oil circul. <p>Description:</p> <p>Adjustment and test of on/off pressostate. (lub. oil, fuel oil, water etc.).</p> <p>Starting position:</p> <p>Functional test and adjustment of safety alarm and monitoring equipment, 509-01.00</p> <p>Related procedure:</p> <p>Manpower:</p> <p>Working time : 1/2 hour Capacity : 1 man</p> <p>Data:</p> <p>Data for pressure and tolerance (Page 500.35) Data for torque moment (Page 500.40) Declaration of weight (Page 500.45)</p>	<p>Special tools:</p> <table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left; border-bottom: 1px solid black;">Plate no</th> <th style="text-align: left; border-bottom: 1px solid black;">Item no</th> <th style="text-align: left; border-bottom: 1px solid black;">Note</th> </tr> </thead> <tbody> <tr> <td style="height: 100px;"> </td> <td> </td> <td> </td> </tr> </tbody> </table> <p>Hand tools:</p> <p>Screw driver. Testing pump. Ring and open end spanner, 10 mm.</p> <p>Replacement and wearing parts:</p> <table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left; border-bottom: 1px solid black;">Plate no</th> <th style="text-align: left; border-bottom: 1px solid black;">Item no</th> <th style="text-align: left; border-bottom: 1px solid black;">Qty/</th> </tr> </thead> <tbody> <tr> <td style="height: 100px;"> </td> <td> </td> <td> </td> </tr> </tbody> </table>	Plate no	Item no	Note				Plate no	Item no	Qty/			
Plate no	Item no	Note											
Plate no	Item no	Qty/											

08028-0D/H5250/94, 08.12

L23/30H

Adjustment:

1) When the pressostate cover is removed and locking screw pos. 5, *fig 1* is loosened, the range can be set with the spindle pos. 1 while at the same time the scale pos. 2 is read.




Fig 1.

2) In pressostates having an adjustable differential, the spindle pos. 3 must be used to make the adjustment. The differential obtained can be read directly on the scale pos. 4.

Set points, *see page 500.30*.

Test:

It is possible to make a functional test of the pressure switch. This is to be carried out according to the following procedure.

3) Shut off system pressure with the valve pos 3, *fig 2*.




Fig 2.

4) Remove the screw pos. 2.

5) Mount the testing pump on the trial flange pos. 1.

Alarm for Falling Pressure:

6) Pump up the pressure until the switch has changed. The pressure will slowly be relieved and it must be checked that the switch change back to the pressure stated as the alarm point.

Alarm for Rising Pressure:

7) Pump up the pressure until the switch changes, and check that it happens at the stated alarm point.

8) After the final check and adjustment, remove the testing pump, mount the screw pos 2 and open the valve pos 3.

Working Card Page 1 (2)	Adjustment and Test of On/Off Thermostate	509-05.01 Edition 01H
----------------------------	--	---------------------------------

L23/30H

<p>Safety precautions:</p> <ul style="list-style-type: none"> <input type="checkbox"/> Stopped engine <input type="checkbox"/> Shut-off starting air <input type="checkbox"/> Shut-off cooling water <input type="checkbox"/> Shut-off fuel oil <input type="checkbox"/> Shut-off cooling oil <input type="checkbox"/> Stopped lub. oil circul. <p>Description:</p> <p>Adjustment and test of on/off thermostate. (lub. oil, fuel oil, water etc.).</p> <p>Starting position:</p> <p>Functional test and adjustment of safety alarm and monitoring equipment, 509-01.00</p> <p>Related procedure:</p> <p>Manpower:</p> <p>Working time : 1/2 hour Capacity : 1 man</p> <p>Data:</p> <p>Data for pressure and tolerance (Page 500.35) Data for torque moment (Page 500.40) Declaration of weight (Page 500.45)</p>	<p>Special tools:</p> <table border="1" style="width: 100%; border-collapse: collapse; margin-top: 10px;"> <thead> <tr> <th style="width: 30%;">Plate no</th> <th style="width: 30%;">Item no</th> <th style="width: 40%;">Note</th> </tr> </thead> <tbody> <tr> <td> </td> <td> </td> <td> </td> </tr> </tbody> </table> <p>Hand tools:</p> <p>Screw driver. Special testing devices.</p> <p>Replacement and wearing parts:</p> <table border="1" style="width: 100%; border-collapse: collapse; margin-top: 10px;"> <thead> <tr> <th style="width: 30%;">Plate no</th> <th style="width: 30%;">Item no</th> <th style="width: 40%;">Qty/</th> </tr> </thead> <tbody> <tr> <td> </td> <td> </td> <td> </td> </tr> </tbody> </table>	Plate no	Item no	Note				Plate no	Item no	Qty/			
Plate no	Item no	Note											
Plate no	Item no	Qty/											

08028-0D/H5250/94.08.12

L23/30H

Adjustment:

1) When the thermostat cover is removed and locking screw pos. 5, *fig 1* is loosened, the range can be set with the spindle pos. 1 while at the same time the scale pos. 2 is read.




Fig 1.

2) Thermostates having an adjustable differential, the spindle pos. 3 can be used while the scale pos. 4 is read.

Set points, see page 500.30.

Test:

3) The functional test of the thermostat is to be carried out according to the following procedure.

4) Take out the sensor of the pocket.

5) Test the sensor in a water bath, where the temperature can be controlled.

Alarm for Falling Temperature:

6) Raise the temperature until the switch has changed.

Then the temperature must slowly be reduced, and check that the switch changes back at the temperature stated in the list *page 500.30*.

Alarm for Rising Temperature:

7) Raise the temperature until the switch changes and check that it happens at the stated alarm points.

8) Adjust if necessary.

9) The sensor is mounted again.

Working Card Page 1 (2)	Function and Test of Level Switch (LAL 25)	509-05.02 Edition 01H
----------------------------	---	---------------------------------

L23/30H

<p>Safety precautions:</p> <ul style="list-style-type: none"> <input checked="" type="checkbox"/> Stopped engine <input checked="" type="checkbox"/> Shut-off starting air <input type="checkbox"/> Shut-off cooling water <input type="checkbox"/> Shut-off fuel oil <input type="checkbox"/> Shut-off cooling oil <input type="checkbox"/> Stopped lub. oil circul. <p>Description:</p> <p>Function and test of level switch, LAL 25, in lubricating oil system.</p> <p>Starting position:</p> <p>Functional test and adjustment of safety alarm and monitoring equipment, 509-01.00</p> <p>Related procedure:</p> <p>Manpower:</p> <p>Working time : 1/2 hour Capacity : 1 man</p> <p>Data:</p> <p>Data for pressure and tolerance (Page 500.35) Data for torque moment (Page 500.40) Declaration of weight (Page 500.45)</p>	<p>Special tools:</p> <table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 30%;">Plate no:</th> <th style="width: 30%;">Item no:</th> <th style="width: 40%;">Note</th> </tr> </thead> <tbody> <tr> <td> </td> <td> </td> <td> </td> </tr> </tbody> </table> <p>Hand tools:</p> <p>Replacement and wearing parts:</p> <table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 25%;">Plate no</th> <th style="width: 25%;">Item no</th> <th style="width: 50%;">Qty/</th> </tr> </thead> <tbody> <tr> <td> </td> <td> </td> <td> </td> </tr> </tbody> </table>	Plate no:	Item no:	Note				Plate no	Item no	Qty/			
Plate no:	Item no:	Note											
Plate no	Item no	Qty/											

08028-0D/H5250/94.08.12

L23/30H

The level switch LAL 25, which is mounted on the main lubricating oil pipe of the engine, gives alarm for missing prelubricating oil.

Function.

- 1) By starting the prelubricating oil pump the main lubricating oil pipe will be filled with lubricating oil, which means that the level switch is lifted and the alarm is disconnected.
- 2) When the prelubricating is interrupted, the lub. oil will run out of the system through the bearings, which means that level switch is lowered and the alarm starts.

Test:

The test is carried out when the engine is stopped.

- 3) Start the lubricating oil pump, and let the pump run about 5 min.
- 4) Stop the prelubricating oil pump. The alarm must be released after 0 - 5 min., depending of the oil viscosity.




Fig 1.

Working Card Page 1 (2)	Adjustment and Test of Analogous Pressure Transmitter	509-05.03 Edition 01H
----------------------------	--	---------------------------------

L23/30H

<p>Safety precautions:</p> <ul style="list-style-type: none"> <input type="checkbox"/> Stopped engine <input type="checkbox"/> Shut-off starting air <input type="checkbox"/> Shut-off cooling water <input type="checkbox"/> Shut-off fuel oil <input type="checkbox"/> Shut-off cooling oil <input type="checkbox"/> Stopped lub. oil circul. <p>Description:</p> <p>Adjustment and test of analogous pressure transmitter.</p> <p>Starting position:</p> <p>Functional test and adjustment of safety alarm and monitoring equipment, 509-01.00</p> <p>Related procedure:</p> <p>Manpower:</p> <p>Working time : 1/2 hour Capacity : 1 man</p> <p>Data:</p> <p>Data for pressure and tolerance (Page 500.35) Data for torque moment (Page 500.40) Declaration of weight (Page 500.45)</p>	<p>Special tools:</p> <table border="1"> <thead> <tr> <th>Plate no</th> <th>Item no</th> <th>Note</th> </tr> </thead> <tbody> <tr> <td> </td> <td> </td> <td> </td> </tr> </tbody> </table> <p>Hand tools:</p> <p>Ring and open end spanner, 10 mm. Testing pump.</p> <p>Replacement and wearing parts:</p> <table border="1"> <thead> <tr> <th>Plate no</th> <th>Item no</th> <th>Qty/</th> </tr> </thead> <tbody> <tr> <td> </td> <td> </td> <td> </td> </tr> </tbody> </table>	Plate no	Item no	Note				Plate no	Item no	Qty/			
Plate no	Item no	Note											
Plate no	Item no	Qty/											

08028-0D/H5250/94.08.12

L23/30H

The pressure transmitter registers the actual pressure and marks the change to an electrical signal, which adjusts the pressure.

Adjustment:

1) The pressure transmitter shall not be adjusted, but the alarm limit must be set on the alarm plant. Kindly see the instruction book for the alarm plant.

Set points, see page 500.30.

Test:

2) It is possible to make a functional test of the pressure transmitter. This is carried out according to the following procedure:

3) Shut off system pressure with the valve pos. 3.

4) Remove the screw pos. 2.

5) Mount the testing apparatus on the trial flange pos. 1. and pump on a pressure within the working area of the transmitter.

If the alarm plant has an instrument unit, the pressure can be read on this. Other wise the test can be carried out by watching if the alarm plant gives any alarm, when the alarm limit which is stated on page 500.30 is exceeded (if the alarm plant is adjusted).

6) The screw pos. 2 is mounted, and the valve pos. 3. is opened after the test is finished.




Fig 1.

Working Card Page 1 (2)	Adjustment and Test of Analogous Temperature Transmitter	509-05.04 Edition 01H
----------------------------	---	---------------------------------

L23/30H

<p>Safety precautions:</p> <ul style="list-style-type: none"> <input type="checkbox"/> Stopped engine <input type="checkbox"/> Shut-off starting air <input type="checkbox"/> Shut-off cooling water <input type="checkbox"/> Shut-off fuel oil <input type="checkbox"/> Shut-off cooling oil <input type="checkbox"/> Stopped lub. oil circul. <p>Description:</p> <p>Adjustment and test of analogous temperature transmitter, (PT 100 sensor).</p> <p>Starting position:</p> <p>Functional test and adjustment of safety alarm and monitoring equipment, 509-01.00</p> <p>Related procedure:</p> <p>Mampower:</p> <p>Working time : 1/2 hour Capacity : 1 man</p> <p>Data:</p> <p>Data for pressure and tolerance (Page 500.35) Data for torque moment (Page 500.40) Declaration of weight (Page 500.45)</p>	<p>Special tools:</p> <table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left; border-bottom: 1px solid black;">Plate no</th> <th style="text-align: left; border-bottom: 1px solid black;">Item no</th> <th style="text-align: left; border-bottom: 1px solid black;">Note</th> </tr> </thead> <tbody> <tr> <td style="height: 100px;"> </td> <td> </td> <td> </td> </tr> </tbody> </table> <p>Hand tools:</p> <p>Special testing devices.</p> <p>Replacement and wearing parts:</p> <table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left; border-bottom: 1px solid black;">Plate no</th> <th style="text-align: left; border-bottom: 1px solid black;">Item no</th> <th style="text-align: left; border-bottom: 1px solid black;">Qty/</th> </tr> </thead> <tbody> <tr> <td style="height: 100px;"> </td> <td> </td> <td> </td> </tr> </tbody> </table>	Plate no	Item no	Note				Plate no	Item no	Qty/			
Plate no	Item no	Note											
Plate no	Item no	Qty/											

08028-0D/H5250/94.08.12

L23/30H

The PT 100 sensor consists of a resistance wire which changes resistance depending on the temperature.

Otherwise the test can be carried out by watching if the alarm plant gives any alarm, when the alarm limit which is stated on page 500.30 is exceeded (if the alarm plant is adjusted).

Look and design vary depending on the place of measurement and manufacture.

Adjustment:

1) The PT 100 sensor cannot be adjusted, but the alarm limit must be set on the alarm plant.

Set point, see page 500.30.

Test:

2) The functional trial of the PT 100 sensor can be carried out according to the following procedure.

3) Take out the sensor of the pocket.

4) Test the sensor by diving the sensor in the water. Compare the signal from the sensor with the water temperature.

If the alarm plant has an instrument unit, the temperature can be read on this.

5) The sensor is mounted again.




Fig 1.

Working Card Page 1 (2)	Lambda Controller	509-10.00 Edition 08H
----------------------------	--------------------------	---------------------------------

L23/30H

<p>Safety precautions</p> <ul style="list-style-type: none"> <input checked="" type="checkbox"/> Stopped engine <input type="checkbox"/> Shut off starting air <input type="checkbox"/> Shut off cooling water <input type="checkbox"/> Shut off fuel oil <input type="checkbox"/> Shut off cooling oil <input type="checkbox"/> Stopped lub. oil circul. <p>Description</p> <p>Adjustment of lambda controller.</p> <p>Starting position</p> <p>Related procedure</p> <p>Manpower</p> <p>Working time : 1 hour Capacity : 1 man</p> <p>Data</p> <p>Data for pressure and tolerance (Page 500.35) Data for torque moment (Page 500.40) Declaration of weight (Page 500.45)</p>	<p>Special tools</p> <table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left; width: 30%;">Plate no</th> <th style="text-align: left; width: 30%;">Item no</th> <th style="text-align: left; width: 40%;">Note</th> </tr> </thead> <tbody> <tr> <td> </td> <td> </td> <td> </td> </tr> </tbody> </table> <p>Hand tools</p> <p>Allen key.</p> <p>Replacement and wearing parts</p> <table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left; width: 30%;">Plate no</th> <th style="text-align: left; width: 30%;">Item no</th> <th style="text-align: left; width: 40%;">Qty /</th> </tr> </thead> <tbody> <tr> <td> </td> <td> </td> <td> </td> </tr> </tbody> </table>	Plate no	Item no	Note				Plate no	Item no	Qty /			
Plate no	Item no	Note											
Plate no	Item no	Qty /											

08028-00/H5250/94.08.12

L23/30H

Lambda Controller

Normally the lambda controller does not need adjustment. The only time adjustment is needed, is when the controller or the governor has been dismantled. The adjustment is to be carried out in standstill position.

1. Check that the free space between the pick-up and the band steel on the regulating arm is min 1 mm, see fig 1.




Fig 1.




Fig 2.




Fig 3.

2. Set the index of the fuel pumps at 17 by means of the governor arm, see plate 50902, item 039.

Note: Set the "load limit" control knob at max in order to protect the governor.

3. Fit the adjustment screw (4), fig 2, until the piston has contact with the spring without compressing the spring.

4. Fasten the adjustment screw.

5. Adjustment finished.

Adjustment of the stop screw

6. Remove pipe for charge air pressure, see fig 3.

7. Supply air pressure until the piston rod reaches its upper position.


8. Adjust the stop screw, see fig 2, to 110% load according to the test bed, plus 1.5 index. Use the index arm on the fuel pump nearest to the lambda controller as control for the index.

9. Adjustment finished.

08029-00/H/5250/94.08.12

Plate Page 1 (2)	Governor and Governor Drive	50901-22H
---------------------	-----------------------------	-----------

L23/30H



06028-0D/H5250/94.08.12

50901-22H

Governor and Governor Drive

Plate
Page 2 (2)

L23/30H

Item No.	Qty.	Designation	Benævnelse	Item No.	Qty.	Designation	Benævnelse
021	1/E	Synchronizing motor	Synkroniseringsmotor	320	1/E	Wear disc	Slidskive
				332	1/E	Key	Feder
033	1/E	Plug screw	Propskrue	439	1/E	Governor 900 rpm	Regulator 900 rpm
045	1/E	Gasket	Pakning				
057	4/E	Nut	Metrik				
069	2/E	Stud	Tap				
070	1/E	O-ring	O-ring				
082	1/E	Castle nut	Kronemotrik				
094	1/E	Split pin	Split				
104	1/E	Shut down solenoid	Shut-down spole				
116	1/E	Governor 720/750 rpm	Regulator 720/750 rpm				
128	4/E	Screw	Skrue				
141	1/E	Shim (set 0,1 - 0,3 - 0,5 - 1,0 mm)	Mellemlæg (sæt 0,1 - 0,3 - 0,5 - 1,0 mm)				
153	1/E	Disc	Skive				
165	1/E	Ball bearing	Kugleleje				
177	1/E	Bevel gear wheel	Konisk tandhjul				
189	1/E	Key	Feder				
190	1/E	Castle nut	Kronemotrik				
200	1/E	Split pin	Split				
212+	1/E	Housing	Hus				
224	2/E	Stud	Tap				
236	2/E	Pin	Stift				
248	1/E	Plug	Prop				
261	1/E	Plug	Prop				
273	1/E	Axle journal	Akseltap				
285	1/E	Bush	Bøsning				
297	1/E	Bevel gear wheel	Konisk tandhjul				
307	1/E	Gear wheel	Tandhjul				

+ Item No. 212 require an individual matching (by shims) before mounting, contact, MAN B&W, Holeby
+ Item nr. 212 kræver en individual tilpasning (med shims) for monteringen, kontakt MAN B&W, Holeby.

When ordering spare parts, see also page 500.50.


Ved bestilling af reservedele, se også side 500.50.

* = Only available as part of a spare parts kit.
Qty./E = Qty./Engine

* = Kun tilgængelig som en del af et reservedelssæt.
Antal/E = Antal/Motor

08028-0D/H5250/94.08.12

L23/30H



98028-0D/H5250/94.06.12

50901-21H

Governor and Governor Drive

Plate
Page 2 (2)

L23/30H

Item No.	Qty.	Designation	Benævnelse	Item No.	Qty.	Designation	Benævnelse
033	1/E	Plug screw	Propskrue	415	4/E	Screw	Skrue
045	1/E	Gasket	Pakning	427	1/E	Shutdown solenoid	Shutdown spole
057	4/E	Nut	Møtrik	439	1/E	Governor, Europa (900 rpm)	Regulator, Europa (900 rpm)
069	2/E	Stud	Tap				
070	1/E	O-ring	O-ring				
082	1/E	Castle nut	Kronemøtrik			+ Item No. 212 require an individual match- ing (by shims) before mounting, contact, MAN B&W, Holeby	+ Item nr. 212 kræver en individual tilpasning (med shims) for monte- ring, kontakt MAN B&W, Holeby.
094	1/E	Split pin	Split				
141	1/E	Shim (set 0,1 - 0,3 - 0,5 - 1,0 mm)	Mellemlæg (sæt 0,1 - 0,3 - 0,5 - 1,0 mm)				
153	1/E	Disc	Skive				
165	1/E	Ball bearing	Kugleleje				
177	1/E	Bevel gear wheel	Konisk tandhjul				
189	1/E	Key	Feder				
190	1/E	Castle nut	Kronemøtrik				
200	1/E	Split pin	Split				
212+	1/E	Housing	Hus				
224	2/E	Stud	Tap				
236	2/E	Pin	Stift				
248	1/E	Plug	Prop				
261	1/E	Plug	Prop				
273	1/E	Axle journal	Akseltap				
285	1/E	Bush	Bøsning				
297	1/E	Bevel gear wheel	Konisk tandhjul				
307	1/E	Gear wheel	Tandhjul				
320	1/E	Wear disc	Slidskive				
332	1/E	Key	Feder				
393	1/E	Synchronizing motor	Synkromiseringsmotor				
403	1/E	Governor, Europa (720/750 rpm)	Regulator, Europa (720/750 rpm)				

When ordering spare parts, see also page 500.50.


Ved bestilling af reservedele, se også side 500.50.

* = Only available as part of a spare parts kit.
Qty./E = Qty./Engine* = Kun tilgængelig som en del af et reservedelssæt.
Antal/E = Antal/Motor

0802B-OD/H5250/94.08.12

L23/30H

For actuator,
see special
instruction book



08028-0D/H5250/94.08.12

50901-23H

Governor and Governor Drive

Plate
Page 2 (2)

L23/30H

Item No.	Qty.	Designation	Benævnelse	Item No.	Qty.	Designation	Benævnelse
033	1/E	Plug screw	Propskruer	320	1/E	Wear disc	Slidskive
045	1/E	Gasket	Pakning	332	1/E	Key	Feder
057	4/E	Nut	Møtrik				
069	2/E	Stud	Tap				
070	1/E	O-ring	O-ring				
082	1/E	Castle nut	Kronemøtrik				
094	1/E	Split pin	Split				
116	1/E	Actuator	Aktuator				
128	4/E	Screw	Skrue				
141	1/E	Shim (set 0,1 - 0,3 - 0,5 - 1,0 mm)	Mellemlæg (sæt 0,1 - 0,3 - 0,5 - 1,0 mm)				
153	1/E	Disc	Skive				
165	1/E	Ball bearing	Kugleleje				
177	1/E	Bevel gear wheel	Konisk tandhjul				
189	1/E	Key	Feder				
190	1/E	Castle nut	Kronemøtrik				
200	1/E	Split pin	Split				
212+	1/E	Housing	Hus				
224	2/E	Stud	Tap				
236	2/E	Pin	Stift				
248	1/E	Plug	Prop				
261	1/E	Plug	Prop				
273	1/E	Axle journal	Akseltap				
285	1/E	Bush	Bøsning				
297	1/E	Bevel gear wheel	Konisk tandhjul				
307	1/E	Gear wheel	Tandhjul				

+ Item No. 212 require an individual matching (by shims) before mounting, contact, MAN Diesel A/S.

+ Item nr. 212 kræver en individual tilpasning (med shims) for montering, kontakt MAN Diesel A/S.

When ordering spare parts, see also page 600.50.

Ved bestilling af reservedele, se også side 600.50.


* = Only available as part of a spare parts kit.
Qty./E = Qty./Engine

* = Kun tilgængelig som en del af et reservedelssæt.
Antal/E = Antal/Motor

08028-0D/H5250/94.06.12

Plate Page 1 (2)	Regulating Device	50902-06H
---------------------	-------------------	-----------

L23/30H



08028-0D/H5250/94 08.12



50902-06H

Regulating Device

Plate
Page 2 (2)

L23/30H

Item No.	Qty.	Designation	Benævnelse	Item No.	Qty.	Designation	Benævnelse
015	1/R	Screw	Skrue	338	1/E	Stop ring	Stopring
027	2/R	Locking plate	Låseblik	351	1/E	Screw	Skrue
039	1/R	Governor arm	Regulatorarm	363	1/C	Linkage	Lænkeled
040	2/R	Split pin	Split	375	1/C	Split pin	Split
052	2/R	Self locking nut	Selvlåsende møtrik	387	1/C	Pin	Stift
064	2/R	Screw for ball head	Skrue for kuglehoved	399	1/C	Pin	Stift
076	1/R	Spring loaded pull rod, complete	Fjederbelastet trækstang, komplet	409	1/C	Spring arm	Fjederarm
088	2/R	Pull rod head	Trækstangshoved	410	1/C	Spring	Fjeder
111	1/R	Split pin	Split	422	3/C	Spring pin	Fjederstift
123	1/R	Pull rod end	Trækstangsende	434	1/C	Armholder	Armholder
135	1/R	Cylindrical pin	Cylindrisk stift	446	1/C	Screw	Skrue
147	1/R	Spring housing	Fjederhus	458	1/C	Bushing	Bøsning
159	1/R	Pointed screw	Pinolskrue	471	1/C	Bearing bracket	Lejeblik
160	1/R	Spring	Fjeder	483	2/C	Spring pin	Fjederstift
172	1/R	Cylindrical pin	Cylindrisk stift	495	2/C	Screw	Skrue
184	1/R	Guide ring	Styrering	530	2/E	Screw	Skrue
196	1/R	Guide ring	Styrering	542	2/E	Screw	Skrue
206	1/R	Pull rod	Trækstang	554	2/E	Washer	Skive
218	1/R	Nut	Møtrik	566	2/E	Nut	Møtrik
231	1/R	Locking plate	Låseblik	578	1/E	Bracket	Konsol
243	1/R	Arm	Arm				
255	1/R	Spring pin	Fjederstift				
267	1/R	Screw	Skrue				
279	1/R	Guide pin	Styrestift				
280	1/R	Screw	Skrue				
292	1/R	Bearing	Leje				
302	1/R	Bushing	Bøsning				
314	1/E	Regulating shaft	Reguleringsaksel				
326	1/E	Washer	Skive				

When ordering spare parts, see also page 500.50.


Ved bestilling af reservedele, se også side 500.50.

* = Only available as part of a spare part kit.
 Qty./E = Qty./Engine
 Qty./C = Qty./Cylinder
 Qty./R = Qty./Regulating device

* = Kun tilgængelig som en del af et reservedelssæt.
 Antal/E = Antal/Motor
 Antal/C = Antal/Cylinder
 Antal/R = Antal/Reguleringsmekanisme

Plate Page 1 (2)	Regulating Device	50902-07H
---------------------	-------------------	-----------

L23/30H



08028-0D/H5250/94.08.12

50902-07H

Regulating Device

Plate
Page 2 (2)

L23/30H

Item No.	Qty.	Designation	Benævnelse	Item No.	Qty.	Designation	Benævnelse
015	1/R	Screw	Skrue	338	1/E	Stop ring	Stopring
027	2/R	Locking plate	Låseblik	351	1/E	Screw	Skrue
039	1/R	Governor arm	Regulatorarm	363	1/C	Linkage	Lænkeled
040	2/R	Split pin	Split	375	1/C	Split pin	Split
052	2/R	Self locking nut	Selvlåsende møtrik	387	1/C	Pin	Stift
064	2/R	Screw for ball head	Skrue for kuglehoved	399	1/C	Pin	Stift
076	1/R	Spring loaded pull rod, complete	Fjederbelastet trækstang, komplet	409	1/C	Spring arm	Fjederarm
088	2/R	Pull rod head	Trækstangshoved	410	1/C	Spring	Fjeder
111	1/R	Split pin	Split	422	3/C	Spring pin	Fjederstift
123	1/R	Pull rod end	Trækstangsende	434	1/C	Armholder	Armholder
135	1/R	Cylindrical pin	Cylindrisk stift	446	1/C	Screw	Skrue
147	1/R	Spring housing	Fjederhus	458	1/C	Bushing	Bøsning
159	1/R	Pointed screw	Pinolskrue	471	1/C	Bearing bracket	Lejeblik
160	1/R	Spring	Fjeder	483	2/C	Spring pin	Fjederstift
172	1/R	Cylindrical pin	Cylindrisk stift	495	2/C	Screw	Skrue
184	1/R	Guide ring	Styrering	530	2/E	Screw	Skrue
196	1/R	Guide ring	Styrering	542	2/E	Screw	Skrue
206	1/R	Pull rod	Trækstang	554	2/E	Washer	Skive
218	1/R	Nut	Møtrik	566	2/E	Nut	Møtrik
231	1/R	Locking plate	Låseblik	578	1/E	Bracket	Konsol
243	1/R	Arm	Arm				
255	1/R	Spring pin	Fjederstift				
267	1/R	Screw	Skrue				
279	1/R	Guide pin	Styrestift				
280	1/R	Screw	Skrue				
292	1/R	Bearing	Leje				
302	1/R	Bushing	Bøsning				
314	1/E	Regulating shaft	Reguleringsaksel				
326	1/E	Washer	Skive				

When ordering spare parts, see also page 500.50.

Ved bestilling af reservedele, se også side 500.50.


* = Only available as part of a spare part kit.
Qty./E = Qty./Engine
Qty./C = Qty./Cylinder
Qty./R = Qty./Regulating device

* = Kun tilgængelig som en del af et reservedelssæt.
Antal/E = Antal/Motor
Antal/C = Antal/Cylinder
Antal/R = Antal/Reguleringsmekanisme

08028-0D/H5250/94.06.12

Plate Page 1 (2)	Overspeed Device	50903-02H
---------------------	------------------	-----------

L23/30H



08028-0D/H5250/94.08.12

50903-02H

Overspeed Device

Plate
Page 2 (2)

L23/30H

Item No.	Qty.	Designation	Benævnelse	Item No.	Qty.	Designation	Benævnelse
010	1/E	Socket	Muffe	345	1/E	Spring	Fjeder
022	1/E	Button	Knap	357	1/E	Button	Knap
034	1/E	Spring pin	Fjederstift	369	1/E	Nipple	Nippel
046	1/E	Spring	Fjeder	370	1/E	Spindle	Spindel
058	4/E	Screw	Skrue	382	1/E	Spring (left)	Fjeder (venstre)
071	1/E	Screw	Skrue	394	1/E	Spindle	Spindel
083	1/E	Cover	Dæksel	404	2/E	Washer	Skive
095	1/E	Spindle	Spindel	416	2/E	Screw	Skrue
105	1/E	Spring pin	Fjederstift	428	1/E	Ball bearing	Kugleleje
117	1/E	Cylindrical pin	Cylindrisk stift	441	1/E	Elastic coupling	Elastisk kobling
129	1/E	Lever	Arm	453	1/E	Spring (right)	Fjeder (højre)
130	1/E	Screw	Skrue	465	1/E	Valve attachment	Ventilholder
142	1/E	Flyweight housing	Hus for svingvægt	477	4/E	Screw	Skrue
154	1/E	Adjusting screw	Justeringskrue	489	1/E	Pneumatic valve	Pneumatisk ventil
166	1/E	Spring 720/750 rpm	Fjeder 720/750 rpm	490	1/E	Silencer	Lyddæmper
178	1/E	Circlip	Sikringsring	500	1/E	Overspeed device, complete	Overspeed anordning, komplet
191	1/E	Flyweight	Svingvægt	512	1/E	Spare parts kit for item 489	Reservedelskit for item 489
201	1/E	Key	Not	524	1/E	Spring 900 rpm	Fjeder 900 rpm
213	1/E	Ball bearing	Kugleleje				
225	1/E	Housing	Hus				
237	1/E	Cover	Dæksel				
249	4/E	Washer	Skive				
250	4/E	Screw	Skrue				
262	1/E	Pin	Stift				
274	1/E	Lever	Arm				
286	1/E	Nut	Motrik				
298	1/E	Gasket	Pakning				
333	1/E	Spindle	Spindel				

When ordering spare parts, see also page 500.50.

Ved bestilling af reservedele, se også side 500.50.


* = Only available as part of a spare parts kit.
Qty./E = Qty./Engine

* = Kun tilgængelig som en del af et reservedelssæt.
Antal/E = Antal/Motor

08028-0D/H5550/94.08.12

Plate Page 1 (2)	Fuel Oil Leakage Alarm (LAH 42)	50905-02H
---------------------	---------------------------------	-----------

L23/30H



08028-0D/H5250/04.08.12

50905-02H	Fuel Oil Leakage Alarm (LAH 42)	Plate Page 2 (2)
-----------	---------------------------------	---------------------

L23/30H

Item No.	Qty.	Designation	Benævnelse	Item No.	Qty.	Designation	Benævnelse
011	1/E	Cable union	Kabelunion				
023	1/E	Plug screw	Propskrue				
035	1/E	Packing ring	Tætningsring				
047	1/E	Level switch	Niveauekontakt				
059	1/E	Plug screw	Propskrue				
060	1/E	Packing ring	Tætningsring				
072	1/E	Fuel leakage alarm, complete	Brændolie lækage- alarm, komplet				

When ordering spare parts, see also page 500.50.

Ved bestilling af reservedele, se også side 500.50


* = Only available as part of a spare parts kit.
Qty./E = Qty./Engine.

* = Kun tilgængelig som en del af et reservedelssæt.
Qty./E = Antal/Motor

08028-0D/H4250/94.08.12

Plate Page 1 (2)	Prelubricating Oil Alarm (LAL 25)	50905-03H
---------------------	-----------------------------------	-----------

L23/30H



08028-0D/H5250/94.08.12

50905-03H

Prelubricating Oil Alarm (LAL 25)

Plate
Page 2 (2)

L23/30H

	Qty.	Designation	Benævnelse		Qty.	Designation	Benævnelse
	096	1/E Plug screw	Propskrue				
	106	1/E Packing ring	Pakningsring				
	118	1/E Loctite 577	Loctite 577				
	131	1/E Level switch	Niveaufbryder				

When ordering spare parts, see also page 500.50.

Ved bestilling af reservedele, se også side 500.50


* = Only available as part of a spare parts kit.
Qty./E = Qty./Engine.

* = Kun tilgængelig som en del af et reservedelssæt.
Qty./E = Antal/Motor

08028-0D/H5250/94.08.12

Plate Page 1 (2)	Level Switch in Oil Sump (LAL 28)	50905-05H
---------------------	-----------------------------------	-----------

L23/30H



06028-0D/H5250/94.08.12

50905-05H	Level Switch in Oil Sump (LAL 28)	Plate Page 2 (2)
-----------	-----------------------------------	---------------------

L23/30H

	Qty.	Designation	Benævnelse		Qty.	Designation	Benævnelse
	429	1/E Gasket	Pakning				
	430	2/E Nut	Møtrik				
	442	1/E Pipe for level alarm	Rør for niveau-alarm				
	454	1/E Level switch with cabel	Niveualarm med kabel				
	466	1/E Plug screw	Propskrue				
	478	1/E Gasket	Pakning				
	491	1/E Red. adaptor	Red. adapter				
	501	4/E Nut	Møtrik				
	513	1/E Flange	Flange				
	525	1/E Gasket	Pakning				
	537	1/E Box for level alarm	Boks for niveualarm				
	549	1/E Level switch, complete	Niveualarm, komplet				

When ordering spare parts, see also page 500.50.

Ved bestilling af reservedele, se også side 500.50


* = Only available as part of a spare parts kit.
Qty./E = Qty./Engine.

* = Kun tilgængelig som en del af et reservedelssæt.
Qty./E = Antal/Motor

08028-0D/H/5250/94.08.12

Plate Page 1 (2)	Instrument Panel	50905-07H
---------------------	------------------	-----------

L23/30H



PI 01	LT fresh water, inlet to air cooler
PI 10	HT fresh water, inlet engine
PI 21/22	Lubricating oil, inlet/outlet to filter
PI 23	Lub. oil, inlet to turbocharger
PI 31	Charge air, outlet from cooler
PI 40	Fuel oil, inlet to engine

08028-0D/HS250/94.08.12

50905-07H	Instrument Panel	Plate Page 2 (2)
-----------	-------------------------	---------------------

L23/30H

Item No	Qty.	Designation	Benævnelse	Item No	Qty.	Designation	Benævnelse
143	1/E	Housing for instrument panel	Hus for instrumentpanel	704	4/E	Screw	Skrue
155	1/E	Bracket for instrument panel	Konsol for instrumentpanel	716	4/E	Serrated lock washer	Stjernefjederskive
167	4/E	Rubber clutch	Gummikobling	728	2/E	Screw	Skrue
179	8/E	Nut	Møtrik	741	2/E	Serrated lock washer	Stjernefjederskive
180	8/E	Spring lock	Fjederskive	753	8/E	Screw	Skrue
192	2/E	Pressure gauge 0-3 bar (PI 31 and PI 23)	Manometer 0-3 bar (PI 31 og PI 23)	765	1/E	Side plate	Sideplade
202	3/E	Pressure gauge 0-6 bar (PI 01, PI 10, PI 21-22)	Manometer 0-3 bar (PI 01, PI 10, PI 21-22)	417	1/E	Instrument panel, complete	Instrument panel, komplet
214	1/E	Pressure gauge 0-10 bar (PI 40)	Manometer 0-10 bar (PI 40)				
226	6/E	Needle valve	Nåleventil				
238	1/E	3-way valve for PI 21-22	3-vejsventil for PI 21-22				
251	1/E	Washer	Skive				
263	1/E	Pipe	Rør				
275	1/E	Angle union	Vinkelforskruning				
287	2/E	Straight union	Ligeforskruning				
299	2/E	Pressure gauge hose 140 mm	Manometer slange 195 mm				
309	2/E	Pressure gauge hose 195 mm	Manometer slange 140 mm				
310	2/E	Pressure gauge hose 340 mm	Manometer slange 300 mm				
322	6/E	Packing ring	Pakningsring				
334	2/E	Reduction	Reduktion				
346	1/E	Damper (fuel oil)	Dæmper (fuel oil)				
358	2/E	Coupling for manometer	Kobling for manometer				
371	1/E	Damper (charging air)	Dæmper (ladeluft)				

When ordering spare parts, see also page 500.50.

Ved bestilling af reservedele, se også side 600.50.


* = Only available as part of a spare parts kit.
Qty./E = Qty./Engine

* = Kun tilgængelig som en del af et reservedelssæt.
Antal/E = Antal/Motor

08028-0D/H5250/94.08.12

Plate Page 1 (2)	Level Switch in Oil Sump (LAL/LAH 28)	50905-09H
---------------------	---------------------------------------	-----------

L23/30H



08028-0D/H5250/94.08.12

50905-09H	Level Switch in Oil Sump (LAL/LAH 28)	Plate Page 2 (2)
-----------	---------------------------------------	---------------------

L23/30H

Qty.	Designation	Benævnelse	Qty.	Designation	Benævnelse
430	2/E Nut	Møtrik			
442	1/E Pipe for level switch	Rør for niveau- alarm			
454	1/E Level switch with cabel	Niveualarm med kabel			
466	1/E Plug screw	Propskrue			
478	1/E Packing	Pakningsring			
491	1/E Red. adaptor	Red. adapter			
501	4/E Screw	Skruer			
513	1/E Flange	Flange			
525	1/E Gasket	Pakning			
537	1/E Box for level switch	Boks for niveualarm			
549	1/E Level switch, complete	Niveualarm, komplet			
579	1/E Pipe	Rør			
580	1/E Level switch incl. cable	Niveaufbryder incl. kabel			
777	1/E Dipstick, complete	Pejlestok, komplet			
789	// Loctite 577	Loctite 577			

When ordering spare parts, see also page 500.50.

Ved bestilling af reservedele, se også side 500.50


* = Only available as part of a spare parts kit.
Qty./E = Qty./Engine
Qty./I = Qty./Individual

* = Kun tilgængelig som en del af et reservedelssæt.
Qty./E = Antal/Motor
Qty./I = Antal/Individuel

08028-0D/H5250/94.08.12

Plate Page 1 (2)	Level Switch in Oil Sump (LAL/LAH 28)	50905-10H
---------------------	---------------------------------------	-----------

L23/30H



08028-0D/H5250/94_08.12

50905-10H	Level Switch in Oil Sump (LAL/LAH 28)	Plate Page 2 (2)
-----------	---------------------------------------	---------------------

L23/30H

Item No.	Qty.	Designation	Benævnelse	Item No.	Qty.	Designation	Benævnelse
550	2/E	Box for level alarm	Box for niveaualarm				
562	2/E	Flange	Flange				
574	8/E	Nut	Møtrik				
586	4/E	Nut	Møtrik				
598	2/E	Gasket	Pakning				
608	1/E	Pipe	Rør				
621	1/E	Pipe	Rør				
633	1/E	Level switch incl. cable "NC"	Niveaufbryder inkl. kabel "NC"				
645	2/E	Plug screw	Propskrue				
657	2/E	Gasket	Pakning				
669	1/E	Gasket	Pakning				
670	8/E	Screw	Skrue				
682	1/E	Level alarm, complete	Niveaualarm, komplet				
694	2/E	Red. adapter	Red. adapter				
812	1/E	Level switch incl. cable "NO"	Niveaufbryder inkl. kabel "NO"				

When ordering spare parts, see also page 500.50.

Ved bestilling af reservedele, se også side 500.50.


* = Only available as part of a spare parts kit.
Qty./E = Qty./Engine

* = Kun tilgængelig som en del af et reservedelssæt.
Antal/E = Antal/Motor

08028-0D/H5250/94.08.12

Plate Page 1 (2)	Instrument Panel	50905-11H
---------------------	-------------------------	------------------

L23/30H



08028-0D/H5250/94 08.12

50905-11H	Instrument Panel	Plate Page 2 (2)
-----------	------------------	---------------------

L23/30H

Qty.	Designation	Benævnelse	Qty.	Designation	Benævnelse
143	1/E Housing for instrument panel	Hus for instrument panel	395	4/E Lock washer	Låseskive
155	1/E Bracket for instrument panel, L23/30H	Konsol for instrument panel, L23/30H	417	1/E Instrument panel, complete, L23/30H	Instrument panel, komplet, L23/30H
167	4/E Rubber clutch	Gummikobling			
179	8/E Nut	Møtrik			
180	8/E Spring locks	Fjedrende skive			
192	2/E Pressure gauge 0-3 bar (PI 31 and PI 23)	Manometer 0-3 bar (PI 31 og PI 23)			
202	3/E Pressure gauge 0-6 bar, PI 01, PI 10, PI 21-22	Manometer 0-3 bar, PI 01, PI 10, PI 21-22			
214	1/E Pressure gauge 0-10 bar (PI 40)	Manometer 0-10 bar (PI 40)			
226	6/E Needle valve	Nåleventil			
238	1/E 3-way valve for PI 21-22	3-vejsventil for PI 21-22			
251	1/E Washer	Skive			
263	1/E Steel pipe	Stålrør			
275	1/E Screwed connection	Forskruning			
287	2/E Union	Forskruning			
299	2/E Pressure gauge hose 140 mm	Manometer slange 140 mm			
309	2/E Pressure gauge hose 195 mm	Manometer slange 195 mm			
310	2/E Pressure gauge hose 340 mm	Manometer slange 340 mm			
322	6/E Gasket	Pakning			
334	2/E Reduction adapter	Reduktionsforskruning			
346	1/E Damper (fuel oil)	Dæmper (fuel oil)			
358	2/E Coupling for manometer	Kobling for manometer			
371	1/E Damper (charging air)	Dæmper (ladeluft)			
383	4/E Screw	Skrue			

When ordering spare parts, see also page 500.50.

Ved bestilling af reservedele, se også side 500.50


* = Only available as part of a spare parts kit.
Qty./E = Qty./Engine.

* = Kun tilgængelig som en del af et reservedelssæt.
Qty./E = Antal/Motor


08028-0D/H5250/94.08.12

Plate Page 1 (2)	Pressostate, Thermostate Difference Pressostate and Pressure Transmitter	50907-01H
---------------------	---	------------------

L23/30H



Fig. and Description	Range	Code	L	Item No.	
Pressostate	0-8 bar	PSL 22 PAL 10 PAL 22		012	
	6-18 bar	PAL 70 PAL 24		024	
	10-35 bar			036	
	1-10 bar	PAL 40		048	
 <p style="text-align: center;">Thermostate</p>	20-60°C	TAL 10	2 m 5 m	061 073	
	50-100°C		2 m 5 m 8 m	085 097 107	
	70-120°C	TAH 12 TSH 12 TAH 20 TSH 22	2 m 5 m 8 m	119 120 132	
	Difference Pressostate	0.2-2.5 bar	PDAH 21-22		144

08028-0D/H5250/94.08.12



50907-01H	Pressostate, Thermostate Difference Pressostate and Pressure Transmitter	Plate Page 2 (2)
-----------	---	---------------------



L23/30H

Fig. and Description	Range	Code	L	Item No.
 <p>Pressure Transmitter</p>	0-2.5 bar	PT 31		156
	0-4 bar	PT 10		168
	0-6 bar	PT 22		181
	0-10 bar	PT 40		193
	0-16 bar	PT 70		203
	0-40 bar			215
	0-400 bar			227
 <p>Needle Valve</p>		Needle Valve with 3/8" pipe thread		239
		Needle valve with 1/2" pipe thread		240

08028-0D/H6250/94.08.12

Plate Page 1 (2)	Thermometer	50907-02H
---------------------	-------------	-----------

L23/30H

Fig.	Scale		Length		Code	Item No.
	°F	°C	L	L1		
	40-240	0-120	110	100	TI 01 TI 02 TI 31	252
	40-240	0-120	110	63	TI 22 TI 20	264
	40-600	0-300	150	100	TI 30	276
	40-400	0-200	110	40	TI 40 TI 51	288
	40-220	0-120	110	100	TI 03 TI 10 TI 11	311

06028-0D/H6250/94.08.12



50907-02H	Thermometer	Plate Page 2 (2)
-----------	-------------	---------------------


L23/30H

Fig.	Scale		Length		Code	Item No.
	°F	°C	L	L1		
<p>335</p>	100-1300	50-650	100	115	TI 60	323
<p>359</p>	100-1300	50-650	65	215	TI 61	347
<p>Pocket</p>				115		335
<p>Pocket</p>				215		359

08028-0D/H5250/94.08.12


Plate Page 1 (1)	Pick-up	50908-01H
---------------------	---------	-----------

L23/30H


Fig. and Description		Range	Item No.
 <p>Cabel length: 3 M.</p>		Working temp. -25°C - 70°C	018

08028-0D/H5250/04 08.12

L23/30H



08028-0D/HS250/94 08.12



50910-02H

Lambda Controller

Plate
Page 2 (2)

L23/30H

Item No.	Qty.	Designation	Benævnelse	Item No.	Qty.	Designation	Benævnelse
019	1/E	Regulating arm, complete	Reguleringsarm, komplet				
020	1/E	Pick-up, incl. sleeve	Pick-up, incl. afstandsring				
032	1/E	Lambda cylinder, complete	Lambdacylinder, komplet				

When ordering spare parts, see also page 500.50.


Ved bestilling af reservedele, se også side 500.50.

* = Only available as part of a spare parts kit.
Qty./E = Qty./Engine

* = Kun tilgængelig som en del af et reservedelssæt.
Antal/E = Antal/Motor

08028-0D/H5250/94.08.12


L23/30H



017

029

030



50935-01H

Starting Box

Plate
Page 2 (2)

L23/30H

Item No.	Qty.	Designation	Benævnelse	Item No.	Qty.	Designation	Benævnelse
017	1/E	Starting box	Startboks				
029	1/E	Terminal box	Terminalboks				
030	1/E	Starting box, complete	Startboks, komplet				

When ordering spare parts, see also page 500.50.

Ved bestilling af reservedele, se også side 500.50.

* = Only available as part of a spare parts kit.
Qty./E = Qty./Engine.* = Kun tilgængelig som en del af et reservedelssæt.
Qty./E = Qty./Motor

UG-8 Speed Adjusting Devices

**Pneumatic and Manifold Speed Setting
for UG Type Governors**

Operation Manual



General Precautions

Read this entire manual and all other publications pertaining to the work to be performed before installing, operating, or servicing this equipment.

Practice all plant and safety instructions and precautions.

Failure to follow instructions can cause personal injury and/or property damage.



Revisions

This publication may have been revised or updated since this copy was produced. To verify that you have the latest revision, check manual **26311**, *Revision Status & Distribution Restrictions of Woodward Technical Publications*, on the *publications page* of the Woodward website:

www.woodward.com/publications

The latest version of most publications is available on the *publications page*. If your publication is not there, please contact your customer service representative to get the latest copy.




Proper Use

Any unauthorized modifications to or use of this equipment outside its specified mechanical, electrical, or other operating limits may cause personal injury and/or property damage, including damage to the equipment. Any such unauthorized modifications: (i) constitute "misuse" and/or "negligence" within the meaning of the product warranty thereby excluding warranty coverage for any resulting damage, and (ii) invalidate product certifications or listings.



Translated Publications

If the cover of this publication states "Translation of the Original Instructions" please note:

The original source of this publication may have been updated since this translation was made. Be sure to check manual **26311**, *Revision Status & Distribution Restrictions of Woodward Technical Publications*, to verify whether this translation is up to date. Out-of-date translations are marked with . Always compare with the original for technical specifications and for proper and safe installation and operation procedures.

Revisions—Changes in this publication since the last revision are indicated by a black line alongside the text.

Woodward reserves the right to update any portion of this publication at any time. Information provided by Woodward is believed to be correct and reliable. However, no responsibility is assumed by Woodward unless otherwise expressly undertaken.

Copyright © Woodward 1983
All Rights Reserved

Warnings and Notices

Important Definitions



This is the safety alert symbol. It is used to alert you to potential personal injury hazards. Obey all safety messages that follow this symbol to avoid possible injury or death.

- **DANGER**—Indicates a hazardous situation which, if not avoided, will result in death or serious injury.
- **WARNING**—Indicates a hazardous situation which, if not avoided, could result in death or serious injury.
- **CAUTION**—Indicates a hazardous situation which, if not avoided, could result in minor or moderate injury.
- **NOTICE**—Indicates a hazard that could result in property damage only (including damage to the control).
- **IMPORTANT**—Designates an operating tip or maintenance suggestion.

WARNING

**Overspeed /
Overtemperature /
Overpressure**

The engine, turbine, or other type of prime mover should be equipped with an overspeed shutdown device to protect against runaway or damage to the prime mover with possible personal injury, loss of life, or property damage.

The overspeed shutdown device must be totally independent of the prime mover control system. An overtemperature or overpressure shutdown device may also be needed for safety, as appropriate.

WARNING

**Personal Protective
Equipment**

The products described in this publication may present risks that could lead to personal injury, loss of life, or property damage. Always wear the appropriate personal protective equipment (PPE) for the job at hand. Equipment that should be considered includes but is not limited to:

- Eye Protection
- Hearing Protection
- Hard Hat
- Gloves
- Safety Boots
- Respirator

Always read the proper Material Safety Data Sheet (MSDS) for any working fluid(s) and comply with recommended safety equipment.

WARNING

Start-up

Be prepared to make an emergency shutdown when starting the engine, turbine, or other type of prime mover, to protect against runaway or overspeed with possible personal injury, loss of life, or property damage.

WARNING

**Automotive
Applications**

On- and off-highway Mobile Applications: Unless Woodward's control functions as the supervisory control, customer should install a system totally independent of the prime mover control system that monitors for supervisory control of engine (and takes appropriate action if supervisory control is lost) to protect against loss of engine control with possible personal injury, loss of life, or property damage.

NOTICE**Battery Charging
Device**

To prevent damage to a control system that uses an alternator or battery-charging device, make sure the charging device is turned off before disconnecting the battery from the system.

Electrostatic Discharge Awareness

NOTICE**Electrostatic
Precautions**

Electronic controls contain static-sensitive parts. Observe the following precautions to prevent damage to these parts:

- Discharge body static before handling the control (with power to the control turned off, contact a grounded surface and maintain contact while handling the control).
- Avoid all plastic, vinyl, and Styrofoam (except antistatic versions) around printed circuit boards.
- Do not touch the components or conductors on a printed circuit board with your hands or with conductive devices.

To prevent damage to electronic components caused by improper handling, read and observe the precautions in Woodward manual **82715**, *Guide for Handling and Protection of Electronic Controls, Printed Circuit Boards, and Modules*.

Follow these precautions when working with or near the control.

1. Avoid the build-up of static electricity on your body by not wearing clothing made of synthetic materials. Wear cotton or cotton-blend materials as much as possible because these do not store static electric charges as much as synthetics.
2. Do not remove the printed circuit board (PCB) from the control cabinet unless absolutely necessary. If you must remove the PCB from the control cabinet, follow these precautions:
 - Do not touch any part of the PCB except the edges.
 - Do not touch the electrical conductors, the connectors, or the components with conductive devices or with your hands.
 - When replacing a PCB, keep the new PCB in the plastic antistatic protective bag it comes in until you are ready to install it. Immediately after removing the old PCB from the control cabinet, place it in the antistatic protective bag.

Pneumatic and Manifold Speed Setting for UG Type Governors

Introduction

This manual provides general information, installation, adjustment and replacement parts for the Pneumatic Speed Adjustment and the Manual Speed Setting Screw options.

Description

The Pneumatic Speed Adjustment device makes it possible to adjust speed pneumatically from a location remote from the prime mover. It is mounted on top of the UG-8 Lever governor in a separate housing. The housing also accepts Woodward's standard shutdown devices such as solenoid, pneumatic, or low lube units.

The Manual Speed Setting Screw allows for on-site setting of the governor should the pneumatic pressure be lost.

Figure 1 shows a UG-8L with Pneumatic Speed Adjustment, a solenoid shutdown, and Manual Speed Setting Screw.

References

Prod. Spec. 03037	Pneumatic Speed Adjustment for UG-5.7/8/10 Lever Governor
Prod. Spec. 03029	UG-5.7/8/10 Governor
Manual 03036	UG-5.7/8/10 Lever Governor
Manual 03016	Low Lube Oil Pressure Shutdown for the UG Governor

Installation

A connection to an air supply is needed to operate the device on an engine or turbine. See Figure 1 for size and location of the air supply connection.

The Manual Speed Setting Screw is normally installed as a optional feature only on governors with the Pneumatic Speed Adjustment feature. Either feature will operate without association with the other.

The Manuel Speed Setting Screw can be easily installed on any existing UG-8L governor. No special tools are needed. The governor does not have to be disassembled to accept the new pieces, but the nameplate must be removed for the installation of a new stop lever and return spring.

Operation

Two styles of plumbing are available to carry governor pressure oil to the pneumatic head.




Figure 1. Outline of UG-8 Lever Governor with Pneumatic Speed Adjustment and Manual Speed Setting Screw

Internally plumbed units carry pressure oil from the controlet inside the governor to the speed-setting head. The internally plumbed units require a special pilot-valve bushing to regulate the amount of oil supplied to the head and a specially machined controlet to accept the plumbing connection. The governor is normally returned to the factory for installation of the internally plumbed speed-setting head.

Externally plumbed units receive pressure oil from the governor base through an external pipe. An orifice in the cover regulates the amount of oil available to the speed-setting head. The externally plumbed unit may be installed on a lever governor in the field. Installation instructions are included with a conversion kit.

Figure 2 is a schematic of the UG-8 Lever governor which has a pneumatic speed adjusting device. This description of operation covers only the speed adjusting devices. Manual 03036 covers the UG-8 Lever governor operation. Reference numbs are from Figures 2 and 4 below.

! WARNING To prevent overspeed, return the lever to the minimum speed position before applying control air pressure.




Figure 2. Schematic of UG-8 Lever Governor with Pneumatic Speed Adjustment

The speed setting air signal is connected to the bellows (5). Lever (16) balances between the force of the bellows and the force of spring (13) under the speed setting piston (11). When the bellows force is more than the spring force, the lever rotates about pin (15). The left end of the lever moves up to close nozzle (25). Oil pressure increases on the speed setting piston, moving it down and increasing the spring load on the lever. When the spring force exceeds the value required to balance the lever against the bellows force the lever rotates counterclockwise, releasing oil through the nozzle. Oil pressure stops increasing and piston movement stops.

When the piston moves down, rod (14) increases the load on the speeder spring, which raises the governor speed setting.

The governor will go to minimum fuel or shutdown in case of failure or interruption of the pneumatic signal. The Manual Speed Setting Screw will act as a minimum speed stop if it is not backed out of the way during normal operation.

Should the pneumatic pressure fail, the manual speed setting screw may be used to set the speed of the governor mechanically. Speed setting increases when the screw is turned clockwise and decreases when it is turned counterclockwise.

The screw is normally locked with the wing nut at minimum speed setting position with visible clearance between the speed setting screw and the speed setting lever. The wing nut provides positive lock of the speed setting screw.

When the pneumatic signal is used for setting the speed, the screw adjustment must be in the minimum speed setting position. Failure to follow this instruction increases the pneumatic speed setting by the amount of the manual setting.

The speed setting shaft must be free to rotate between high and low speed stops during pneumatic operation.

Adjustment

External

There are two external adjustments on the pneumatic speed adjustment device:

- The eccentric bellows (5 – Figure 4) changes the range.
- Screw (33 – Figure 4) is used to change the speed setting level.

The speed setting functions of the Speed Setting Screw Assembly are all visible. As the screw is threaded down, it increases speed; and retracting it lowers the speed setting.



WARNING

Be prepared to make an emergency shutdown when starting the engine, turbine, or other type of prime mover, to protect against runaway or overspeed with possible personal injury, loss of life, or property damage.

Internal

Make the initial setting of rod (14) with the unit off the governor.

1. Set the low speed stop on the governor panel approximately 10 rpm lower than the required low air speed setting.

IMPORTANT

Any time the low speed stop is changed, the length of rod (14) must be changed or the new low speed setting may not be attained.

2. See Figure 3. Measure the distance from the top surface of the governor case to the top of the rod with the governor's speed setting against the low speed stop.

This distance should be 2.500 inches +0.005 or –0.010 inches (63.50 mm +0.13 or –0.25 mm).




Figure 3. Speed Setting Plug

3, Lock the nuts in place.

IMPORTANT

If the rod length is too long or too short, it may not be possible to attain the low air set speed.

4. Install the speed adjusting device on the governor. Rod (14) should enter the hole in lever (16) below the piston. (Figure 4).
5. Use a thin screwdriver and force the oil pipe into the hole in the cover until the O-ring enters the hole.
6. Tighten screws (34).
7. Connect the air supply pipe.
8. Apply the minimum air signal.
9. Adjust screw (33) until the specified speed, at minimum air signal, is reached. Turn the screw clockwise to decrease the speed and counterclockwise to increase the speed.
10. Apply the maximum speed air signal and check the speed. A range adjustment must be made if speed is incorrect at the maximum air signal.

To make a range adjustment:

- A. Reduce the air signal to zero.
- B. Loosen the bellows clamp screws.
- C. Rotate the bellows clockwise to increase the range and counterclockwise to decrease the range.

IMPORTANT

Adjustment is limited to 90 degrees in either direction from the alignment marks on the cover and the top of the eccentric.

11. Re-check the minimum and maximum speeds and repeat steps 8 through 10 as required.
12. Set the maximum speed stop screw located on the front panel.

Parts List For Figure 4

Ref. No.	Part Name	Quantity
03045-1	Cover	1
03045-2	Screw, 10-32 x 0.500	2
03045-3	Lock Washer, No. 10, 0.190 ID	9
03045-4	Strap	1
03045-5	Eccentric Bellows	1
03045-6	O-ring, 1.364 ID x 0.070	1
03045-7	O-ring, 1.234 ID x 0.070	1
03045-8	O-ring, 0.145 ID x 0.070, See Fig. 6 ...	1
03045-9	Tube, See Fig. 6	1
03045-10	O-ring, 0.208 ID x 0.070, See Fig. 6 ...	1
03045-11	Piston	1
03045-12	Rod Seat	1
03045-13	Spring	1
03045-14	Rod	1
03045-15	Shaft	1
03045-16	Lever	1
03045-17	Needle Bearing	2
03045-18	Nozzle Seat	1
03045-19	Nut, 10-32	1
03045-20	Spring	1
03045-21	Nut	1
03045-22	Spring	1
03045-23	Spring Seat	1
03045-24	Ball, 0.156	1
03045-25	Nozzle	1
03045-26	Filler Cap	1
03045-27	Retaining ring, 0.338	1
03045-28	Rod	1
03045-29	Body	1
03045-30	Spring	1
03045-31	Cap	1
03045-32	O-ring, 0.176 ID x 0.070	2
03045-33	Screw	1
03045-34	Screw	7
03045-35	Screw	1
03045-36	Plug	1
03045-37	Gasket	1
03045-38	Plug, See Fig.6	1
03045-39	O-ring, See Fig. 6	1
03045-40	Not Used	
03045-41	Not Used	
03045-42	Not Used	
03045-43	See Fig. 6	
03045-44	See Fig. 6	
03045-45	Not Used	
03045-46	Jet Insert	1
03045-47	Expander Pin	1
03045-48-50	Not Used	
03045-51-55	See Fig. 6	
03045-56	Not Used	
03045-57	Not Used	
03045-58-66	See Fig. 6	
03045-67	Not Used	
03045-68	Filter	1
03045-69	Spring	1
03045-70	O-ring	1
03045-71	Plug	1
03045-72	Elbow, Straight Thread	1
03045-73	Orifice Assy .1251 -4 Elbow	1
03045-74	Tube Assy	1
03045-75-100	Not Used	





Figure 4. Parts of UG-8 Pneumatic Speed Adjustment with Manual Shutdown

03000-A-305



Parts List For Figure 6

Ref. No.	Part Name	Quantity	Ref. No.	Part Name	Quantity
03045-1	Not Used		03045-37	Gasket	1
03045-2	Screw, 10-32 x 0.500	2	03045-38	Plug, Hex Head	1
03045-3	Lock Washer, No. 10, 0.190 ID	9	03045-39	O-ring	1
03045-4	Strap	1	03045-40	Not Used	
03045-5	Eccentric Bellows	1	03045-41	Not Used	
03045-6	O-ring, 1.364 ID x 0.070	1	03045-42	Not Used	
03045-7	O-ring, 1.234 ID x 0.070	1	03045-43	Screw, Filter Retention	1
03045-8	O-ring, 0.145 ID x 0.070	1	03045-44	Filter	1
03045-9	Tube	1	03045045	Not Used	
03045-10	O-ring, 0.208 ID x 0.070	1	03045-46	See Fig. 4	
03045-11	Piston	1	03045-47	See Fig. 4	
03045-12	Rod Seat	1	03045-48-50	Not Used	
03045-13	Spring	1	03045-51	Screw	2
03045-14	Rod	1	03045-52	Lockwasher	2
03045-15	Shaft	1	03045-53	Clamp, 0.188 ID	2
03045-16	Lever	1	03045-54	Tube, 0.337 ID	2
03045-17	Needle Bearing	2	03045-55	Connector, No. 16	1
03045-18	Nozzle Seat	1	03045-56	Not Used	
03045-19	Nut, 10-32	1	03045-57	Not Used	
03045-20	Spring	1	03045-58	Bushing	1
03045-21	Nut	1	03045-59	Potting Stop	1
03045-22	Spring	1	03045-60	Solenoid Assembly (see manual 03013 for individual parts)	1
03045-23	Spring Seat	1	03045-61	Cover	1
03045-24	Ball, 0.156	1	03045-62	Tubing	2
03045-25	Nozzle	1	03045-63	Set Screw 10-32 x 0.250	1
03045-26	Filler Cap	1	03045-64	Diode	1
03045-27-31	Not Used		03045-65	Lock Washer	1
03045-32	O-ring, 0.176 ID X 0.070, See Fig. 4	2	03045-66	Screw	1
03045-33	Screw, See Fig. 4	1	03045-67	Not Used	
03045-34	Screw	7	03045-68-74	See Fig. 4	
03045-35	Screw	1	03045-75-100	Not Used	
03045-36	Plug	1			




Figure 5. Wiring Diagram

SEE FIGURE 4 FOR PREFERRED FILTER CONFIGURATION





Figure 6. Parts for UG-8 Pneumatic Speed Adjustment with Solenoid Shutdown



Parts List For Figure 7

Ref. No.	Part Name	Quantity
03045-101	Front Plate
03045-102	Screw, 8-32 x .250 Soc. Set
03045-103	Disc
03045-104	Lever, Speed Setting
03045-105	Washer, Spring Lock No. 10
03045-106	Screw, 10-32 x .500 Soc. Hd Cap
03045-107	Bracket
03045-108	Washer, Spring Lock No. 10
03045-109	Screw, 10-32 x 1.250 Socket Cap
03045-110	Nut, M8 Wing
03045-111	Screw, M8, Knurled Head
03045-112	Stop Lever
03045-113	Lock Washer
03045-114	Screw, 10-32 Socket Cap
03045-115	Return Spring




Figure 7. Parts for UG-8 Manual Speed Adjustment



Speed Setting Filter

The speed setting filter is provided to protect the small orifices in the head from accumulations of dirt. The filter should be removed and backflushed if the speed setting head becomes sluggish or during overhaul of the governor.

SLNC Goodwill Governor testing outline protocol

1. Photographic images should record the condition of the governors before they are packed. This includes the setting positions of the dials on the governor front plate and the position of the compensation arm.
2. Serial numbers and unique identifying features should be recorded.
3. The governor(s) should be packed in suitable casing to ensure that damage or further damage cannot be incurred during transit.
4. Photographic images should record the condition of the governors before sealing of the crates.
5. The packing crates should be sealed with tamper proof tape to ensure that ingress into the crates does not occur during transit to the approved Woodward governor test location.
6. The approved Woodward test location should beforehand nominate staff who will undertake the governor testing.
7. Photographic images should record the condition of the sealed crate. The sealing should be signed off by witnessing personnel. Witness names should be recorded in block capitals. Senior ships staff are best placed to fulfil such roles.
8. On arrival at the testing location, photographic images should be recorded of the received crate(s). comparison with images taken before despatch should be made.
9. It is considered appropriate for independent witness to be in attendance when the crates are opened and for the period of testing of the governors. If independent witnesses are not available, then it is considered prudent that high quality video recordings of the opening, removal, inspection, repair and testing processes should be made.
10. On opening of the crates, a decision will need to be made as to the order in which the testing is carried out.
11. On removal from the packaging, the condition of both governors should be recorded. The inspection should detail:
 - The general condition and state of the packaging
 - The position of the dials on the governor front plate
 - The position of the compensation lever
 - The position of the output spindle and attached lever. If no lever attached, then it should be recorded.
 - All damages to the governors
12. Given that one of the governors is damaged, an assessment will need to be made as to repairs required in order to return the governor to a functioning condition. The degree of repair require will need to be confirmed with owners and/or owners representatives before being undertaken.
13. If it is deemed that the damaged governor is uneconomical to repair and be tested, then investigation should be undertaken to examine the governor internal components to assess whether the condition as found: Aspects to consider are :
 - error in re-assembly, bearing in mind the governor had been overhauled in 2019 and had not been fitted to any engine
 - impacts caused by the damaged flywheel
 - normal wear and tear
14. The dismantling should be undertaken in a controlled manner nominally in accordance with Woodward overhaul procedures. This should include the recording of all fastener tightness or torque values where applicable.,
15. Assessment should be made as to whether the found condition could be attributable to the cause of overspeed immediately after installation on the engine.
16. It is however, important to ensure that where feasible, no adjustments are made to the governor settings before they are installed on the test rig.
17. If possible, the governors should be installed on the rig and connected in accordance with test requirements

18. As a first test before commencing the TSP 152 procedures, if possible and advice from Woodward test engineers will need to be sought if this is possible, the rig should be run up to assess the as received or as repaired condition of the respective governors. The response to this test should be recorded. Photographic images of test rig indicators should be recorded if allowed.
19. If the response to the as received or as repaired tests are unsatisfactory, then investigation should be undertaken to understand the cause of the response.
20. The findings will then be assessed in relation to the ongoing investigation and the cause of engine overspeed and previously, the cause of engine speed instability.

WORK ORDER/SERVICE REQUISITION FORM

Ship Name : SLNC GOODWILL
WO/SR No : 1121478
Performed By : SO
PO No : 1100180(1)
Net Cost : 4,146.24 USD

Title : AUX ENGINE #1 GOVERNOR TROUBLE SHOOTING & OVERHAUL

SCHEDULING DATA

Scheduled : 06/18/2019
Completed : 05/31/2019 (b) (6), (b) (7)(C)
Canceled :
Next Due Date :
Event :
Interval :

ADMINISTRATIVE DATA

Created By: (b) (6), (b) (7)(C) On : 06/01/2019
Auth. By: (b) (6), (b) (7)(C) On : 06/01/2019
Apprvd. By: (b) (6), (b) (7)(C) On : 06/01/2019
Account No: 51104 - Ship Maintenance
Project No: Priority :A
Job Catg:ENGINE REPAIRS Class Job No :
Sugg Vend: Jewon Engineering Co LTD
Dept.: ENGINE

EQUIPMENT PARTICULARS

Name: AE 1 GOVERNOR Class Equipment Name : Class Eq Code:
Equip Code : NGOO01U2SUL Manufacturer :
Model : MAN B&W 6L23/30H Serial No : 08365/08366/08367
Size : Type :
Equip. Location : Criticality:C

SPACE PARTICULARS

RESOURCES & COST DATA

Estimated Cost : 0.00 Estimated Man-Hrs : 0
Std. Job Cost : Actual. Man-Hrs : 0
Resource :

WO DESCRIPTION

vendor to attend vessel for AUX ENGINE #1 GOVERNOR TROUBLE SHOOTING & OVERHAUL

WO FINDINGS

after inspection it was confirmed that governor unit need an overhaul it recomed every 2 years service interval

Perform By:

Tested By:

Signature:

Designation:

JOB SAFETY ANALYSIS

JSA Required : NO

Use Template :

WORK ORDER/SERVICE REQUISITION FORM

Ship Name : SLNC GOODWILL

WO/SR No : 8052082

Performed By : WO/Crew

Title : AE 1 GOVERNOR ANNUAL TEST

SCHEDULING DATA

Scheduled : 11/16/2019

Event :

Completed : 12/26/2019 (b) (6), (b) (7)(C) (b) (6), (b) (7)(C)

Canceled :

Next Due Date : 12/24/2020

Interval : 52 W

ADMINISTRATIVE DATA

Created By: (b) (6), (b) (7)(C)

On : 12/26/2019

Auth. By:

On :

Apprvd. By:

On :

Account No:

Project No:

Priority :C

Job Catg:ENGINE REPAIRS

Class Job No :

Sugg Vend:

Dept.: ENGINE

EQUIPMENT PARTICULARS

Name: AE 1 GOVERNOR

Class Equipment Name :

Class Eq Code:

Equip Code : NGOO01U2SUL

Manufacturer :

Model : MAN B&W 6L23/30H

Serial No : 08365/08366/08367

Size :

Type :

Equip. Location :

Criticality:C

SPACE PARTICULARS

RESOURCES & COST DATA

Estimated Cost : 0.00

Estimated Man-Hrs : 0

Std. Job Cost :

Actual. Man-Hrs : 0

Resource :

WO DESCRIPTION

GOVERNOR CHECK

TASK: CONDITION AND FUNCTION CHECK OF GOVERNOR

INSPECT WHILE UNDER NORMAL OPERATING CONDITIONS
CHECK OIL LEVELS
CHECK FOR AIR, OIL LEAKS, INSPECT FITTINGS, CONNECTORS
EXAMINE LINKAGE, LUBRICATE AS NEEDED.
CLEAN SENSORS AS REQUIRED.
CHECK ALL ALARMS, TRIPS, READOUTS, SENSORS.

ALL REMARKS, DEFICIENCIES, ACTIONS TAKEN/PERFORMED, OR NOTEWORTHY COMMENTS SHALL BE REPORTED IN THE WO FINDINGS TAB. INCLUDE CORRESPONDING REQUISITION NUMBER FOR ORDERING OF NEW/REPLACEMENT ITEMS/PARTS IN WO FINDINGS TAB.

ANY DEFICIENCIES NOTED REQUIRING ADDITIONAL ATTENTION, ARE SAFETY RELATED OR ARE BEYOND THE SCOPE OF NORMAL MAINTENANCE ACTIVITIES SHALL HAVE AN ASSOCIATED SERVICE REQUISITION WRITTEN.

WO FINDINGS

In May 2019 rebuilt governor installed and topped off with 827. New micro switch installed on over speed device. Work done at 41114

Governor observed at idle and at multiple loads, holds 900 rpm and reacts to change in load with no erratic movement or hunting

Oil level checked and oil is clear with a 'new" appearance
Linkage, fitting and wires all checked for tightness and leakage
Fuel rack checked, lubricated and exercised weekly by 3ae
Speed sensor checked

Current run hours 42617, roughly 1500 hours on rebuilt governor

Completed by 1ae (b) (6), (b) (7)(C) 12/26/2019

Perform By:

Tested By:

Signature:

Designation:

JOB SAFETY ANALYSIS

JSA Required : NO

Use Template :






































(b) (6), (b) (7)(C)



(b) (6), (b) (7)(C)





Alarm History

07.08.2011
18:19:00

Date & Time	Tagname	Tag description	Func	Value	Engunit	Alarm	Alarm
05-08-20 13:40:08.810	2002	NO.1 DIG START. AIR INLET PRESS.	PAL	ALARM		ALARM	ALM
05-08-20 13:40:08.270	2004	NO.1 DIG L.O. FILTER DIFF PRESS	DPAH	ALARM		ALARM	ALM
05-08-20 13:40:06.435	2009	NO.1 DIG C.F.W OUTLET TEMP.	TAH	511.2 °C		IFH	ALM
05-08-20 13:40:06.341	2113	NO.3 DIG TACHO. & PWR FAIL	XA	ALARM		ALARM	ALM
05-08-20 13:40:06.341	2115	NO.3 DIG PRE L.O. LEVL	LAL	ALARM		ALARM	ALM
05-08-20 13:40:06.095	2006	NO.1 DIG L.O. INLET TEMP.	TAH	511.2 °C		IFH	ALM
05-08-20 13:40:05.991	2014	NO.1 DIG JET SYS FAIL & OVERLOA	XA	ALARM		ALARM	ALM
05-08-20 13:40:05.911	2001	NO.1 DIG START FAIL	XA	ALARM		ALARM	ALM
05-08-20 13:40:05.911	2013	NO.1 DIG TACHO. & PWR FAIL	XA	ALARM		ALARM	ALM
05-08-20 13:40:05.910	2039	NO.1 DIG F.O. FILTER HIGH DIFF.	XA	ALARM		ALARM	ALM
05-08-20 13:40:04.327	2005	NO.1 DIG L.O. INLET PRESSURE	PAL	-0.25 MPa		IFL	ALM
05-08-20 13:40:04.317	2016	NO.1 DIG EXH GAS INLET TIC TEMP	TAH	-150.0 °C		IFL	ALM
05-08-20 13:40:04.317	2025	NO.1 DIG EXH GAS TEMP OUT. CYL1	TAH	-149.9 °C		IFL	ALM
05-08-20 13:40:04.317	2027	NO.1 DIG EXH GAS TEMP OUT. CYL2	TAH	-150.0 °C		IFL	ALM
05-08-20 13:40:04.317	2029	NO.1 DIG EXH GAS TEMP OUT. CYL3	TAH	-150.0 °C		IFL	ALM
05-08-20 13:40:04.317	2032	NO.1 DIG EXH GAS TEMP OUT. CYL4	TAH	-149.9 °C		IFL	ALM
05-08-20 13:40:04.317	2034	NO.1 DIG EXH GAS TEMP OUT. CYL5	TAH	-149.9 °C		IFL	ALM
05-08-20 13:40:04.317	2036	NO.1 DIG EXH GAS TEMP OUT. CYL6	TAH	-149.4 °C		IFL	ALM
05-08-20 13:39:51.647	2011	NO.1 DIG SHUTDOWN	XA	ALARM		ALARM	ALM
31-07-20 18:55:51.017	4271	WASTE OIL SETTLING LL	LAL	NORMAL		OFFSC	ALM
31-07-20 18:52:40.361	1401	BOW THRUSTER COMM ALARM	XA	ALARM		ALARM	ALM
29-07-20 21:59:08.896	5005	M5B AC220V EARTH LEAK	XA	NORMAL		OFFSC	ALM
23-07-20 14:59:52.063	1213	CARGO TK/RADAR SYS FAIL	XA	ALARM		OFFSC	ALM
17-07-20 14:28:11.899	4226	L.S. F.O. SETTING TK. LEVL	LAL	ALARM		ALARM	ALM
10-07-20 17:44:12.897	4118	NO.1 MAIN AIR COMPRESSOR ABN.	XA	ALARM		OFFSC	ALM
07-06-20 10:14:40.280	4104	NO.1 ME L.O. PURIFIER ABN.	XA	NORMAL		OFFSC	ALM
25-01-20 07:26:48.320	5013	BATTERY CHARGE PANEL EARTH FAULT	XA	NORMAL		OFFSC	ALM
19-12-19 10:01:38.144	1211	F.W.TK & BOILER W.TK LEVEL	LAH	ALARM		OFFSC	ALM
22-09-19 13:18:26.327	4266	L.S. F.O. SERVICE TK. LEVL	LAL	ALARM		ALARM	ALM
02-07-19 07:52:44.464	4342	FRESH WATER TK.(PS) LEVL	LAL	ALARM		ALARM	ALM
11-05-19 04:34:48.895	2010	ME AXIAL VIBRATION HIGH	XA	-3.00 mm		IFL	ALM

Auto Log

ECR WATCH

Date & Time	Tagname	Tag description	Func	Value	Eng.unit	Alarm
06-08-20 16:57:00.296	UTC time changed	(-41 sec) to 06-08-20 07:56:19, New local time:	06-08-20	16:56:19		
06-08-20 16:56:43.000	UTC time changed	(2 sec) to 06-08-20 07:56:45, New local time:	06-08-20	16:56:45		
06-08-20 16:56:41.015	UTC time changed	(2 sec) to 06-08-20 07:56:43, New local time:	06-08-20	16:56:43		
06-08-20 16:56:39.000	UTC time changed	(2 sec) to 06-08-20 07:56:41, New local time:	06-08-20	16:56:41		
06-08-20 16:56:37.000	UTC time changed	(2 sec) to 06-08-20 07:56:39, New local time:	06-08-20	16:56:39		
06-08-20 16:56:30.781	UTC time changed	(7 sec) to 06-08-20 07:56:37, New local time:	06-08-20	16:56:37		
06-08-20 16:46:18.974	SAFETY SLD	SLOWDOWN ACTIVE	XA	1.6		HIGH ALM
06-08-20 16:46:17.474	SLD 05	ME L.O. INLET PRESS.	SLD	SLOWDN		SLOWDN ALM
06-08-20 15:57:29.136	4107	F.O. BOOSTER UNIT COMM ALARM	XA	ALARM		ALARM ALM
06-08-20 13:08:17.110	3013	ME AUX BLOWER ABN. STOP	XA	ALARM		ALARM ALM
06-08-20 13:03:27.185	ST AIR LOW	Start air pressure low	XA	ALARM		ALARM ALM
06-08-20 13:03:01.912	3073	ME STARTING AIR INLET PRESS	PIAL	1.42 MPa		LOW ALM
06-08-20 12:58:54.691	SAFETY SHD	Engine tripped	XA	0.2		HIGH ALM
06-08-20 12:58:49.926	3032	ME L.O. INLET PRESS	PIAL	0.11 MPa		LO-LO ALM
06-08-20 12:58:49.618	SHD 01	MAIN L.O. INLET LOW LOW PRESSURE	XA	SHUTDN		SHUTDN ALM
06-08-20 12:58:46.775	3038	ME TIC L.O. INLET PRESS	PIAL	0.04 MPa		LOW ALM
06-08-20 23:00:14.634	2068	NO.2 DIG F.O. FILTER HIGH DIFF.	XA	ALARM		ALARM ALM
06-08-20 19:15:15.825	4109	F.O. VISCOSITY HIGH/LOW	VIAHL	ALARM		ALARM ALM
06-08-20 18:39:04.463	1102	AUX BOILER NON-SHD COMMON ALARM	XA	ALARM		ALARM ALM
06-08-20 18:39:02.660	1205	IGS PLANT FAILURE	XA	ALARM		ALARM ALM
06-08-20 18:37:41.202	4122	AUX AIR RESEVOIR PRESSURE	PIAL	1.42 MPa		LOW ALM
06-08-20 17:03:21.777	2030	NO.1 DIG F.O. INLET PRESSURE LOW	PIAL	-0.00 MPa		IFL ALM
06-08-20 13:51:46.821	4234	ER AFT BILGE WELL LEV.H.	LAH	ALARM		ALARM ALM
06-08-20 13:43:03.919	2016	NO.1 DIG PRE LUB OIL LEV.L.	LAL	ALARM		ALARM ALM
06-08-20 13:42:08.885	2005	NO.1 DIG L.O. SUMP TK. LEV.L.	LAL	ALARM		ALARM ALM
06-08-20 13:42:04.672	4128	WORK AIR RESEVOIR PRESSURE LOW	PIAL	-3.08 MPa		IFL ALM
06-08-20 13:41:58.662	2007	NO.1DIG C.F.W. INLET PRESSURE	PIAL	-0.15 MPa		IFL ALM
06-08-20 13:41:23.069	1209	IGS DECK MAIN LINE PRESS LOW-LOW	PALL	ALARM		ALARM ALM
06-08-20 13:41:23.069	1209	IGS DECK MAIN LINE PRESS LOW-LOW	PALL	ALARM		ALARM ALM
06-08-20 13:40:21.245	2003	NO.1 DIG F.O. LEAKAGE TK.	LAH	ALARM		ALARM ALM
06-08-20 13:40:11.528	1307	WATER MIST SYS. FAILURE	XC	ALARM		ALARM ALM
06-08-20 13:40:09.600	2062	NO.2 DIG START. AIR INLET PRESS.	PAL	ALARM		ALARM ALM

Auto log

SCR WATCH

Date & Time	Tagname	Tag description	Func	Value	Eng Unit	Alarm	
06-08-20 20:45:07.678	1309	CARGO SYS POWER FAILURE	XA	NORMAL		ALARM	RET
06-08-20 20:41:32.663	1309	CARGO SYS POWER FAILURE	XA	ALARM		ALARM	ALM
06-08-20 18:47:56.608	4107	F.O. BOOSTER UNIT COMM ALARM	XA	NORMAL		ALARM	RET
06-08-20 16:57:53.046	COMERR_A032	COMM ROS1 RAI_16 DPU32 (1/34)	XA	NORMAL		FAIL	RET
06-08-20 16:57:53.046	COMERR_A033	COMM ROS1 RDI_32 DPU33 (1/35)	XA	NORMAL		FAIL	RET
06-08-20 16:57:53.046	COMERR_A034	COMM ROS1 RAI_16 DPU34 (1/36)	XA	NORMAL		FAIL	RET
06-08-20 16:57:53.046	COMERR_A035	COMM ROS1 RAI_16 DPU35 (1/37)	XA	NORMAL		FAIL	RET
06-08-20 16:57:53.046	COMERR_A036	COMM ROS1 RDI_32 DPU36 (1/38)	XA	NORMAL		FAIL	RET
06-08-20 16:57:52.046	COMERR_A013	COMM ROS1 ACP DPU13 (1/172)	XA	NORMAL		FAIL	RET
06-08-20 16:57:51.046	COMERR_A012	COMM ROS1 ACP DPU12 (1/171)	XA	NORMAL		FAIL	RET
06-08-20 16:57:50.046	COMERR_A016	COMM ROS1 LTU DPU16 (1/133)	XA	NORMAL		FAIL	RET
06-08-20 16:57:50.046	COMERR_A017	COMM ROS1 MPP DPU17 (1/134)	XA	NORMAL		FAIL	RET
06-08-20 16:57:49.046	COMERR_A015	COMM ROS1 MPP DPU15 (1/132)	XA	NORMAL		FAIL	RET
06-08-20 16:57:48.046	COMERR_A012	COMM ROS1 ACP DPU12 (1/171)	XA	FAIL		FAIL	ALM
06-08-20 16:57:48.046	COMERR_A013	COMM ROS1 ACP DPU13 (1/172)	XA	FAIL		FAIL	ALM
06-08-20 16:57:48.046	COMERR_A015	COMM ROS1 MPP DPU15 (1/132)	XA	FAIL		FAIL	ALM
06-08-20 16:57:48.046	COMERR_A016	COMM ROS1 LTU DPU16 (1/133)	XA	FAIL		FAIL	ALM
06-08-20 16:57:48.046	COMERR_A017	COMM ROS1 MPP DPU17 (1/134)	XA	FAIL		FAIL	ALM
06-08-20 16:57:46.046	COMERR_A032	COMM ROS1 RAI_16 DPU32 (1/34)	XA	FAIL		FAIL	ALM
06-08-20 16:57:36.046	COMERR_A033	COMM ROS1 RDI_32 DPU33 (1/35)	XA	FAIL		FAIL	ALM
06-08-20 16:57:36.046	COMERR_A034	COMM ROS1 RAI_16 DPU34 (1/36)	XA	FAIL		FAIL	ALM
06-08-20 16:57:36.046	COMERR_A035	COMM ROS1 RAI_16 DPU35 (1/37)	XA	FAIL		FAIL	ALM
06-08-20 16:57:36.046	COMERR_A036	COMM ROS1 RDI_32 DPU36 (1/38)	XA	FAIL		FAIL	ALM
06-08-20 16:56:59.734	UTC time changed	(16 sec) to 06-08-20 07:57:16, New local time:	06-08-20	16:57:16			
06-08-20 16:57:16.000	Timezone changed	(0 min) to UTC+9 h, New local time:	06-08-20	16:57:16			
06-08-20 16:56:57.015	UTC time changed	(2 sec) to 06-08-20 07:56:59, New local time:	06-08-20	16:56:59			
06-08-20 16:56:56.000	UTC time changed	(2 sec) to 06-08-20 07:56:57, New local time:	06-08-20	16:56:57			
06-08-20 16:56:53.015	UTC time changed	(2 sec) to 06-08-20 07:56:55, New local time:	06-08-20	16:56:55			
06-08-20 16:56:51.000	UTC time changed	(2 sec) to 06-08-20 07:56:53, New local time:	06-08-20	16:56:53			
06-08-20 16:56:49.000	UTC time changed	(2 sec) to 06-08-20 07:56:51, New local time:	06-08-20	16:56:51			
06-08-20 16:56:47.015	UTC time changed	(2 sec) to 06-08-20 07:56:49, New local time:	06-08-20	16:56:49			
06-08-20 16:56:46.000	UTC time changed	(2 sec) to 06-08-20 07:56:47, New local time:	06-08-20	16:56:47			

ECR WATCH

AUTO log

Date & Time	Tagname	Tag description	Func	Value	Eng.unit	Alarm
06-08-20 20:45:07.678	1209	CARGO SYS POWER FAILURE	XA	NORMAL		ALARM
06-08-20 20:41:32.663	1209	CARGO SYS POWER FAILURE	XA	ALARM		ALARM
06-08-20 18:47:55.608	4107	F.O. BOOSTER UNIT COMM ALARM	XA	NORMAL		ALARM
06-08-20 16:57:53.046	COMERR A032	COMM ROS1 RAI_16 DPU32 (1/34)	XA	NORMAL		FAIL
06-08-20 16:57:53.046	COMERR A033	COMM ROS1 RDI_32 DPU33 (1/35)	XA	NORMAL		FAIL
06-08-20 16:57:53.046	COMERR A034	COMM ROS1 RAI_16 DPU34 (1/36)	XA	NORMAL		FAIL
06-08-20 16:57:53.046	COMERR A035	COMM ROS1 RAI_16 DPU35 (1/37)	XA	NORMAL		FAIL
06-08-20 16:57:53.046	COMERR A036	COMM ROS1 RDI_32 DPU36 (1/38)	XA	NORMAL		FAIL
06-08-20 16:57:52.046	COMERR A013	COMM ROS1 ACP DPU13 (19/72)	XA	NORMAL		FAIL
06-08-20 16:57:51.046	COMERR A012	COMM ROS1 ACP DPU12 (19/71)	XA	NORMAL		FAIL
06-08-20 16:57:50.046	COMERR A016	COMM ROS1 LTU DPU16 (19/33)	XA	NORMAL		FAIL
06-08-20 16:57:50.046	COMERR A017	COMM ROS1 MPP DPU17 (19/34)	XA	NORMAL		FAIL
06-08-20 16:57:49.046	COMERR A015	COMM ROS1 MPP DPU15 (19/32)	XA	NORMAL		FAIL
06-08-20 16:57:48.046	COMERR A012	COMM ROS1 ACP DPU12 (19/71)	XA	FAIL		FAIL
06-08-20 16:57:48.046	COMERR A013	COMM ROS1 ACP DPU13 (19/72)	XA	FAIL		FAIL
06-08-20 16:57:48.046	COMERR A015	COMM ROS1 MPP DPU15 (19/32)	XA	FAIL		FAIL
06-08-20 16:57:48.046	COMERR A016	COMM ROS1 LTU DPU16 (19/33)	XA	FAIL		FAIL
06-08-20 16:57:48.046	COMERR A017	COMM ROS1 MPP DPU17 (19/34)	XA	FAIL		FAIL
06-08-20 16:57:46.046	COMERR A032	COMM ROS1 RAI_16 DPU32 (1/34)	XA	FAIL		FAIL
06-08-20 16:57:36.046	COMERR A033	COMM ROS1 RDI_32 DPU33 (1/35)	XA	FAIL		FAIL
06-08-20 16:57:36.046	COMERR A034	COMM ROS1 RAI_16 DPU34 (1/36)	XA	FAIL		FAIL
06-08-20 16:57:36.046	COMERR A035	COMM ROS1 RAI_16 DPU35 (1/37)	XA	FAIL		FAIL
06-08-20 16:57:36.046	COMERR A036	COMM ROS1 RDI_32 DPU36 (1/38)	XA	FAIL		FAIL
06-08-20 16:56:59.734	UTC time changed	(16 sec) to 06-08-20 07:57:15, New local time:	06-08-20	16:57:15		
06-08-20 16:57:15.000	Timezone changed	(0 min) to UTC+9 h , New local time:	06-08-20	16:57:15		
06-08-20 16:56:57.016	UTC time changed	(2 sec) to 06-08-20 07:56:59, New local time:	06-08-20	16:56:59		
06-08-20 16:56:55.000	UTC time changed	(2 sec) to 06-08-20 07:56:57, New local time:	06-08-20	16:56:57		
06-08-20 16:56:53.016	UTC time changed	(2 sec) to 06-08-20 07:56:55, New local time:	06-08-20	16:56:55		
06-08-20 16:56:49.000	UTC time changed	(2 sec) to 06-08-20 07:56:53, New local time:	06-08-20	16:56:53		
06-08-20 16:56:47.016	UTC time changed	(2 sec) to 06-08-20 07:56:51, New local time:	06-08-20	16:56:51		
06-08-20 16:56:45.000	UTC time changed	(2 sec) to 06-08-20 07:56:49, New local time:	06-08-20	16:56:49		

SCR WATCH

Auto log

M/V SLNC GOODWILL: Engine Log

073 On voyage from G444 to ONSAN R.O.K. Date 8/2/80 Page 002

OPERATIONS	EXH. VALVE		JACKET	SCAV	DIESEL GENERATORS			PUMPS		BOILER SYS.		COMMENTS
	#1	#2			#1	#2	#3	SW		Com		
120	25.8	25.3	28	27	EXH.1	366	278	HT	1	BOILER OIL		DUTY ENGINEER
70	25.8	25.3	28	27	EXH.2	396	329	LT	2	SLDAD	0	
	25.8	26.1	28	27	EXH.3	333	336	FW BOOST	3	WTR LEV	41	
103	25.8	26.1	28	27	EXH.4	333	336	FEED		BOILER P	3.1	Flow down complete
27	25.8	334	28	27	EXH.5	333	336	SUPPLY		FUEL P	4.2	boiler
			JACKET CW IN P	3.7	EXH.6	386	325	CIRC		AIR PRESSURE		Cleaned and
			JACKET CW OUT	2.1	LO P	5.0	4.6	STEERING	1	START AIR	39	inspected MFO
8			LT CW IN P	2.1	LOTW	67.2	66.0	TK		CONF AIR	3	transfer pump
2.7			LT CW OUT	3.5	HT P	5.2	3.0	IG		WORK AIR	9.7	Shutted
2.7			LO IN P	2.4	HT IN	26.5	67.7	AIR COMPRESSOR		WHISTLE	70	Roller treatment
21			LO OUT	2.4	LT WTR IN	3.7	3.8	START AIR #1		REFRIG. COMP.		0.15 to evaporator.
30			LO IN P	2.4	LT WTR OUT	3.8	4.0	HR. METER	2111	SUCT P	15	2.1E WREC
			LO OUT	2.4	CHG AIR %	50	50	HR. METER	1811	DISCH P	11	
			LO IN P	2.4	CHG AIR IN	110	78	OIL PRESS		OW WY	33	1300 - stop 25 PM/turnover
			LO OUT	2.4	CHG AIR OUT	47	48	START AIR #2		OW OUT	38	
			LO IN P	2.4	CHG AIR P	0.7	0.8	HR. METER	1836	BOX F	-131	
			LO OUT	2.4	KW	367	369	HRS RUN		ON LINE	2	
			LO IN P	2.4	AMPS	580	640	OIL PRESS		AC COMP		
			LO OUT	2.4	LUMP	5	5	EMERG COMP		SUCT P	43	
			LO IN P	2.4	Pressure	5	5	HR. METER	1474	DISCH P	43	
			LO OUT	2.4	Pressure	5	5	HRS RUN		OIL P	+ 30	
			LO IN P	2.4	Pressure	5	5	WORK AIR		CW IN F	22	
			LO OUT	2.4	Pressure	5	5	HR. METER	2939	CW OUT F	58	1400 - engine to pull ahead
			LO IN P	2.4	Pressure	5	5	HRS RUN	27367	CLR IN F	23	
			LO OUT	2.4	Pressure	5	5	CLR IN F		CLR OUT F	24	
			LO IN P	2.4	Pressure	5	5	ON LINE		ON LINE	1	
			LO OUT	2.4	Pressure	5	5	EVAPORATOR				
			LO IN P	2.4	Pressure	5	5	FEED TEMP				
			LO OUT	2.4	Pressure	5	5	VACUUM				
			LO IN P	2.4	Pressure	5	5	SHELL TEMP				
			LO OUT	2.4	Pressure	5	5	PPM				
			LO IN P	2.4	Pressure	5	5	METER				
			LO OUT	2.4	Pressure	5	5	WTR MADE				
			LO IN P	2.4	Pressure	5	5	HOURS ON				
			LO OUT	2.4	Pressure	5	5	HRS RAN				
			LO IN P	2.4	Pressure	5	5	TOTAL				
			LO OUT	2.4	Pressure	5	5	LD				
			LO IN P	2.4	Pressure	5	5	MAIN ENGINE				
			LO OUT	2.4	Pressure	5	5	#1 DIESEL GEN				
			LO IN P	2.4	Pressure	5	5	#2 DIESEL GEN				
			LO OUT	2.4	Pressure	5	5	#3 DIESEL GEN				
			LO IN P	2.4	Pressure	5	5	#4 DIESEL GEN				

(b) (6), (b) (7)(C)

(b) (6), (b) (7)(C)

CHIEF ENGINEER	DATE
(b) (6), (b) (7)(C)	2/2/80

M/V SLNC GOODWILL: Engine Log

073

On voyage from

GUAM

to ONSAN, ROK

Date 8/11/20 Page 001

OPERATIONS	EXH VALVE			JACKET		SCAV		DIESEL GENERATORS			PUMPS		BOILER SYS		COMMENTS
	EXH #1	EXH #2	EXH #3	JACKET CW IN P	JACKET CW IN T	SCAV #1	SCAV #2	#1	#2	#3	S/W	HT	HT	HT	
COOLING	126	356	353	7.2	4.4	4.8	4.8	35.4				35.4	35.4	35.4	DUTY ENGINEER
MEAN	362	366	352	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #1	356	353	362	4.8	4.8	4.8	4.8	4.8				4.8	4.8	4.8	Added treatment to M/E turbo Cool exhaust 802.5 / 1500 rpm 2.016 W/C O/RYS - FULL (O/R) 100 - AIR FULL (O/R)
EXH #2	366	352	356	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #3	352	356	366	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #4	356	366	352	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #5	352	356	366	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #6	366	352	356	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #7	352	356	366	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #8	356	366	352	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #9	366	352	356	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #10	352	356	366	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #11	356	366	352	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #12	366	352	356	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #13	352	356	366	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #14	356	366	352	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #15	366	352	356	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #16	352	356	366	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #17	356	366	352	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #18	366	352	356	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #19	352	356	366	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #20	356	366	352	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #21	366	352	356	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #22	352	356	366	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #23	356	366	352	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #24	366	352	356	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #25	352	356	366	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #26	356	366	352	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #27	366	352	356	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #28	352	356	366	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #29	356	366	352	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #30	366	352	356	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #31	352	356	366	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #32	356	366	352	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #33	366	352	356	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #34	352	356	366	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #35	356	366	352	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #36	366	352	356	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #37	352	356	366	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #38	356	366	352	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #39	366	352	356	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #40	352	356	366	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #41	356	366	352	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #42	366	352	356	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #43	352	356	366	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #44	356	366	352	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #45	366	352	356	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #46	352	356	366	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #47	356	366	352	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #48	366	352	356	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #49	352	356	366	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #50	356	366	352	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #51	366	352	356	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #52	352	356	366	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #53	356	366	352	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #54	366	352	356	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #55	352	356	366	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #56	356	366	352	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #57	366	352	356	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #58	352	356	366	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #59	356	366	352	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #60	366	352	356	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #61	352	356	366	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #62	356	366	352	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #63	366	352	356	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #64	352	356	366	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #65	356	366	352	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #66	366	352	356	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #67	352	356	366	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #68	356	366	352	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #69	366	352	356	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #70	352	356	366	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #71	356	366	352	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #72	366	352	356	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #73	352	356	366	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #74	356	366	352	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #75	366	352	356	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #76	352	356	366	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #77	356	366	352	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #78	366	352	356	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #79	352	356	366	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #80	356	366	352	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #81	366	352	356	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #82	352	356	366	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #83	356	366	352	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #84	366	352	356	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #85	352	356	366	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #86	356	366	352	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #87	366	352	356	5.1	5.1	5.1	5.1	5.1				5.1	5.1	5.1	
EXH #8															



REMARKS:

1. M. 100148487
TYPE-100-2

100148487
TYPE-100-2



WINDUP IN 1305

1305



W. WOODWARD
TYPE UG-8

PART NO.

W220-CX21

SERIAL NO.

W222175

GOVERNOR SPEED

1000-1500 RPM

CUSTOMER'S NO.



TYPE UG-8

PART NO
8520-3041

SERIAL NO
15592175



LEAD LIMIT
LIMITE DE CHARGE
LASTBECHTEL
CHARGE DE CHARGE

SPEED SETTING INDICATOR
VITESSE AFFICHE
V. WERTANZEIGER
TYPE DE VELOCIM

WOODWARD
Jeff. S.

WOODWARD
2019 P

REMARKS:
Please do not
change the
speed setting
after you have
checked the
operation for
the day.



WOODWARD
PART NO
8520-3041
SERIAL NO
15592175
CUSTOMER NO

WOODWARD
TYPE UG-8
SPEED SETTING INDICATOR
VITESSE AFFICHE
V. WERTANZEIGER
TYPE DE VELOCIM

TYPE UG-8
GOVERNOR SPEED

PART NO. *107A*

SERIAL NO. *107A*

40 50 60 70 80 90 100

0 1 2 3 4

0 10 20 30 40 50 60 70 80 90 100

0 10 20

0 10 20

LEAD LIMIT
LIMIT OF CHANGE
LAST POSITION
10-15 20

SPEED SETTING INDICATOR
INDICATES SPEED
TO WHICH SET
TYPE OF REGULATOR

WOODWARD
20/4 5

WOODWARD
TYPE UG-8

PART NO. _____

SERIAL NO. _____

40 50 60 70 80 90 100

0 1 2 3 4

0 10 20 30 40 50 60 70 80 90 100

0 10 20

0 10 20

REMARKS:

Before starting engine
please turn load limit
from 0 to 10 (max.)
After you have done linkage
connecting to fuel pump

WOODWARD
20/4 5









16732
26-Jan-22

SLNC GOODWILL / LOSS OF LIFE
(MISLE PIA 7025153 AND MISLE IIA 7025155)

OFFICER IN CHARGE, MARINE INSPECTION, MISLE ENDORSEMENT

1. The record and report of the marine investigation conducted for this incident have been reviewed as documented below. The report, including its findings of fact, conclusions, and any recommendations are approved, subject to the comments provided here and documented in the subject MISLE Preliminary Investigations Activity (PIA) and MISLE Incident Investigation Activity (IIA).

(b) (6), (b) (7)(C) [Redacted]

(b) (6), (b) (7)(C) [Redacted]

- [Redacted] ○ [Redacted]
- [Redacted] ○ [Redacted]
- [Redacted] ○ [Redacted]
- [Redacted] ○ [Redacted]
- [Redacted] ○ [Redacted]
- [Redacted] ○ [Redacted]
- [Redacted] ○ [Redacted]

[Redacted]

- [Redacted] ○ [Redacted]
- [Redacted] ○ [Redacted]
- [Redacted] ○ [Redacted]
- [Redacted] ○ [Redacted]
- [Redacted] ○ [Redacted]
- [Redacted] ○ [Redacted]
- [Redacted] ○ [Redacted]
- [Redacted] ○ [Redacted]
- [Redacted] ○ [Redacted]
- [Redacted] ○ [Redacted]

(b) (6), (b) (7)(C)

3. Reviewing/Approving Official

Signature

(b) (4) (b) (4) (b) (4)

Executive Officer

(b) (4)

United States Coast Guard Photographic Evidence Index

MISLE Case # 1229748

ECN # 7025155 (b) (6), (b) (7)(C) 016

Photographer: (b) (6), (b) (7)(C)

Photograph Received by: (b) (6), (b) (7)(C)

Type of Camera:

Date: 07Aug20 Time:

File Type: JPG

File Name- Brief Description

IMG_0124 - Engine room alarm history

IMG_0125 - Engine room alarm history

IMG_0126 - Engine room alarm history

IMG_0127 - Engine room alarm history

Alterations: Enlarged

I certify the digital photograph reproduced on this identification sheet is a correct representation of events that I observed or of a scene with which I am familiar. Any alterations have been specifically identified above.

(b) (6), (b) (7)(C)

Enclosure: CG-16 page 1 of 1
Case# 1229748
ECN 7025155 (b) (6), (b) (7)(C) 016

United States Coast Guard Photographic Evidence Index

MISLE Case # 1229748

ECN # 7025155-^{(b) (6), (b) (7)(C)}024

Photographer: ^{(b) (6), (b) (7)(C)}

Photograph Received by: ^{(b) (6), (b) (7)(C)} ^{(b) (6), (b) (7)(C)}

Type of Camera:

Date: 07Aug20 Time:

File Type: JPG

File Name- Brief Description

IMG_0067 - damage to engine room overhead from flywheel debris

IMG_0068 - damage to engine room overhead from flywheel debris

IMG_0069 - damage to engine room bulkhead from flywheel debris

IMG_0114 - damage to engine room bulkhead from flywheel debris

Alterations: None

I certify the digital photograph reproduced on this identification sheet is a correct representation of events that I observed or of a scene with which I am familiar. Any alterations have been specifically identified above.

(b) (6), (b) (7)(C)

Enclosure: CG-24 page 1 of 1
Case# 1229748
ECN 7025155-^{(b) (6), (b) (7)(C)}024

United States Coast Guard Photographic Evidence Index

MISLE Case # 1229748

ECN # 7025155-^{(b) (6), (b) (7)(C)}018

Photographer: ^{(b) (6), (b) (7)(C)}

Photograph Received by: ^{(b) (6), (b) (7)(C)}

Type of Camera:

Date: 07Aug20 Time:

File Type: JPG

File Name- Brief Description

IMG_0042 - Debris on deck of machinery space in between DG#1 (on right) and DG#2 (on left)

IMG_0043 - Debris on deck of machinery space in between DG#1 (on right) and DG#2 (on left)

IMG_0044 - Debris on deck of machinery space in between DG#1 (on right) and DG#2 (on left)

IMG_0047 - Debris on deck of machinery space in between DG#1 (on right) and DG#2 (on left)

Alterations: None

I certify the digital photograph reproduced on this identification sheet is a correct representation of events that I observed or of a scene with which I am familiar. Any alterations have been specifically identified above.

(b) (6), (b) (7)(C)

Enclosure: CG-18 page 1 of 1
Case# 1229748
ECN 7025155-^{(b) (6), (b) (7)(C)}018

United States Coast Guard Photographic Evidence Index

MISLE Case # 1229748

ECN # 7025155-^{(b) (6), (b) (7)(C)}019

Photographer: ^{(b) (6), (b) (7)(C)}

Photograph Received by ^{(b) (6), (b) (7)(C)}

Type of Camera:

Date: 07Aug20 Time:

File Type: JPG

File Name- Brief Description

IMG_0045 - Close up on the side of DG#1; governor is hanging off of the engine

IMG_0049 - Close up of DG#1 at empty space where flywheel assembly was attached prior to casualty

IMG_0060 - DG#1, where flywheel assembly was located prior to incident

IMG_0065 - DG#1, where flywheel assembly was located prior to incident

IMG_0066 - Side of DG#1, covered removed and fuel rail shown

IMG_0074 - Other side of DG#1 and associated damage

Alterations: None

I certify the digital photograph reproduced on this identification sheet is a correct representation of events that I observed or of a scene with which I am familiar. Any alterations have been specifically identified above.

(b) (6), (b) (7)(C)

Enclosure: CG-19 page 1 of 1
Case# 1229748
ECN 7025155-^{(b) (6), (b) (7)(C)}019

United States Coast Guard Photographic Evidence Index

MISLE Case # 1229748

ECN # 7025155-^{(b) (6), (b) (7)(C)}020

Photographer: ^{(b) (6), (b) (7)(C)}

Photograph Received by ^{(b) (6), (b) (7)(C)}

Type of Camera:

Date: 07Aug20 Time:

File Type: JPG

File Name- Brief Description

IMG_0082 - Reference photo, side of DG#2 (undamaged) in left of photo

IMG_0083 - Reference photo, DG#2 (undamaged) flywheel assembly

IMG_0085 - Reference photo, DG#2 (undamaged) flywheel assembly

IMG_0099 - Reference photo, governor on DG#2 (undamaged)

Alterations: None

I certify the digital photograph reproduced on this identification sheet is a correct representation of events that I observed or of a scene with which I am familiar. Any alterations have been specifically identified above.

(b) (6), (b) (7)(C)

Enclosure: CG-20 page 1 of 1
Case# 1229748
ECN 7025155-^{(b) (6), (b) (7)(C)}020

United States Coast Guard Photographic Evidence Index

MISLE Case # 1229748

ECN # 7025155 (b) (6), (b) (7)(C) 017

Photographer: (b) (6), (b) (7)(C)

Photograph Received by (b) (6), (b) (7)(C)

Type of Camera:

Date: 07Aug20 Time:

File Type: JPG

File Name- Brief Description

IMG_0129 - Engine room logbook entries for 05Aug2020

IMG_0130 - Engine room logbook entries for 04Aug2020

IMG_0131 - Engine room logbook entries for 03Aug2020

IMG_0132 - Engine room logbook entries for 02Aug2020

IMG_0133 - Engine room logbook entries for 01Aug2020

IMG_0135 - Engine room logbook entries for 07Aug2020

Alterations: Enlarged

I certify the digital photograph reproduced on this identification sheet is a correct representation of events that I observed or of a scene with which I am familiar. Any alterations have been specifically identified above.

(b) (6), (b) (7)(C)

Enclosure: CG-17 page 1 of 1
Case# 1229748
ECN 7025155 (b) (6), (b) (7)(C) 017

United States Coast Guard Photographic Evidence Index

MISLE Case # 1229748

ECN # 7025155 (b) (6), (b) (7)(C) 022

Photographer: (b) (6), (b) (7)(C)

Photograph Received by: (b) (6), (b) (7)(C)

Type of Camera:

Date: 07Aug20 Time:

File Type: JPG

File Name- Brief Description

IMG_0208 - piece of flywheel located on deck between DG#1 and DG #2

IMG_0209 - same piece of flywheel as IMG_0208, different angle

IMG_0211 - same piece of flywheel as IMG_0208, different angle

Alterations: None

I certify the digital photograph reproduced on this identification sheet is a correct representation of events that I observed or of a scene with which I am familiar. Any alterations have been specifically identified above.

(b) (6), (b) (7)(C)

Enclosure: CG-22 page 1 of 1
Case# 1229748
ECN 7025155 (b) (6), (b) (7)(C) 022

United States Coast Guard Photographic Evidence Index

MISLE Case # 1229748

ECN # 7025155 (b) (6), (b) (7)(C) 021

Photographer: (b) (6), (b) (7)(C)

Photograph Received by: (b) (6), (b) (7)(C)

Type of Camera:

Date: 07Aug20 Time:

File Type: JPG

File Name- Brief Description

IMG_0161 - governor installed on DG#1 at time of casualty

IMG_0162 - governor installed on DG#1 at time of casualty

IMG_0163 - governor installed on DG#1 at time of casualty

IMG_0165 - data plate of governor installed on DG#1 at time of casualty

IMG_0184 - governor installed on DG#1 previously (left), governor installed at time of casualty (right)

IMG_0193 - governor installed on DG#1 previously (left), governor installed at time of casualty (right)

Alterations: None

I certify the digital photograph reproduced on this identification sheet is a correct representation of events that I observed or of a scene with which I am familiar. Any alterations have been specifically identified above.

(b) (6), (b) (7)(C)

Enclosure: CG-21 page 1 of 1
Case# 1229748
ECN 7025155 (b) (6), (b) (7)(C) 021

United States Coast Guard Photographic Evidence Sheet

MISLE Case # 1229748

Photographer: (b) (6), (b) (7)(C)

Type of Camera: unknown

Name of Electronic File: IMG_0214


Alterations: None

ECN # 7025155 (b) (6), (b) (7)(C) 023

Photograph Received by: (b) (6), (b) (7)(C)

Date: 07Aug20 Time:

Type of File: JPG



Description of Photograph:

Post-casualty depiction by Chief Engineer showing where he saw the 1AE at the time of the casualty. The position indicated that during the casualty, the 1AE was attempting to shut down the generator using the shut-off lever.

I certify the digital photograph reproduced on this identification sheet is a correct representation of events that I observed or of a scene with which I am familiar. Any alterations have been specifically identified above.

(b) (6), (b) (7)(C)

Enclosure: CG-23 Page: 1 of: 1

Case # 1229748

ECN # 7025155 (b) (6), (b) (7)(C) 023

WORK ORDER/SERVICE REQUISITION FORM

Ship Name : SLNC GOODWILL

WO/SR No : 8053518

Performed By : WO/Crew

Title : 651 MOTOR AGGREGATE 1 QUARTERLY SAFETY

SCHEDULING DATA

Scheduled : 07/07/2020

Event :

Completed : 07/13/2020 goodwill, 3ae

Canceled :

Next Due Date : 10/12/2020

Interval : 13 W

ADMINISTRATIVE DATA

Created By:goodwill,3ae

On :07/13/2020

Auth. By:

On :

Apprvd. By:

On :

Account No:

Project No:

Priority :B

Job Catg:ENGINE REPAIRS

Class Job No :

Sugg Vend:

Dept.: ENGINE

EQUIPMENT PARTICULARS

Name:651 MOTOR AGGREGATE 1

Class Equipment Name :

Class Eq Code:

Equip Code :NGOO0651

Manufacturer :

Model :

Serial No :

Size :

Type :

Equip. Location :

Criticality:C

SPACE PARTICULARS

RESOURCES & COST DATA

Estimated Cost : 0.00

Estimated Man-Hrs : 4

Std. Job Cost :

Actual. Man-Hrs : 2

Resource : 3RD ASST ENG , OILER

WO DESCRIPTION

DG ENGINE ROUTINE SAFETY CUTOUT CHECK

TASK: TEST ENGINE SAFETY ALARMS AND CUTOUTS

REFER TO ENGINE MANUFACTURE SERVICE MANUAL.

TEST LO LUBE OIL ALARM AND NOTE PRESSURE
TEST LO LUBE OIL TRIP AND NOTE PRESSURE
TEST HIGH JW TEMP ALARM AND NOTE TEMPERATURE
TEST HIGH JW TEMP TRIP AND NOTE TEMPERATURE
TEST OVERSPEED TRIP, NOTE RPM
IF FITTED TEST OIL MIST DETECTOR

RECORD IN LOGBOOK.

ALL REMARKS, DEFICIENCIES OR NOTEWORTHY COMMENTS SHALL BE REPORTED IN THE [FINDINGS] OF WO IN PMS OR FILED AS A DEDICATED ATTACHMENT.

ANY DEFICIENCIES NOTED REQUIRING ADDITIONAL ATTENTION, ARE SAFETY RELATED OR ARE BEYOND THE SCOPE OF NORMAL MAINTENANCE ACTIVITIES SHALL BE ENTERED INTO THE PMS WO/SR SYSTEM FOR PROCESSING.



WO FINDINGS

Engine alarm testing conducted 7/13/2020. Carried out as per PTSP and Manual.

Generator set to 2nd standby. Set to local.

Pressure testing conducted using Omicron OTE-P202 - calibrated 2 NOV 2019 Keppel Shipyard,
Temperature testing conducted using Omicron OTE-T700 - calibrated 13 FEB 2020 A.C.S.

EXP 2 DEC 2020
EXP 13 FEB 2021

Low LO alarm: 4.3 Bar on tester
Low LO Shutdown: 2.3 Bar on tester

CW H alarm: 91 on tester
CW H shutdown: 95 on tester

Overspeed trip not tested at this time.

Engine set back to normal operation, test run, all sat.

3 A/E T. Lloyd-Rees

Perform By:

Tested By:

Signature:

Designation:

JOB SAFETY ANALYSIS

JSA Required : NO

Use Template :

From: (b) (6), (b) (7)(C) USCG D14 (USA)
To: (b) (6), (b) (7)(C) USCG ACTIVITIES FAR EAS (USA)
Subject: RE: ROI - SLNC GOODWILL / Loss of Life, 05Aug20
Date: Friday, May 13, 2022 3:57:56 AM

Walt, returned to you....I think. Call if you didn't get it. Since you don't have any Safety Recs or Findings of concern, you can send directly to INV. D14 review complete. (b) (6), (b) (7)(C)

From: (b) (6), (b) (7)(C) USCG ACTIVITIES FAR EAS (USA) <(b) (6), (b) (7)(C)@uscg.mil>
Sent: Monday, May 9, 2022 6:06 PM
To: (b) (6), (b) (7)(C) CIV USCG D14 (USA) (b) (6), (b) (7)(C)@uscg.mil>
Subject: RE: ROI - SLNC GOODWILL / Loss of Life, 05Aug20

No problem sir. Just return it to me and I'll knock it out quick and resubmit. I forgot to resign the version I sent you, so it's no good anyway.

From: (b) (6), (b) (7)(C) USCG D14 (USA) (b) (6), (b) (7)(C)
Sent: Tuesday, May 10, 2022 11:20 AM
To: (b) (6), (b) (7)(C) USCG ACTIVITIES FAR EAS (USA) <(b) (6), (b) (7)(C)@uscg.mil>
Subject: RE: ROI - SLNC GOODWILL / Loss of Life, 05Aug20

Got it. My MISLE skills are poor at best, but I will try to remove and replace. Otherwise I'll return to you.

Great verbiage on post mortem.

From: (b) (6), (b) (7)(C) USCG ACTIVITIES FAR EAS (USA) <(b) (6), (b) (7)(C)@uscg.mil>
Sent: Monday, May 9, 2022 3:59 PM
To: (b) (6), (b) (7)(C) USCG D14 (USA) (b) (6), (b) (7)(C)@uscg.mil>
Subject: RE: ROI - SLNC GOODWILL / Loss of Life, 05Aug20

(b) (6), (b) (7)(C)

Thank you for the feedback, I have corrected the date and added the following paragraph to address your concern regarding post-mortem drug/alcohol testing:

"4.1.26. No toxicological analysis was conducted on the 3/AE by the Japanese medical facility that generated the "Report of Death of a U.S. Citizen or U.S. Non-Citizen National Abroad" regarding this fatality. As the body was embalmed prior to being transported back to the United States for burial, no further opportunity to conduct postmortem drug or alcohol testing was available."

Because I've transferred the activity, I'm unable to upload the revised ROI. Feel free to either transfer it back to me for correction or replace the old version with the updated (attached).

v/r

(b) (6), (b) (7)(C)

From: (b) (6), (b) (7)(C) (b) (6), (b) (7)(C) USCG D14 (USA) (b) (6), (b) (7)(C)@uscg.mil>

Sent: Tuesday, May 10, 2022 6:25 AM

To: (b) (6), (b) (7)(C) (b) (6), (b) (7)(C) USCG ACTIVITIES FAR EAS (USA) <(b) (6), (b) (7)(C)uscg.mil>

Subject: RE: ROI - SLNC GOODWILL / Loss of Life, 05Aug20

(b) (6), (b) (7)(C) I hate to bring this up, cause I hate doing yesterday's work again today.

But on the drug testing....all the crew tested (b) (7)(C), (b) (6) but no mention of autopsy toxicology. Are medical examiner's services even available in Japan for foreigners? During covid? Body returned to family and they object or won't cooperate?

Except for Honolulu and main Hawaiian islands which generally have fully staffed offices, America Samoa, CNMI, and Guam ME services are hit and miss; during COVID generally a miss. Not existent in Oceania. Bodies flown home (sometimes to Indonesia or PI) and many families won't cooperate.

If you spend more than 3-5 minutes on a sentence or two, fine. Otherwise leave paragraph as is.

(b) (6), (b) (7)(C)

From: (b) (6), (b) (7)(C) (b) (6), (b) (7)(C) USCG ACTIVITIES FAR EAS (USA) <(b) (6), (b) (7)(C)uscg.mil>

Sent: Friday, May 6, 2022 5:23 PM

To: (b) (6), (b) (7)(C) (b) (6), (b) (7)(C) USCG D14 (USA) (b) (6), (b) (7)(C)

Cc: (b) (6), (b) (7)(C) USCG D14 (USA) (b) (6), (b) (7)(C) >

Subject: RE: ROI - SLNC GOODWILL / Loss of Life, 05Aug20

(b) (6), (b) (7)(C)

Thank you sir. Good catch on the date, it should be "2020". I will correct when I'm back in the office on Monday, upload the corrected version in MISLE, and email you when that is done and case is ready to send to INV. Thanks for your time.

v/r

(b) (6), (b) (7)(C)

From: (b) (6), (b) (7)(C) A CIV USCG D14 (USA) (b) (6), (b) (7)(C)

Date: Saturday, May 07, 2022, 9:04 AM

To: (b) (6), (b) (7)(C) (b) (6), (b) (7)(C) USCG ACTIVITIES FAR EAS (USA) <(b) (6), (b) (7)(C)uscg.mil>

Cc: (b) (6), (b) (7)(C) USCG D14 (USA) (b) (6), (b) (7)(C)

Subject: RE: ROI - SLNC GOODWILL / Loss of Life, 05Aug20

(b) (6), (b) (7)(C) case looks great thx.

Over speed on DG1 due to newly installed governor that appears to have been stored incorrectly for 15 months (laid on side vs vertical). Safety system worked and shut down the first over speed event. Short interval and little risk assessment prior to the second restart. Over speed again, but this time safety systems failed. An under strengthened (likely during manufacturing) flywheel came apart as RPMs increased, and one piece struck 3rd Eng, killing him.

Para 4.1.24 – Alcohol Testing: thy missed 2 hr window for alcohol testing due to emergencies. Very good follow on sentence stating ‘no evidence was discovered (uncovered) during the investigation’. Nice.

One nit-pick at Para 4.4.12, check date and year in sentence 2....August 4th, 2021? Or should be August 4th 2020??

I’m ready to fwd to INV, let me know.

(b) (6), (b) (7)(C)

From: (b) (6), (b) (7)(C) (b) (6), (b) (7)(C) USCG ACTIVITIES FAR EAS (USA) <(b) (6), (b) (7)(C)@uscg.mil>
Sent: Friday, April 29, 2022 1:54 AM
To: (b) (6), (b) (7)(C) (b) (6), (b) (7)(C) USCG D14 (USA) <(b) (6), (b) (7)(C)@uscg.mil>
Cc: (b) (6), (b) (7)(C) USCG D14 (USA) (b) (6), (b) (7)(C)
USCG ACTIVITIES FAR EAS (USA) (b) (6), (b) (7)(C) USCG D14 (USA)
(b) (6), (b) (7)(C)
Subject: Re: ROI - SLNC GOODWILL / Loss of Life, 05Aug20

(b) (6), (b) (7)(C)

No sir, only a District level review and then forward on to HQ for completion.

Thank you.

v/r

(b) (6), (b) (7)(C)

From: (b) (6), (b) (7)(C) A CIV USCG D14 (USA) (b) (6), (b) (7)(C) >
Sent: Friday, April 29, 2022 3:00 AM
To: (b) (6), (b) (7)(C) (b) (6), (b) (7)(C) USCG ACTIVITIES FAR EAS (USA) <(b) (6), (b) (7)(C)@uscg.mil>
Cc: (b) (6), (b) (7)(C) USCG D14 (USA) (b) (6), (b) (7)(C)
USCG ACTIVITIES FAR EAS (USA) (b) (6), (b) (7)(C) USCG D14 (USA)
(b) (6), (b) (7)(C)
Subject: RE: ROI - SLNC GOODWILL / Loss of Life, 05Aug20

(b) (6), (b) (7)(C) we're committed to getting the GOODWILL case processed in the next couple of weeks.....printed and on my desk.

I ask that you double check MISLE/case work....do we owe you anything else?

(b) (6), (b) (7)(C)

From: (b) (6), (b) (7)(C) USCG D14 (USA) (b) (6), (b) (7)(C)
Sent: Monday, March 21, 2022 2:26 PM
To: (b) (6), (b) (7)(C) (b) (6), (b) (7)(C) USCG ACTIVITIES FAR EAS (USA) <(b) (6), (b) (7)(C)@uscg.mil>; (b) (6), (b) (7)(C) (b) (6), (b) (7)(C) USCG D14 (USA) (b) (6), (b) (7)(C)@uscg.mil>
Cc: (b) (6), (b) (7)(C) USCG ACTIVITIES FAR EAS (USA) (b) (6), (b) (7)(C) (b) (6), (b) (7)(C) USCG (USA) (b) (6), (b) (7)(C)
Subject: RE: ROI - SLNC GOODWILL / Loss of Life, 05Aug20

Aloha (b) (6), (b) (7)(C)

Thank you for the email, (b) (6), (b) (7)(C) will be the one reviewing at the District level. Will let you know if we have any comments, concerns or questions.

V/R,

(b) (6), (b) (7)(C)

D14 Prevention Inspections & Investigations
300 Ala Moana Blvd, 9th Floor
Honolulu, HI 96850-4982
Cell: (b) (6), (b) (7)(C)
Office: 808-535-3421

From: (b) (6), (b) (7)(C) (b) (6), (b) (7)(C) USCG ACTIVITIES FAR EAS (USA) <(b) (6), (b) (7)(C)@uscg.mil>
Sent: Monday, March 21, 2022 1:54 PM
To: (b) (6), (b) (7)(C) USCG D14 (USA) (b) (6), (b) (7)(C)
Cc: (b) (6), (b) (7)(C) USCG ACTIVITIES FAR EAS (USA) (b) (6), (b) (7)(C) (b) (6), (b) (7)(C) CAPT USCG (USA) (b) (6), (b) (7)(C)
Subject: ROI - SLNC GOODWILL / Loss of Life, 05Aug20

(b) (6), (b) (7)(C)

Good morning sir. For your visibility, the subject investigation has been reviewed and endorsed at the unit level and I have forwarded it on for review at the District level. The IIA# is 7025155 and a copy of the ROI has been saved in "Correspondence". Any questions, please don't hesitate to contact me.

Thank you for your time.

v/r

(b) (6), (b) (7)(C) [REDACTED]

Senior Investigating Officer
US Coast Guard Activities Far East
Yokota Air Base
Fussa-shi, Tokyo, Japan 197-0001

(b) (6), (b) (7)(C) [REDACTED]

DSN: 225-7833

Mobile: (b) (6), (b) (7)(C) [REDACTED]

[FEACT Marine Investigations \(uscg.mil\)](mailto:FEACT_Marine_Investigations@uscg.mil)

U.S. Department of
Homeland Security

United States
Coast Guard



Commanding Officer
United States Coast Guard
Activities Far East

Unit# 5073
APO, AP 96326-5073
Phone: 81-42-507-6545
Fax: 81-42-551-5571
Email: (b) (6), (b) (7)(C)

16732/011

**LOSS OF LIFE ABOARD THE SLNC GOODWILL (O.N. 1266919) WHILE
UNDERWAY IN THE SEA OF JAPAN ON AUGUST 05, 2020**

ENDORSEMENT BY THE OFFICER IN CHARGE, MARINE INSPECTION

The record and the report of the investigation convened for the subject casualty have been reviewed. The record and the report, including the findings of fact, analysis, conclusions, and recommendations are approved with no further comments. It is recommended that this marine casualty investigation be closed.

(b) (6), (b) (7)(C)

Officer in Charge, Marine Inspection

Enclosures: (1) Executive Summary
(2) Investigating Officer's Report



UNITED STATES COAST GUARD

**REPORT OF THE INVESTIGATION
INTO THE
LOSS OF LIFE ABOARD THE SLNC GOODWILL
(ON 1266919) WHILE UNDERWAY IN THE SEA
OF JAPAN ON AUGUST 05, 2020**



MISLE ACTIVITY NUMBER: 7025155



16732
March 14, 2022

**LOSS OF LIFE ABOARD THE SLNC GOODWILL (ON 1266919) WHILE UNDERWAY
IN THE SEA OF JAPAN ON AUGUST 05, 2020**

EXECUTIVE SUMMARY

On 05Aug20, the SLNC GOODWILL (ON 1266919) was underway en route to Busan, Republic of Korea. At approx. 1342 Japan Standard Time (Zulu +9), the #1 ship's service diesel generator (SSDG), hereafter referred to as DG#1, was being restarted following a change-out of the generator's governor; this restart was being conducted by the Chief Engineer (CE), 1st Assistant Engineer (1/AE), and 3rd Assistant Engineer (3/AE). The first attempt to restart DG #1 resulted in the rpms increasing to the point that the overspeed protection device tripped. The governor was visually examined for loose connections, leaks, or other signs of malfunction; none were identified. The overspeed protection device was reset and DG #1 was restarted a second time. Again, the rpms steadily increased, but this time the overspeed protection device didn't trip. The 1/AE quickly attempted to manually stop the engine at the governor, but was unsuccessful. While the 1/AE ran to the aft of the generator to manually activate the overspeed protection device, the generator's flywheel broke apart at high speed sending large sections of the component hurtling through the surrounding area. One such section struck the 3/AE, who was still standing in the vicinity of the engine at the time, in the neck and upper torso.

The vessel's Fire Team arrived on scene within minutes and transported the 3/AE to the vessel's hospital space. The Medical Officer supervised the treatment of the 3/AE along with support from other crewmembers as well as a shore-side medical advisory service. The 3/AE was semi-conscious during initial treatment, but later lost consciousness and died as a result of the injuries sustained from being struck by the flywheel section.

As a result of this investigation, the U.S. Coast Guard has determined that the initiating event for this casualty was a mechanical failure of the governor recently installed on DG #1. This failure resulted in an uncontrolled supply of fuel to the engine which in turn resulted in an uncontrolled increase of the engine's rpms. The overspeed protection device failed to trip and the rpms increased to the point that the flywheel fractured, fatally striking the 3/AE and damaging the vessel's electrical and propulsion control systems. The causal factors that contributed to this casualty include: (1) mechanical damage to internal components of the governor installed on DG #1, (2) improper storage of the governor, (3) failure to verify internal condition of the governor, (4) governor storage procedures and recommendations, (5) inability to confirm the governor's maintenance history, (6) improper recordkeeping of governor, (7) failure of the engine's overspeed protection device, (8) inadequate mechanical properties of DG #1 flywheel, (9) inadequate chemical composition of DG#1 flywheel, (10) no reasonable PPE exists to prevent loss of life, (11) inability to conduct visual teleconferencing during medical treatment, (12) significant damage to vessel's electrical generation/distribution system, and (13) significant damage to the vessel's propulsion control systems.



16732
March 14, 2022

LOSS OF LIFE ABOARD THE SLNC GOODWILL (ON 1266919) WHILE UNDERWAY IN THE SEA OF JAPAN ON AUGUST 05, 2020

INVESTIGATING OFFICER'S REPORT

1. Preliminary Statement

1.1. This marine casualty investigation was conducted and this report was submitted in accordance with Title 46, Code of Federal Regulations (CFR), Subpart 4.07, and under the authority of Title 46, United States Code (USC) Chapter 63.

1.2. No parties-in-interest were designated during the investigation.

1.3. No coordination or cooperation with the National Transportation Board, any foreign flag State Administration investigators, or other parties was provided during the investigation.

1.4. All times listed in this Report of Investigation are written in Japan Standard Time (Zulu +9), use a 24-hour format, and are approximate.

2. Vessel Involved in the Incident



Figure 1. Undated Photograph of SLNC GOODWILL

Official Name:	SLNC GOODWILL
Identification Number:	1266919
Flag:	United States
Vessel Class/Type/Sub-Type	Oil & Chemical Tank Ship
Build Year:	2008
Gross Tonnage:	30,241 GT ITC
Length:	580.4 Feet
Beam/Width:	105.6 Feet
Draft/Depth:	59.7 Feet
Main/Primary Propulsion:	Slow speed diesel (<300 rpm)
Owner:	NORD GOODWILL LLC Wilmington, DE
Operator:	Schuyler Line Navigation Co. Annapolis, MD

3. Deceased, Missing, and/or Injured Persons

Relationship to Vessel	Sex	Age	Status
Third Assistant Engineer (3/AE)	Male	23	Deceased

4. Findings of Fact

4.1. The Incident:

4.1.1. On July 31st, 2020, the oil and chemical tankship SLNC GOODWILL completed cargo operations and got underway from Guam bound for Busan, Republic of Korea.

4.1.2. While underway and conducting tank cleaning operations, diesel generator #1 (DG #1) began to "hunt". This meant that the rotational speed (rpms) of the engine were fluctuating and wouldn't remain consistent. When placed in idle, DG #1 shut down.

4.1.3. On August 4th, 2020, work had begun to replace the governor on DG #1. The crewmembers conducting the replacement were the Chief Engineer (C/E), First Assistant Engineer (1/AE), and Third Assistant Engineer (3/AE); the 3/AE was present for training purposes only.

4.1.4. During the replacement of the governor, two (02) pages of the manufacturer's manual were used as a reference, as well as the governor on DG #2 as a visual aid. The 1/AE had replaced governors on other vessels, but not on the SLNC GOODWILL.

4.1.5. On August 5th, 2020 at 1230, the replacement of the governor on DG #1 was resumed by the 1/AE and 3/AE; the C/E arrived later to be present for the final steps and testing the installation. Prior to finishing the installation, the governor was visually inspected for obvious signs of damage, water staining, or debris; no discrepancies were noted.

4.1.6. The governor's overspeed protection device and pneumatic shut off were tested by the C/E and 1/AE with the 3/AE present for training; no discrepancies were noted.

4.1.7. At 1335, DG #1 was started for the first time since replacing the governor. The engine rotations-per-minute (rpms) were unsteady, but continued to increase.

4.1.8. Shortly after starting DG #1, its overspeed protection device, or “overspeed trip”, activated and shut down the engine.

4.1.9. The C/E, 1/AE, and 3/AE visually inspected the governor installation to ensure fittings were secure and to check for obvious signs of a reason for the overspeed; none were found and the overspeed protection device was reset.

4.1.10. At 1339, DG #1 was restarted for the second time.

4.1.11. The rpms on DG #1 continued to increase again, but this time accompanied by an unfamiliar noise and vibration.

4.1.12. Neither the electrical nor mechanical overspeed protection device activated once the rpms exceed the set point of approx. 1,020; the rpms continued to increase.

4.1.13. The 1/AE attempted to manually engage the electrical and mechanical overspeed trip at the governor and start box, but neither activated to shut down the engine.




Figure 2. Representative installation location of governor and start box on an auxiliary diesel engine aboard SLNC GOODWILL.

4.1.14. The 1/AE quickly ran to the aft end of DG #1 to secure fuel oil to the engine.




Figure 3. Location of 1/AE while securing fuel oil to DG #1

4.1.15. The C/E yelled for everyone to move clear of DG #1.

4.1.16. At 1342, the flywheel on DG #1 broke apart into several fragments that were hurled throughout the generator space at a high rate of speed.

4.1.17. One large flywheel fragment struck the 3/AE, who was standing near the DG #1 governor, in the upper torso and neck; the impact caused significant blunt-force trauma and bleeding. The 3/AE was evacuated from the engine room and taken to the medical space where he received medical treatment for his injuries, but was unable to recover from the trauma. His death was recorded as having occurred at 1823; cause of death was listed as hemorrhagic shock.



Figure 4. Area where 3 A/E was standing at the time of the casualty

4.1.18. Other fragments of the flywheel struck piping that was vital to the vessel's electrical and propulsion systems to include air and cooling water distribution.



Figure 5. One area of damaged overhead/piping caused by a flywheel fragment

4.1.19. The vessel lost electrical power, main propulsion, and was adrift approx. 12 NM from the coast of Japan.

4.1.20. At 1402, the Master radioed to request a medical evacuation (medevac) of the 3/AE via helicopter (helo) and was given an estimated time of arrival by the Moji Coast Guard of 1730.

4.1.21. The engineering crew worked to restore power and propulsion to the vessel while the deck crew continued to provide medical treatment to the 3/AE.

4.1.22. At 1700, the Moji Coast Guard helo arrived on station and lowered personnel to the vessel. The 3/AE was transported out on deck and raised to the helicopter, then the remaining helo personnel were recovered and the helo returned to shore to continue medical treatment of the 3/AE.

4.1.23. By 1800, power and propulsion were restored to the vessel. It got underway and proceeded to Sasebo, Japan where it anchored.

4.1.24. No alcohol testing was conducted on any of the crew due to the extended medical response and engineering repairs being conducted. No evidence was discovered that suggests any person directly involved were under the influence of alcohol leading up to the casualty.

4.1.25. The entire crew, with the exception of the 3/AE, was subject to post-casualty DOT drug testing in accordance with 46 CFR 4.06; all results were (b) (6), (b) (7)(C)

4.1.26. No toxicological analysis was conducted on the 3/AE by the Japanese medical facility that generated the “Report of Death of a U.S. Citizen or U.S. Non-Citizen National Abroad” regarding this fatality. As the body was embalmed prior to being transported back to the United States for burial, no further opportunity to conduct post-mortem drug or alcohol testing was available.

4.2. Additional/Supporting Information:

4.2.1. The SLNC GOODWILL (ON 1266919) was a 580.4 ft, 30,241 GT chemical/tank ship of steel construction with a keel laid date of 21Nov2008. It had diesel direct propulsion on an oceans/SOLAS route owned by Nord Goodwill LLC and operated by Schuyler Line Navigation Company, LLC (SLNC). The vessel's initial COI was issued IAW MSP on 29Jan2016 (reflagged); most recent COI annual inspection was conducted remotely from 01 to 27Apr20 with 00 deficiencies noted and 00 outstanding.

4.2.2. The Third Assistant Engineer (3/AE), Trenton Lloyd-Rees, started employment with SLNC in October 2019 and had been assigned to the SLNC GOODWILL prior to this casualty.

4.2.3. The Chief Engineer (C/E), (b) (6), (b) (7)(C) (b) (6), (b) (7)(C) had been sailing since 2002. He had been employed by SLNC since November 2019; this was his third assignment aboard the SLNC GOODWILL.

4.2.4. The First Assistant Engineer (1/AE), (b) (6), (b) (7)(C) has been in the maritime industry since 1981. He was hired by SLNC in April 2016 and has only sailed on the SLNC GOODWILL since that time.

4.2.5. The Second Mate (2/M) and Medical Officer, (b) (6), (b) (7)(C) (b) (6), (b) (7)(C) had been sailing since 2004. He had completed two previous trips on another vessel owned by SLNC. This was his first assignment to the SLNC GOODWILL. He had completed Medical Officer training course three (03) times previously and had served in this position on other vessels.

4.2.6. The Master, (b) (6), (b) (7)(C) had been sailing as an officer since 2007. He had worked for SLNC since 2016 and had been the Master of the SLNC GOODWILL since 2018.

4.2.7. Electrical services for the SLNC GOODWILL were provided by three (03) auxiliary generating sets each with a MAN B&W - ZJMD 6L23/30H type prime mover rated to deliver 960 KW at 900 rpm.

4.2.8. Each of the vessel's generators was equipped with a governor. The purpose of the governor was to regulate the flow of fuel to the engine in order to maintain a relatively constant speed, or rotations per minute (rpms), independent of the electrical load placed on the generator*.

*See Zhenjiang Marine Diesel Works Instruction Book L23/30H; Control and Safety systems, Automatics and Instruments.

4.2.9. The governor on DG #1's engine had an electronic and mechanical overspeed protection component set to activate and shut down the engine if the rpms exceeded approx. 1,020. The normal, designed operating speed was 900 rpms.

4.2.10. The manufacturers of the governor installed on DG #1, Woodward Inc., released instructions for the storage of mechanical-hydraulic controls (governors). These instructions included that oil meeting the US MIL-H-17672 should be used to coat the internal surfaces of the device and that they should be stored in an upright position.

4.2.11. On May 22nd, 2019, the governor installed on DG #1 prior to the casualty, Governor B (Part # 8520-0041, Serial # 15592175), was serviced in place by third party contractors licensed by the governor's manufacturing company.

4.2.12. That same day (May 22nd, 2019), another governor arrived onboard the vessel for use as a spare. It was a rebuilt governor, not brand new, and was not installed on any generator onboard the vessel prior to the DG #1 on August 4th, 2020. For the purposes of this investigation, that governor was designated as Governor C.



Figure 6. Governor C (right) was installed at the time of the casualty. Governor B (left) had been removed the day prior.

4.2.13. The data plate affixed to Governor C listed the same serial number and part number as the data plate affixed to Governor B. Despite this, the operating company believed the original serial number for Governor C was 16178255.

4.2.14. At some point, either during or after the overhaul of Governor C, mechanical damage was sustained to the surfaces of its valve bushing and shaft drive. There was no evidence available to determine exactly when/where the damage occurred.

4.2.15. On July 22nd, 2019, the governor installed on DG #2, Governor A (Part # 8521-0047DC, Serial # 14639129), was overhauled.

4.2.16. On December 26th, 2019, an annual test was conducted on the DG #1 governor under normal operating conditions. At the time of the test, the engine had 42,617 run

hours and the rebuild governor had 1,500 run hours. Oil levels, linkages, the fuel rack, and the speed sensor were all checked and a new micro-switch was installed on the electrical overspeed device. The next annual maintenance for the DG #1 generator was scheduled for December 24th, 2020.

4.2.17. On July 13th, 2020, a quarterly safety check was conducted on the DG #1. This check included alarm, pressure, and temperature testing; it did not include a test of the overspeed trip device. The next quarterly safety check was scheduled for October 12th, 2020.

4.2.18. On July 23rd, 2020, the 2,000 hour scheduled, preventative maintenance was conducted on DG #1. Included in the maintenance was a test of the governor's overspeed alarm, engine shut-downs, and replacing the oil in the governor; no deficiencies were noted during the DG #1 test run following preventative maintenance.

4.2.19. During the four (04) days leading up to the casualty, the C/E had worked 9.5 hours each day. The day prior to the casualty, he stopped work at 1830 and resumed at 0600 the day of.

4.2.20. During the four (04) days leading up to the casualty, the 1/AE had worked an average of forty (40) hours. The day prior to the casualty, he stopped work at 1830 and resumed at 0700 the day of.

4.2.21. During the four (04) days leading up to the casualty, the 3/AE worked 10.5 hours each day. The day of the casualty, he stopped work at 0000 and resumed at 1200.

4.2.22. Each generator was equipped with a flywheel that was mounted to the engine's crank shaft and designed to store the mechanical energy of the engine during power stroke and impart that stored energy to the preparatory strokes in an effort to keep shaft rotation uniform*.

4.2.23. The design specification requirement for the DG #21 flywheel was for grey cast iron of Grade C4 with an ultimate tensile strength of between 300-400 megapascals (MPa) and a Brinell hardness of between 200-250 HB.

4.2.24. The flywheel installed on DG #1 did not meet the design requirements of the engine licensor. After eight (08) post-casualty tests, the flywheel measured between 56%-64% of the required minimum strength and the hardness was, on average, 83% of the required minimum hardness.

4.2.25. Post-casualty analysis using a scanning electron microscope revealed the presence of micro-shrinkage voids in the area around the flywheel coupling. The term "micro-shrinkage voids" refers to conditions within a casting where small voids formed.

*See Principles of Naval Engineering: An Introduction to the Theory and Design of Engineering Equipment and Machinery Aboard Ship, ISBN: 9789-0-9825854-2-9

4.2.26. Post-casualty medical treatment received by the 3/AE while awaiting medical evacuation included the following: application of dressings/bandages, morphine injection (01), epinephrine injection (02), needle thoracotomy, nasopharyngeal airway, CPR, and application of an automated external defibrillator (AED; never advised to shock).

4.2.27. The mechanical portion of the DG #1 overspeed protection device was destroyed when the flywheel broke apart; no post-casualty inspection was done on the electrical overspeed protection component.

4.2.28. The vessel's crew administered medical treatment to the 3/AE while receiving consultation from a shore side medical alert service. There was no video-conferencing capability in the hospital space, the consulting was done by the crew describing the injuries, then the medical service advising on the appropriate treatment.

5. Analysis

5.1. *Mechanical Damage to Internal Components of the Governor.* Post-casualty analysis of the governor installed on DG #1 at the time of the casualty (Governor C) identified visible evidence of mechanical damage to the surfaces of the governor pilot valve bushing and shaft drive. The damage was deemed to be inconsistent with what would be expected following the break-up of the flywheel, which indicates that it was present prior to the casualty. Because both those internal components are involved with regulating the oil pressure in the governor, which in turn directly affects the amount of fuel supplied to DG #1, damage to either of them could have prevented an indication or response to an overspeed of DG #1. Had both of those components been operating as designed, the oil pressure and fuel supply should have remained within designed parameters and prevented DG #1 from an overspeed condition.

5.2. *Improper Storage of the Governor.* Governor C had been kept in storage onboard the vessel since May 2019. Either since that time or at some point after, the governor was drained of oil and not refilled. Additionally, despite being installed in a vertical position once placed in service, it was kept horizontally while in storage. Neither of these conditions of storage accurately reflect the conditions of use experienced when the governor is installed and operational, and could well result in some of the internal components not operating as designed either through an increased propensity for damage to or misalignment of internal components. Additionally, the manufacturer had storage instructions that specify the internal surfaces should be coated with oil that meets US MIL-H-17672 specification. Had Governor C been stored in a vertical position with the appropriate amount of oil it would have been in compliance with manufacturer's storage procedures, more accurately reflected the component's actual working conditions, and made them less likely to fail once the governor was installed.

5.3. *Failure to Verify the Internal Condition of the Governor.* After being kept in storage for over a year, being found in a horizontal position, and then realizing no oil was present in Governor C, there were no additional steps taken by the vessel's engineering crew to verify if its internal components were still fully operational. Even if

a year wouldn't be considered an excessively long time for a governor to sit in storage, either the fact that it was stored on its side or that there was no oil in it could have prompted someone to either open the governor and visually inspect the internal components or wait for the vessel to make port in Korea and have a third party technician confirm proper operation of the governor. Because the first option would require specific certifications, the second option would seem more plausible especially since the vessel had already sailed from Guam using Governor B. Had someone waited to verify the internal condition of Governor C, the material defects may have been found prior to it being used.

5.4. Inadequate Governor Storage Procedures and Recommendations. The governor manufacturer (Woodward) published Manual 25075 (Revision B, Mar2015) which detailed the storage procedures for mechanical-hydraulic controls. They also recommend their governors be kept in an upright position to keep the internal components in their proper positions and to prevent oil from leaking out of "breather holes" in the top of the assembly. It is unknown if Governor C was initially stored on its side, or if it fell over at some point later on. Also, it's unclear whether Governor C had oil originally that leaked out due to it being on its side, or if it never had oil after being overhauled. Either way, the result was the same: on the day it was retrieved for installation, Governor C was on its side and empty of oil. Had the storage procedures been followed fully and maintained during storage, that may have prevented damage to the internal components of Governor C and allowed it to function as designed.

5.5. Inability to Confirm the Governor's Maintenance History. All three (03) governors referenced in this incident were subject to preventative maintenance which included them being sent ashore to qualified technicians for overhaul, inspection, and repair. However, because the same part # and serial # were used for both Governor B and Governor C, this made it difficult to determine which one was being inspected. Had the data plates for Governor B and Governor C been maintained with the correct part # and serial #, it would have been obvious which one was being maintained and which one needed maintenance performed on it. Currently, there is no way to clearly identify whether it was Governor B or Governor C that was overhauled in May 2019, so it is possible that Governor C was well past its inspection interval and should not have been placed in service. Had the data plates been correct, it would have been clear to trace which governor was currently on maintenance schedule and should have been installed for use.

5.6. Improper Recordkeeping of Governor Information. Following the casualty, it was found that Governor B and Governor C, both installed on DG #1, had the same serial # and part # stamped on their data plates. Because the work completion report uses these numbers to identify which governor was overhauled, this error made it very difficult to determine whether or not both governors were actually overhauled and, if it was only one that was overhauled, which one it was. Had either someone on the 3rd party repair team or a crewmember/manager of the vessel noticed the mistaken numbers stamped on the data plate, they could have clarified the work done and condition of each governor and have a clear record for each.

5.7. Failure of the Engine's Overspeed Protection Device. DG #1 was equipped with an electrical and mechanical overspeed protection device, or "overspeed trip", which is a secondary safety measure designed to prevent an uncontrolled increase in engine rpms should the governor fail to operate as designed. In this specific instance, DG #1 normally operates at 900 rpms and the overspeed device is set to trip at 1,020 rpms. All evidence clearly indicates that the rpms on DG #1 exceeded 1,020 rpms, but the overspeed device failed to trip. Additionally, the overspeed device had operated as designed just prior to this casualty: the first attempt to start DG #1 resulted in increased rpms and the activation of the overspeed protection device. Whether it was reset incorrectly or experienced a mechanical failure that prevented it from activating is unknown and cannot be supported either way using the evidence provided. Either way, had the overspeed trip device worked as designed it would have prevented the uncontrolled increase in rpms.

5.8. Inadequate Mechanical Properties of DG #1's Flywheel. The engine licensor, MAN Energy Solutions SE, established design requirements for the flywheel that include an ultimate tensile strength of between 300MPa and 400MPa. Eight post-casualty tensile tests of flywheel fragments showed a range of results between 168 MPa and 194MPa; this is 56% to 64% of the required minimum strength. Additionally, microscopic inspection of the flywheel's bolt holes revealed areas of "micro-shrinkage", which are voids within the casting that can develop during the pour. These would have also reduced the flywheel's tensile strength because they induce planes of weakness and propagate cracking. Had the flywheel's tensile strength met at least the minimum requirements specified by the engine licensor, it is possible that the flywheel could have remained intact until either the 1/AE could have secured the fuel to DG #1 or, failing to secure DG #1, the crew could have had time to evacuate the space before it broke apart.

5.9. Inadequate Chemical Composition of DG #1's Flywheel. The engine licensor, MAN Energy Solutions SE, established design requirements for the flywheel that include a Brinell hardness of between 200HB and 250HB. Eight post-casualty tests of flywheel fragments found the hardness to be 167HB on average; this is 83% of the required minimum hardness. Had the flywheel's hardness met at least the minimum requirements specified by the engine licensor, it is possible that the flywheel could have remained intact until either the 1/AE could have secured the fuel to DG #1 or, failing to secure DG #1, the crew could have had time to evacuate the space before it broke apart.

5.10. No Reasonable Personal Protective Equipment Available. The 3/AE was standing in a position that should have been reasonably safe under routine operating conditions and was wearing all the applicable personal protective equipment (PPE) for working in the vessel's engine room. Once the flywheel broke apart, there was no time to react, nor any PPE normally worn in that environment that could have reasonably prevented the 3/AE from sustaining the injury that ultimately led to his death.

5.11. Inability to Conduct Visual Teleconferencing During Medical Treatment. During interview, the 2/M stated that he had served on at least one other vessel that had the ability to conduct video teleconferencing in its medical space. However, the SLNC

GOODWILL was not equipped with that capability. As a result, a crewmember was required to describe the injury, sometimes while actively applying medical treatment, to a shore side medical support service who was then required to visualize the description and attempt to offer the appropriate treatment option. If the vessel was able to dial up the same medical personnel and have them watching the treatment and see the extent of the injuries, it may have led to more timely recommendations/advice and active feedback during more technical medical treatment that was performed during this casualty such as use of a nasopharyngeal airway, intravenous injection, and needle thoracotomy.

5.12. *Significant Damage to the Vessel's Electrical Generation and Distribution System.* When the flywheel on DG #1 broke apart violently, the fragments caused significant damage to multiple systems within the vessel's engine room to include control, water supply, air supply, and electrical distribution. There was no reasonable defense that could have been used to prevent the fragments from causing this damage which subsequently resulted in a loss of power until repairs could be made.

5.13. *Significant Damage to the Vessel's Propulsion Control Systems.* When the flywheel on DG #1 broke apart violently, the fragments caused significant damage to multiple systems within the vessel's generator room to include control, water supply, air supply, and electrical distribution. All of these systems are necessary in order to maintain operation of the main diesel engine. There was no reasonable defense that could have been used to prevent the fragments from causing this damage which directly resulted in a loss of propulsion until repairs could be made.

6. Conclusions

6.1. Cause of the Casualty:

6.1.1. The initiating event for this casualty occurred when the governor installed on DG #1 at the time of the casualty (Governor C) failed to operate as designed, providing improper fuel regulation to DG #1. Actions and conditions which contributed to this failure were:

6.1.1.1. Mechanical damage found on some internal components of Governor C, specifically the pilot valve bushing and shaft drive, that were inconsistent with damage expected following the fracture of the flywheel. Had those internal components been undamaged and operating as designed, the oil pressure and fuel supply would have remained within designed parameters and prevented DG #1 from an overspeed condition.

6.1.1.2. Governor C being stored without oil and in a horizontal position for approximately 15 months. Had it been stored in a vertical position with the appropriate amount of oil, Governor C would have been in compliance with the manufacturer's storage procedures, more accurately reflected the component's actual working conditions, and made internal components less likely to fail once the governor was installed.

6.1.1.3. Duplicated information on the data plates for both Governor B and Governor C following their latest overhaul. Had a technician or crewmember noticed the mistaken numbers stamped on the data plate, they could have clarified the work done and condition of each governor.

6.1.1.4. Failure to follow the governor manufacturer's guidance on storage of Governor C, which stated it was to be stored with oil and in a vertical position. Had the manufacturer's guidance been followed, Governor C would have been less susceptible to damage and any oil wouldn't have been able to drain out of "breather holes" located on the governor housing.

6.1.1.5. Ambiguity between the maintenance history of Governor B and Governor C due to the duplication of their Part Number and Serial Number. Had the data plates contained the correct information, it would have been clear to trace which governor was currently on maintenance schedule and should have been installed for use.

6.1.1.6. A failure of the vessel's crew to recognize Governor C's inadequate storage condition and incorrect data plate information. Had a crewmember identified either of those inconsistencies, they could have either verified the internal condition of Governor C or waited until arriving at their next port of call and had a technician inspect the internal components.

6.1.2. As DG #1 received excessive fuel, the overspeed protection device failed to activate and secure the engine in order to prevent the engine's rpms from increasing beyond normal, and then designed, operating speed. Causal factors contributing to this were:

6.1.2.1. Due to the mechanical component of the overspeed protection being destroyed in the casualty and the lack of post-casualty testing on the electrical component, it is inconclusive as to the exact cause of the overspeed protection device failure.

6.1.3. The failure of Governor C to prevent an overspeed condition resulted in the next event, which was the breaking apart of the flywheel on DG #1 and those fragments hurling through the engine room space at a high rate of speed. Causal factors contributing to this were:

6.1.3.1. The inadequate mechanical properties contained in DG #1's flywheel. Had its tensile strength met at least the minimum requirements specified by the engine licensor and the "micro-shrinkage" voids weren't present, it is possible the flywheel could have remained intact until DG #1 had been secured or until all crewmembers had time to evacuate the space.

6.1.3.2. The inadequate chemical composition of DG #1's flywheel. Had its hardness met at least the minimum requirements specified by the engine licensor, it is possible the flywheel could have remained intact until DG #1 had been secured or until all crewmembers had time to evacuate the space.

6.1.4 The flywheel being broken apart resulted in the next event, which was the 3 A/E being violently struck by one of the flywheel fragments. The trauma sustained by this impact ultimately resulted in the death of the 3 A/E with the cause of death listed as hemorrhagic shock. Causal factors contributing to this were:

6.1.4.1. No reasonable personal protective measures exist for this specific scenario. Once the flywheel broke apart, there was no time to react nor any personal protective equipment normally worn in that environment that could have reasonably prevented the 3 A/E from sustaining the injury that resulted in his death.

6.1.4.2. The inability to conduct visual teleconferencing during medical treatment. Understanding that there are many challenges with enabling this capability, had the professional medical service been able to see the condition of the 3 A/E and the effects of his treatment in real time for themselves it would have facilitated more timely and better-informed recommendations and allowed for active feedback during the more technical medical treatment being administered by the vessel's crew.

6.1.5. The flywheel being broken apart resulted in damage sustained to the vessel's electrical generation and distribution system, which in turn caused the vessel to lose electrical power. Causal factors contributing to this were:

6.1.5.1. There was no design or construction feature in place at the time that could have prevented the damage sustained to the generator's control systems or distribution cabling.

6.1.6. The flywheel being broken apart resulted in additional damage sustained to the vessel's propulsion support systems, which in turn caused the vessel to lose propulsion. Causal factors contributing to this were:

6.1.6.1. There was no design or construction feature in place at the time that could have prevented the damage sustained to the control and support systems that provided the vessel's propulsion.

6.2. Evidence of Act(s) or Violation(s) of Law by Any Coast Guard Credentialed Mariner Subject to Action Under 46 USC Chapter 77: There were no acts of misconduct, incompetence, negligence, unskillfulness, or violation of law by a credentialed mariner identified as part of this investigation.

6.3. Evidence of Act(s) or Violation(s) of Law by U.S. Coast Guard Personnel, or any other person: No evidence of acts or violations of law by U.S. Coast Guard Personnel or any other person was identified.

6.4. Evidence of Act(s) Subject to Civil Penalty: No evidence of acts subject to Civil Penalty were identified.

6.5. Evidence of Criminal Act(s): No evidence of criminal acts were identified.

6.6. Need for New or Amended U.S. Law or Regulation: No need for new or amended U.S. law or regulation was identified.

6.7. Unsafe Actions or Conditions that Were Not Causal Factors:

6.7.1. Although not identified as a causal factor, the decision to restart DG #1 within a relatively brief period of time after the overspeed device activated could be considered an unsafe action. Because of the technical nature of the governor installation, there are multiple conditions that could have contributed to the overspeed device activating and several obvious ones, such as leaks and fittings, were visually checked prior to the restart. However, if there was a more comprehensive checklist of steps to take and items to verify in the event an overspeed device trips during a governor installation, this would then help standardize the process and require additional attention and time to identify potential causes and allow for corrective action prior to restarting.

7. Actions Taken Since the Incident

7.1. There are no actions taken since the incident to include in this report.

8. Recommendations

8.1. Safety Recommendation:

8.1.1. There are no Safety Recommendations submitted with this report.

8.2. Administrative Recommendations:

8.2.1. Recommend the investigation into this casualty be closed.

(b) (6), (b) (7)(C)

(b) (6), (b) (7)(C) J.S. Coast Guard
Senior Investigating Officer



UNITED STATES COAST GUARD

**REPORT OF THE INVESTIGATION
INTO THE
LOSS OF LIFE ABOARD THE SLNC GOODWILL
(ON 1266919) WHILE UNDERWAY IN THE SEA
OF JAPAN ON AUGUST 05, 2020**



U.S. Department of
Homeland Security

United States
Coast Guard



Commanding Officer
United States Coast Guard
Activities Far East

Unit# 5073
APO, AP 96326-5073
Phone: 81-42-507-6545
Fax: 81-42-551-5571
Email: (b) (6), (b) (7)(C)

16732/011

**LOSS OF LIFE ABOARD THE SLNC GOODWILL (O.N. 1266919) WHILE
UNDERWAY IN THE SEA OF JAPAN ON AUGUST 05, 2020**

ENDORSEMENT BY THE OFFICER IN CHARGE, MARINE INSPECTION

The record and the report of the investigation convened for the subject casualty have been reviewed. The record and the report, including the findings of fact, analysis, conclusions, and recommendations are approved with no further comments. It is recommended that this marine casualty investigation be closed.

(b) (6), (b) (7)(C)

(b) (6), (b) (7)(C)

Officer in Charge, Marine Inspection

Enclosures: (1) Executive Summary
(2) Investigating Officer's Report



16732
March 14, 2022

LOSS OF LIFE ABOARD THE SLNC GOODWILL (ON 1266919) WHILE UNDERWAY IN THE SEA OF JAPAN ON AUGUST 05, 2020

EXECUTIVE SUMMARY

On 05Aug20, the SLNC GOODWILL (ON 1266919) was underway en route to Busan, Republic of Korea. At approx. 1342 Japan Standard Time (Zulu +9), the #1 ship's service diesel generator (SSDG), hereafter referred to as DG#1, was being restarted following a change-out of the generator's governor; this restart was being conducted by the Chief Engineer (CE), 1st Assistant Engineer (1/AE), and 3rd Assistant Engineer (3/AE). The first attempt to restart DG #1 resulted in the rpms increasing to the point that the overspeed protection device tripped. The governor was visually examined for loose connections, leaks, or other signs of malfunction; none were identified. The overspeed protection device was reset and DG #1 was restarted a second time. Again, the rpms steadily increased, but this time the overspeed protection device didn't trip. The 1/AE quickly attempted to manually stop the engine at the governor, but was unsuccessful. While the 1/AE ran to the aft of the generator to manually activate the overspeed protection device, the generator's flywheel broke apart at high speed sending large sections of the component hurtling through the surrounding area. One such section struck the 3/AE, who was still standing in the vicinity of the engine at the time, in the neck and upper torso.

The vessel's Fire Team arrived on scene within minutes and transported the 3/AE to the vessel's hospital space. The Medical Officer supervised the treatment of the 3/AE along with support from other crewmembers as well as a shore-side medical advisory service. The 3/AE was semi-conscious during initial treatment, but later lost consciousness and died as a result of the injuries sustained from being struck by the flywheel section.

As a result of this investigation, the U.S. Coast Guard has determined that the initiating event for this casualty was a mechanical failure of the governor recently installed on DG #1. This failure resulted in an uncontrolled supply of fuel to the engine which in turn resulted in an uncontrolled increase of the engine's rpms. The overspeed protection device failed to trip and the rpms increased to the point that the flywheel fractured, fatally striking the 3/AE and damaging the vessel's electrical and propulsion control systems. The causal factors that contributed to this casualty include: (1) mechanical damage to internal components of the governor installed on DG #1, (2) improper storage of the governor, (3) failure to verify internal condition of the governor, (4) governor storage procedures and recommendations, (5) inability to confirm the governor's maintenance history, (6) improper recordkeeping of governor, (7) failure of the engine's overspeed protection device, (8) inadequate mechanical properties of DG #1 flywheel, (9) inadequate chemical composition of DG#1 flywheel, (10) no reasonable PPE exists to prevent loss of life, (11) inability to conduct visual teleconferencing during medical treatment, (12) significant damage to vessel's electrical generation/distribution system, and (13) significant damage to the vessel's propulsion control systems.



16732
March 14, 2022

LOSS OF LIFE ABOARD THE SLNC GOODWILL (ON 1266919) WHILE UNDERWAY IN THE SEA OF JAPAN ON AUGUST 05, 2020

INVESTIGATING OFFICER'S REPORT

1. Preliminary Statement

1.1. This marine casualty investigation was conducted and this report was submitted in accordance with Title 46, Code of Federal Regulations (CFR), Subpart 4.07, and under the authority of Title 46, United States Code (USC) Chapter 63.

1.2. No parties-in-interest were designated during the investigation.

1.3. No coordination or cooperation with the National Transportation Board, any foreign flag State Administration investigators, or other parties was provided during the investigation.

1.4. All times listed in this Report of Investigation are written in Japan Standard Time (Zulu +9), use a 24-hour format, and are approximate.

2. Vessel Involved in the Incident



Figure 1. Undated Photograph of SLNC GOODWILL

Official Name:	SLNC GOODWILL
Identification Number:	1266919
Flag:	United States
Vessel Class/Type/Sub-Type	Oil & Chemical Tank Ship
Build Year:	2008
Gross Tonnage:	30,241 GT ITC
Length:	580.4 Feet
Beam/Width:	105.6 Feet
Draft/Depth:	59.7 Feet
Main/Primary Propulsion:	Slow speed diesel (<300 rpm)
Owner:	NORD GOODWILL LLC Wilmington, DE
Operator:	Schuyler Line Navigation Co. Annapolis, MD

3. Deceased, Missing, and/or Injured Persons

Relationship to Vessel	Sex	Age	Status
Third Assistant Engineer (3/AE)	Male	23	Deceased

4. Findings of Fact

4.1. The Incident:

4.1.1. On July 31st, 2020, the oil and chemical tankship SLNC GOODWILL completed cargo operations and got underway from Guam bound for Busan, Republic of Korea.

4.1.2. While underway and conducting tank cleaning operations, diesel generator #1 (DG #1) began to "hunt". This meant that the rotational speed (rpms) of the engine were fluctuating and wouldn't remain consistent. When placed in idle, DG #1 shut down.

4.1.3. On August 4th, 2020, work had begun to replace the governor on DG #1. The crewmembers conducting the replacement were the Chief Engineer (C/E), First Assistant Engineer (1/AE), and Third Assistant Engineer (3/AE); the 3/AE was present for training purposes only.

4.1.4. During the replacement of the governor, two (02) pages of the manufacturer's manual were used as a reference, as well as the governor on DG #2 as a visual aid. The 1/AE had replaced governors on other vessels, but not on the SLNC GOODWILL.

4.1.5. On August 5th, 2020 at 1230, the replacement of the governor on DG #1 was resumed by the 1/AE and 3/AE; the C/E arrived later to be present for the final steps and testing the installation. Prior to finishing the installation, the governor was visually inspected for obvious signs of damage, water staining, or debris; no discrepancies were noted.

4.1.6. The governor's overspeed protection device and pneumatic shut off were tested by the C/E and 1/AE with the 3/AE present for training; no discrepancies were noted.

4.1.7. At 1335, DG #1 was started for the first time since replacing the governor. The engine rotations-per-minute (rpms) were unsteady, but continued to increase.

4.1.8. Shortly after starting DG #1, its overspeed protection device, or "overspeed trip", activated and shut down the engine.

4.1.9. The C/E, 1/AE, and 3/AE visually inspected the governor installation to ensure fittings were secure and to check for obvious signs of a reason for the overspeed; none were found and the overspeed protection device was reset.

4.1.10. At 1339, DG #1 was restarted for the second time.

4.1.11. The rpms on DG #1 continued to increase again, but this time accompanied by an unfamiliar noise and vibration.

4.1.12. Neither the electrical nor mechanical overspeed protection device activated once the rpms exceed the set point of approx. 1,020; the rpms continued to increase.

4.1.13. The 1/AE attempted to manually engage the electrical and mechanical overspeed trip at the governor and start box, but neither activated to shut down the engine.




Figure 2. Representative installation location of governor and start box on an auxiliary diesel engine aboard SLNC GOODWILL.

4.1.14. The 1/AE quickly ran to the aft end of DG #1 to secure fuel oil to the engine.




Figure 3. Location of 1/AE while securing fuel oil to DG #1

4.1.15. The C/E yelled for everyone to move clear of DG #1.

4.1.16. At 1342, the flywheel on DG #1 broke apart into several fragments that were hurled throughout the generator space at a high rate of speed.

4.1.17. One large flywheel fragment struck the 3/AE, who was standing near the DG #1 governor, in the upper torso and neck; the impact caused significant blunt-force trauma and bleeding. The 3/AE was evacuated from the engine room and taken to the medical space where he received medical treatment for his injuries, but was unable to recover from the trauma. His death was recorded as having occurred at 1823; cause of death was listed as hemorrhagic shock.



Figure 4. Area where 3 A/E was standing at the time of the casualty

4.1.18. Other fragments of the flywheel struck piping that was vital to the vessel's electrical and propulsion systems to include air and cooling water distribution.



Figure 5. One area of damaged overhead/piping caused by a flywheel fragment

4.1.19. The vessel lost electrical power, main propulsion, and was adrift approx. 12 NM from the coast of Japan.

4.1.20. At 1402, the Master radioed to request a medical evacuation (medevac) of the 3/AE via helicopter (helo) and was given an estimated time of arrival by the Moji Coast Guard of 1730.

4.1.21. The engineering crew worked to restore power and propulsion to the vessel while the deck crew continued to provide medical treatment to the 3/AE.

4.1.22. At 1700, the Moji Coast Guard helo arrived on station and lowered personnel to the vessel. The 3/AE was transported out on deck and raised to the helicopter, then the remaining helo personnel were recovered and the helo returned to shore to continue medical treatment of the 3/AE.

4.1.23. By 1800, power and propulsion were restored to the vessel. It got underway and proceeded to Sasebo, Japan where it anchored.

4.1.24. No alcohol testing was conducted on any of the crew due to the extended medical response and engineering repairs being conducted. No evidence was discovered that suggests any person directly involved were under the influence of alcohol leading up to the casualty.

4.1.25. The entire crew, with the exception of the 3/AE, was subject to post-casualty DOT drug testing in accordance with 46 CFR 4.06; all results were [REDACTED].

4.1.26. No toxicological analysis was conducted on the 3/AE by the Japanese medical facility that generated the “Report of Death of a U.S. Citizen or U.S. Non-Citizen National Abroad” regarding this fatality. As the body was embalmed prior to being transported back to the United States for burial, no further opportunity to conduct post-mortem drug or alcohol testing was available.

4.2. Additional/Supporting Information:

4.2.1. The SLNC GOODWILL (ON 1266919) was a 580.4 ft, 30,241 GT chemical/tank ship of steel construction with a keel laid date of 21Nov2008. It had diesel direct propulsion on an oceans/SOLAS route owned by Nord Goodwill LLC and operated by Schuyler Line Navigation Company, LLC (SLNC). The vessel's initial COI was issued IAW MSP on 29Jan2016 (reflagged); most recent COI annual inspection was conducted remotely from 01 to 27Apr20 with 00 deficiencies noted and 00 outstanding.

4.2.2. The Third Assistant Engineer (3/AE), Trenton Lloyd-Rees, started employment with SLNC in October 2019 and had been assigned to the SLNC GOODWILL prior to this casualty.

4.2.3. The Chief Engineer (C/E), [REDACTED], had been sailing since 2002. He had been employed by SLNC since November 2019; this was his third assignment aboard the SLNC GOODWILL.

4.2.4. The First Assistant Engineer (1/AE), [REDACTED], has been in the maritime industry since 1981. He was hired by SLNC in April 2016 and has only sailed on the SLNC GOODWILL since that time.

4.2.5. The Second Mate (2/M) and Medical Officer, [REDACTED], had been sailing since 2004. He had completed two previous trips on another vessel owned by SLNC. This was his first assignment to the SLNC GOODWILL. He had completed Medical Officer training course three (03) times previously and had served in this position on other vessels.

4.2.6. The Master, [REDACTED], had been sailing as an officer since 2007. He had worked for SLNC since 2016 and had been the Master of the SLNC GOODWILL since 2018.

4.2.7. Electrical services for the SLNC GOODWILL were provided by three (03) auxiliary generating sets each with a MAN B&W - ZJMD 6L23/30H type prime mover rated to deliver 960 KW at 900 rpm.

4.2.8. Each of the vessel's generators was equipped with a governor. The purpose of the governor was to regulate the flow of fuel to the engine in order to maintain a relatively constant speed, or rotations per minute (rpms), independent of the electrical load placed on the generator*.

*See Zhenjiang Marine Diesel Works Instruction Book L23/30H; Control and Safety systems, Automatics and Instruments.

4.2.9. The governor on DG #1's engine had an electronic and mechanical overspeed protection component set to activate and shut down the engine if the rpms exceeded approx. 1,020. The normal, designed operating speed was 900 rpms.

4.2.10. The manufacturers of the governor installed on DG #1, Woodward Inc., released instructions for the storage of mechanical-hydraulic controls (governors). These instructions included that oil meeting the US MIL-H-17672 should be used to coat the internal surfaces of the device and that they should be stored in an upright position.

4.2.11. On May 22nd, 2019, the governor installed on DG #1 prior to the casualty, Governor B (Part # 8520-0041, Serial # 15592175), was serviced in place by third party contractors licensed by the governor's manufacturing company.

4.2.12. That same day (May 22nd, 2019), another governor arrived onboard the vessel for use as a spare. It was a rebuilt governor, not brand new, and was not installed on any generator onboard the vessel prior to the DG #1 on August 4th, 2020. For the purposes of this investigation, that governor was designated as Governor C.



Figure 6. Governor C (right) was installed at the time of the casualty. Governor B (left) had been removed the day prior.

4.2.13. The data plate affixed to Governor C listed the same serial number and part number as the data plate affixed to Governor B. Despite this, the operating company believed the original serial number for Governor C was 16178255.

4.2.14. At some point, either during or after the overhaul of Governor C, mechanical damage was sustained to the surfaces of its valve bushing and shaft drive. There was no evidence available to determine exactly when/where the damage occurred.

4.2.15. On July 22nd, 2019, the governor installed on DG #2, Governor A (Part # 8521-0047DC, Serial # 14639129), was overhauled.

4.2.16. On December 26th, 2019, an annual test was conducted on the DG #1 governor under normal operating conditions. At the time of the test, the engine had 42,617 run

hours and the rebuild governor had 1,500 run hours. Oil levels, linkages, the fuel rack, and the speed sensor were all checked and a new micro-switch was installed on the electrical overspeed device. The next annual maintenance for the DG #1 generator was scheduled for December 24th, 2020.

4.2.17. On July 13th, 2020, a quarterly safety check was conducted on the DG #1. This check included alarm, pressure, and temperature testing; it did not include a test of the overspeed trip device. The next quarterly safety check was scheduled for October 12th, 2020.

4.2.18. On July 23rd, 2020, the 2,000 hour scheduled, preventative maintenance was conducted on DG #1. Included in the maintenance was a test of the governor's overspeed alarm, engine shut-downs, and replacing the oil in the governor; no deficiencies were noted during the DG #1 test run following preventative maintenance.

4.2.19. During the four (04) days leading up to the casualty, the C/E had worked 9.5 hours each day. The day prior to the casualty, he stopped work at 1830 and resumed at 0600 the day of.

4.2.20. During the four (04) days leading up to the casualty, the 1/AE had worked an average of forty (40) hours. The day prior to the casualty, he stopped work at 1830 and resumed at 0700 the day of.

4.2.21. During the four (04) days leading up to the casualty, the 3/AE worked 10.5 hours each day. The day of the casualty, he stopped work at 0000 and resumed at 1200.

4.2.22. Each generator was equipped with a flywheel that was mounted to the engine's crank shaft and designed to store the mechanical energy of the engine during power stroke and impart that stored energy to the preparatory strokes in an effort to keep shaft rotation uniform*.

4.2.23. The design specification requirement for the DG #21 flywheel was for grey cast iron of Grade C4 with an ultimate tensile strength of between 300-400 megapascals (MPa) and a Brinell hardness of between 200-250 HB.

4.2.24. The flywheel installed on DG #1 did not meet the design requirements of the engine licenser. After eight (08) post-casualty tests, the flywheel measured between 56%-64% of the required minimum strength and the hardness was, on average, 83% of the required minimum hardness.

4.2.25. Post-casualty analysis using a scanning electron microscope revealed the presence of micro-shrinkage voids in the area around the flywheel coupling. The term "micro-shrinkage voids" refers to conditions within a casting where small voids formed.

*See Principles of Naval Engineering: An Introduction to the Theory and Design of Engineering Equipment and Machinery Aboard Ship, ISBN: 9789-0-9825854-2-9

4.2.26. Post-casualty medical treatment received by the 3/AE while awaiting medical evacuation included the following: application of dressings/bandages, morphine injection (01), epinephrine injection (02), needle thoracotomy, nasopharyngeal airway, CPR, and application of an automated external defibrillator (AED; never advised to shock).

4.2.27. The mechanical portion of the DG #1 overspeed protection device was destroyed when the flywheel broke apart; no post-casualty inspection was done on the electrical overspeed protection component.

4.2.28. The vessel's crew administered medical treatment to the 3/AE while receiving consultation from a shore side medical alert service. There was no video-conferencing capability in the hospital space, the consulting was done by the crew describing the injuries, then the medial service advising on the appropriate treatment.

5. Analysis

5.1. *Mechanical Damage to Internal Components of the Governor.* Post-casualty analysis of the governor installed on DG #1 at the time of the casualty (Governor C) identified visible evidence of mechanical damage to the surfaces of the governor pilot valve bushing and shaft drive. The damage was deemed to be inconsistent with what would be expected following the break-up of the flywheel, which indicates that it was present prior to the casualty. Because both those internal components are involved with regulating the oil pressure in the governor, which in turn directly affects the amount of fuel supplied to DG #1, damage to either of them could have prevented an indication or response to an overspeed of DG #1. Had both of those components been operating as designed, the oil pressure and fuel supply should have remained within designed parameters and prevented DG #1 from an overspeed condition.

5.2. *Improper Storage of the Governor.* Governor C had been kept in storage onboard the vessel since May 2019. Either since that time or at some point after, the governor was drained of oil and not refilled. Additionally, despite being installed in a vertical position once placed in service, it was kept horizontally while in storage. Neither of these conditions of storage accurately reflect the conditions of use experienced when the governor is installed and operational, and could well result in some of the internal components not operating as designed either through an increased propensity for damage to or misalignment of internal components. Additionally, the manufacturer had storage instructions that specify the internal surfaces should be coated with oil that meets US MIL-H-17672 specification. Had Governor C been stored in a vertical position with the appropriate amount of oil it would have been in compliance with manufacturer's storage procedures, more accurately reflected the component's actual working conditions, and made them less likely to fail once the governor was installed.

5.3. *Failure to Verify the Internal Condition of the Governor.* After being kept in storage for over a year, being found in a horizontal position, and then realizing no oil was present in Governor C, there were no additional steps taken by the vessel's engineering crew to verify if its internal components were still fully operational. Even if

a year wouldn't be considered an excessively long time for a governor to sit in storage, either the fact that it was stored on its side or that there was no oil in it could have prompted someone to either open the governor and visually inspect the internal components or wait for the vessel to make port in Korea and have a third party technician confirm proper operation of the governor. Because the first option would require specific certifications, the second option would seem more plausible especially since the vessel had already sailed from Guam using Governor B. Had someone waited to verify the internal condition of Governor C, the material defects may have been found prior to it being used.

5.4. Inadequate Governor Storage Procedures and Recommendations. The governor manufacturer (Woodward) published Manual 25075 (Revision B, Mar2015) which detailed the storage procedures for mechanical-hydraulic controls. They also recommend their governors be kept in an upright position to keep the internal components in their proper positions and to prevent oil from leaking out of "breather holes" in the top of the assembly. It is unknown if Governor C was initially stored on its side, or if it fell over at some point later on. Also, it's unclear whether Governor C had oil originally that leaked out due to it being on its side, or if it never had oil after being overhauled. Either way, the result was the same: on the day it was retrieved for installation, Governor C was on its side and empty of oil. Had the storage procedures been followed fully and maintained during storage, that may have prevented damage to the internal components of Governor C and allowed it to function as designed.

5.5. Inability to Confirm the Governor's Maintenance History. All three (03) governors referenced in this incident were subject to preventative maintenance which included them being sent ashore to qualified technicians for overhaul, inspection, and repair. However, because the same part # and serial # were used for both Governor B and Governor C, this made it difficult to determine which one was being inspected. Had the data plates for Governor B and Governor C been maintained with the correct part # and serial #, it would have been obvious which one was being maintained and which one needed maintenance performed on it. Currently, there is no way to clearly identify whether it was Governor B or Governor C that was overhauled in May 2019, so it is possible that Governor C was well past its inspection interval and should not have been placed in service. Had the data plates been correct, it would have been clear to trace which governor was currently on maintenance schedule and should have been installed for use.

5.6. Improper Recordkeeping of Governor Information. Following the casualty, it was found that Governor B and Governor C, both installed on DG #1, had the same serial # and part # stamped on their data plates. Because the work completion report uses these numbers to identify which governor was overhauled, this error made it very difficult to determine whether or not both governors were actually overhauled and, if it was only one that was overhauled, which one it was. Had either someone on the 3rd party repair team or a crewmember/manager of the vessel noticed the mistaken numbers stamped on the data plate, they could have clarified the work done and condition of each governor and have a clear record for each.

5.7. Failure of the Engine's Overspeed Protection Device. DG #1 was equipped with an electrical and mechanical overspeed protection device, or "overspeed trip", which is a secondary safety measure designed to prevent an uncontrolled increase in engine rpms should the governor fail to operate as designed. In this specific instance, DG #1 normally operates at 900 rpms and the overspeed device is set to trip at 1,020 rpms. All evidence clearly indicates that the rpms on DG #1 exceeded 1,020 rpms, but the overspeed device failed to trip. Additionally, the overspeed device had operated as designed just prior to this casualty: the first attempt to start DG #1 resulted in increased rpms and the activation of the overspeed protection device. Whether it was reset incorrectly or experienced a mechanical failure that prevented it from activating is unknown and cannot be supported either way using the evidence provided. Either way, had the overspeed trip device worked as designed it would have prevented the uncontrolled increase in rpms.

5.8. Inadequate Mechanical Properties of DG #1's Flywheel. The engine licensor, MAN Energy Solutions SE, established design requirements for the flywheel that include an ultimate tensile strength of between 300MPa and 400MPa. Eight post-casualty tensile tests of flywheel fragments showed a range of results between 168 MPa and 194MPa; this is 56% to 64% of the required minimum strength. Additionally, microscopic inspection of the flywheel's bolt holes revealed areas of "micro-shrinkage", which are voids within the casting that can develop during the pour. These would have also reduced the flywheel's tensile strength because they induce planes of weakness and propagate cracking. Had the flywheel's tensile strength met at least the minimum requirements specified by the engine licensor, it is possible that the flywheel could have remained intact until either the 1/AE could have secured the fuel to DG #1 or, failing to secure DG #1, the crew could have had time to evacuate the space before it broke apart.

5.9. Inadequate Chemical Composition of DG #1's Flywheel. The engine licensor, MAN Energy Solutions SE, established design requirements for the flywheel that include a Brinell hardness of between 200HB and 250HB. Eight post-casualty tests of flywheel fragments found the hardness to be 167HB on average; this is 83% of the required minimum hardness. Had the flywheel's hardness met at least the minimum requirements specified by the engine licensor, it is possible that the flywheel could have remained intact until either the 1/AE could have secured the fuel to DG #1 or, failing to secure DG #1, the crew could have had time to evacuate the space before it broke apart.

5.10. No Reasonable Personal Protective Equipment Available. The 3/AE was standing in a position that should have been reasonably safe under routine operating conditions and was wearing all the applicable personal protective equipment (PPE) for working in the vessel's engine room. Once the flywheel broke apart, there was no time to react, nor any PPE normally worn in that environment that could have reasonably prevented the 3/AE from sustaining the injury that ultimately led to his death.

5.11. Inability to Conduct Visual Teleconferencing During Medical Treatment. During interview, the 2/M stated that he had served on at least one other vessel that had the ability to conduct video teleconferencing in its medical space. However, the SLNC

GOODWILL was not equipped with that capability. As a result, a crewmember was required to describe the injury, sometimes while actively applying medical treatment, to a shore side medical support service who was then required to visualize the description and attempt to offer the appropriate treatment option. If the vessel was able to dial up the same medical personnel and have them watching the treatment and see the extent of the injuries, it may have led to more timely recommendations/advice and active feedback during more technical medical treatment that was performed during this casualty such as use of a nasopharyngeal airway, intravenous injection, and needle thoracotomy.

5.12. *Significant Damage to the Vessel's Electrical Generation and Distribution System.* When the flywheel on DG #1 broke apart violently, the fragments caused significant damage to multiple systems within the vessel's engine room to include control, water supply, air supply, and electrical distribution. There was no reasonable defense that could have been used to prevent the fragments from causing this damage which subsequently resulted in a loss of power until repairs could be made.

5.13. *Significant Damage to the Vessel's Propulsion Control Systems.* When the flywheel on DG #1 broke apart violently, the fragments caused significant damage to multiple systems within the vessel's generator room to include control, water supply, air supply, and electrical distribution. All of these systems are necessary in order to maintain operation of the main diesel engine. There was no reasonable defense that could have been used to prevent the fragments from causing this damage which directly resulted in a loss of propulsion until repairs could be made.

6. Conclusions

6.1. Cause of the Casualty:

6.1.1. The initiating event for this casualty occurred when the governor installed on DG #1 at the time of the casualty (Governor C) failed to operate as designed, providing improper fuel regulation to DG #1. Actions and conditions which contributed to this failure were:

6.1.1.1. Mechanical damage found on some internal components of Governor C, specifically the pilot valve bushing and shaft drive, that were inconsistent with damage expected following the fracture of the flywheel. Had those internal components been undamaged and operating as designed, the oil pressure and fuel supply would have remained within designed parameters and prevented DG #1 from an overspeed condition.

6.1.1.2. Governor C being stored without oil and in a horizontal position for approximately 15 months. Had it been stored in a vertical position with the appropriate amount of oil, Governor C would have been in compliance with the manufacturer's storage procedures, more accurately reflected the component's actual working conditions, and made internal components less likely to fail once the governor was installed.

6.1.1.3. Duplicated information on the data plates for both Governor B and Governor C following their latest overhaul. Had a technician or crewmember noticed the mistaken numbers stamped on the data plate, they could have clarified the work done and condition of each governor.

6.1.1.4. Failure to follow the governor manufacturer's guidance on storage of Governor C, which stated it was to be stored with oil and in a vertical position. Had the manufacturer's guidance been followed, Governor C would have been less susceptible to damage and any oil wouldn't have been able to drain out of "breather holes" located on the governor housing.

6.1.1.5. Ambiguity between the maintenance history of Governor B and Governor C due to the duplication of their Part Number and Serial Number. Had the data plates contained the correct information, it would have been clear to trace which governor was currently on maintenance schedule and should have been installed for use.

6.1.1.6. A failure of the vessel's crew to recognize Governor C's inadequate storage condition and incorrect data plate information. Had a crewmember identified either of those inconsistencies, they could have either verified the internal condition of Governor C or waited until arriving at their next port of call and had a technician inspect the internal components.

6.1.2. As DG #1 received excessive fuel, the overspeed protection device failed to activate and secure the engine in order to prevent the engine's rpms from increasing beyond normal, and then designed, operating speed. Causal factors contributing to this were:

6.1.2.1. Due to the mechanical component of the overspeed protection being destroyed in the casualty and the lack of post-casualty testing on the electrical component, it is inconclusive as to the exact cause of the overspeed protection device failure.

6.1.3. The failure of Governor C to prevent an overspeed condition resulted in the next event, which was the breaking apart of the flywheel on DG #1 and those fragments hurling through the engine room space at a high rate of speed. Causal factors contributing to this were:

6.1.3.1. The inadequate mechanical properties contained in DG #1's flywheel. Had its tensile strength met at least the minimum requirements specified by the engine licensor and the "micro-shrinkage" voids weren't present, it is possible the flywheel could have remained intact until DG #1 had been secured or until all crewmembers had time to evacuate the space.

6.1.3.2. The inadequate chemical composition of DG #1's flywheel. Had its hardness met at least the minimum requirements specified by the engine licensor, it is possible the flywheel could have remained intact until DG #1 had been secured or until all crewmembers had time to evacuate the space.

6.1.4 The flywheel being broken apart resulted in the next event, which was the 3 A/E being violently struck by one of the flywheel fragments. The trauma sustained by this impact ultimately resulted in the death of the 3 A/E with the cause of death listed as hemorrhagic shock. Causal factors contributing to this were:

6.1.4.1. No reasonable personal protective measures exist for this specific scenario. Once the flywheel broke apart, there was no time to react nor any personal protective equipment normally worn in that environment that could have reasonably prevented the 3 A/E from sustaining the injury that resulted in his death.

6.1.4.2. The inability to conduct visual teleconferencing during medical treatment. Understanding that there are many challenges with enabling this capability, had the professional medical service been able to see the condition of the 3 A/E and the effects of his treatment in real time for themselves it would have facilitated more timely and better-informed recommendations and allowed for active feedback during the more technical medical treatment being administered by the vessel's crew.

6.1.5. The flywheel being broken apart resulted in damage sustained to the vessel's electrical generation and distribution system, which in turn caused the vessel to lose electrical power. Causal factors contributing to this were:

6.1.5.1. There was no design or construction feature in place at the time that could have prevented the damage sustained to the generator's control systems or distribution cabling.

6.1.6. The flywheel being broken apart resulted in additional damage sustained to the vessel's propulsion support systems, which in turn caused the vessel to lose propulsion. Causal factors contributing to this were:

6.1.6.1. There was no design or construction feature in place at the time that could have prevented the damage sustained to the control and support systems that provided the vessel's propulsion.

6.2. Evidence of Act(s) or Violation(s) of Law by Any Coast Guard Credentialed Mariner Subject to Action Under 46 USC Chapter 77: There were no acts of misconduct, incompetence, negligence, unskillfulness, or violation of law by a credentialed mariner identified as part of this investigation.

6.3. Evidence of Act(s) or Violation(s) of Law by U.S. Coast Guard Personnel, or any other person: No evidence of acts or violations of law by U.S. Coast Guard Personnel or any other person was identified.

6.4. Evidence of Act(s) Subject to Civil Penalty: No evidence of acts subject to Civil Penalty were identified.

6.5. Evidence of Criminal Act(s): No evidence of criminal acts were identified.

6.6. Need for New or Amended U.S. Law or Regulation: No need for new or amended U.S. law or regulation was identified.

6.7. Unsafe Actions or Conditions that Were Not Causal Factors:

6.7.1. Although not identified as a causal factor, the decision to restart DG #1 within a relatively brief period of time after the overspeed device activated could be considered an unsafe action. Because of the technical nature of the governor installation, there are multiple conditions that could have contributed to the overspeed device activating and several obvious ones, such as leaks and fittings, were visually checked prior to the restart. However, if there was a more comprehensive checklist of steps to take and items to verify in the event an overspeed device trips during a governor installation, this would then help standardize the process and require additional attention and time to identify potential causes and allow for corrective action prior to restarting.

7. Actions Taken Since the Incident

7.1. There are no actions taken since the incident to include in this report.

8. Recommendations

8.1. Safety Recommendation:

8.1.1. There are no Safety Recommendations submitted with this report.

8.2. Administrative Recommendations:

8.2.1. Recommend the investigation into this casualty be closed.



Lieutenant Commander, U.S. Coast Guard
Senior Investigating Officer

Generator Maintenance Rough Log

May 25th 2016 to current date

Gen 1

5/30 - Spinner filter cleaned

6/8- spinner filter done at 32158 hours, 1-2cm sludge built up on spinner

6/8 – on the 5th we had a high differential pressure alarm across the fuel strainers.

They were with clean filter found on the shelves in the purifier room. There are still two on standby along with two orings for the seal. The left filter had to bad studs, new ones were made out of 8mm bolts in the shop. All work done at 32158 hours.

6/9 – left lube oil cartridge filter done at 32158

6/9 – turbo wrap done at 32158

6/9 – water wash at 32158, 4-5 buckets of water were taken out and water was gray

6/14 – right side lube oil cartridge filter done at 32169

6/21 – left side lube oil cartridge filter done at 32211 (53 hours since last done)

6/21 – spinner done at 32212 54 hours since done last ½ cm of sludge built up

6/22 – performance test was taken at 32212 see folder for details. All pressures were very close

6/28 – shore crew came aboard and changed out the turbo charger at 32220

6/30- BOTH cartridge lube oil filters done at 32224

7/14 – spinner done at 32462, 3-4 cm of sludge built up (250 hours since last)

7/22/16- both cartridge filters done at 32539

7/25/16- lube oil temp. Thermostats were changed due to high lube oil temp. (around 73 degrees) after the new ones were put in the temp dropped to about 55-60 degrees depending on the generator load. The lube oil pressure was also bumped up to roughly 5.2 bar at 500ish kw. The two new tstats were taken from the store room. New ones are on order. Work done at 32550 hours

8/3 left side lube oil cartridge filter was done at 32718 hours

8/4 – turbo wrap done and turbo water wash done went through about 4 buckets of water, water was a little clearer than previous time , work done at 32719

8/5 spinner done at 32723, 261 hours since last done, 4 cm of sludge built up

8/15 spinner done at 32839, 116 hours since last done about 1cm of sludge built up

8/19 RIGHT side cartridge filter done at 32873, 334 hours since last done

8/29/16 spinner done at 32995, 156 since last done about 2 cm sludge built up

8/30 WATER WASH DONE ON TURBO, WENT THROUGH ABOUT 1.5 5 GAL BUCKETS OF WATER. WATER WAS VERY BLACK

9/2 left side cartridge filter done at 33041, 330 since last done

9/6 green oil filter was changed out at 33098, 3 new filter in steering gear store room

9/13 right side cartridge filter done at 33187 hrs.

9/21 turbo water wash done at 33317 hrs. Water was very black

9/27 cleaned spinner filter. 220 hours since last time. 3-4 cm of buildup, will reduce interval to 150 hours.

10/1 turbo wrap was replaced at 33489 hrs, 172 hrs since last. has to be done more frequently than the others due to exhaust leak.

10/8 water was done at 33495 hrs, 170 hrs since last. water was pretty black

10/25 replaced rectangular gasket on turbo the exhaust side of the turbo. No longer leaks exhaust gas.

11/2 right cartridge filter changed at 33756 hrs, 228 hrs since last time.

11/5 all injectors were replaced at 33738.

11/5 number 5 fuel pump was replaced

11/14 turbo water wash at 33800 hrs, 146 since last. water was black

11/14 cleaned spinner filter at 33800 hrs, 146 since last. 3 cm of buildup

11/23 left cartridge filter changed at 33941 hrs. left in standby

11/23 cleaned spinner filter at 33941 hrs, 141 since last. 3 cm of buildup

11/23 water wash at 33941 hrs, 141 since last. water was black

12/3 cleaned spinner filter at 34086 hrs, 145 since last. 3 cm of buildup

12/6 valve lash done at 34102 hrs.

12/13 spinner cleaned at 34216 hrs, 130 since last. 3 cm of buildup

12/13 water wash done at 34216 hrs, 126 since last.

12/24 left cartridge filter changed at 34437 hrs, 496 since last.

12/20 spinner cleaned at 34535 hrs, 134 since last. 3 cm of buildup

1/6 spinner cleaned at 34651 hrs, 116 since last. 3 cm of buildup

1/12 left cartridge filter done at 34708, last 245 hrs ago

1/18/17 spinner done at 34783

1/19 water wash done at 34785, 127 since last done 3 buckets of black water

1/30 spinner was done at 34920, was packed full of sludge, 137 hrs since

1/30 both cartridge filters were done at 34920

1/31 at 34920 lo sump was changed out with approx. 750L of new oil, the sump low level alarm was tested while draining and filling

2/3 water wash done at 34944

2/17 all done at 35073, right side cartridge filter

Spinner filter done 153 hour since last, about 2-3 cm of sludge built up, New Turbo wrap done

2/23 turbo wash done at 35123, about three buckets of dirty water ran through

3/1 work done at 35185, spinner done 3ish cm of sludge built up after 110 hours

Right side cartridge filter done

3/4 the rectangular exhaust gasket was replaced because the old one, we used two that were made on board and it seems to have fixed the leak, work done at 35187

3/6 work done at 35200, number 2 fuel pump (used blunger and bar) and 4 fuel pump (new plunger and bar) were changed in an attempt to rectify the high exhaust temps at 350-450 kw load. Number 2 cylinder came down but number 4 cylinder still goes high at full load. After Guam I will be checking the internals on number 5 fuel pump suspected of being the wrong gear tooth setting inside the pump

3/7 as a quick fix the number 4 fuel rack was adjusted roughly -1mm to deal with the high exhaust gas temp on the cylinder, I want to check the injector on this cylinder at the next available time and see if the popping pressure is off

3/18 – turbo wash done at 35262

3/21 – spinner done at 35294, about 3cm sludge was hard to get apart, done at 109 hours

3/25 – right side cartridge filter done at 35350

3/25 – spinner filter done at 35350 after 56 hours, about 1 cm sludge built up

4/1 – work done 39350 water wash done on turbo, 3 buckets of water ran through water start getting a little clearer on the last bucket

5/11/2017 - all fuel pumps and injectors were replaced at 35601

6/26- Generator 1 exhaust pipe to turbo charger gasket was replaced at 36047 hours.

8/3 – spinner filter done at 36472 about 150 hours on 2cm sludge built up

8/3 – left cartridge filter done at 36472

8/9 – turbo wash complete at 36472, after 400 ish hours, water was really bad

8/27/2017 – heads and connecting rods on number 5 and 6 cylinder were taken off. The connecting rods ovality were found to be out of spec. The piston rings were replaced along with all new orings and gaskets on the heads. 2 new injectors were also used

from the injector room. Refurbished heads were placed back on the generator and test ran. All work was done at 36500 hours

9/7 spinner done after 103 hours about 1.5 cm of sludge built up, work done at 36575

9/9 water wash done on turbo after about 110hrs, about 2 buckets of water ran through, work done at 36586

9/16 right side cartridge filter done after roughly 320 hours work done at 36644

9/22/17 spinner done after 104 hours, about 1 cm sludge built up, work done 36679

9/27 – spinner done after 100 hours 1.5cm of sludge built up, right side cartridge filter done after 138 hours, turbo water wash done on after 196 hours, 2 buckets of water ran through and was very dirty, turbo wrap also done after 270 hours, all work done at 36782

9/27/17 – start air pressure reducer was leaking air pretty badly, after generator was turned on. The reducer was taken out and a few of the orings were worn and replaced. It was tested after and no more air leaks. Work done 36782 hours, we have a new oring kit and a new diaphragm, along with an old bottom piston in a newly marked back in the generator cabinet, new rebuild kits are on order

10/9 turbo wash done after 50 hours, 3 buckets of water ran through still very dirty, spinner done after 50 hours, about .5 cm sludge build up, work done at 36832

10/24 alarm for jet assist is going off intermittently, can clear alarm and will go away. Usually comes back at change of load

11/2/17 spinner done at 36950

11/7 banjo fitting on fuel branch pipe cleaned and new copper gaskets. Rebuilt #4 injector with new nozzle and spring

11/8 cylinder head swap on cylinder 4. Reason for doing: with new injector the exh temp was still at alarm point. Used head rebuilt by 1A/E. Piston was not removed per order of the C/E because we do not have a new conrod to replace if bad. Top of piston cleaned as best as possible with piston in place. The inboard forward cylinder head stud required extra attention when removing, but was due to dirty threads on stud. After soaking penetrant on nut/threads the bolt became free. All studs were cleaned and looked satisfactory. New flame ring and head gasket used. New o-rings on jumpers, push rod protecting tube and coolant. New exhaust manifold gasket.

11/14/17 water wash turbo 2 gal until clean. Work done at 36978

11/15/17 Left side cartridge filter done at 37000

11/16/17 right side cartridge filter done at 37010 running on right side now

11/25/17 water wash turbo 3 gal until clean. Work done at 37100

11/26/17 replace o-ring on after part of knife edge filter. The previous person to do this job had used 2 o-rings.

11/30/17 Spinner done at 37145.

12/2/17 right side cartridge filter done at 37148

1/5/18 LEFT SIDE FILTER DONE 37289

1/6/18 SPINNER DONE AT 37289

1/6/18 WATER WASH 37289

1/25/18 spinner done at 37370

1/31/18 right cartridge filter done

2/2/18 spinner done at 37480, about 2 cm sludge built up after 110 hours

2/4 right filter done at 37507

2/8 water wash on exhaust side of the turbo 6 dirty buckets of water ran through work done at 37508 after 219 hours

2/14 spinner done after 76 hours about 1 cm sludge built up work done 37556 hours

Turbo wrap changed

3/2 work done at 37660

Quick turbo wash 2 buckets of water ran through after 150 hours

Spinner done 2 cm of sludge built up after 106 hours

Right side cartridge filter changes after 153 hours

3/11/2018 – WORK DONE AT 37682, injectors 1,2,3 were changed with new ones from the injector room, the old ones pop tested very low

3/19/2018 – Start motor failed this morning, new one was installed no more spares on board, old one will be check and possibly rebuilt, work done 37727

3/20/2018 – work done at 37728, injectors 4,5,6 were changes with new ones from the injector room, the old ones pop tested very low

3/25 turbo wrap changed 37754

3/26 work done at 43325 , left side cartridge filter after 94 hours and turbo water wash 3 buckets ran through after 94 hours

3/27 spinner done at 37772, about .5 cm sludge built up after 112 hours

4/11 work done at 37945, spinner done about 2 cm sludge built up after 160 hours

Right side cartridge filter done

4/29/18 spinner done at 38094

5/14/18 spinner done at 38223

5/23/18 Left side done at 38307.

5/28/18 spinner done at 38408

6/5/18 water wash 38461

6/5/18 right side cartridge done at 38462
6/9/18 spinner 38559
6/11/18 right side cartridge filter done at 38573
6/12/18 injector on cylinder #2 replaced at 38573
6/17/18 right side cartridge filter done at 38657
6/17/18 spinner done at 38657
6/21/18 spinner 38747
6/26/18 spinner 38871
7/2/18 left side cartridge done at 38875
7/7/18 water wash and left side filter done at 38972
7/14/18 – Spinner Filter Cleaned 39115
7/14/18 – Turbo Wrap Replaced 39115
9/22/18 – SPINNER FILTER DONE AT 39957
10/4/18- SPINNER AND RIGHT SIDE CARTRIDGE FILTER DONE AT 40087
10/12/18 water wash turbo at 40197
10/13/18 – spinner filter done at 40215
11/2/18 right side done at 40304
11/8/18 WATER WASH AT 40323
11/10/18 spinner done at 40323
11/19/18 40384 left side cartridge filter changed
12/12/18 SPINNER FILTER DONE AT 40414
1/5/19 spinner done at 40485
 -dumped diesel down fuel leak off gallery drain
 -note governor-fuel rack linkage shock absorber stuck.
1/21/19- left side cartridge filter changed @ 40515
1/23/19 water wash turbine and compressor @ 40566
1/29/19- new turbo wrap @40644
1/31/19-Both Cartridge Filters Changed@40672
02/03/19 WATER WASH TURBINE SIDE 45 MINS 4 BUCKETS @ 40673

02/08/19- 40709 hours change out injectors 1, 2, and 5. all leaked and did not pop, full release around 270bar, new injectors have the orange packaged nozzles

02/21/19 40838 hours Injectors 3, 4 and 6 changed out, full release around 250bar, leaked from tip at 100 bar. New injectors all pop at 320 bar and the yellow packaged nozzles were used.

02/21/19- 40838 Turbo wrap changed

02/23/19-40849 hours- water wash performed for 30 mins, running on diesel. Water came out clear. Collected 1 bucket full

2/28/19-40859hrs- spinner done

4/30/19 – 12,000 overhaul done at 41076 including turbo. All new fuel pumps. All new injectors. Replaced bearings and con rods on out of spec units. Refer to Junma’s report from shipyard.

5/24/19 – rebuilt turbo governor installed and topped off with 827. New micro switch installed on over speed device. Work done at 41114

6/7/19 – new overspeed device and micro switch installed. Spinner filter cleaned at 41251

6/10/19 – water wash at 41279

6/15/19 – spinner done at 41368

08/02/19- left side cartridge filter changed-41982

9/27/19- LO Pressure alarm/trip, JW Temp alarm/trip, Overspeed Trip tested

10/9/2019 - Replaced Right side blade filter assembly.

11/19/2019 - Knife edge filter drain line removed, cleared, deck line cleared with tubing.

Update: Draining Issue persists. Clog suspected to be after 90 in deck line. In need of small diameter drain snake.

11/20/2019 - Leak off alarm float switch serviced, working. Two spares in storeroom.

11/20/2019 – 11/22/2019 Sump on purifier

12/23/2019 – Valve lash completed 42620

1/7/2020 – Tested LO Low pressure and trip / CW High temp and trip. WO: 8052150

1/25/2020 – ETO replaces FO pressure transmitter. Tightened multitude of connections

2/11/2020- 42781hrs-Left side lo cartridge replaced.

2/23/2020-42910hrs- water wash

4/15/2020- 43424hrs- spinner done

4/15/2020- 43424hrs -Gauges replaced on gauge panel

5/23/2020- 43562hrs- Complete water wash and turbo wrap replaced


6/5/2020- 43567 hrs Green Oil filter changed and pre filter cleaned

6/25/2020 – Spinner done

7/13/2020- Quarterly alarm testing conducted WO 8053518

7/17/2020 – 43794 Purified sump 30 hours

7/20/2020 – Replaced #3 injector with rebuilt, new nozzle.



Shutdown Solenoid for UG Governor

Installation and Operation Manual



General Precautions

Read this entire manual and all other publications pertaining to the work to be performed before installing, operating, or servicing this equipment.

Practice all plant and safety instructions and precautions.

Failure to follow instructions can cause personal injury and/or property damage.



Revisions

This publication may have been revised or updated since this copy was produced. To verify that you have the latest revision, check manual **26311**, *Revision Status & Distribution Restrictions of Woodward Technical Publications*, on the *publications page* of the Woodward website:

www.woodward.com/publications

The latest version of most publications is available on the *publications page*. If your publication is not there, please contact your customer service representative to get the latest copy.




Proper Use

Any unauthorized modifications to or use of this equipment outside its specified mechanical, electrical, or other operating limits may cause personal injury and/or property damage, including damage to the equipment. Any such unauthorized modifications: (i) constitute "misuse" and/or "negligence" within the meaning of the product warranty thereby excluding warranty coverage for any resulting damage, and (ii) invalidate product certifications or listings.



Translated Publications

If the cover of this publication states "Translation of the Original Instructions" please note:

The original source of this publication may have been updated since this translation was made. Be sure to check manual **26311**, *Revision Status & Distribution Restrictions of Woodward Technical Publications*, to verify whether this translation is up to date. Out-of-date translations are marked with . Always compare with the original for technical specifications and for proper and safe installation and operation procedures.

Revisions—Changes in this publication since the last revision are indicated by a black line alongside the text.

Woodward reserves the right to update any portion of this publication at any time. Information provided by Woodward is believed to be correct and reliable. However, no responsibility is assumed by Woodward unless otherwise expressly undertaken.

Copyright © Woodward 1985
All Rights Reserved

Contents

WARNINGS AND NOTICES	II
ELECTROSTATIC DISCHARGE AWARENESS	III
CHAPTER 1. OPERATION AND ADJUSTMENT.....	1
Description.....	1
Operation.....	2
Adjustments—Installation	3
Solenoid Suppression Diodes	8
CHAPTER 2. PARTS LISTS	9
Parts Information	9
CHAPTER 3. PRODUCT SUPPORT AND SERVICE OPTIONS.....	16
Product Support Options	16
Product Service Options.....	16
Returning Equipment for Repair.....	17
Replacement Parts	17
Engineering Services.....	18
Contacting Woodward's Support Organization	18
Technical Assistance.....	19

Illustrations and Tables

Figure 1. De-Energize to Shut Down Models.....	3
Figure 2. Vibration-Resistant De-energize to Shut Down	4
Figure 3. Energize to Shut Down Models.....	6
Figure 4. Vibration-Resistant Energize to Shut Down, without Latch	7
Figure 5. Solenoid Suppression Diode.....	8
Figure 6. Cover Assembly (with speed setting motor)	10
Figure 6a. PM Motor Assembly (see manual 03035).....	11
Figure 7. Energize to Shut Down with Latch	12
Figure 8. De-Energize to Shut Down with Latch	13
Figure 9. Vibration Resistant Energize to Shut Down, without Latch.....	14
Figure 10. Vibration Resistant De-energize to Shut Down, with Latch	15

Warnings and Notices

Important Definitions



This is the safety alert symbol. It is used to alert you to potential personal injury hazards. Obey all safety messages that follow this symbol to avoid possible injury or death.

- **DANGER**—Indicates a hazardous situation which, if not avoided, will result in death or serious injury.
- **WARNING**—Indicates a hazardous situation which, if not avoided, could result in death or serious injury.
- **CAUTION**—Indicates a hazardous situation which, if not avoided, could result in minor or moderate injury.
- **NOTICE**—Indicates a hazard that could result in property damage only (including damage to the control).
- **IMPORTANT**—Designates an operating tip or maintenance suggestion.

WARNING

**Overspeed /
Overtemperature /
Overpressure**

The engine, turbine, or other type of prime mover should be equipped with an overspeed shutdown device to protect against runaway or damage to the prime mover with possible personal injury, loss of life, or property damage.

The overspeed shutdown device must be totally independent of the prime mover control system. An overtemperature or overpressure shutdown device may also be needed for safety, as appropriate.

WARNING

**Personal Protective
Equipment**

The products described in this publication may present risks that could lead to personal injury, loss of life, or property damage. Always wear the appropriate personal protective equipment (PPE) for the job at hand. Equipment that should be considered includes but is not limited to:

- Eye Protection
- Hearing Protection
- Hard Hat
- Gloves
- Safety Boots
- Respirator

Always read the proper Material Safety Data Sheet (MSDS) for any working fluid(s) and comply with recommended safety equipment.

WARNING

Start-up

Be prepared to make an emergency shutdown when starting the engine, turbine, or other type of prime mover, to protect against runaway or overspeed with possible personal injury, loss of life, or property damage.

WARNING

**Automotive
Applications**

On- and off-highway Mobile Applications: Unless Woodward's control functions as the supervisory control, customer should install a system totally independent of the prime mover control system that monitors for supervisory control of engine (and takes appropriate action if supervisory control is lost) to protect against loss of engine control with possible personal injury, loss of life, or property damage.

NOTICE**Battery Charging
Device**

To prevent damage to a control system that uses an alternator or battery-charging device, make sure the charging device is turned off before disconnecting the battery from the system.

Electrostatic Discharge Awareness

NOTICE**Electrostatic
Precautions**

Electronic controls contain static-sensitive parts. Observe the following precautions to prevent damage to these parts:

- Discharge body static before handling the control (with power to the control turned off, contact a grounded surface and maintain contact while handling the control).
- Avoid all plastic, vinyl, and Styrofoam (except antistatic versions) around printed circuit boards.
- Do not touch the components or conductors on a printed circuit board with your hands or with conductive devices.

To prevent damage to electronic components caused by improper handling, read and observe the precautions in Woodward manual **82715**, *Guide for Handling and Protection of Electronic Controls, Printed Circuit Boards, and Modules*.

Follow these precautions when working with or near the control.

1. Avoid the build-up of static electricity on your body by not wearing clothing made of synthetic materials. Wear cotton or cotton-blend materials as much as possible because these do not store static electric charges as much as synthetics.
2. Do not remove the printed circuit board (PCB) from the control cabinet unless absolutely necessary. If you must remove the PCB from the control cabinet, follow these precautions:
 - Do not touch any part of the PCB except the edges.
 - Do not touch the electrical conductors, the connectors, or the components with conductive devices or with your hands.
 - When replacing a PCB, keep the new PCB in the plastic antistatic protective bag it comes in until you are ready to install it. Immediately after removing the old PCB from the control cabinet, place it in the antistatic protective bag.

Chapter 1.

Operation and Adjustment

Description

A shutdown solenoid is available for use on dial type UG8, UG32, and UG40 governors. Two basic models are available. One will cause shutdown when energized, and the other will cause shutdown when de-energized.

Vibration-resistant models are available for both styles.

The energize and de-energize models are available with a latch that requires manual resetting for restarting the engine. Vibration-resistant models are not built with the latching feature.



The shutdown solenoid must not be used as an overspeed protection device. Overspeed protection must come from a unit entirely separate from the UG governor. Failure of a governor or governor-related part of the system control can cause a life- or engine-threatening overspeed condition. In these cases, it is possible that the shutdown solenoid could not stop the runaway condition.

If voltage is available, the engine may be started without manual reset of the solenoid if the solenoid with latch is of the energize-to-run type.

All shutdown solenoids move the load-limit strap down to effect shutdown.

The solenoid can be supplied with various coils to accommodate the more common dc voltages. If operation on ac is desired, rectifiers can be incorporated in the cover assembly to rectify either 110 or 220 volts to dc. In addition, other ac voltages can be adapted on special order.

The special governor cover, required for mounting the unit, is available with or without accommodations for a speed-adjusting motor.

Operation

De-energize to Shut Down Model

The de-energize to shut down models shown in Figures 1 and 2 will shut the engine down on loss of current to the solenoid. The solenoid plunger moves up to allow the engine to run. To start an engine when no current is available, lift the solenoid plunger manually by means of the shutdown-latch knob (see Figure 1). As it approaches the top of its stroke, the lock pin may be pressed in to latch the shutdown-latch knob just below its upper position. This permits starting and running the engine. ***Operating with the latch pin holding the solenoid at the top of its stroke eliminates the possibility of using the solenoid to shut down the engine.***

When current is applied to the solenoid, it will move to its full upward position, unloading the lock pin, which is moved outward by the circular latch spring. With loss of current, the load spring will cause the solenoid plunger to move down, lifting the governor pilot valve and closing off fuel.



WARNING During start-up, if for any reason the solenoid has no current and the lock-in is latched, the solenoid will be inoperative. This will eliminate any safety systems which may use the solenoid to shut down the engine.

A de-energize to shut down model can be supplied without the latching feature, generally for operation in automatic plants. The vibration-resistant de-energize to shut down model is available only in non-latching design. The non-latching solenoids present an “energize to run” limitation on the engine, a condition which is required in many plants.

Energize to Shut Down Model

The energize to shut down model shown in Figures 3 and 4 will shut the engine down as current is applied (even momentarily in the case of the latching model).

The solenoid plunger moves downward through a tapered plunger stop, which contains seven spring-loaded steel balls. The binding action of the steel balls against the shutdown rod prevents the solenoid from returning. To restart the engine, return the plunger to its original position by pressing the reset button, which forces the steel balls away from the plunger and allows the spring force to push the load-limit strap and the solenoid plunger to the uppermost positions.

The energize to shut down system is available in non-latching designs for both the regular and the vibration-resistant models. The vibration-resistant model is not available in the latching mode.

The non-latching model requires a “shutdown current” to the solenoid until shutdown is complete.

Adjustments—Installation

Solenoid shutdown devices supplied on governors as original equipment are adjusted at the factory. It will be necessary to make the following adjustments on units which are to be installed on governors already in service.

NOTICE

When assembling or adjusting a shutdown solenoid, **ALWAYS** remove the cover and do the work away from the governor. **IF ANY PART OF THE SOLENOID DEVICE SHOULD DROP INTO THE GOVERNOR, IT WILL REQUIRE EXTENSIVE DISASSEMBLY OF THE GOVERNOR.**




Figure 1. De-Energize to Shut Down Models

De-Energize to Shut Down Model

1. Position the shutdown rod assembly in the solenoid plunger with the end of the plunger friction screw 3 mm (1/8 inch) inside the solenoid plunger nose as shown in Figure 1. This adjustment is necessary only when the shutdown device has been disassembled for cleaning or replacing parts. New assemblies sent from the factory will have this adjustment completed.
2. Loosen the lock nut and, with the solenoid de-energized, turn the solenoid plunger guide clockwise until it is tight against the plunger. The plunger should now be seated against the governor cover. Back off the solenoid plunger guide 3 to 4 turns and tighten the lock nut.

3. Attach the cover assembly (including the shutdown device) to the governor case.
4. Remove the set screw from the hole in the rod extension. With the engine running and the governor in operation and controlling the speed, de-energize the solenoid and use a screwdriver to turn the shutdown rod assembly clockwise until the governor just starts to shut down, then screw the shutdown rod down one additional turn.

Steps 5, 6, and 7 pertain to the latching model. Skip to step 8 if adjusting a non-latching model.

5. De-energize the solenoid. Lift the shutdown latch knob and press in the latch pin so the pin remains engaged when the knob is released.
6. With a screwdriver in the slot of the shutdown rod to prevent it from turning, screw the rod extension clockwise until the solenoid plunger is pulled up against the solenoid plunger guide.
7. Energize the solenoid. Back off the rod extension until the latch pin releases. Then back off 1/4 turn more. Lock in place with the 10-32 set screw.
8. Check for normal operation with the solenoid energized and for shutdown when the solenoid is de-energized. Check the latching device to verify that it will latch up to allow starting and unlatch when the solenoid is energized.

Vibration-Resistant De-Energize to Shut Down Model




Figure 2. Vibration-Resistant De-energize to Shut Down

1. Install the shutdown solenoid in the cover with the Plunger Guide Assembly slightly below the surface of the inside of the cover. Thread the adjusting nut onto the solenoid plunger rod as far as it will go. **DO NOT LOCK WITH THE ROLL PIN AT THIS TIME.**
2. Turn the solenoid plunger guide down until the rod just moves a little farther out of the bottom of the solenoid assembly. Then back off the plunger guide four full turns and lock with the lock nut.
3. With the engine running and the governor controlling engine speed, place the cover and gasket on the governor. If the engine does not shut down, remove the cover, screw the adjusting nut out one full turn, and replace the cover assembly on the governor.
4. Continue this procedure until the engine shuts down when then the cover is placed on the governor.

NOTICE

Completely remove the cover from the governor and make the adjustments in the adjusting nut away from the governor to prevent accidentally dropping the adjusting nut into the operating governor. Extensive damage to the governor can occur should the nut drop off the end of the shaft. Should the adjusting nut thread out more than 5 turns before causing shutdown, loosen the set screw and thread the entire shutdown solenoid farther into the governor cover, then start the adjusting nut setting again.

5. When the governor shuts the engine down when the cover is placed on the governor, remove the cover a final time and thread the adjusting nut until the roll pin can be pressed into the shaft, locking the adjusting nut into place. Do not risk dropping the roll pin into the governor while making this final installation.
6. Complete the wiring to the plug on the cover and check that the application of the required voltage causes the plunger to retract.
7. Install the cover-solenoid assembly onto the governor and check that the engine shuts down when the solenoid is de-energized, and that the engine can start and run with the solenoid energized. Check for normal operation with the solenoid de-energized, making sure that the governor is not sluggish in adding fuel to pick up load.

If the governor is sluggish in adding fuel to pick up load, check for excessive drag in the movement of the solenoid plunger, a misaligned shutdown rod, a bent plunger guide, or solidified preservative lubricant on any of the moving parts.

Energize to Shut Down Model

1. Position the shutdown rod assembly in the solenoid plunger with the end of the plunger friction screw 3 mm (1/8 inch) inside the plunger nose as shown in Figure 2. This adjustment is necessary only when the shutdown device has been disassembled for cleaning or replacing parts. New assemblies from the factory will have this adjustment completed.
2. Attach the cover assembly (including the shutdown device) to the governor case.
3. Unscrew the knurled reset button retainer and remove the reset button and spring. Loosen the lock nut. Turn the plunger stop down until the solenoid plunger is tight against the solenoid plunger guide. Back off 3 to 4 turns. Tighten the lock nut.
4. With the governor in operation and controlling engine speed, energize the solenoid and turn the slotted shutdown rod clockwise until shutdown occurs. Turn clockwise one more turn past the point of shutdown, and install the spring, reset button, and reset button retainer.
5. Check for normal operation with the solenoid de-energized, making sure that the governor is not sluggish in adding fuel to pick up load.
6. Energize the solenoid. After shutdown, check to see that the governor remains inoperative until the latch is released by pressing the reset button. Recheck for normal operation.




Figure 3. Energize to Shut Down Models

The energize to shut down model without the latching feature is adjusted in the following manner: Remove the plunger stop plug and, with the unit running, energize the solenoid. With the governor in operation and controlling speed, turn the slotted shutdown rod clockwise until shutdown occurs. Turn clockwise one more turn past the point of shutdown. Replace the plunger stop plug and screw it down until the solenoid plunger is tight against the solenoid plunger guide. Back off 3 to 4 turns on UG5.7, UG8, and UG12.8 governors or 4 turns on UG32 or UG40 governors. Lock in place with the lock nut. Make the final check as described in steps 5 and 6 above.

Vibration-Resistant Energize to Shut Down Model, without Latch




Figure 4. Vibration-Resistant Energize to Shut Down, without Latch

1. With the governor controlling and the governor cover removed: Loosen the locknut. Turn the plunger stop all the way in to immobilize the plunger, and run the adjusting nut all the way in to secure a starting position.
2. Install the cover and gasket on the governor.

NOTICE

Completely remove the cover from the governor and make the adjustments in the adjusting nut away from the governor to prevent accidentally dropping the adjusting nut into the operating governor. Extensive damage to the governor can occur should the nut drop off the end of the shaft. Should the adjusting nut thread out more than 5 turns before causing shutdown, loosen the set screw and thread the entire shutdown solenoid farther into the governor cover, then start the adjusting nut setting again.

3. With the engine running and the governor controlling engine speed, place the cover and gasket on the governor. If the engine does not shut down, remove the cover, screw the adjusting nut out one full turn, and replace the cover assembly on the governor.
4. Continue this procedure until the engine shuts down when then the cover is placed on the governor.
5. When the governor shuts the engine down when the cover is placed on the governor, remove the cover a final time and thread the adjusting nut until the roll pin can be pressed into the shaft, locking the adjusting nut into place. Do not risk dropping the roll pin into the governor while making this final installation.
6. Back out the plunger stop four turns and lock in place with the lock nut.
7. Complete the wiring to the plug on the cover and check that the application of the required voltage causes the plunger to extend from the solenoid.
8. Install the cover-solenoid assembly onto the governor and check that the engine shuts down when the solenoid is energized, and that the engine can start and run with the solenoid de-energized. Check for normal operation with the solenoid energized, making sure that the governor is not sluggish in adding fuel to pick up load. If the governor is sluggish in adding fuel to pick up load, check for excessive drag in the movement of the solenoid plunger, a misaligned shutdown rod, a bent plunger guide, or solidified preservative lubricant on any of the moving parts.

Solenoid Suppression Diodes

Solenoid coils used by Woodward, whether operated on ac or dc, have two diodes wired in the circuit as shown in Figure 5.

Diodes rectify ac to supply dc to the solenoid coils and also to provide shock hazard protection when used on ac when the ac is disconnected at the peak of a cycle (counter EMF is generated when the power is removed from the coil).

The diodes should be used on dc power solenoid coils because of the counter EMF.

IMPORTANT

Open or shorted diodes impair operation of the shutdown solenoid.




Figure 5. Solenoid Suppression Diode

Chapter 2. Parts Lists

Parts Information

When ordering replacement parts, include the following information:

1. Governor serial number and part number shown on the nameplate.
2. Manual number (this is manual 03013).
3. Part reference number and part name from parts list.

NOTICE

Damage may result if any parts are allowed to drop into the governor. Use extreme caution when working on the shutdown solenoid. Any part that should drop into the governor must be retrieved before attempting to operate the governor.

Ref.	Part Description	Quantity	Ref.	Part Description	Quantity
03013-1	Cable Clamp	1	03013-41	1/16 Pipe Plug	1
03013-2	Plug	1	03013-42	Jam Nut	1
03013-3	Screw, 4-40 x 5/16" Fil Hd	4	03013-43	Solenoid Plunger Guide	1
03013-4	Receptacle	1	03013-44	Shutdown Rod	1
03013-5	Cover	1	03013-45	Solenoid Case	1
03013-6	Set Screw, 10-32 x 1/4"	1	03013-46	Solenoid Plunger Guide	1
03013-7	Screw, 10-32 x 3/4" Fil Hd	4	03013-50	Ball Loading Spring	1
03013-8	Split Lock Washer, No. 10	4	03013-51	Washer	1
03013-9	Grommet	1	03013-52	Latch Spring	1
03013-10	Motor Seal Spring	1	03013-53	Shutdown Push Button	1
03013-11	Oil Cup	1	03013-54	Push button Retainer	1
03013-12	Bodine Motor	1	03013-55	Plunger Stop Plug	1
03013-13	Solenoid Case	1	03013-56	O Ring	2
03013-14	Load Spring	1	03013-57	Adjusting Screw	1
03013-15	Insulating Paper	1	03013-58	Snap Ring	1
03013-16	Solenoid Coil	1	03013-59	Shutdown Rod	1
03013-17	Parallel Connector	2	03013-60	Solenoid Plunger	1
03013-18	Wire, White Flamenol O.D.	AR	03013-61	Soldering Shield Washer	2
03013-19	Wire Strap, 2 Wires	2	03013-62	Varnished Tubing 3/16" long	2
03013-20	Screw, Fil Hd 8-32 x 1/4"	2	03013-63	Shutdown Rod	1
03013-21	Clear Tubing 3/4" Long	2	03013-64	Latch Rod	1
03013-22	Air Gap Washer	1	03013-65	Snap Ring	1
03013-23	Solenoid Plunger	1	03013-66	Washer Assembly	1
03013-24	Solenoid Plunger Locking Pin	1	03013-67	Ball	7
03013-25	Not Used		03013-68	Bushing, Ball Release	1
03013-26	Solenoid Plunger Guide	1	03013-69	Plunger Stop	1
03013-27	Shutdown Spring	1	03013-70	Diodes (Figure 4) (not shown in parts breakdown)	2
03013-28	Washer, Shutdown Spring Ret.	1	03013-71	Plunger Stop Assembly	1
03013-29	Roll Pin, 1/16" x 1/4"	1	03013-72	O-Ring, .739" ID x .070"	1
03013-30	Plunger Friction Screw	1	03013-73	Washer, .875" x 1.125" x .047"	1
03013-31	Shutdown Rod	1	03013-74	Plunger Assembly	1
03013-32	Roll Pin	1	03013-75	Roll Pin, .062" Dia. x .312", S.S.	1
03013-33	Plunger Guide Bushing	2	03013-76	Solenoid Coil Assembly	1
03013-34	Solenoid Plunger Guide	1	03013-77	Solenoid Plunger Guide Assm.	1
03013-35	Latch Spring	1	03013-78	Adjusting Nut	1
03013-36	Snap Ring	1	03013-79	Not Used	
03013-37	Shutdown Latch Knob	1	03013-80	Not Used	
03013-38	Lock Pin	1			
03013-39	Rod Extension	1			
03013-40	Lock Wire	AR			





Figure 6a. PM Motor Assembly (see manual 03035)



03000-B-49

Figure 7. Energize to Shut Down with Latch




Figure 8. De-Energize to Shut Down with Latch




Figure 9. Vibration Resistant Energize to Shut Down, without Latch




Figure 10. Vibration Resistant De-energize to Shut Down, with Latch

Chapter 3.

Product Support and Service Options

Product Support Options

If you are experiencing problems with the installation, or unsatisfactory performance of a Woodward product, the following options are available:

1. Consult the troubleshooting guide in the manual.
2. Contact the **OE Manufacturer or Packager** of your system.
3. Contact the **Woodward Business Partner** serving your area.
4. Contact Woodward technical assistance via email (EngineHelpDesk@Woodward.com) with detailed information on the product, application, and symptoms. Your email will be forwarded to an appropriate expert on the product and application to respond by telephone or return email.
5. If the issue cannot be resolved, you can select a further course of action to pursue based on the available services listed in this chapter.

OEM or Packager Support: Many Woodward controls and control devices are installed into the equipment system and programmed by an Original Equipment Manufacturer (OEM) or Equipment Packager at their factory. In some cases, the programming is password-protected by the OEM or packager, and they are the best source for product service and support. Warranty service for Woodward products shipped with an equipment system should also be handled through the OEM or Packager. Please review your equipment system documentation for details.

Woodward Business Partner Support: Woodward works with and supports a global network of independent business partners whose mission is to serve the users of Woodward controls, as described here:

- A **Full-Service Distributor** has the primary responsibility for sales, service, system integration solutions, technical desk support, and aftermarket marketing of standard Woodward products within a specific geographic area and market segment.
- An **Authorized Independent Service Facility (AISF)** provides authorized service that includes repairs, repair parts, and warranty service on Woodward's behalf. Service (not new unit sales) is an AISF's primary mission.
- A **Recognized Engine Retrofitter (RER)** is an independent company that does retrofits and upgrades on reciprocating gas engines and dual-fuel conversions, and can provide the full line of Woodward systems and components for the retrofits and overhauls, emission compliance upgrades, long term service contracts, emergency repairs, etc.

A current list of Woodward Business Partners is available at www.woodward.com/directory.

Product Service Options

Depending on the type of product, the following options for servicing Woodward products may be available through your local Full-Service Distributor or the OEM or Packager of the equipment system.

- Replacement/Exchange (24-hour service)
- Flat Rate Repair
- Flat Rate Remanufacture

Replacement/Exchange: Replacement/Exchange is a premium program designed for the user who is in need of immediate service. It allows you to request and receive a like-new replacement unit in minimum time (usually within 24 hours of the request), providing a suitable unit is available at the time of the request, thereby minimizing costly downtime.

This option allows you to call your Full-Service Distributor in the event of an unexpected outage, or in advance of a scheduled outage, to request a replacement control unit. If the unit is available at the time of the call, it can usually be shipped out within 24 hours. You replace your field control unit with the like-new replacement and return the field unit to the Full-Service Distributor.

Flat Rate Repair: Flat Rate Repair is available for many of the standard mechanical products and some of the electronic products in the field. This program offers you repair service for your products with the advantage of knowing in advance what the cost will be.

Flat Rate Remanufacture: Flat Rate Remanufacture is very similar to the Flat Rate Repair option, with the exception that the unit will be returned to you in “like-new” condition. This option is applicable to mechanical products only.

Returning Equipment for Repair

If a control (or any part of an electronic control) is to be returned for repair, please contact your Full-Service Distributor in advance to obtain Return Authorization and shipping instructions.

When shipping the item(s), attach a tag with the following information:

- return number;
- name and location where the control is installed;
- name and phone number of contact person;
- complete Woodward part number(s) and serial number(s);
- description of the problem;
- instructions describing the desired type of repair.

Packing a Control

Use the following materials when returning a complete control:

- protective caps on any connectors;
- antistatic protective bags on all electronic modules;
- packing materials that will not damage the surface of the unit;
- at least 100 mm (4 inches) of tightly packed, industry-approved packing material;
- a packing carton with double walls;
- a strong tape around the outside of the carton for increased strength.

NOTICE

To prevent damage to electronic components caused by improper handling, read and observe the precautions in Woodward manual 82715, *Guide for Handling and Protection of Electronic Controls, Printed Circuit Boards, and Modules*.

Replacement Parts

When ordering replacement parts for controls, include the following information:

- the part number(s) (XXXX-XXXX) that is on the enclosure nameplate;
- the unit serial number, which is also on the nameplate.

Engineering Services

Woodward's Full-Service Distributors offer various Engineering Services for our products. For these services, you can contact the Distributor by telephone or by email.

- Technical Support
- Product Training
- Field Service

Technical Support is available from your equipment system supplier, your local Full-Service Distributor, or from many of Woodward's worldwide locations, depending upon the product and application. This service can assist you with technical questions or problem solving during the normal business hours of the Woodward location you contact.

Product Training is available as standard classes at many Distributor locations. Customized classes are also available, which can be tailored to your needs and held at one of our Distributor locations or at your site. This training, conducted by experienced personnel, will assure that you will be able to maintain system reliability and availability.

Field Service engineering on-site support is available, depending on the product and location, from one of our Full-Service Distributors. The field engineers are experienced both on Woodward products as well as on much of the non-Woodward equipment with which our products interface.

For information on these services, please contact one of the Full-Service Distributors listed at www.woodward.com/directory.

Contacting Woodward's Support Organization

For the name of your nearest Woodward Full-Service Distributor or service facility, please consult our worldwide directory published at www.woodward.com/directory.

You can also contact the Woodward Customer Service Department at one of the following Woodward facilities to obtain the address and phone number of the nearest facility at which you can obtain information and service.

Products Used In Electrical Power Systems	Products Used In Engine Systems	Products Used In Industrial Turbomachinery Systems
<u>Facility</u> ----- <u>Phone Number</u>	<u>Facility</u> ----- <u>Phone Number</u>	<u>Facility</u> ----- <u>Phone Number</u>
Brazil -----+55 (19) 3708 4800	Brazil -----+55 (19) 3708 4800	Brazil -----+55 (19) 3708 4800
China -----+86 (512) 6762 6727	China -----+86 (512) 6762 6727	China -----+86 (512) 6762 6727
Germany:	Germany-----+49 (711) 78954-510	India -----+91 (129) 4097100
Kempen----+49 (0) 21 52 14 51	India -----+91 (129) 4097100	Japan-----+81 (43) 213-2191
Stuttgart-- +49 (711) 78954-510	Japan-----+81 (43) 213-2191	Korea-----+82 (51) 636-7080
India -----+91 (129) 4097100	Korea-----+82 (51) 636-7080	The Netherlands- +31 (23) 5661111
Japan-----+81 (43) 213-2191	The Netherlands- +31 (23) 5661111	Poland-----+48 12 295 13 00
Korea-----+82 (51) 636-7080	United States---- +1 (970) 482-5811	United States---- +1 (970) 482-5811
Poland-----+48 12 295 13 00		
United States---- +1 (970) 482-5811		

For the most current product support and contact information, please visit our website directory at www.woodward.com/directory.



Personnel	Doc:	SMM-PER-05-F1
	Page:	1
Familiarization Checklist	Date:	29 Dec 16
	Rev:	3

LYOND DEES, TRENTON
Name: Last, First

BLNC GOODWILL
Vessel

OCT 4, 2019
Date

In accordance with SMS procedure SMM-PER-05, ISM Code Section 6.3 and STCW Code Section A VII/1, the following training for new employees was completed prior to being assigned shipboard duties or vessel sailing whichever takes place first, included but not limited to the following:

Section 1- GENERAL

✓	Item Reviewed
✓	Common language; communicate fluently in the English language.
✓	Certificates and inoculations; current and appropriate for rating employed.
✓	Anti-Harassment Policy, explain to employee.
✓	Drug and Alcohol Policy, explain to employee.
✓	Personal comportment; employee has read and understands firing offense list.
✓	Bulletin/Notices - Location of posted policies; company and vessel specific.
✓	Performance evaluation; employee understands policies.
✓	Medical Sign-On Form completed.
✓	Safety issues reporting; knows to report possible unsafe conditions or situations in order to prevent accidents or injuries.
✓	Waste management procedures, including segregation, stowage locations and proper disposal of waste.
✓	Basic CBRD Introduction and Notice to All U.S. Government Contractor Employees on Accessing and Protecting Classified Information (MSC Only)
✓	Sight Conservation Indoctrination – Review use of eye protection.
✓	Respiratory Protection Indoctrination – Review use of PPE
✓	Hearing conservation – Review of hearing protection devices
✓	Heat stress review

Section 2 - SAFETY

✓	Item Reviewed
✓	Communicate with other persons on board on elementary safety matters and understand safety information symbols, signs and alarms.
✓	Emergency duties, know what to do if: <ul style="list-style-type: none"> • A person falls overboard • Fire or smoke is detected • Fire or abandon ship alarm is sounded
✓	Identify muster and embarkation stations and emergency escape routes.
✓	Locate and don lifejackets.
✓	Location of immersion suits.
✓	Emergency signals, activating alarms and have basic knowledge on the location and use of fixed and portable fire extinguishers.
✓	Take immediate action upon encountering an accident or other medical emergency before seeking further medical assistance on board
✓	Close and open the fire, weathertight, and watertight doors fitted, other than for hull openings.
✓	SOPEP Locker location and contents
✓	Importance of alarms, determining root cause of alarms, and importance of promptly notifying senior shipboard personnel of alarms and/or equipment casualties.
✓	Safety Management System indoctrination including reporting of non-conformities
✓	Basic walkaround tour of vessel and relevant work areas
✓	Work area review of exit and escape areas

Personnel

Doc: SMM-PER-05-F1

Familiarization Checklist

Page: 2

Date: 29 Dec 16

Rev: 3

Section 3 - LICENSED OFFICER (To be completed within one week of joining)

✓	<u>DECK DEPARTMENT</u>
	<u>Ballast control operations</u>
	<u>Bridge area and configuration</u>
	<u>Cargo Control Room (CCR)</u>
	<u>Cargo operations, stability</u>
	<u>Contingency plans</u>
	<u>Emergency equipment</u>
	<u>GMDSS</u>
	<u>Log books and records</u>
	<u>Maintenance plans and schedules</u>
	<u>Navigation aids</u>
	<u>Route planning</u>
	<u>Standing Orders</u>
	<u>Mooring equipment and ground tackle operation and maintenance</u>
	<u>Hazardous materials handling training</u>
	<u>Cargo gear maintenance</u>
	<u>Spare parts and ordering</u>

✓	<u>ENGINE DEPARTMENT</u>
✓	<u>HVAC system</u>
✓	<u>Auxiliary engines</u>
✓	<u>Bilge and ballast systems</u>
✓	<u>Boilers</u>
✓	<u>Contingency plans</u>
✓	<u>Emergency equipment</u>
✓	<u>Engine Control Room (ECR)</u>
✓	<u>Freshwater system</u>
✓	<u>Fuel and lube systems</u>
✓	<u>Log books</u>
✓	<u>Main Engine</u>
✓	<u>Maintenance plan and schedule</u>
✓	<u>Pollution control equipment</u>
✓	<u>Sanitary system</u>
✓	<u>Steering gear</u>
✓	<u>Workshop and tools</u>
✓	<u>Cargo gear maintenance</u>
✓	<u>Spare parts and ordering</u>

(b) (6), (b) (7)(C)

10/7/19

Personnel	Doc:	SMM-PER-05-F1
	Page:	3
Familiarization Checklist	Date:	29 Dec 16
	Rev:	3

I, the undersigned person joining this vessel, have had the items listed on this page explained to me, have had a chance to question these requirements, understand what they mean with respect to my position aboard this ship, and agree to abide by them.

LLOYD-DEES, TRENTON **(b) (4)**
 Print (person joining) Signature

(b) (6), (b) (7)(C)
 Print (person conducting familiarization) Signature

10/7/19
 Date

04 Oct 2019

(b) (6), (b) (7)(C)

Trenton Lloyd-Rees

Sign-on Date

Position

Crewmember Name

SLNC Goodwill Sign-on Paperwork

A. Vessel Familiarization

- 1. SLNC SMM PER-05-F1 Vessel Familiarization
- 2. Security Briefing
- 3. Signed Job Description
- 4. Door Nametag
- 5. Goodwill Welcome Aboard Packet
- 6. Termination Offenses

B. Credentials

- 7. MMC
 - 1. Expiration date valid through end of discharge date? Y or N
 - 2. Certified rating for position? Y or N
 - 3. Tankerman PIC or PIC Assist.? Y or N (N/A for Jr. 3/M Position)
 - 4. STCW Compliant? Y or N
 - 5. VSO or VPDS? Y or N
 - 6. Radar Valid Through Discharge Date? Y or N (Deck Officer Only)
 - 7. TRANSAS Navi-Sailor Cert? Y or N (Deck Officers Only)
- 8. Passport
 - 1. Valid Through Discharge Date? Y or N
- 9. GMDSS (Deck Officers Only)
- 10. TWIC Card
 - 1. Valid Through Discharge Date? Y or N
- 11. Shot Card
- 12. Drug Free
 - 1. Current and Valid? Y or N
- 13. USCG Medical Certificate
 - 1. Exp. Date Valid on STCW Time? Y or N

C. Employment Documents

14. Employee Information Form
- 1. Contact Number Y or N
 - 2. Email Y or N
 - 3. Next of kin/Emergency contact Y or N
 - 4. Signature Y or N
15. I-9 Form, Page 1
- 1. Signature Y or N
 - 2. US Citizen? Y or N If no, Proper Paperwork? Y or N
16. W-4
- 1. Box checked for single or married? Y or N
 - 2. Line 5 Filled out? Y or N
17. Chesapeake Crewing Direct Deposit Form
- 1. Routing Number Y or N
 - 2. Account Number Y or N
 - 3. Signature Y or N
- N/A 18. MMP 401K Enrollment (Deck Officers Only)
19. MEBA 401K Enrollment (Engine Officers Only)
20. Chesapeake Crewing Health Statement Sign On
- 1. Allergies? Y or N (If yes make sure filled out on form)
 - 2. Medical Conditions? Y or N (If yes make sure filled out on form)
 - 3. Medicine required on board? Y or N (If yes make sure filled out on form)

D. Other Documents

21. Union Dispatch (c/o Captain)
22. Fit Test
- 1. Test conducted
 - 2. Test filed in training binder
23. Internal Threat Program
- 1. Course taken

- 2. Certificate attached
- 3. Quiz filed in training binder
- N/A 24. Extreme Weather Gear Receipt
- N/A 25. SEEMP Training
- 26. N/A 1. SEEMP Polices And PP reviewed and understood.
MSC Credentials
- N/A 1. Small Arms
- 2. Anti-Terrorism Level 1
- N/A 3. Ship's Reaction Force
- 4. CBR-D
- 5. Cyber Security
- 6. Active Shooter

Person Conducting Familiarization:

New Crew Member:

(b) (6), (b) (7)(C)

TRANTON, LI QD-DEES BAE



Schuyler Line Navigation Company, LLC
M.T. SLNC GOODWILL
Ship Specific Security Brief

WELCOME ABOARD

Welcome aboard our Vessel, the MT SLNC Goodwill. This Vessel is a Commercial Oil/Chemical Tanker on long term charter to Military Sealift Command. Due to our unique status as an asset of the US Department of Defense, it makes us a unique target for those who do not appreciate our values or way of life. Through vigilance and effective security measures, we can effectively protect ourselves and our shipmates against those who wish us harm. To do this, the Vessel and all of her crewmembers are must uphold the highest security standards to protect the Ship and the facilities we visit. All crew members play a role in our security.

VISITORS

When coming aboard the Vessel, all visitors must identify themselves and state their business. If they are unwilling to comply, the Officer of the Watch must be notified immediately. The gangway watch assigns wristbands or badges to visitors depending on their business aboard:

- Not allowed inside Restricted Areas. Business is strictly on deck or CCR. Wrist band is assigned to people who are:
 - Longshoremen (Cargo samplers, cargo arm connectors).
 - If a group of contractors come aboard, the foreman will receive a badge, the rest will receive wrist bands.

White Badge

- Allowed inside Restricted Areas relating to their business without being escorted. This badge is assigned to people who:
 - Have a TWIC card.
 - Known by the Vessel's Crew (Example: Company Personnel, Agents).

Yellow Badge

- Allowed inside Common Areas relating to their business without being escorted. This badge is assigned to people who:
 - Hold a TWIC or CAC card.
 - Unknown to the Vessel (Example: Vendors, Military Personnel).

- The visitor must be escorted at all times. This badge is assigned to people who:
 - Do not hold a TWIC/CAC Card.
 - Have Government Issued Photo-ID.

If you find visitors in a Restricted Area:

- Ask what their business is.
- If they do not have a badge, escort them to the gangway and notify the Officer of the Watch.
- If they have a red badge, but are not where their work is, escort them back to their authorized workspace. Then notify the Officer of the Watch.
- If you find them suspicious, notify the Officer of the Watch.

When the Officer of the Watch is notified of suspicious or unauthorized activity, he or she shall notify the Vessel Security Officer (VSO) immediately.

An Inventory of all badges and visitor locations aboard the vessel shall be done and reported at the beginning of each watch as part of a proper turnover.

RESTRICTED AREAS

In port, access points to Restricted Areas must be locked when not in use. If open, it must be manned or monitored. Restricted Spaces include the following:

- Bridge



- Store rooms
- Lockers
- Engine Room
- Steering Gear Room
- Forecastle
- Hospital
- Emergency generator
- I.G. room
- Cargo Control Room.

All exterior doors must be kept locked in port to ensure that access is secured to restricted spaces. The only entry shall be through the A Deck Portside door. All personnel must pass through the Cargo Control Room. The A Deck Port Side Passageway Door (adjacent to the Smoking Room) is to remain locked at all times.

DURESS WORD

In the event of a Security Threat, muster as per the Station Bill for a security briefing and further direction.

In event of a Security Breach, the duress word shall be spoken over the Public Address System or passed by word of mouth. This is the signal to retreat to the Citadel. Lock down until the all clear is given. If attack is imminent or underway, non-essential personal will proceed to the Citadel. Engineering Officers will man the Engine Room and the Security Reaction Force (SRF) will be activated.

Security Duties

The Officer of the Watch:

- The Officer of the Watch is reports to the Vessel's Master and is responsible for:
 - o Supervising the Gangway Watch and Security Rover.
 - o Assisting Gangway Watch as required
 - o Processing Visitors.

Gangway Watch and Security Rover:

- The Gangway Watch and Security rover report to the Officer of the Watch and are responsible for:
 - o Ensuring only authorized personnel are allowed aboard.
 - o Visually checking over the side and surrounding areas of the ship in port.
 - o Escorting Visitors.
 - o Ensuring Integrity of locks where applicable.
 - o Checking the identity of embarking crewmembers and visitors.
 - o Maintenance of Visitors Log.
 - o Screening all persons boarding the vessel and their hand-carried articles, at rates specified by the Vessel Security Plan, Officer of the Watch, or Master.
 - o Maintain security vigilance during their tour of duty
 - o Challenge Unescorted Persons on board who are not properly credentialed.
 - o Assist in the performance of vessel searches.
 - o Report deficiencies e.g. broken or missing locks.

All crewmembers are expected to uphold the security of the Vessel by complying with these policies. By signing below, you acknowledge that you have been trained, read, understand this security briefing.

Trenton Lloyd-Rees

Name

(b) (6), (b) (7)(C)

Signature

10/7/19

Date



International Organization of
Masters, Mates & Pilots

Port: Houston
13850 Gulf Freeway, Suite 250
Houston, TX 77034-0000
Phone: (281)464-9650

Online: www.bridgedeck.org Email: (b) (6), (b) (7)(C)

Master SLNC GOODWILL

This will introduce TRENTON D LLOYD-REES

Dispatched to your vessel as 3AE

Company: CHESAPEAKE CREWING, LLC

SSN: (b) (6), (b) (7)(C)

Mariner Ref#: 3757105

Assignment Information:

Date Dispatched: 9/20/2019
Date Registered: 09/20/2019
Registered List: APP
Fly Starts: 10/02/2019
Return to Work Date:
Length: 420 ⁹⁰

Report In: 9/30/2019
Port to: NY/NJ
Dues Paid to: 9/30/2019
Relieving: (b) (6), (b) (7)(C)
For Reason of: Assignment Complete
Assignment Type: ROTARY
Assignment End Date: 1/30/2020 4:00:00 AM

Remarks: Dispatch Period: 120 days
Anticipated Fly Date: o/a 31-SEP-201
Anticipated First Day Aboard: o/a 26-AUG-2016
Location where Joining Vessel: ROK

Professional Information

License

Passport Expiration: 7/27/2025
TWIC Expiration: 6/12/2020
Rank: Serial: Expiration: Details:
(b) (6), (b) (7)(C) /2024

<u>Endorsements</u>	<u>Expiration</u>	<u>Endorsements</u>	<u>Expiration</u>	<u>Endorsements</u>	<u>Expiration</u>
DRUG-FREE	10/26/2019	VSO	5/4/2024		
OS	5/4/2024				
STCW	5/4/2024				
STCWMC	10/25/2020				
PDSD	5/4/2024				

I certify that the above Officer/Seaman has been dispatched in accordance with MM&P rules and that I have verified the above information against original documents presented to me by the Officer/Seaman named above.

9/20/2019

Date

(b) (6), (b) (7)(C)
Dispatcher

Personal Information

W-4/Mail Address

(b) (6), (b) (7)(C)

Next of Kin Information:

(b) (6), (b) (7)(C)

Cell: (b) (6), (b) (7)(C)

Email: (b) (6), (b) (7)(C)

I certify that the above Officer/Seaman has been dispatched in accordance with MM&P rules and that I have verified the above information against original documents presented to me by the Officer/Seaman named above.

9/20/2019

Date

(b) (6), (b) (7)(C)

TRENTON D LLOYD-REES (b) (6), (b) (7)(C)

Chesapeake Crewing LLC.

Employee Information Form

--- please print clearly ---

Name Trenton Lloyd-Rees SSN (b) (6), (b) (7)(C)
Address (b) (6), (b) (7)(C)
City (b) (6), (b) (7)(C) State (b) (6), (b) (7)(C)
Email Address (b) (6), (b) (7)(C)
Phone: Home (b) (6), (b) (7)(C) Cell (b) (6), (b) (7)(C)
Date of Birth (b) (6), (b) (7)(C) Birth Place (b) (6), (b) (7)(C)
Drivers License (b) (6), (b) (7)(C) Issuing State (b) (6), (b) (7)(C)
MMC # (b) (6), (b) (7)(C) Date of Issue (b) (6), (b) (7)(C)
Nearest Major Commercial Airport IAH

EMERGENCY CONTACT INFO:

Contact Name (b) (6), (b) (7)(C) Relationship Parents
Address (b) (6), (b) (7)(C)
City (b) (6), (b) (7)(C) State (b) (6), (b) (7)(C)
Phone #1 (b) (6), (b) (7)(C) #2 (b) (6), (b) (7)(C)

I understand that the above information will be entered into my permanent file. The above address provided by me will be used for tax forms and other company correspondence.

I further understand that I must notify the company as soon as there are any changes to the above information as a condition of continued employment.

Signed (Employee) (b) (6), (b) (7)(C) Date 10, 6, 19



Employment Eligibility Verification
Department of Homeland Security
U.S. Citizenship and Immigration Services


IIS/CIS
Form I-9
 OMB No. 1615-0047
 Expires 08/31/2019

▶ **START HERE:** Read instructions carefully before completing this form. The instructions must be available, either in paper or electronically, during completion of this form. Employers are liable for errors in the completion of this form.

ANTI-DISCRIMINATION NOTICE: It is illegal to discriminate against work-authorized individuals. Employers **CANNOT** specify which document(s) an employee may present to establish employment authorization and identity. The refusal to hire or continue to employ an individual because the documentation presented has a future expiration date may also constitute illegal discrimination.

Section 1. Employee Information and Attestation (Employees must complete and sign Section 1 of Form I-9 no later than the first day of employment, but not before accepting a job offer.)

Last Name (Family Name) Lloyd-Rees	First Name (Given Name) Trenton	Middle Initial D	Other Last Names Used (if any)
---------------------------------------	------------------------------------	---------------------	--------------------------------



I am aware that federal law provides for imprisonment and/or fines for false statements or use of false documents in connection with the completion of this form.

I attest, under penalty of perjury, that I am (check one of the following boxes):

<input checked="" type="checkbox"/> 1. A citizen of the United States	QR Code - Section 1 Do Not Write In This Space
<input type="checkbox"/> 2. A noncitizen national of the United States (See instructions)	
<input type="checkbox"/> 3. A lawful permanent resident (Alien Registration Number/USCIS Number): _____	
<input type="checkbox"/> 4. An alien authorized to work until (expiration date, if applicable, mm/dd/yyyy): _____ Some aliens may write "N/A" in the expiration date field. (See instructions) Aliens authorized to work must provide only one of the following document numbers to complete Form I-9: An Alien Registration Number/USCIS Number OR Form I-94 Admission Number OR Foreign Passport Number. 1. Alien Registration Number/USCIS Number: _____ OR 2. Form I-94 Admission Number: _____ OR 3. Foreign Passport Number: _____ Country of Issuance: _____	

Signature of Employer (b)(6), (b)(7)(C)	Today's Date (mm/dd/yyyy) 10/6/2019
--	-------------------------------------

Preparer and/or Translator Certification (check one):
 I did not use a preparer or translator. A preparer(s) and/or translator(s) assisted the employee in completing Section 1.
 (Fields below must be completed and signed when preparers and/or translators assist an employee in completing Section 1.)

I attest, under penalty of perjury, that I have assisted in the completion of Section 1 of this form and that to the best of my knowledge the information is true and correct.

Signature of Preparer or Translator		Today's Date (mm/dd/yyyy)	
Last Name (Family Name)		First Name (Given Name)	
Address (Street Number and Name)	City or Town	State	ZIP Code

STEP Employer Completes Next Page STEP

(b)(6), (b)(7)(C)

Form W-4 (2019)

Future developments. For the latest information about any future developments related to Form W-4, such as legislation enacted after it was published, go to www.irs.gov/FormW4.

Purpose. Complete Form W-4 so that your employer can withhold the correct federal income tax from your pay. Consider completing a new Form W-4 each year and when your personal or financial situation changes.

Exemption from withholding. You may claim exemption from withholding for 2019 if both of the following apply.

- For 2018 you had a right to a refund of all federal income tax withheld because you had **no tax liability, and**

- For 2019 you expect a refund of all federal income tax withheld because you expect to have **no tax liability.**

If you're exempt, complete **only** lines 1, 2, 3, 4, and 7 and sign the form to validate it. Your exemption for 2019 expires February 17, 2020. See Pub. 505, Tax Withholding and Estimated Tax, to learn more about whether you qualify for exemption from withholding.

General Instructions

If you aren't exempt, follow the rest of these instructions to determine the number of withholding allowances you should claim for withholding for 2019 and any additional amount of tax to have withheld. For regular wages, withholding must be based on allowances you claimed and may not be a flat amount or percentage of wages.

You can also use the calculator at www.irs.gov/W4App to determine your tax withholding more accurately. Consider

using this calculator if you have a more complicated tax situation, such as if you have a working spouse, more than one job, or a large amount of nonwage income not subject to withholding outside of your job. After your Form W-4 takes effect, you can also use this calculator to see how the amount of tax you're having withheld compares to your projected total tax for 2019. If you use the calculator, you don't need to complete any of the worksheets for Form W-4.

Note that if you have too much tax withheld, you will receive a refund when you file your tax return. If you have too little tax withheld, you will owe tax when you file your tax return, and you might owe a penalty.

Filers with multiple jobs or working spouses. If you have more than one job at a time, or if you're married filing jointly and your spouse is also working, read all of the instructions including the instructions for the Two-Earners/Multiple Jobs Worksheet before beginning.

Nonwage income. If you have a large amount of nonwage income not subject to withholding, such as interest or dividends, consider making estimated tax payments using Form 1040-ES, Estimated Tax for Individuals. Otherwise, you might owe additional tax. Or, you can use the Deductions, Adjustments, and Additional Income Worksheet on page 3 or the calculator at www.irs.gov/W4App to make sure you have enough tax withheld from your paycheck. If you have pension or annuity income, see Pub. 505 or use the calculator at www.irs.gov/W4App to find out if you should adjust your withholding on Form W-4 or W-4P.

Nonresident alien. If you're a nonresident alien, see Notice 1392, Supplemental Form W-4 Instructions for Nonresident Aliens, before completing this form.

Specific Instructions

Personal Allowances Worksheet

Complete this worksheet on page 3 first to determine the number of withholding allowances to claim.

Line C. Head of household please note: Generally, you may claim head of household filing status on your tax return only if you're unmarried and pay more than 50% of the costs of keeping up a home for yourself and a qualifying individual. See Pub. 501 for more information about filing status.

Line E. Child tax credit. When you file your tax return, you may be eligible to claim a child tax credit for each of your eligible children. To qualify, the child must be under age 17 as of December 31, must be your dependent who lives with you for more than half the year, and must have a valid social security number. To learn more about this credit, see Pub. 972, Child Tax Credit. To reduce the tax withheld from your pay by taking this credit into account, follow the instructions on line E of the worksheet. On the worksheet you will be asked about your total income. For this purpose, total income includes all of your wages and other income, including income earned by a spouse if you are filing a joint return.

Line F. Credit for other dependents. When you file your tax return, you may be eligible to claim a credit for other dependents for whom a child tax credit can't be claimed, such as a qualifying child who doesn't meet the age or social security number requirement for the child tax credit, or a qualifying relative. To learn more about this credit, see Pub. 972. To reduce the tax withheld from your pay by taking this credit into account, follow the instructions on line F of the worksheet. On the worksheet, you will be asked about your total income. For this purpose, total

Separate here and give Form W-4 to your employer. Keep the worksheet(s) for your records.

Form W-4 Department of the Treasury Internal Revenue Service		Employee's Withholding Allowance Certificate		OMB No. 1545-0074 2019	
▶ Whether you're entitled to claim a certain number of allowances or exemption from withholding is subject to review by the IRS. Your employer may be required to send a copy of this form to the IRS.					
1 Your first name and middle initial Trenton D		Last name Lloyd-Rees		2 Your social security number (b) (6), (b) (7)(C)	
Home address (number and street or rural route) (b) (6), (b) (7)(C)		3 <input checked="" type="checkbox"/> Single <input type="checkbox"/> Married <input type="checkbox"/> Married, but withhold at higher Single rate. Note: If married filing separately, check "Married, but withhold at higher Single rate."			
		4 If your last name differs from that shown on your social security card, check here. You must call 800-772-1213 for a replacement card. <input type="checkbox"/>			
5 Total number of allowances you're claiming (from the applicable worksheet on the following pages)				5	
6 Additional amount, if any, you want withheld from each paycheck				6 \$	
7 I claim exemption from withholding for 2019, and I certify that I meet both of the following conditions for exemption.					
<ul style="list-style-type: none"> • Last year I had a right to a refund of all federal income tax withheld because I had no tax liability, and • This year I expect a refund of all federal income tax withheld because I expect to have no tax liability. 					
If you meet both conditions, write "Exempt" here ▶ 7					
Under penalties of perjury, I declare that the information on this form is true, correct, and complete.					
Employee's signature (This form is not valid unless you sign)				Date ▶ 10/6/2019	
8 Employer's name and address (Employer: Complete boxes 8 and 10 if sending to IRS and complete boxes 8, 9, and 10 if sending to State Directory of New Hires.)				10 Employer identification number (EIN)	

Income includes all of your wages and other income, including income earned by a spouse if you are filing a joint return.

Line G. Other credits. You may be able to reduce the tax withheld from your paycheck if you expect to claim other tax credits, such as tax credits for education (see Pub. 970). If you do so, your paycheck will be larger, but the amount of any refund that you receive when you file your tax return will be smaller. Follow the instructions for Worksheet 1-6 in Pub. 505 if you want to reduce your withholding to take these credits into account. Enter "-0-" on lines E and F if you use Worksheet 1-6.

Deductions, Adjustments, and Additional Income Worksheet

Complete this worksheet to determine if you're able to reduce the tax withheld from your paycheck to account for your itemized deductions and other adjustments to income, such as IRA contributions. If you do so, your refund at the end of the year will be smaller, but your paycheck will be larger. You're not required to complete this worksheet or reduce your withholding if you don't wish to do so.

You can also use this worksheet to figure out how much to increase the tax withheld from your paycheck if you have a large amount of nonwage income not subject to withholding, such as interest or dividends.

Another option is to take these items into account and make your withholding more accurate by using the calculator at www.irs.gov/W4App. If you use the calculator, you don't need to complete any of the worksheets for Form W-4.

Two-Earners/Multiple Jobs Worksheet

Complete this worksheet if you have more than one job at a time or are married filing jointly and have a working spouse. If you

don't complete this worksheet, you might have too little tax withheld. If so, you will owe tax when you file your tax return and might be subject to a penalty.

Figure the total number of allowances you're entitled to claim and any additional amount of tax to withhold on all jobs using worksheets from only one Form W-4. Claim all allowances on the W-4 that you or your spouse file for the highest paying job in your family and claim zero allowances on Forms W-4 filed for all other jobs. For example, if you earn \$60,000 per year and your spouse earns \$20,000, you should complete the worksheets to determine what to enter on lines 5 and 6 of your Form W-4, and your spouse should enter zero ("-0-") on lines 5 and 6 of his or her Form W-4. See Pub. 505 for details.

Another option is to use the calculator at www.irs.gov/W4App to make your withholding more accurate.

Tip: If you have a working spouse and your incomes are similar, you can check the "Married, but withhold at higher Single rate" box instead of using this worksheet. If you choose this option, then each spouse should fill out the Personal Allowances Worksheet and check the "Married, but withhold at higher Single rate" box on Form W-4, but only one spouse should claim any allowances for credits or fill out the Deductions, Adjustments, and Additional Income Worksheet.

Instructions for Employer

Employees, do not complete box 8, 9, or 10. Your employer will complete these boxes if necessary.

New hire reporting. Employers are required by law to report new employees to a designated State Directory of New Hires. Employers may use Form W-4, boxes 8, 9,

and 10 to comply with the new hire reporting requirement for a newly hired employee. A newly hired employee is an employee who hasn't previously been employed by the employer, or who was previously employed by the employer but has been separated from such prior employment for at least 60 consecutive days. Employers should contact the appropriate State Directory of New Hires to find out how to submit a copy of the completed Form W-4. For information and links to each designated State Directory of New Hires (including for U.S. territories), go to www.acf.hhs.gov/css/employers.

If an employer is sending a copy of Form W-4 to a designated State Directory of New Hires to comply with the new hire reporting requirement for a newly hired employee, complete boxes 8, 9, and 10 as follows.

Box 8. Enter the employer's name and address. If the employer is sending a copy of this form to a State Directory of New Hires, enter the address where child support agencies should send income withholding orders.

Box 9. If the employer is sending a copy of this form to a State Directory of New Hires, enter the employee's first date of employment, which is the date services for payment were first performed by the employee. If the employer rehired the employee after the employee had been separated from the employer's service for at least 60 days, enter the rehire date.

Box 10. Enter the employer's employer identification number (EIN).

Personal Allowances Worksheet (Keep for your records.)

A	Enter "1" for yourself	A	_____
B	Enter "1" if you will file as married filing jointly	B	_____
C	Enter "1" if you will file as head of household	C	_____
D	Enter "1" if: { • You're single, or married filing separately, and have only one job; or • You're married filing jointly, have only one job, and your spouse doesn't work; or • Your wages from a second job or your spouse's wages (or the total of both) are \$1,500 or less. }	D	_____
E	Child tax credit. See Pub. 972, Child Tax Credit, for more information. • If your total income will be less than \$71,201 (\$103,351 if married filing jointly), enter "4" for each eligible child. • If your total income will be from \$71,201 to \$179,050 (\$103,351 to \$345,850 if married filing jointly), enter "2" for each eligible child. • If your total income will be from \$179,051 to \$200,000 (\$345,851 to \$400,000 if married filing jointly), enter "1" for each eligible child. • If your total income will be higher than \$200,000 (\$400,000 if married filing jointly), enter "-0-"	E	_____
F	Credit for other dependents. See Pub. 972, Child Tax Credit, for more information. • If your total income will be less than \$71,201 (\$103,351 if married filing jointly), enter "1" for each eligible dependent. • If your total income will be from \$71,201 to \$179,050 (\$103,351 to \$345,850 if married filing jointly), enter "1" for every two dependents (for example, "-0-" for one dependent, "1" if you have two or three dependents, and "2" if you have four dependents). • If your total income will be higher than \$179,050 (\$345,850 if married filing jointly), enter "-0-"	F	_____
G	Other credits. If you have other credits, see Worksheet 1-6 of Pub. 505 and enter the amount from that worksheet here. If you use Worksheet 1-6, enter "-0-" on lines E and F	G	_____
H	Add lines A through G and enter the total here	H	_____

For accuracy, complete all worksheets that apply.

- If you plan to itemize or claim adjustments to income and want to reduce your withholding, or if you have a large amount of nonwage income not subject to withholding and want to increase your withholding, see the **Deductions, Adjustments, and Additional Income Worksheet** below.
- If you have more than one job at a time or are married filing jointly and you and your spouse both work, and the combined earnings from all jobs exceed \$53,000 (\$24,450 if married filing jointly), see the **Two-Earners/Multiple Jobs Worksheet** on page 4 to avoid having too little tax withheld.
- If neither of the above situations applies, stop here and enter the number from line H on line 5 of Form W-4 above.

Deductions, Adjustments, and Additional Income Worksheet

Note: Use this worksheet *only* if you plan to itemize deductions, claim certain adjustments to income, or have a large amount of nonwage income not subject to withholding.

1	Enter an estimate of your 2019 itemized deductions. These include qualifying home mortgage interest, charitable contributions, state and local taxes (up to \$10,000), and medical expenses in excess of 10% of your income. See Pub. 505 for details	1	\$ _____
2	Enter: { \$24,400 if you're married filing jointly or qualifying widow(er) \$18,350 if you're head of household \$12,200 if you're single or married filing separately }	2	\$ _____
3	Subtract line 2 from line 1. If zero or less, enter "-0-"	3	\$ _____
4	Enter an estimate of your 2019 adjustments to income, qualified business income deduction, and any additional standard deduction for age or blindness (see Pub. 505 for information about these items)	4	\$ _____
5	Add lines 3 and 4 and enter the total	5	\$ _____
6	Enter an estimate of your 2019 nonwage income not subject to withholding (such as dividends or interest)	6	\$ _____
7	Subtract line 6 from line 5. If zero, enter "-0-". If less than zero, enter the amount in parentheses	7	\$ _____
8	Divide the amount on line 7 by \$4,200 and enter the result here. If a negative amount, enter in parentheses. Drop any fraction	8	_____
9	Enter the number from the Personal Allowances Worksheet , line H, above	9	_____
10	Add lines 8 and 9 and enter the total here. If zero or less, enter "-0-". If you plan to use the Two-Earners/Multiple Jobs Worksheet , also enter this total on line 1 of that worksheet on page 4. Otherwise, stop here and enter this total on Form W-4, line 5, page 1	10	_____

Two-Earners/Multiple Jobs Worksheet

Note: Use this worksheet *only* if the instructions under line H from the **Personal Allowances Worksheet** direct you here.

- 1 Enter the number from the **Personal Allowances Worksheet**, line H, page 3 (or, if you used the **Deductions, Adjustments, and Additional Income Worksheet** on page 3, the number from line 10 of that worksheet) 1 _____
 - 2 Find the number in **Table 1** below that applies to the **LOWEST** paying job and enter it here. **However**, if you're married filing jointly and wages from the highest paying job are \$75,000 or less and the combined wages for you and your spouse are \$107,000 or less, don't enter more than "3" 2 _____
 - 3 If line 1 is **more than or equal to** line 2, subtract line 2 from line 1. Enter the result here (if zero, enter "-0-") and on Form W-4, line 5, page 1. **Do not** use the rest of this worksheet. 3 _____
- Note:** If line 1 is **less than** line 2, enter "-0-" on Form W-4, line 5, page 1. Complete lines 4 through 9 below to figure the additional withholding amount necessary to avoid a year-end tax bill.
- 4 Enter the number from line 2 of this worksheet 4 _____
 - 5 Enter the number from line 1 of this worksheet 5 _____
 - 6 Subtract line 5 from line 4 6 _____
 - 7 Find the amount in **Table 2** below that applies to the **HIGHEST** paying job and enter it here 7 \$ _____
 - 8 Multiply line 7 by line 6 and enter the result here. This is the additional annual withholding needed 8 \$ _____
 - 9 Divide line 8 by the number of pay periods remaining in 2019. For example, divide by 18 if you're paid every 2 weeks and you complete this form on a date in late April when there are 18 pay periods remaining in 2019. Enter the result here and on Form W-4, line 6, page 1. This is the additional amount to be withheld from each paycheck 9 \$ _____

Table 1				Table 2			
Married Filing Jointly		All Others		Married Filing Jointly		All Others	
If wages from LOWEST paying job are—	Enter on line 2 above	If wages from LOWEST paying job are—	Enter on line 2 above	If wages from HIGHEST paying job are—	Enter on line 7 above	If wages from HIGHEST paying job are—	Enter on line 7 above
\$0 - \$5,000	0	\$0 - \$7,000	0	\$0 - \$24,900	\$420	\$0 - \$7,200	\$420
5,001 - 9,500	1	7,001 - 13,000	1	24,901 - 84,450	500	7,201 - 36,975	500
9,501 - 19,500	2	13,001 - 27,500	2	84,451 - 173,900	910	36,976 - 81,700	910
19,501 - 35,000	3	27,501 - 32,000	3	173,901 - 326,950	1,000	81,701 - 158,225	1,000
35,001 - 40,000	4	32,001 - 40,000	4	326,951 - 410,700	1,000	158,226 - 201,000	1,000
40,001 - 46,000	5	40,001 - 60,000	5	410,701 - 617,850	1,450	201,001 - 507,800	1,450
46,001 - 55,000	6	60,001 - 75,000	6	617,851 and over	1,540	507,801 and over	1,540
55,001 - 60,000	7	75,001 - 85,000	7				
60,001 - 70,000	8	85,001 - 95,000	8				
70,001 - 75,000	9	95,001 - 100,000	9				
75,001 - 85,000	10	100,001 - 110,000	10				
85,001 - 95,000	11	110,001 - 115,000	11				
95,001 - 125,000	12	115,001 - 125,000	12				
125,001 - 155,000	13	125,001 - 135,000	13				
155,001 - 165,000	14	135,001 - 145,000	14				
165,001 - 175,000	15	145,001 - 160,000	15				
175,001 - 180,000	16	160,001 - 180,000	16				
180,001 - 195,000	17	180,001 and over	17				
195,001 - 205,000	18						
205,001 and over	19						

Privacy Act and Paperwork Reduction Act Notice. We ask for the information on this form to carry out the Internal Revenue laws of the United States. Internal Revenue Code sections 3402(f)(2) and 6109 and their regulations require you to provide this information; your employer uses it to determine your federal income tax withholding. Failure to provide a properly completed form will result in your being treated as a single person who claims no withholding allowances; providing fraudulent information may subject you to penalties. Routine uses of this information include giving it to the Department of Justice for civil and criminal litigation; to

cities, states, the District of Columbia, and U.S. commonwealths and possessions for use in administering their tax laws; and to the Department of Health and Human Services for use in the National Directory of New Hires. We may also disclose this information to other countries under a tax treaty, to federal and state agencies to enforce federal nontax criminal laws, or to federal law enforcement and intelligence agencies to combat terrorism.

You aren't required to provide the information requested on a form that's subject to the Paperwork Reduction Act unless the form displays a valid OMB control number. Books or records relating

to a form or its instructions must be retained as long as their contents may become material in the administration of any Internal Revenue law. Generally, tax returns and return information are confidential, as required by Code section 6103.

The average time and expenses required to complete and file this form will vary depending on individual circumstances. For estimated averages, see the instructions for your income tax return.

If you have suggestions for making this form simpler, we would be happy to hear from you. See the instructions for your income tax return.

ADP Employee Direct Deposit Enrollment Form

Payroll Manager—Please complete this section.

Company Code: _____ Company Name: _____ Date: _____

Payroll Mgr. Name: _____ Payroll Mgr. Signature: _____

To enroll in Full Service Direct Deposit, simply fill out this form and give it to your payroll manager. Attach a voided check for each checking account — not a deposit slip. If depositing to a savings account, ask your bank to give you the Routing/Transit Number for your account. It isn't always the same as the number on a savings deposit slip. This will help ensure that you are paid correctly.

Bank Name: _____

(b) (6), (b) (7)(C)

(A 9-digit number always between these two marks)

Checking Account #

Check #
(this number matches the number in the upper right corner of the check— not needed for sign-up)

Important! Please read and sign before completing and submitting.

I hereby authorize my employer (hereinafter "Company") to deposit any amounts owed me by initiating credit entries to my accounts at the financial institutions (hereinafter "Bank") indicated on this form. Further, I authorize Bank to accept and to credit any credit entries indicated by Company to my accounts. Unless prohibited by applicable law, in the event that Employer deposits funds erroneously into my account, I authorize Employer, either directly or through its payroll service provider, to debit my account for an amount not to exceed the original amount of the erroneous credit.

This authorization is to remain in full force and effect until Company and Bank have received written notice from me of its termination in such time and in such manner as to afford Company and Bank reasonable opportunity to act on it.

Employee Name: Trenton Henderson

Employee Signature: (b) (6), (b) (7)(C) Date: 10/6/19

Account Information

The last item must be for the remaining amount owed to you. To distribute to more accounts, please complete another form. **Make sure to indicate what kind of account, along with amount to be deposited, if less than your total net paycheck.**

1. Bank Name/City/State: (b) (6), (b) (7)(C)

Routing/Transit #: (b) (6), (b) (7)(C)

Checking Savings Other I wish to deposit: \$ _____ or Entire Net Amount

2. Bank Name/City/State: _____

Routing/Transit #: _____ Account Number: _____

Checking Savings Other I wish to deposit: \$ _____ or Entire Net Amount

3. Bank Name/City/State: _____


Routing/Transit #: _____ Account Number: _____

Checking Savings Other I wish to deposit: \$ _____ or Entire Net Amount

ATTENTION PAYROLL MANAGER:

Employers must keep each original employee enrollment form on file as long as the employee is using FSDD, and for two years thereafter.

(b) (6), (b) (7)(C)



Speed Adjusting (Synchronizing) Motor

Parts Catalog and Lubrication Guide

Operation Manual

IMPORTANT



This is the safety alert symbol. It is used to alert you to potential personal injury hazards. Obey all safety messages that follow this symbol to avoid possible injury or death.

DEFINITIONS

- **DANGER**—Indicates a hazardous situation which, if not avoided, will result in death or serious injury.
- **WARNING**—Indicates a hazardous situation which, if not avoided, could result in death or serious injury.
- **CAUTION**—Indicates a hazardous situation which, if not avoided, could result in minor or moderate injury.
- **NOTICE**—Indicates a hazard that could result in property damage only (including damage to the control).
- **IMPORTANT**—Designates an operating tip or maintenance suggestion.

WARNING

The engine, turbine, or other type of prime mover should be equipped with an overspeed shutdown device to protect against runaway or damage to the prime mover with possible personal injury, loss of life, or property damage.

The overspeed shutdown device must be totally independent of the prime mover control system. An overtemperature or overpressure shutdown device may also be needed for safety, as appropriate.



Read this entire manual and all other publications pertaining to the work to be performed before installing, operating, or servicing this equipment. Practice all plant and safety instructions and precautions. Failure to follow instructions can cause personal injury and/or property damage.



This publication may have been revised or updated since this copy was produced. To verify that you have the latest revision, be sure to check the *publications page* on the Woodward website:

www.woodward.com/publications

The current revision and distribution restriction of all publications are shown in manual **26311**.

The latest version of most publications is available on the *publications page*. If your publication is not there, please contact your customer service representative to get the latest copy.



Any unauthorized modifications to or use of this equipment outside its specified mechanical, electrical, or other operating limits may cause personal injury and/or property damage, including damage to the equipment. Any such unauthorized modifications: (i) constitute "misuse" and/or "negligence" within the meaning of the product warranty thereby excluding warranty coverage for any resulting damage, and (ii) invalidate product certifications or listings.

NOTICE

To prevent damage to a control system that uses an alternator or battery-charging device, make sure the charging device is turned off before disconnecting the battery from the system.

NOTICE

To prevent damage to electronic components caused by improper handling, read and observe the precautions in Woodward manual **82715**, *Guide for Handling and Protection of Electronic Controls, Printed Circuit Boards, and Modules*.

Speed Adjusting (Synchronizing) Motor

General Information

The motor most often used for speed adjusting or synchronizing purposes on Woodward engine and turbine controls is the Bodine type V10R motor with integral worm gear speed reducer. This manual describes the maintenance of these motors.

Lubricating Instructions

The following instructions apply to this motor model regardless of voltage input or output shaft speed.

Bearings

Use Royal A oil or a good 10 weight oil for bearing lubrication. Under normal, intermittent operation, apply 5 drops of oil to the oil hole and oil cup every year. If the motor is run for long periods of time, apply 5 drops of oil to the oil hole and oil cup every six months.

Speed Reduction Gearbox

The speed reduction gear housing of a new motor is filled with sufficient lubricant to last for two years under normal, intermittent operation. Under extensive use, when the motor is run for long periods of time, the lubricant will last about one year.

To replace grease, remove screws a, b, and c (see Figure 2) and slip off the gear housing, (see Figure 3). Clean out the old grease from the housing, and refill the gear housing 3/4 full with one of the following greases:

- Bodine Grease
- Supermil Grease No. A 72832, by Standard Oil Company
- Dow Corning Grease No. 44, when specified (temperature range is -40 to +400 °F/-40 to +204 °C)

Make sure the ball thrust bearing is reinstalled with the gear box.

Adjustments

Adjustments are unnecessary unless one of the locknuts securing the adjusting screws should loosen, changing the adjustment. In this case there are three adjustments possible with the gear housing removed.

1st Adjustment—At d of Figure 2, turn the screw in until it is hand tight, then back it off one quarter turn and tighten the locknut while holding the adjusting screw stationary. Rotate the bakelite gear (5 in Figure 2) to make sure it turns freely. Check the output shaft for endplay by pulling it in the lengthwise direction while holding the gear housing firmly. When adjusted properly, the output shaft should show no visible movement.

2nd Adjustment—At e of Figure 2 (both sides of the worm shaft), turn the worm adjusting screws to center the worm shaft with the output shaft. Check visually to determine proper alignment of the two gears. The worm adjusting screws should be positioned so each protrudes equally from its locknut when hand-tight. After hand tightening, the worm adjusting screws should be loosened just enough so that the bakelite gear (5 in Figure 2) turns freely and there is no side play in the worm shaft.

3rd Adjustment—With the gear housing reassembled on the motor, hold the motor firmly and shake it in a lengthwise direction. If a faint clicking sound is heard inside the motor, then an adjustment should be made. At f of Figure 3, with the locknut loosened, turn the screw in just enough to take the play out of the armature shaft. Adjust the screw so that the clicking sound is absent, then back the screw up a few degrees. Check by shaking the motor again. If the clicking sound is there again, adjust the screw forward approximately one-half the number of degrees it was reversed and tighten the locknut while holding the adjusting screw stationary. Check again, and with the absence of the clicking sound, this should be the approximate adjustment.

IMPORTANT	Do not bind the armature.
------------------	----------------------------------

3rd Adjustment on Optional Bodine Motor Friction Loading Kit—This adjustment can be made only on V10R motors equipped with Bodine Motor Friction Loading Kits. This is shown in Figure 4. To take play out of the armature shaft, start with the adjustment screw loose and tighten until the motor slows. Then back up the screw until normal speed is just regained. Tighten the locknut while holding adjusting screw stationary.

WARNING	This adjustment is not to be used to slow the speed of the motor. It is only used to take end play out of the armature shaft and to stop possible armature rotation caused by vibration from the engine when the motor is not powered.
----------------	---

Principal Replacement Parts

When requesting information concerning V10R Bodine Motors, or when ordering repair parts, it is essential that the following information accompany the request:

- Serial number of governor and motor type
- Voltage of motor
- Part number, name of part, or description of part
- Manual number (this is manual 03505)

Ref. No.	Part Name	Quantity	Ref. No.	Part Name	Quantity
03505-1	Motor Brush	2	03505-9	End Shield, Front	1
03505-2	Brush Spring	2	03505-10	Gear Housing Assy.	1
03505-3	Brush and Spring Assy.	2	03505-11	Field Frame Assy. Complete	1
03505-4	Worm Shaft	1	03505-12	Armature Wound Complete	1
03505-5	Bakelite Gear	1	03505-13	Output Shaft	1
03505-6	Brushholder Cap Screw	2	03505-14	Ball Thrust Washer	1
03505-7	Brushholder	2	03505-15	Spring	1
03505-8	Bronze Gear	1	03505-16	Screw	1




Figure 1




Figure 2





Figure 3



03500-A-1

Figure 4

S/LNC Goodwill - ENGINE ROOM CASUALTY w/ FA
ME: MED-PIC / 2ND MATE

~1330 awoke to a large thud. Audible from D deck, and the whole ship jerked.

I started getting dressed. The general alarm was sounding before my boots were on...

radio on: heard of a crew member "down" injured in the E/R. I headed to the hospital.

When I got to the hospital, the emergency squad was on their way to the scene with Trauma & Resuscitation go-bags.

I reported in by radio and was told to make the hospital ready to receive a patient.

I cleared off the bed, unlocked the cabinets and waited while wondering what else I could get ready.

BAE was CARRIED in on a backboard but not fully strapped down, UNCONSCIOUS, pale, covered in soot/oil, abrasions possible burns, with a serious neck wound pulsing arterial.

We treated for shock - elevated legs. - O2 started.

We cut off his shirt and belt and right upper thigh.

INITIAL Assessment found: abrasions to his arm, right torso, neck wound on right side of his neck (arterial pulsing flow), and he responded to anywhere we touched as being painful.

Everything hurt him. He was incoherent in pain. When he wasn't delirious with pain, he was complaining that he couldn't breathe. Asking to sit up to cough.

We had trouble keeping his O₂ mask on him, and had the 2AE holding it on him, even as he complained he couldn't breathe.

The arterial neck wound - one of the AB's was holding constant pressure on it, gauze was added every few minutes.

I bandaged his arms where they were scrapped and bleeding.

The CAPTAIN was there WITH MAS ON THE SAT PHONE, WE tried to start an IV.

I failed 2 IV's, 3rd one went in, was good. barely had a tape on it when he jerked his arm out of grasp. It knocked out the IV.

3M was assigned to talking to MAS. AED applied. NO SHOCK

I tried another IV. no good.

We got approval from MAS for 1mL morphine. @1427 without the IV, we opted for intermuscular Morphine was given. it didn't seem to ease any pain initially.

Another IV attempted in left hand, succeeded. Drip started.

3AE is and out of consciousness. AED - NO SHOCK

MAS authorizes epi-pen from trauma bag w/ 3AE UNCONSCIOUS. @1533

Listing meds onboard to MAS - they want more epi-pen. OS gets his personal epi-pen. administered. ~1540?

3AE unconscious. Blood pressures steady at first, 135/117

We lose pulse. CPR STARTED. @ 1528. AED - no shock

IV DRIP NOT going in, embolise? local puffing and drip NOT going in affectively. removed.

MAS asks to ventilate right lung with IV needle.

CPR continues. AED - no shock

NASAL AIRWAY inserted. CPR continues.

MAS asks again to ventilate lung with IV needle. FIRST ONE has fallen out. New one inserted.

CPR continues AED - no shock

Captain consults MAS, returns and makes the decision to stop CPR. All agree that we've done all we can, helo estimates more than 30 minutes out.

Crew preparing for helo-ops. Crew told to rest and be ready for emergency tow-ops. AED disconnected. O₂ STOPPED.

I start cleaning up hospital. Radio UHF - JAPAN doctor says to resume CPR until helo arrives.

CPR resumes. With helo in sight? we prepare basket for 3AE transport. Carry him on deck outside hospital.

Japanese doctor has us continue CPR on deck WITH THEIR AED. Still no shock advised. 3AE transported to stern to be med-evac'd.

I continued to clean up the hospital until I was told to stop and rest until I'm needed for emergency tow. Hospital locked up. emergency tow estimated arrival 20:00.

No AC - I go up to the bridge for some air.

I offer to take the watch (my normal watch hours). CAPT checks that I've eaten and had water. I confirm that I can stand watch until 20:00 at least and let the 3M step below for food.

I create a voyage plan to Sasebo for anchoring. CAPTAN reviews it and approves it.

20:00 I'm relieved of watch for rest. Vessel drifting NUC with 1 generator online - no propulsion. There was communication with JAPAN COAST GUARD that if we get wks 6 nm of shore we will accept e-tow from on station cutter, but we are awaiting salvage tug arrival.

//
0400-0800 watch 06AUG20.

We are underway w/ our own propulsion, following voyage plan track to SASEBO for safe harbor anchorage for repairs.

0800-1200. Continue cleaning hospital - inventory to be done and re-order supplies after.

1600-2000 AT ANCHOR SASEBO, JP

(b) (6), (b) (7)(C)

Chief Engineer's Statement 08 AUGUST 2020

On 03 August 2020 DG#1 when started was observed to hunt excessively. Upon troubleshooting it was determined to change the governor and install overhauled spare in stock. This overhauled spare was taken from storage location and inspected for use.

04 August 2020 First Assistant Engineer and Third Assistant Engineer removed old governor and installed new one. I came down to see how progress was made and gave a hand with installing the new one. This was not completed due being at the end of the work day. It was decided to continue the following day.

05 August 2020 after lunch time the First Assistant Engineer and Third Assistant Engineer completed final assembly items of the governor. I came down to the engine room to see their progress. Everything was ready and the engine was inspected to ensure all items in correct status prior to starting the engine. I was located at the after end of the generator room between #1 and #2 generators. First Assistant Engineer and Third Assistant Engineer were facing the starting box and governor assembly. Engine was started, came up to speed, hunted for a few seconds and then shut off on overspeed as indicated on the starting box. Parameters were double checked, governor parameters checked and overspeed device reset. It was decided to try this again in order to determine what the cause of the engine hunting was. Engine was started, sped up fast and seemed like it went past overspeed rpm. First Assistant engineer tried shut the engine down at the starting box without any success. Then he ran over to the mechanical overspeed device to attempt to shut down the engine. I yelled over for them to get out of the way and at that point something seemed to break on the engine with smoke coming from it, explosion happened and then the lights went out. All of this happened very quickly. I got my flashlight out and turned it on, then proceeded through the #3DG room and coming out of the forward exit. As I went through the #3 generator room I observed it was still running but no power being supplied. As I exited the #3 generator room the emergency lights came on. I then proceed to call for the First Assistant and Third Assistant Engineer. I went into the #1 and #2 generator room, all lights were out, smoke in the air, water spraying in different directions. I found the Third Assistant Engineer laying on the deck with a piece of the flywheel leaned up against his torso. I ran over calling his name with no response and pulled the piece of flywheel away from him. I saw a cut by the lower part of his throat and I put a rag I found on it, applied pressure and held his head stable calling for help. Then proceeded to check for breathing and he was breathing but unconscious. By then the Chief Mate and emergency team arrived to help me move the Third Assistant Engineer out of the #1 and #2 Generator Room. The emergency team began to administer first aid and stabilize the Third Assistant Engineer in order to move him to the ship's hospital.

I was then called by the Captain to provide an assessment of the main power and propulsion. I gave him a status report and then I was ordered to get the engine crew and begin restoring power and propulsion.

DG3 oil temperature was hot by this time and no 24VDC supply to tachometer start box and control relays. We had to secure DG3 until these issues were corrected. Went to establish condition of start air pressure and found one bottle had air supply and the other depleted. 1AE began working on start air supply, securing the isolation valves for DG1 and DG2 and ensured start air supply for DG3 was healthy. Also he started the emergency air compressor.

At this point the K-Chief system was supposed to still be operating due to UPS battery supplies, however these units were offline. I then ran extension cords to the K-Chief computers and restarted them.

Then I fabricated a 220VAC to 24VDC power supply to get ready to install on #3 just in case this unit could not be started. We then established that there was sufficient air to start DG3 with the emergency air start device.

DG3 was started and put online but cooling water supply was not cooling the generator lube oil. We then checked the regulating valve and tried to open this manually. After it was opened manually it would close again due to not having the 24VDC signal to stay open. We shut the power back off and secured the generator until we could get the regulating valve open. Opened the valve manually and removed the terminal cables from the unit and then decided to start again.

DG3 was started, put online and sea water and LT cooling pumps energized. DG3 began to cool off and operate successfully. We then proceeded to line up fuel supply for diesel fuel operation. After lining up diesel fuel operation we bled the oil from the exhaust valves on the main engine and then prepared main engine for operation. Rolled over on gear and tested on starting air. Test successful. Gave control to Bridge and Propulsion restored.

(b) (6), (b) (7)(C)

Chief Engineer SLNC GOODWILL

(b) (4)



(b) (6), (b) (7)(C)

August 6, 2020

Statement to the Events of 05 August 2020

- Working in the focsle when the ship went quiet and dark.
- Called by Capt. multiple alarms on the fire and water mist detector panel in the ER
- Ran back to the house and proceeded into the ER
- Immediately upon opening of the engine room space there was smoke, steam and it was hot.
- Proceeded to the Generator Flat and looked for fire, no fire noted, reported no fire to the bridge.
- Saw the CE in between the No1 and No2 Generator calling for help. He was holding the 3AE
- Reported medical emergency to bridge
- Proceeded to assist CE in moving the 3AE from the scene of the accident into the main engine room.
- Transferred 3AE to stretcher with neck collar in place
- Moved 3AE up to hospital
- Once on Upper deck, broke off from transporting to check IGG space for fire, due to alarm reported from the bridge.
- On arrival to hospital MAS phone handed to me by Capt.
- Started conversation with MAS and reported what was asked described injuries, bruising and assigned people to do jobs, get vitals, try to stick an IV, provide oxygen, connected the AED, etc.
- Noted complications with breathing, short rapid breaths
- Multiple attempts with MAS to understand procedure to release fluid or air trapped in lung. After failure to understand handed phone off to 4M to see if he could understand procedure. Continued to stick 3 times to relieve pressure, never noted any air or liquid coming out.
- Weakening breath, until finally ceased to breath
- Immediately started CPR, tried to establish radial pulse
- Continued CPR 30 compressions and 2 breaths as instructed by MAS
- 1620 At instruction of Capt and MAS checked pupils twice with flashlight, no response. Ordered to stop providing CPR.
- 1626 on order of Japanese Coast Guard resumed CPR
- Approximately 5 mins before arrival of helicopter proceeded on deck to ensure no loose items and everything was secured.
- Met helicopter crew at the Hospital, JP Coast Guard placed AED on 3AE, ordered to continue CPR
- Transported 3AE to stbd stern
- Transferred to JP Coast Guard stokes litter
- JP Coast Guard winched off ship.

(b) (6), (b) (7)(C)

WORK COMPLETION REPORT

JEWON ENGINEERING
Technical Repairing Team

- ◆ CUSTOMER/END USER : SCHUYLERLINE
- ◆ Location : BUSAN / Rep of KOREA
- ◆ Site / Ship(Hull)'s Name : M/V SLNC GOODWILL
- ◆ Reason : UG-8D GOVERNOR 1 SET OVERHAUL
- ◆ Charged Person : (b) (6), (b) (7)(C)
- ◆ GOVERNOR INFORMATION
 - 1. Governor Manufacturer : WOODWARD
 - 2. Governor Vendor/Type : UG-8D
 - 3. Governor P/N & S/N : Part No. : 8521-0047DC, Serial No. : 14639129

◆ TIME TABLE for TRAVEL/WORK SERVICE

DATE	TIME for WORK				TIME for TRAVEL		REMARKS
	Start Time	End Time	Reg. Times	Over Times	Reg. Times	Over Times	
2019.07.08							Received
-							Overhauled
2019.07.22							Exchange



I certify and confirm that the works contained in this report has been completed to my satisfaction and list of replacement is correct.


CUSTOMER Signature
(b) (6), (b) (7)(C)

SERVICE ENGINEER'S
(b) (6), (b) (7)(C)

(b) (6), (b) (7)(C)

◆ DEFECTIVE & USED SPARE PARTS

	Part. Name.	Reference No.	Part. No.	Number	Unit	Remark
1	DIAL PLATE		3099-935	1	EA	
2	BALLHEAD ASSEMBLY		31507	1	SET	MODIFYING
3	DIAL PANEL ASSEMBLY		34535	1	SET	
4	NEEDLE VALVE		30009	1	EA	DEFECTIVE
5	-Blank-					
6						
7						
8						
9						
10						
11						
12						
13						
14						
15						
16						
17						
18						
19						
20						
21						
22						
23						
24						
25						
26						
27						



I certify and confirm that the works contained in this report has been completed to my satisfaction and list of replacement is correct.

CUSTOMER Signature
 (b) (6), (b) (7)(C)

(b) (6), (b) (7)(C)
 (b) (6), (b) (7)(C)


(b) (6), (b) (7)(C)

◆ PURPOSE OF WORK


- A. It is Highly recommended that Hydraulic-Mechanical Governor/Actuator should be done periodical maintenance in order to extend its service life, Hydraulic-Mechanical Governor/Actuator consist of mechanically moving parts and life limited parts in it that requires periodical maintenance or overhaul
- B. Carrying out work for modification and maintenance of the Governor.
- C. Modifying from 8521-0047DC to 8520-0041

◆ WORK

- 1. Jul.08th.2019. Visit agent office at Po-hang, Rep. of Korea, and received the UG-8D governor for M/V SLNC GOODWILL (1 set)
- 2. Disassembled governor
 - 2-1 Disassembled governor




3. Clean each parts and carry out parts inspection for modifying.



4. Defective & Need spare parts.

Part name	Part No.	Number	unit	Remark
DIAL PLATE	3099-935	1	EA	
BALLHEAD ASSEMBLY	31507	1	SET	Spare parts needed for modifying.
DIAL PANEL ASSEMBLY	34535	1	SET	
NEEDLE VALVE	30009	1	EA	Defective part.

4.1. Ballhead A'ssy




4.2. Dial panel A'ssy.



4.3. Dial plate



4.4. Needle valve : Mark point was were down.



5. Tested governor on test stand




6. 2019.07.22 onboard to M/V SLNC GOODWILL at Busan, Rep. of Korea for exchange the governor.
7. Exchange the governor of No.2 generator engine after conference with the ship's crew.
8. Test governor with ship's crew. And found good condition.

◆ Remark

1. The spare parts for modifying of governor were used.
2. Because no have new spare parts in my company and the delivery date takes a long time.

- END -





RECORD OF HOURS OF REST

Aug 2020

IMO STCW 2010(+Manila)

Vessel: SLNC Goodwill

IMO No: 9448334

Flag: United States

Seafarer (Full Name): (b) (6), (b) (7)(C)

Position (Rank): (b) (6), (b) (7)(C)

Watchkeeper: NO



Date	Periods of work are shaded																								Hours of work in 24h period	Hours of rest in 24h period	Comments	NOT TO BE COMPLETED BY THE SEAFARER		
	00	01	02	03	04	05	06	07	08	09	10	11	12	13	14	15	16	17	18	19	20	21	22	23				24	Hours of rest in any 24h period	Hours of rest in any 7 day period
8/1/2020																										11.0	13.0		13.0	94.5
8/2/2020																										11.0	13.0		13.0	91.0
8/3/2020																										11.0	13.0		13.0	91.0
8/4/2020																										11.0	13.0		13.0	91.0
8/5/2020																										11.0	13.0		13.0	91.0
8/6/2020																										11.0	13.0		13.0	91.0
8/7/2020																										6.5	17.5		13.0	95.5
8/8/2020																										11.0	13.0		11.5	95.5
8/9/2020																										11.0	13.0		12.0	95.5
8/10/2020																										11.0	13.0		12.0	95.5
8/11/2020																										11.0	13.0		12.0	95.5
8/12/2020																										11.0	13.0		12.0	95.5
8/13/2020																										11.0	13.0		12.0	95.5
8/14/2020																										11.0	13.0		12.0	91.0
8/15/2020																										11.0	13.0		12.0	91.0
8/16/2020																										11.0	13.0		12.0	91.0
8/17/2020																										11.0	13.0		12.0	91.0
8/18/2020																										11.0	13.0		12.0	91.0
8/19/2020																										11.0	13.0		12.0	91.0
8/20/2020																										11.0	13.0		12.0	91.0
8/21/2020																										11.0	13.0		12.0	91.0
8/22/2020																										11.0	13.0		12.0	91.0
8/23/2020																										11.0	13.0		12.0	91.0
8/24/2020																										11.0	13.0		12.0	91.0
8/25/2020																										11.0	13.0		12.0	91.0
8/26/2020																										11.0	13.0		12.0	91.0
8/27/2020																										11.0	13.0		12.0	91.0
8/28/2020																										11.0	13.0		12.0	91.0
8/29/2020																										11.0	13.0		12.0	91.0
8/30/2020																										11.0	13.0		12.0	91.0
8/31/2020																										11.0	13.0		12.0	91.0
	00	01	02	03	04	05	06	07	08	09	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	336.5	407.5			

The following national laws, regulations and/or collective agreements governing limitations on working hours or minimum rest periods apply to this ship:

USCG, IMO STCW 2010, OPA 90, MM&P, SIU

I AGREE THAT THIS RECORD IS AN ACCURATE REFLECTION OF THE HOURS OF WORK OR REST OF THE SEAFARER CONCERNED.

Name of master or person authorized by master to sign this record: (b) (6), (b) (7)(C) (b) (6), (b) (7)(C)

Signature of master or authorized person: _____

Signature of seafarer: _____

A copy of this record is to be given to the seafarer. This form is subject to examination and endorsement under procedures established by:

United States (name of competent authority)



RECORD OF HOURS OF REST

Aug 2020

IMO STCW 2010(+Manila)

Vessel: SLNC Goodwill

IMO No: 9448334

Flag: United States

Seafarer (Full Name): (b) (6), (b) (7)(C)

Position (Rank): (b) (6), (b) (7)(C)

Watchkeeper: YES



Date	Periods of work are shaded																								Hours of work in 24h period	Hours of rest in 24h period	Comments	NOT TO BE COMPLETED BY THE SEAFARER		
	00	01	02	03	04	05	06	07	08	09	10	11	12	13	14	15	16	17	18	19	20	21	22	23				24	Hours of rest in any 24h period	Hours of rest in any 7 day period
8/1/2020																										10.5	13.5		13.0	94.5
8/2/2020																										10.5	13.5		13.0	94.5
8/3/2020																										10.5	13.5		13.0	94.5
8/4/2020																										10.5	13.5		13.0	94.5
8/5/2020																										10.5	13.5		13.0	94.5
8/6/2020																										10.5	13.5		13.0	94.5
8/7/2020																										10.5	13.5		13.0	94.5
8/8/2020																										10.5	13.5		13.0	94.5
8/9/2020																										10.5	13.5		13.0	94.5
8/10/2020																										10.5	13.5		13.0	94.5
8/11/2020																										10.5	13.5		13.0	94.5
8/12/2020																										10.5	13.5		13.0	94.5
8/13/2020																										10.5	13.5		13.0	94.5
8/14/2020																										10.5	13.5		13.0	94.5
8/15/2020																										10.5	13.5		13.0	94.5
8/16/2020																										10.5	13.5		13.0	94.5
8/17/2020																										10.5	13.5		13.0	94.5
8/18/2020																										10.5	13.5		13.0	94.5
8/19/2020																										10.5	13.5		13.0	94.5
8/20/2020																										10.5	13.5		13.0	94.5
8/21/2020																										10.5	13.5		13.0	94.5
8/22/2020																										10.5	13.5		13.0	94.5
8/23/2020																										10.5	13.5		13.0	94.5
8/24/2020																										10.5	13.5		13.0	94.5
8/25/2020																										10.5	13.5		13.0	94.5
8/26/2020																										10.5	13.5		13.0	94.5
8/27/2020																										10.5	13.5		13.0	94.5
8/28/2020																										10.5	13.5		13.0	94.5
8/29/2020																										10.5	13.5		13.0	94.5
8/30/2020																										10.5	13.5		13.0	94.5
8/31/2020																										10.5	13.5		13.0	94.5
	00	01	02	03	04	05	06	07	08	09	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	325.5	418.5			

The following national laws, regulations and/or collective agreements governing limitations on working hours or minimum rest periods apply to this ship:

USCG, IMO STCW 2010, OPA 90, MM&P, SIU

I AGREE THAT THIS RECORD IS AN ACCURATE REFLECTION OF THE HOURS OF WORK OR REST OF THE SEAFARER CONCERNED.

Name of master or person authorized by master to sign this record: (b) (6), (b) (7)(C) (b) (6), (b) (7)(C)

Signature of master or authorized person: _____

Signature of seafarer: _____

A copy of this record is to be given to the seafarer. This form is subject to examination and endorsement under procedures established by:

United States (name of competent authority)



RECORD OF HOURS OF REST

Aug 2020

IMO STCW 2010(+Manila)

Vessel: SLNC Goodwill

IMO No: 9448334

Flag: United States

Seafarer (Full Name): (b) (6), (b) (7)(C)

Position (Rank): (b) (6), (b) (7)(C)

Watchkeeper: NO



Date	Periods of work are shaded																								Hours of work in 24h period	Hours of rest in 24h period	Comments	NOT TO BE COMPLETED BY THE SEAFARER		
	00	01	02	03	04	05	06	07	08	09	10	11	12	13	14	15	16	17	18	19	20	21	22	23				24	Hours of rest in any 24h period	Hours of rest in any 7 day period
8/1/2020																										10.5	13.5		12.0	94.5
8/2/2020																										10.5	13.5		12.0	94.5
8/3/2020																										10.5	13.5		12.0	94.5
8/4/2020																										10.5	13.5		12.0	94.5
8/5/2020																										10.5	13.5		12.0	94.5
8/6/2020																										10.5	13.5		12.0	94.5
8/7/2020																										10.5	13.5		12.0	94.5
8/8/2020																										10.5	13.5		12.0	94.5
8/9/2020																										10.5	13.5		12.0	94.5
8/10/2020																										10.5	13.5		12.0	94.5
8/11/2020																										10.5	13.5		12.0	94.5
8/12/2020																										10.5	13.5		12.0	94.5
8/13/2020																										10.5	13.5		12.0	94.5
8/14/2020																										10.5	13.5		12.0	94.5
8/15/2020																										10.5	13.5		12.0	94.5
8/16/2020																										10.5	13.5		12.0	94.5
8/17/2020																										10.5	13.5		12.0	94.5
8/18/2020																										10.5	13.5		12.0	94.5
8/19/2020																										10.5	13.5		12.0	94.5
8/20/2020																										10.5	13.5		12.0	94.5
8/21/2020																										10.5	13.5		12.0	94.5
8/22/2020																										10.5	13.5		12.0	94.5
8/23/2020																										10.5	13.5		12.0	94.5
8/24/2020																										10.5	13.5		12.0	94.5
8/25/2020																										10.5	13.5		12.0	94.5
8/26/2020																										10.5	13.5		12.0	94.5
8/27/2020																										10.5	13.5		12.0	94.5
8/28/2020																										10.5	13.5		12.0	94.5
8/29/2020																										10.5	13.5		12.0	94.5
8/30/2020																										10.5	13.5		12.0	94.5
8/31/2020																										10.5	13.5		12.0	94.5
	00	01	02	03	04	05	06	07	08	09	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	325.5	418.5			

The following national laws, regulations and/or collective agreements governing limitations on working hours or minimum rest periods apply to this ship:

USCG, IMO STCW 2010, OPA 90, MM&P, SIU

I AGREE THAT THIS RECORD IS AN ACCURATE REFLECTION OF THE HOURS OF WORK OR REST OF THE SEAFARER CONCERNED.

Name of master or person authorized by master to sign this record: (b) (6), (b) (7)(C)

Signature of master or authorized person: _____

Signature of seafarer: _____

A copy of this record is to be given to the seafarer. This form is subject to examination and endorsement under procedures established by:

United States (name of competent authority)



RECORD OF HOURS OF REST

Aug 2020

IMO STCW 2010(+Manila)

Vessel: SLNC Goodwill

IMO No: 9448334

Flag: United States

Seafarer (Full Name): (b) (6), (b) (7)(C)

Position (Rank): (b) (6), (b) (7)(C)

Watchkeeper: YES



Date	Periods of work are shaded																								Hours of work in 24h period	Hours of rest in 24h period	Comments	NOT TO BE COMPLETED BY THE SEAFARER		
	00	01	02	03	04	05	06	07	08	09	10	11	12	13	14	15	16	17	18	19	20	21	22	23				24	Hours of rest in any 24h period	Hours of rest in any 7 day period
8/1/2020																										10.0	14.0		12.5	101.0
8/2/2020																										10.5	13.5		12.0	100.0
8/3/2020																										8.5	15.5		12.0	101.0
8/4/2020																										11.0	13.0		11.5	99.5
8/5/2020																										13.0	11.0		9.5	96.0
8/6/2020																										9.5	14.5		9.5	96.0
8/7/2020																										8.5	15.5		13.0	97.0
8/8/2020																										9.5	14.5		13.0	97.5
8/9/2020																										9.5	14.5		13.0	98.5
8/10/2020																										9.5	14.5		13.0	97.5
8/11/2020																										9.5	14.5		13.0	99.0
8/12/2020																										9.5	14.5		13.0	102.5
8/13/2020																										9.5	14.5		13.0	102.5
8/14/2020																										9.5	14.5		13.0	101.5
8/15/2020																										9.5	14.5		13.0	101.5
8/16/2020																										9.5	14.5		13.0	101.5
8/17/2020																										9.5	14.5		13.0	101.5
8/18/2020																										9.5	14.5		13.0	101.5
8/19/2020																										9.5	14.5		13.0	101.5
8/20/2020																										9.5	14.5		13.0	101.5
8/21/2020																										9.5	14.5		13.0	101.5
8/22/2020																										9.5	14.5		13.0	101.5
8/23/2020																										9.5	14.5		13.0	101.5
8/24/2020																										9.5	14.5		13.0	101.5
8/25/2020																										9.5	14.5		13.0	101.5
8/26/2020																										9.5	14.5		13.0	101.5
8/27/2020																										9.5	14.5		13.0	101.5
8/28/2020																										9.5	14.5		13.0	101.5
8/29/2020																										9.5	14.5		13.0	101.5
8/30/2020																										9.5	14.5		13.0	101.5
8/31/2020																										9.5	14.5		13.0	101.5
	00	01	02	03	04	05	06	07	08	09	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	299.0	445.0			

The following national laws, regulations and/or collective agreements governing limitations on working hours or minimum rest periods apply to this ship:

USCG, IMO STCW 2010, OPA 90, MM&P, SIU

I AGREE THAT THIS RECORD IS AN ACCURATE REFLECTION OF THE HOURS OF WORK OR REST OF THE SEAFARER CONCERNED.

Name of master or person authorized by master to sign this record: (b) (6), (b) (7)(C)

Signature of master or authorized person: _____

Signature of seafarer: _____

A copy of this record is to be given to the seafarer. This form is subject to examination and endorsement under procedures established by:

United States (name of competent authority)



RECORD OF HOURS OF REST

Aug 2020

IMO STCW 2010(+Manila)

Vessel: SLNC Goodwill

IMO No: 9448334

Flag: United States

Seafarer (Full Name): (b) (6), (b) (7)(C)

Position (Rank): (b) (6), (b) (7)(C) (b) (6), (b) (7)(C) (b) (6), (b) (7)(C)

Watchkeeper: NO



Date	Periods of work are shaded																								Hours of work in 24h period	Hours of rest in 24h period	Comments	NOT TO BE COMPLETED BY THE SEAFARER		
	00	01	02	03	04	05	06	07	08	09	10	11	12	13	14	15	16	17	18	19	20	21	22	23				24	Hours of rest in any 24h period	Hours of rest in any 7 day period
8/1/2020																										11.0	13.0		13.0	91.0
8/2/2020																										11.0	13.0		13.0	91.0
8/3/2020																										11.0	13.0		13.0	91.0
8/4/2020																										11.0	13.0		13.0	91.0
8/5/2020																										11.0	13.0		13.0	91.0
8/6/2020																										11.0	13.0		13.0	91.0
8/7/2020																										11.0	13.0		13.0	91.0
8/8/2020																										11.0	13.0		13.0	91.0
8/9/2020																										11.0	13.0		13.0	91.0
8/10/2020																										11.0	13.0		13.0	91.0
8/11/2020																										11.0	13.0		13.0	91.0
8/12/2020																										11.0	13.0		13.0	91.0
8/13/2020																										11.0	13.0		13.0	91.0
8/14/2020																										11.0	13.0		13.0	91.0
8/15/2020																										11.0	13.0		13.0	91.0
8/16/2020																										11.0	13.0		13.0	91.0
8/17/2020																										11.0	13.0		13.0	91.0
8/18/2020																										11.0	13.0		13.0	91.0
8/19/2020																										11.0	13.0		13.0	91.0
8/20/2020																										11.0	13.0		13.0	91.0
8/21/2020																										11.0	13.0		13.0	91.0
8/22/2020																										11.0	13.0		13.0	91.0
8/23/2020																										11.0	13.0		13.0	91.0
8/24/2020																										11.0	13.0		13.0	91.0
8/25/2020																										11.0	13.0		13.0	91.0
8/26/2020																										11.0	13.0		13.0	91.0
8/27/2020																										11.0	13.0		13.0	91.0
8/28/2020																										11.0	13.0		13.0	91.0
8/29/2020																										11.0	13.0		13.0	91.0
8/30/2020																										11.0	13.0		13.0	91.0
8/31/2020																										11.0	13.0		13.0	91.0
	00	01	02	03	04	05	06	07	08	09	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	341.0	403.0			

The following national laws, regulations and/or collective agreements governing limitations on working hours or minimum rest periods apply to this ship:

USCG, IMO STCW 2010, OPA 90, MM&P, SIU

I AGREE THAT THIS RECORD IS AN ACCURATE REFLECTION OF THE HOURS OF WORK OR REST OF THE SEAFARER CONCERNED.

Name of master or person authorized by master to sign this record: (b) (6), (b) (7)(C)

Signature of master or authorized person: _____

Signature of seafarer: _____

A copy of this record is to be given to the seafarer. This form is subject to examination and endorsement under procedures established by:

United States (name of competent authority)



RECORD OF HOURS OF REST

Aug 2020

IMO STCW 2010(+Manila)

Vessel: SLNC Goodwill

IMO No: 9448334

Flag: United States

Seafarer (Full Name): 09 Trenton Lloyd-Rees

Position (Rank): (b) (6), (b) (7)(C)

Watchkeeper: YES



Date	Periods of work are shaded																								Hours of work in 24h period	Hours of rest in 24h period	Comments	NOT TO BE COMPLETED BY THE SEAFARER		
	00	01	02	03	04	05	06	07	08	09	10	11	12	13	14	15	16	17	18	19	20	21	22	23				24	Hours of rest in any 24h period	Hours of rest in any 7 day period
8/1/2020																										10.5	13.5		13.0	92.0
8/2/2020																										10.5	13.5		13.0	92.0
8/3/2020																										10.5	13.5		13.0	95.0
8/4/2020																										10.5	13.5		13.0	94.5
8/5/2020																										10.5	13.5		13.0	94.5
8/6/2020																										10.5	13.5		13.0	94.5
8/7/2020																										10.5	13.5		13.0	94.5
8/8/2020																										10.5	13.5		13.0	94.5
8/9/2020																										10.5	13.5		13.0	94.5
8/10/2020																										10.5	13.5		13.0	94.5
8/11/2020																										10.5	13.5		13.0	94.5
8/12/2020																										10.5	13.5		13.0	94.5
8/13/2020																										10.5	13.5		13.0	94.5
8/14/2020																										10.5	13.5		13.0	94.5
8/15/2020																										10.5	13.5		13.0	94.5
8/16/2020																										10.5	13.5		13.0	94.5
8/17/2020																										10.5	13.5		13.0	94.5
8/18/2020																										10.5	13.5		13.0	94.5
8/19/2020																										10.5	13.5		13.0	94.5
8/20/2020																										10.5	13.5		13.0	94.5
8/21/2020																										10.5	13.5		13.0	94.5
8/22/2020																										10.5	13.5		13.0	94.5
8/23/2020																										10.5	13.5		13.0	94.5
8/24/2020																										10.5	13.5		13.0	94.5
8/25/2020																										10.5	13.5		13.0	94.5
8/26/2020																										10.5	13.5		13.0	94.5
8/27/2020																										10.5	13.5		13.0	94.5
8/28/2020																										10.5	13.5		13.0	94.5
8/29/2020																										10.5	13.5		13.0	94.5
8/30/2020																										10.5	13.5		13.0	94.5
8/31/2020																										10.5	13.5		13.0	94.5
	00	01	02	03	04	05	06	07	08	09	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	325.5	418.5			

The following national laws, regulations and/or collective agreements governing limitations on working hours or minimum rest periods apply to this ship:

USCG, IMO STCW 2010, OPA 90, MM&P, SIU

I AGREE THAT THIS RECORD IS AN ACCURATE REFLECTION OF THE HOURS OF WORK OR REST OF THE SEAFARER CONCERNED.

Name of master or person authorized by master to sign this record: (b) (6), (b) (7)(C)

Signature of master or authorized person: _____

Signature of seafarer: _____

A copy of this record is to be given to the seafarer. This form is subject to examination and endorsement under procedures established by:

United States (name of competent authority)